Tree Conservation Report 424 Churchill Avenue North Ottawa, Ontario

Document Control Page

CLIENT:	GSI Properties					
PROJECT NAME:	Tree Conservation Report 424 Churchill Avenue North Ottawa, Ontario					
REPORT TITLE:	Tree Conservation Report 424 Churchill Avenue North Ottawa, Ontario					
IBI REFERENCE:	139413					
VERSION:	1.0					
DIGITAL MASTER:	https://ibigroup.sharepoint.com/sites/Projects2/139413/Internal Documents/6.0_Technical/6.05_Landscape/03_Reports/LTR_424_Churchilll_2022-10-07_DRAFT.docx\202 14\MG					
ORIGINATOR:	Tim McCormick					
REVIEWER:	Erin Hellinga					
AUTHORIZATION:	Tim McCormick					
CIRCULATION LIST:	Jemmy Taing (GSI Properties), Kris Benes (Open Plan Architects Inc.)					
HISTORY:						

Table of Contents

1	Introdu	iction and Overview				
2	Methodology					
	2.1	Definitions of Measurements for Tree Inventory Data Collection				
		2.1.1 Tree Condition Assessment				
3	Observ	vations				
	3.1	Species				
		3.1.1 Species at Risk				
		3.1.2 Invasive Species				
	3.2	Shared Boundary Trees and Impacts to Trees on Adjacent Properties				
4	Analysis					
	4.1	Trees to be Preserved and Protected				
	4.2	Trees to be Removed				
	4.3	Tree Preservation/Removal Summary				
5	Recommendations4					
	5.1	Tree Protection Fencing				
6	Constr	uction Impact Mitigation				
	6.1	Potential Construction Impacts to Trees				
		6.1.1 Soil Compaction and Root Damage				
		6.1.2 Mechanical Damage				
		6.1.3 Root Damage				
	6.2	Protecting and Managing Trees During Construction				
7	Dieclai					

Table of Contents

List of Appendices

Appendix A Tree Conservation Plan, Sheets TPP-1 and TPP-2

1 Introduction and Overview

Arcadis IBI Group (IBI) was retained by GSI Properties to prepare a Tree Conservation Report for the proposed development property at 424 Churchill Avenue located in Ottawa, Ontario.

The subject property (Study Area) has an area of approximately 0.11 ha and is currently a commercial plaza with the associated parking lot. The proposed project includes the development of the subject property with a midrise tower that includes underground parking. The property is bounded by Danforth Avenue to the north and Byron Avenue to the south.

The report and plans will become part of any and all formal *Planning Act* submissions. It is informed by and aligns with the following:

The City of Ottawa Tree Protection By-law No. 2020-340

Tree Conservation Plan, drawings TPP-1 (dated October 7, 2022), must be read and understood in conjunction with this report.

2 Methodology

Mr. Tim McCormick, OALA, CSLA, ISA Certified Arborist ON-0899A, completed an onsite review and assessment of the trees within the subject property on May 7, 2022. Ms. Brittany Semmler, Ecologist completed an additional review on August 7, 2022. The Study Area included the subject property and adjacent private property within 5.0 m of the property boundaries. Trees within the Study Area that were 10 cm diameter at breast height (DBH) and greater were inventoried and assigned unique tree identifications.

Each tree inventoried had the following data gathered: tree species, DBH in centimetres, health condition, and dripline radius in metres. The location of each tree was total station surveyed and is included on the Tree Preservation/Enhancement Plan (TPEP Plan), drawings No. TPP-1 and TPP-2. Tree data has been compiled into Table 1 and is included in Appendix A of this document.

2.1 Definitions of Measurements for Tree Inventory Data Collection

Tree assessment includes specific measurements as part of the field review. Outlined below are measurements taken as part of the field tree inventory:

DBH: Measurement of the trunk at 1.4 m above grade. Expressed as diameter in centimetres.

Drip line: Measurement of the approximate extents of the branches as measured from the trunk of the tree. This also represents the general root zone of the tree. Expressed as a radius in metres.

2.1.1 Tree Condition Assessment

Excellent: (Healthy)

No major branch mortality: crown is reasonably normal with less than 10% branch or twig mortality; no signs of decay.

Very Good: (Healthy)

Minimal major branch mortality: crown is reasonably normal with twig dieback in 10-20% of the crown; minimal signs of decay.

Good: (Light Decline)

Branch mortality, twig dieback in 20-30% of the crown: broken branches or crown missing based on presence of old snags is less than 26%; minor evidence of decay.

Fair: (Moderate Decline)

Branch mortality, twig dieback in 40-50% of the crown: broken branches or crown area missing based on presence of old snags is 50% or less; decay evident.

Poor: (Severe Decline)

Branch mortality, twig dieback in more than 50% of the crown: broken branches or crown area missing based on presence of old snags in more than 50%; decay resulting in high hazard assessment.

Dead:

Tree is dead, either standing or down: phloem under bark has brown streaks: few epicormic shoots may be present.

3 Observations

The property at 424 Churchill Avenue North is bounded by Byron Avenue to the south and Danforth Avenue to the north, refer to Figure 1. A total of thirty-five (35) trees were inventoried within the subject property boundary and another four (4) trees located on adjacent properties or at the boundary edge that were reviewed within the overall Study Area. The trees reviewed consisted of only deciduous species. Several of the species are non-native or invasive species. There are isolated native species intermixed on the property. The trees are located primarily along north side of the property below a retaining wall that extends through the subject property.



Figure 1: Aerial Imagery of Study Area (Google Earth image)

3.1 Species

Species observed in the Study Area included: Manitoba Maple (*Acer negundo*), Norway Maple (*Acer platanoides*), Black Walnut (*Juglans nigra*), Burr Oak (*Quercus macrocarpa*), Common Buckthorn (*Rhamnus cathartica*), Basswood (*Tilia americana*), and White Elm (*Ulmus americana*).

3.1.1 Species at Risk

There were no rare, endangered, threatened, or significant tree or shrub species observed within the subject area or adjacent residential properties.

3.1.2 Invasive Species

Present within the Study Area were two (2) non-native invasive species (Norway Maple and Common Buckthorn) and one (1) native invasive (Manitoba Maple). These invasive species are considered threats to the local ecosystem and biodiversity as they can quickly outcompete native plants. Control of these invasive species requires long-term management and one-off removals can encourage spread. As such, only those invasive species located within the active development area will be removed.

3.2 Shared Boundary Trees and Impacts to Trees on Adjacent Properties

During the field inventory it was observed that there is one (1) tree are located at or in close proximity to the property boundaries. Per Section 10(2) of *The Forestry Act*, RSO 1990, C. F.26, "Every tree whose trunk is growing on the boundary between adjoining lands is the common property of the owners of the adjoining lands." A desktop analysis of the surveyed tree locations was completed to identify ownership and shared boundary trees. Any tree located on a property boundary or within close proximity (~0.3 m) has been assumed to be a shared boundary tree.

An additional four (4) trees located beyond the subject property boundaries may be impacted by the proposed works and development. Tree protection fencing (TPF) is recommended along the property limit where these trees are located (see Appendix A for TPF recommendations).

The location and presumed ownership information for each tree is included in Table 1 (Appendix A). Any impacts to trees on adjacent properties or shared boundary trees will require written approval from all property owners prior to initiation of any work and/or tree removals on site. Written approvals shall be appended to this report for City records prior to the City's authorization for site demolition.

4 Analysis

4.1 Trees to be Preserved and Protected

Based on the layout of the subject property, location of the trees, and necessary site work to facilitate the construction onsite, there will be no trees preserved or protected on the subject site. Tree 1, Tree 2, Tree 5, and Tree 6 will be preserved and protected on the adjacent property. Tree preservation fencing will be erected at the property limit to protect these trees during construction.

4.2 Trees to be Removed

There are thirty-four (34) trees that will need to be removed to facilitate the construction of the proposed building and development. There is one (1) dead tree within property that will also be removed within the proposed building area.

4.3 Tree Preservation/Removal Summary

Thirty-five (35) trees were inventoried on the subject property and another four (4) on adjacent properties, for a total of thirty-nine (39) trees included in the detailed inventory and assessment.

Based on the information presented above, the following is a summary of recommendations for the proposed development of the subject property:

- Four (4) trees are recommended to be preserved and protected.
- Thirty-five (35) trees are recommended to be removed:
 - Thirty-four (34) live trees and one (1) dead tree.

5 Recommendations

5.1 Tree Protection Fencing

Tree Protection Fencing (TPF) is to be installed on site along the western property line to protect four (4) trees on the adjacent property (Appendix A). The limits of TPF have been indicated on the Tree Conservation Plan sheet TPP-1 and shall be considered to delineate the limits of work. All TPF shall conform to the City of Ottawa's current standards and Tree Protection Specification as shown on Detail 1-TPP2.

6 Construction Impact Mitigation

6.1 Potential Construction Impacts to Trees

Trees are living organisms that react to changes in their environment. Trees can be damaged during construction without showing signs of damage until some years later. Most of the impacts relate to the removal of roots that results in the slow death of the tree as a result of its inability to absorb sufficient water and nutrients. Contained within this section are descriptions of the potential impacts this project may have on the trees, and impact mitigation methods that are intended to aid in the mitigation of impact during construction.

6.1.1 Soil Compaction and Root Damage

The leading cause of construction damage to trees is compaction of the soil around the roots or within the Tree Protection Zone (TPZ). The TPZ is the area around the tree or group of trees in which no grading or construction activity may occur. Equipment entering a TPZ compresses the air pockets around the roots inhibiting the tree from absorbing nutrients and water. This damage ultimately degrades the health of the tree. Accordingly, during the removal stage, equipment use within the TPZ should be restricted to ensure that the tree's roots are not disturbed, thereby assisting in maintaining their continued health. The TPZ is protected and delineated by the TPF.

6.1.2 Mechanical Damage

Equipment can physically damage the trees through striking the trunk, limbs, and/or roots. Felled trees can also cause damage during the tree removal stage of construction. Some damage is unavoidable due to the proximity of adjacent trees; however, by using proper equipment and best management practices the damage can be minimized. The Contractor should be held responsible for all avoidable damage to the trees during all stages of development. Note: trees shall always be felled away from adjacent trees to be retained.

6.1.3 Root Damage

The success of tree preservation is dependent not only on protecting the root zone from compaction and damage, it is also contingent upon the ability to ensure that the structural roots within the root plate are not disturbed. Impacts to this area may result in the structural failure of these trees. Excavating soil 1 m outside a tree's drip line, or within a drip line can damage roots by tearing and splitting back to the stem. This damage can later lead to rot that can kill the tree. All work within the drip line of an existing tree shall be approved by an Arborist. When excavating the top 30-60 cm of soil adjacent to trees, care must be taken. Excavation should cleanly sever the roots prior to stripping and removal of soil. Exposed roots with a diameter greater than 2.5 cm (1 inch) shall be pruned back to the soil face to prevent damage to the tree.

6.2 Protecting and Managing Trees During Construction

The following recommendations are presented to provide appropriate tree protection and management during the future development and construction of this project:

- 1. Tree Protection Fencing (TPF) should be installed to protect all trees identified for preservation. TPF should conform to City of Ottawa standards and the locations indicated on the TPP (Appendix A). Upon installation of the TPF, the Contractor should contact the Project Arborist to review and approve the fencing and its location prior to commencement of any site work. This should be coordinated with City staff for approval. The TPF should remain intact throughout the entire construction period, as specified on the plans. The TPF should be inspected monthly and repaired as required and should be removed at the completion of all site works.
- 2. Upon receiving the necessary project approvals and prior to the commencement of tree removals, all trees designated for preservation must be flagged in the field. All designated preservation areas must be left standing and undamaged during site works. Removals are to be completed outside the window of April 1 to August 31. This window offers protection through the main migratory bird nesting and bat maternity roosting season. If removals occur within the restricted activity period, due diligence measures, including pre-clearing nest and roost sweeps will be employed to reduce risk to nesting birds protected under the *Migratory Birds Convention Act*, 1994 and Species at Risk Bats under the *Endangered Species Act*, 2007, and all applicable regulations. These surveys are required to be completed by a qualified biologist experienced in bird and bat identification and monitoring.
- 3. The TPZ is the area around a retained tree that is to be protected by TPF. The TPZ is not to be used for any type of storage (e.g., storage of debris, construction material, surplus soils, and construction equipment). No trenching or tunneling for underground services shall be located within the TPZ. Construction equipment shall not be allowed to idle or exhaust within the TPZ.
- 4. Trees shall not have any rigging cables or hardware of any sort attached or wrapped around them, nor shall any contaminants be dumped within the protective areas. Further, no contaminants shall be dumped or flushed where they may come into contact

with the feeder roots of the trees. In the event that roots from retained trees are exposed, or if it is necessary to remove limbs or portions of trees after construction has commenced, the Project Arborist shall be informed and the proper actions conforming to City Policies and By-laws shall be carried out.

- 5. Upon completion of the tree removals, all felled trees are to be removed from the subject property. No lumber or brush from the clearing is to be stored onsite. Any chipping, cutting or brush clean-up is to be completed outside the bird nesting season (i.e., not between April 1 and August 31). If these activities are to occur within the restricted activity period, due diligence measures, including pre-clearing nest sweeps will be employed to reduce risk to nesting birds protected under the Migratory Birds Convention Act, 1994 and Migratory Birds Regulations. These surveys will be completed by a qualified biologist.
- 6. Excavation adjacent to trees to be preserved must be completed with due care and attention. Excavation should cleanly sever the roots prior to stripping and removal of soil. Should roots be encountered during excavation all exposed roots with a diameter greater than 2.5 cm (1 inch) shall be pruned back to the soil face to prevent damage to the tree. Roots smaller than 2.5m (1 inch) should be cleanly cut using a sharpened spade or bypass pruners at the limits of excavation.

7 Disclaimer

The assessment of the trees presented within this report has been prepared using accepted arboricultural techniques. These include a visual examination of the above-ground parts of each tree for structural defects, scars, external indications of decay, evidence of insect presence, discoloured foliage, the general condition if the trees and the surrounding site, as well as the proximity of property and people. None of the trees examined were dissected, cored, probed, or climbed, and detailed root crown examinations involving excavation were not undertaken.

Notwithstanding the recommendations and conclusions made in this report, it must be realized that trees are living organisms and their health and vigour is constantly changing. They are not immune to changes in site conditions or seasonal variations in the weather.

While reasonable efforts have been made to ensure the trees recommended for retention are healthy, no guarantees are offered or implied, that these trees or any part of them will remain standing. It is both professionally and practically impossible to predict with absolute certainty the behavior of any single tree or group of trees in all circumstances. Inevitably a standing tree will always pose some risk. Most trees have the potential for failure provided with the necessary combinations of stresses and elements. This risk can only be eliminated if the tree is removed.

Although every effort has been made to ensure that this assessment is reasonably accurate the trees should be re-assessed periodically. The assessment presented in this report is valid at the time of inspection.

Respectfully Submitted,

Tim McCormick, OALA, CSLA, ISA Certified Arborist ON-0899A

Associate Director

ARCADIS IBI GROUP

410 Albert Street, Suite 101 Waterloo, ON N2L 3V3 Canada


tel + 1 519 585 2255 ext 63258


Email: tim.mccormick@ibigroup.com

IBI GROUP DRAFT
TREE CONSERVATION REPORT
424 CHURCHILL AVENUE NORTH
OTTAWA, ONTARIO
Submitted to GSI PROPERTIES

Appendix A

Tree Conservation Plan TPP-1 and TPP-2






TO BE IMPLEMENTED FOR RETAINED TREES, BOTH ON SITE AND ON ADJACENT SITES, PRIOR TO ANY TREE REMOVAL OR SITE WORKS AND MAINTAINED FOR THE DURATION OF WORK ACTIVITIES ON SITE.

DRAWING NO.: 1 of 1

1 TREE PROTECTION SPECIFICATIOM



2 EROSION CONTROL AND SEDIMENTATION FENCING

TPP-2 N.T.S

Table 1 - Existing Tree Inventory 424 Churchill, Ottawa, Ontario

Tag #	Species	Common Name	Breast Height (DBH) cm or range (cm)	Drip Line Radius (cm)	Multistem Tree	Overall Condition	Recommended Action	Notes	Ownership
1	Acer negundo	Manitoba Maple	10	480		Good	Protection to installed at property limits with reduced protection areas.	Hard lean to south	Private on adjoining site
2	Ulmus americana	American Elm	22	280		Fair	Protection to installed at property limits with reduced protection areas.	Lean to south	Private on adjoining site
3	Acer platanoides	Norway Maple	11	250		Poor	Remove - Due to grading and infrastructure improvement		Private on site
4	Acer platanoides	Norway Maple	11	200		Good	Remove - Due to grading and infrastructure improvement		Private on site
							Protection to installed at property limits with reduced protection areas.		Private on adjoining site
5	Malus spp.	Apple spp.	11	200		Good	Protection to installed at property limits with		Private on adjoining site
6	Juglans nigra	Black Walnut	26	500		Good	reduced protection areas. Remove - Due to grading and infrastructure		Private on site
7	Acer negundo	Manitoba Maple	11	350		Fair	improvement Remove - Due to grading		Private on site
8	Ulmus americana	American Elm	25	350		Poor	and infrastructure improvement Remove - Due to building		Private on site
9	Acer platanoides	Norway Maple	13	490		Very Good	construction and excavation		Private on site
10	Acer negundo	Manitoba Maple	11	370		Good	Remove - Due to building construction and excavation		Tilvate on site
11	Acer negundo	Manitoba Maple	37	850		Very Good	Remove - Due to grading and infrastructure improvement		Private on site
	Acer negundo	паппова маро	01	030		-	Remove - Due to grading and infrastructure		Private on site
12	Acer platanoides	Norway Maple	17	360		Very Good	improvement Remove - Due to grading and infrastructure		Private on site
13	Acer negundo	Manitoba Maple	12	280		Poor	improvement Remove - Due to building		Private on site
14	Ulmus americana	American Elm	15	50		Poor	construction and excavation		Private on site
15	Acer negundo	Manitoba Maple	19	440		Poor	Remove - Due to building construction and excavation		1 mate on site
							Remove - Due to building construction and excavation		Private on site
16	Unk nown	Unknown	19	240		Dead	Remove - Due to grading and infrastructure		City Tree
17	Acer platanoides	Norway Maple	19	580		Very Good	improvement Remove - Due to grading		City Tree
18	Rhamnus cathartica	Common Buckthorn	10	730		Good	and infrastructure improvement	Hard lean north	Private on site
19	Acer negundo	Manitoba Maple	25	1220		Very Good	Remove - Due to building construction and excavation		1 mate on site
			0.5				Remove - Due to grading and infrastructure improvement		Private on site
20	Acer negundo	Manitoba Maple	35	640		Good	Remove - Due to grading and infrastructure		City Tree
21	Tilia americana	Basswood	11	520	Yes	Poor	improvement Remove - Due to grading		City Tree
22	Tilia americana	Basswood	12	540	Yes	Good	and infrastructure improvement Remove - Due to grading		City Tree
23	Acer platanoides	Norway Maple	15	360		Very Good	and infrastructure improvement		211 =
24	Acer negundo	Manitoba Maple	35	1090	Yes	Poor	Remove - Due to grading and infrastructure improvement		City Tree
	, teer megamae						Remove - Due to grading and infrastructure		City Tree
25	Ulmus americana	American Elm	20	470		Good	improvement Remove - Due to grading and infrastructure		City Tree
26	Ulmus americana	American Elm	16	440		Good	improvement Remove - Due to grading		City Tree
27	Juglans nigra	Black Walnut	20	1040		Good	and infrastructure improvement		City Tree
28	Tilia americana	Basswood	14	0		Dead	Remove - Due to grading and infrastructure improvement		Only 1100
29	Acer negundo	Manitoba Maple	18	710		Good	Remove - Due to grading and infrastructure improvement		City Tree
29	Acer negundo	іманнова імаріе	10	710			Remove - Due to grading and infrastructure		City Tree
30	Acer negundo	Manitoba Maple	19	350		Very Good	improvement Remove - Due to grading and infrastructure		City Tree
31	Acer negundo	Manitoba Maple	15	410		Good	improvement Remove - Due to grading		City Tree
32	Acer negundo	Manitoba Maple	11	0		Dead	and infrastructure improvement		City Tree
33	Rhamnus cathartica	Common Buckthorn	11	810		Very Good	Remove - Due to grading and infrastructure improvement		Oity Tree
31	Tilia americana	Rasswood	20	420			Remove - Due to grading and infrastructure improvement		City Tree
34	Tilia americana	Basswood	28	430		Poor	Remove - Due to grading and infrastructure		City Tree
35	Acer negundo	Manitoba Maple	12	0		Dead	improvement Remove - Due to grading		City Tree
36	Acer platanoides	Norway Maple	11	30		Very Good	and infrastructure improvement Remove - Due to grading		City Tree
37	Acer negundo	Manitoba Maple	27	810	Yes	Poor	and infrastructure improvement		·
38	Acer negundo	Manitoba Maple	14	450	Yes	Very Good	Remove - Due to grading and infrastructure improvement		City Tree
- 55			17	700	103	151y G00u	Remove - Due to grading and infrastructure		City Tree

CHURCHILL PROPERTIES INC.

5-145 SELECT AVE., TORONTO, ONTARIO

COPYRIGHT

This drawing has been prepared solely for the intended use, thus any reproduction or distribution for any purpose other than authorized by Arcadis is forbidden. Written dimensions shall have precedence over scaled dimensions. Contractors shall verify and be responsible for all dimensions and conditions on the job, and Arcadis shall be informed of any variations from the dimensions and conditions shown on the drawing. Shop drawings shall be submitted to Arcadis for general conformance before proceeding with fabrication.

Arcadis Professional Services (Canada) Inc. formerly IBI Group Professional Services (Canada) Inc.

No.	DESCRIPTION	DATE				
1	ISSUED FOR ZBA & SPA REVIEW	2022-10-21				
2	ISSUED FOR ZBA & SPA REVIEW	2023-03-24				
3	ISSUED FOR ZBA & SPA REVIEW	2024-08-12				
- N	OLID ISOT	THE RES				



SEA

E CONSULTANT



410 Albert Street - Suite 101 Waterloo ON N2L 3V3 Canada tel 519 585 2255 www.arcadis.com

PROJECT

424 Churchill Ave

CITY OF OTTAWA

PROJECT MGR: M.P	APPROVED BY: T.M
DRAWN BY: E.L	CHECKED BY: E.L
139413	

SHEET TITLE

TREE PRESERVATION PLAN

SHEET NUMBER

TPP-2

ISSUE 3