

HINCHEY AVENUE

TREE CONSERVATION PLAN

Very poor (Acer To be removed dead, another dying back); tree is in decline saccharum) Bur oak (Quercus Good Good; Maturing; co-dominant leaders at 4m – parallel (conflicts with construction) To be removed macrocarpa) White cedar Poor; Mature; hedge form; unmaintained; shade from seeded Manitoba maples (Acer negundo) (Thuja Poor To be removed has caused decline in health and appearance occidentalis) (Thuja Poor Poor; Mature; previously topped at 2m To be removed occidentalis) (Thuja Poor Poor; Mature; previously topped at 2m To be removed occidentalis) Crab apple Poor; Mature; asymmetric crown; poor growth increment; major deadwood present; Poor To be removed (Malus spp.) tree is in decline (Thuja Dead Dead; Recommended for removal To be removed occidentalis) Scots pine (Pinus Poor; Mature; stunted and asymmetric form due to shading from nearby Manitoba maple Poor sylvestris) White cedar Fair; Mature; grouping of six trees – likely part of a former hedge; asymmetric due to shading from (Thuja To be removed nearby pine and Manitoba maples; some stems growing against back of house; previously topped occidentalis) ¹ D.B.H.: INDICATES DIAMETER (cm) MEASUREMENT AT BREAST HEIGHT (1.3m ABOVE GRADE); ² TO BE RETAINED OR REMOVED ³ CRZ: INDICATES RADIUS OF CRITICAL ROOTING ZONE AND IS ESTABLISHED AS BEING 10 CENTIMETERS FROM THE TRUNK OF A TREE FOR EVERY 1 CENTIMETER OF TRUNK DIAMETER AT BREAST HEIGHT (DBH). THE CRZ

TABLE 1: TREE INVENTORY AND ASSESSMENT

TREE CONDITION

Fair; Mature; double-stemmed at 0.5m from grade; previously topped at 2.5m

Fair; Mature; double-stemmed from grade; growing against front of house – asymmetric form

Very poor; Maturing; main stem removed at 2m – several leaders have regenerated (one now

REFER TO RECOMMENDATIONS IN REPORT PREPARED BY IFS Associates FOR TECHNIQUES TO PRESERVE TREES.

THE ARBORIST/LANDSCAPE ARCHITECT. SEE ALSO NOTE (5) ON #3/TC-1 FOR MORE INFORMATION.

D.B.H.¹ (cm)

Condition


NO. SPECIES

(Thuja

Sugar maple

1. INFORMATION ON TABLE ABOVE IS EXTRACTED FROM THE TREE CONSERVATION REPORT PREPARED BY CERTIFIED ARBORIST, IFS ASSOCIATES, DATED MAY 6, 2020. 2. REFER TO 'TREE PRESERVATION AND PROTECTION MEASURES' ON THE ARBORIST REPORT PRIOR TO ANY CONSTRUCTION WORKS ON SITE. 3. ANY WORKS WITHIN CRITICAL ROOT ZONE OF THE EXISTING TREES TO BE RETAINED NEEDS TO BE UNDERTAKEN BY HAND AND LIGHT EQUIPMENT TO THE SATISFACTION OF

TABLE 1



TREE PROTECTION FENCING

n.t.s.

Client / Client

CRZ ³(m)

2.0

STATUS²

To be removed


To be removed

Praveen Mupalla 450 Creekview Way, Ottawa, ON K1T 0J5

key plan / plan repère




legend / légende



CRITICAL ROOTING ZONE (CRZ) IDENTIFIED - REFER TO TABLE # FOR RADIUS OF CRZ

TREE PROTECTION FENCING


PROPOSED BUILDING



EXISTING TREES TO BE REMOVED -APPROXIMATE LOCATIONS BASED ON FIELD OBSERVATION NOTES BY IFS ASSOCIATES



EXISTING VEGETATIVE COMMUNITY TO BE REMOVED REFER TO TABLE 1 AND REPORT PREPARED BY IFS ASSOCIATES



north / le nord

396 Cooper Street, Suite 300 Ottawa, ON, CANADA K2P 2H7



project / projet

161 HINCHEY AVENUE

drawing / dessin

TREE CONSERVATION PLAN

date April 2020	project number / No. du projet X ##-##	
KA	PM/KA	KA