



P.O. Box 13593, Stn. Kanata, Ottawa, ON K2K 1X6  
Telephone: (613) 838-5717  
Website: [www.ifsassociates.ca](http://www.ifsassociates.ca)

URBAN FORESTRY & FOREST MANAGEMENT CONSULTING

June 21, 2023

Brad Schlegel  
VP Design & Construction  
RBJ Schlegel Holdings  
325 Max Becker Dr. #201  
Kitchener, ON  
N2E 4H5

**RE: TREE CONSERVATION REPORT FOR 1919 RIVERSIDE DRIVE, OTTAWA**

Dear Brad,

This report details a pre-construction tree conservation report (TCR) for the above-noted property located in Ottawa. The need for this TCR is related to the proposed construction of two multiple-storey buildings on the subject property, with associated surface and below grade parking.

The need for this report is related to trees protected under the City of Ottawa's Tree Protection By-law No. 2020-340. Tree conservation reports are required for all site plan control applications for properties on which a tree of ten centimetres in diameter or greater is present. The approval of this TCR by the City of Ottawa authorizes site clearing activities, including the removal of any approved trees. **Importantly, although this report may be used to support the application for a City tree removal permit, it does not by itself constitute permission to remove trees or begin site clearing activities. No such work should occur before a tree removal permit is issued by the City of Ottawa. Further, if any trees fully on or shared with adjacent properties are to be removed permission from adjacent land owners must first be obtained.**

In terms of existing vegetation, there is a mixture of planted amenity trees and trees which would have originated from seed spread from nearby parent trees. The individual trees are located throughout the property while seeded trees are in linear groupings adjacent to unmaintained property lines.

Under the current site plan few existing trees can be retained as building layouts, excavation for the below grade parking and the necessary grade changes associated with this work will impact the entire property. A proposed crash wall along the eastern property line will result in the loss of most of the planted trees there as well. Field work for this report was completed in September 2020.



**TREE SPECIES, SIZE AND CONDITION**

All current vegetation is shown on the tree conservation plan included on page 9 of this report. By the numbers indicated on the plan, each tree and grouping of trees is detailed below:

Table 1. Species, condition, size (diameter) and status of trees at 1919 Riverside Drive

Tree No.	Tree species	Condition (VP→E)	DBH <sup>1</sup> (cm)	Age class, tree condition notes & <b>preservation status</b> (to be removed or preserved and protected)
1	Austrian pine ( <i>Pinus nigra</i> )	Fair	18.2	Mature; crown very asymmetric towards west; fair crown density, growth increment and needle colour; introduced species; <b>to be preserved and protected</b>
2	Austrian pine	Fair	29.2	Mature; crown asymmetric towards north; fair density, growth increment and needle colour; introduced species; <b>to be preserved and protected</b>
3	Bur oak ( <i>Quercus macrocarpa</i> )	Poor	90.3	Overmature; continuously topped for clearance from overhead Hydro lines; located within a restricted rooting zone – parking median; significant dieback; tree is in advanced decline; native species; <b>to be removed</b>
4	Colorado spruce ( <i>Picea pungens</i> )	Poor	28.8	Mature; lower crown asymmetric; poor crown density, growth increment and needle colour – tree is in advanced decline; introduced species; <b>to be removed</b>
5	Colorado spruce	Very good	36.4	Mature; lower crown asymmetric; very good density, increment and colour; introduced species; <b>to be removed</b>
6	Colorado spruce	Good	24.7	Mature; lower crown asymmetric; good density, increment and colour; introduced species; <b>to be removed</b>
7	Austrian pine	Very good	40.9	Mature; very good density, increment and colour; introduced species; <b>to be removed</b>
8	European larch ( <i>Larix decidua</i> )	Fair	19.1	Maturing; salt spray damage to west side of crown – extensive dieback; fair density, increment and colour; introduced species; <b>to be removed</b>
9	Honey-locust ( <i>Gleditsia triacanthos</i> )	Good	22.6	Maturing; central stem with competing lateral at 1.5m on south side; good crown density, leaf size and colour; introduced species; <b>to be removed</b>

Table 1. Con't

Tree No.	Tree species	Condition (VP→E)	DBH <sup>1</sup> (cm)	Age class, tree condition notes & <b>preservation status</b> (to be removed or preserved and protected)
10	Honey-locust	Good	19.5	Maturing; multiple competing stems at 2m – broad crown; good crown density, leaf size and colour; introduced species; <b>to be removed</b>
11	White spruce ( <i>Picea glauca</i> )	Good	19.9	Maturing; mildly asymmetric crown due to influence of tree #10; very good density, increment and colour; native species; <b>to be removed</b>
12	Colorado spruce	Very poor	22.3	Maturing; holding less than 10% living foliage; tree is in advanced decline; introduced species; <b>to be removed</b>
13	Siberian elm ( <i>Ulmus pumila</i> )	Fair	32.7	Maturing; upright form; heavy salt spray damage to lower crown - poor crown density, leaf size and colour; introduced invasive species; <b>to be removed</b>
14	White spruce	Very poor	15.3	Maturing; heavily divergent towards southeast; physical damage to main stem – crown asymmetric; poor density, increment and colour; native species; <b>to be removed</b>
15	White spruce	Very poor	14.7	Maturing; divergent towards southeast; leader is dead; tree is in decline; poor density, increment and colour; native species; <b>to be removed</b>
16	Colorado spruce	Very good	24.1	Mature; good growth form; very good density, increment and colour; introduced species; <b>to be removed</b>
17	Little-leaf linden ( <i>Tilia cordata</i> )	Good	23.9	Maturing; co-dominant stems at 3m – moderately divergent; good crown density, leaf size and colour; introduced species; <b>to be removed</b>
18	Little-leaf linden	Good	27.1 (at 1m)	Maturing; multiple stems at 2-2.5m – broad crown; good crown density, leaf size and colour; embedded guy wire at 1.3m; introduced species; <b>to be removed</b>
19	Colorado spruce	Very poor	25.3	Maturing; holding less than 10% living foliage; tree is in advanced decline; embedded guy wire at 0.6m; introduced species; <b>to be removed</b>
20	Colorado spruce	Poor	23.6	Maturing; holding less than 50% living foliage; tree is in decline; heavy basal damage; introduced species; <b>to be removed</b>

Table 1. Con't

Tree No.	Tree species	Condition (VP→E)	DBH <sup>1</sup> (cm)	Age class, tree condition notes & <b>preservation status</b> (to be removed or preserved and protected)
21	Colorado spruce	Fair	24.9	Maturing; fair density, increment and colour; leader strongly divergent towards southeast; introduced species; <b>to be removed</b>
22	Colorado spruce	Fair	17.9	Maturing; fair density, increment and colour; scattered dead branches; introduced species; <b>to be removed</b>
23	Scots pine ( <i>Pinus sylvestris</i> )	Very poor	35.1	Mature; holding less than 10% living foliage; tree is in advanced decline – only 4 lowest branches alive; located within a restricted rooting zone – parking median; introduced invasive species; <b>to be removed</b>
24	Scots pine	Poor	58.4	Mature; very poor density, poor increment and colour; tree is in advanced decline; located within a restricted rooting zone – parking median; introduced invasive species; <b>to be removed</b>
25	White spruce	Fair	34.7	Mature; fair density, good increment and colour; dieback throughout crown - tree is in early decline; located within a restricted rooting zone – parking median; native species; <b>to be removed</b>
26	Colorado spruce	Fair	34.2	Mature; poor density, fair increment and colour; leader dead - tree is in early decline; located within a restricted rooting zone – parking median; introduced species; <b>to be removed</b>
27	Colorado spruce	Fair	27.3	Mature; poor density, fair increment and colour; leader dead - tree is in early decline; located within a restricted rooting zone – parking median; introduced species; <b>to be removed</b>
28	Crab apple ( <i>Malus spp.</i> )	Fair	25.8	Mature; central stem with suppressed laterals at 1.5, 2.0 and 2.25m from grade; dense crown; heavy basal sprouting; ornamental variety; <b>to be removed</b>
29	Crab apple	Poor	20.5	Mature; holding less than 20% living foliage; major deadwood; ornamental variety; <b>to be removed</b>
30	White spruce	Good	38.5	Mature; upright stem, generally symmetric crown; good density, increment and colour; native species; <b>to be preserved and protected</b>

Table 1. Con't

Tree No.	Tree species	Condition (VP→E)	DBH <sup>1</sup> (cm)	Age class, tree condition notes & <b>preservation status</b> (to be removed or preserved and protected)
31	Scots pine	Good	39.8	Mature; crown asymmetric towards southeast; good density, increment and colour; introduced invasive species; <b>to be preserved and protected</b>
32	Colorado spruce	Very good	37.8	Mature; very good density, increment and colour; introduced species; <b>to be removed</b>
33	Colorado spruce	Good	28.2	Mature; good density, increment and colour; scattered dead branches; introduced species; <b>to be removed</b>
34	Scots pine	Good	41.4	Mature; upright stem, crown asymmetric towards southwest; good density, increment and colour; introduced invasive species; <b>to be removed</b>
35	White spruce	Fair	28.2	Mature; leader dead; scattered dead and dieback, especially near crown apex; fair density, increment and colour; native species; <b>to be removed</b>
36	Scots pine	Good	53.3	Mature; upright stem, crown asymmetric towards west; good density, increment and colour; introduced invasive species; <b>to be removed</b>
37	Scots pine	Good	37.8	Mature; upright stem, crown asymmetric towards northwest; good density, increment and colour; introduced invasive species; <b>to be removed</b>
38	Scots pine	Fair	47.4	Mature; upright narrow crown; sweep in main stem at 6m; fair density, increment and colour; introduced invasive species; <b>to be removed</b>
39	Scots pine	Fair	54.4	Mature; crown asymmetric towards west; sweep in main stem at 6m; good density, increment and colour; introduced invasive species; <b>to be removed</b>
40	Austrian pine	Very poor	27.5	Mature; holding only 50% living foliage; poor density, increment and colour; crown very asymmetric towards northwest; located within a restricted rooting zone – parking median; introduced species; <b>to be removed</b>

Table 1. Con't

Tree No.	Tree species	Condition (VP→E)	DBH <sup>1</sup> (cm)	Age class, tree condition notes & <b>preservation status</b> (to be removed or preserved and protected)
41	Austrian pine	Poor	25.7	Mature; central stem with competing laterals starting at 1m; leader dead; fair density, increment and colour; stunted growth form; located within a restricted rooting zone – parking median; introduced species; <b>to be removed</b>

<sup>1</sup>Diameter at breast height, or 1.4m from grade.

Tree grouping A1: A line of eleven mature Scots pine **to be preserved and protected**. All of these trees would have been planted. Generally they are in good condition – upright with good crown densities, growth increments and needle colour. Their crowns are held high above the understory and are often asymmetric towards the northwest due to intercompetition between trees. The understory is primarily introduced invasive buckthorn (*Rhamnus* spp.) and Norway maple (*Acer platanoides*) with scattered mountain-ash (*Sorbus* spp.), hawthorn (*Crataegus* spp.), bur oak and ash (*Fraxinus* spp.) – all of which are native species. All ash remaining on the property are either now dead or heavily infested with emerald ash borer (*Agrilus planipennis*).

Tree grouping A2: A line of fourteen mature Scots pine and five mature white spruce **to be removed** due to conflicts with the proposed crash wall. All of these trees would have been planted. Generally they are in good condition – upright with good crown densities, growth increments and needle colour. Their crowns are held high above the understory and are often asymmetric towards the northwest due to intercompetition between trees. The understory is primarily introduced invasive buckthorn (*Rhamnus* spp.) and Norway maple (*Acer platanoides*) with scattered mountain-ash (*Sorbus* spp.), hawthorn (*Crataegus* spp.), bur oak and ash (*Fraxinus* spp.) – all of which are native species. All ash remaining on the property are either now dead or heavily infested with emerald ash borer (*Agrilus planipennis*).

Tree grouping B: A line of scattered three over-mature Scots pine, one mature Norway spruce (*Picea abies*) and one naturally occurring mature bur oak **to be removed** due to conflicts with the proposed crash wall. The spruce and oak are in good condition, the pines are senescent. The understory within this grouping is almost completely buckthorn.

Tree grouping C: A dense grouping of maturing planted trees (Colorado spruce and European larch), native trees (black walnut (*Juglans nigra*)), and those spread by seed - Manitoba maple (*Acer negundo*) and little-leaf linden **to be removed** due to conflicts with the footprint of the proposed building, walkways and site servicing. A large amount of equally tall buckthorn is also present.

Tree grouping D: Three planted Scots pine and two American elms (*Ulmus americana*) **to be removed** due to conflicts with the proposed west parking lot. The pines are mature, upright in form and hold their living crowns high above the buckthorn in the understory. They are in good

condition, with good crown densities, growth increments and needle colour. The elms show no outward signs of Dutch elm disease (*Ophiostoma novo-ulmi*).

Tree grouping E1: In the overstory are naturalized Manitoba maple from seed, naturally occurring trembling aspen (*Populus tremuloides*) spreading via root sprouts from the adjacent forest, naturalized black locust (*Robinia pseudoacacia*) spreading similarly and dead ash. Buckthorn once again dominates the understory. **To be preserved and protected** except for a small linear area which conflicts with a proposed walkway (E2).

### **FEDERAL AND PROVINCIAL REGULATIONS**

Federal and provincial regulations can be applicable to trees on private property. In particular, the following two regulations have been considered for this property:

- 1) Endangered Species Act (2007): No butternuts (*Juglans cinerea*) were identified on the subject or adjacent properties. This species of tree is listed as threatened under the Province of Ontario's Endangered Species Act (2007) and so is protected from harm.
- 2) Migratory Bird Convention Act (1994): In the period between April and August of each year nest surveys must be performed by a suitably trained person no more than five (5) days before trees or other similar nesting habitat are to be removed.

### **TREE PRESERVATION AND PROTECTION MEASURES**

Preservation and protection measures intended to mitigate damage during construction will be applied for the trees to be retained on and adjacent to the subject property. The following measures are the minimum required by the City of Ottawa to ensure tree survival during and following construction:

1. As per the City of Ottawa's tree protection barrier specification, erect a fence as close as possible to the CRZ of each tree (see City of Ottawa Tree Protection Barrier specifications on page 10).
2. Do not place any material or equipment within the CRZ of the tree;
3. Do not attach any signs, notices or posters to any tree;
4. Do not raise or lower the existing grade within the CRZ without approval;
5. Tunnel or bore when digging within the CRZ of a tree;
6. Do not damage the root system, trunk or branches of any tree;
7. Ensure that exhaust fumes from all equipment are NOT directed towards any tree's canopy.

<sup>1</sup> The critical root zone (CRZ) is established as being 10 centimetres from the trunk of a tree for every centimetre of trunk Diameter at breast height (DBH). The CRZ is calculated as DBH x 10 cm.

**REPLACEMENT TREE PLANTING OR COMPENSATION**

Numerous trees will be proposed for planting in the new landscape. As their numbers may not achieve parity with what was lost, monetary compensation may be required.

Pictures 1 through 8 on pages 11 to 16 of this report show selected tree groupings and individual trees on the subject property.

This report is subject to the attached Limitations of Tree Assessments to which the reader's attention is directed. Please do not hesitate to contact me with any questions concerning this report.

Yours,









Andrew K. Boyd, B.Sc.F, R.P.F. (#1828)  
Certified Arborist #ON-0496A and TRAQualified  
Consulting Urban Forester




GENERAL NOTES

PLANS COMPLETED BY CVS ARCHITECTS 18/05/23

LEGEND

-  CONIFEROUS TREE TO REMAIN
-  CONIFEROUS TREE TO BE REMOVED
-  DECIDUOUS TREE TO REMAIN
-  DECIDUOUS TREE TO BE REMOVED
-  TREES TO REMAIN
-  TREES TO BE REMOVED

 TREES



DRAWING: Tree Conservation Plan

PROJECT: 1919 RIVERSIDE DRIVE  
CITY OF OTTAWA




613-838-5717

*Andrew K. Boyd*  
Andrew K. Boyd, R.P.F.


SCALE: 1:360	DRAWING NO. 1919
DATE: 2023-05-31	
DRAWN BY: SS	
SHEET NO. 1	





TREE PROTECTION FENCING  
TREE TRUNK

PLAN VIEW



CRZ = DBH X 10CM.  
CRZ IS TO BE MEASURED FROM THE OUTSIDE EDGE OF THE TREE BASE

TREE PROTECTION SIGNAGE AS PER CITY STANDARD

GRADE

1.2M MIN. HIGH TREE PROTECTION FENCING AS PER REQUIREMENT # 3

POSTS TO BE SPACED AT 2.4M O/C MAX AS PER REQUIREMENT # 3

GRADE

SOIL AND ROOT DISTURBANCE NOT PERMITTED

**TREE PROTECTION REQUIREMENTS:**

1. PRIOR TO ANY WORK ACTIVITY WITHIN THE CRITICAL ROOT ZONE (CRZ = 10 X DIAMETER) OF A TREE, TREE PROTECTION FENCING MUST BE INSTALLED SURROUNDING THE CRITICAL ROOT ZONE, AND REMAIN IN PLACE UNTIL THE WORK IS COMPLETE.
2. UNLESS PLANS ARE APPROVED BY CITY FORESTRY STAFF, FOR WORK WITHIN THE CRZ:
  - DO NOT PLACE ANY MATERIAL OR EQUIPMENT - INCLUDING OUTHOUSES;
  - DO NOT ATTACH ANY SIGNS, NOTICES OR POSTERS TO ANY TREE;
  - DO NOT RAISE OR LOWER THE EXISTING GRADE;
  - TUNNEL OR BORE WHEN DIGGING;
  - DO NOT DAMAGE THE ROOT SYSTEM, TRUNK, OR BRANCHES OR ANY TREE;
  - ENSURE THAT EXHAUST FUMES FROM ALL EQUIPMENT ARE NOT DIRECTED TOWARD ANY TREE CANOPY.
  - DO NOT EXTEND HARD SURFACE OR SIGNIFICANTLY CHANGE LANDSCAPING
3. TREE PROTECTION FENCING MUST BE AT LEAST 1.2M IN HEIGHT, AND CONSTRUCTED OF RIGID OR FRAMED MATERIALS (E.G. MODULOC - STEEL, PLYWOOD HOARDING, OR SNOW FENCE ON A 2"X4" WOOD FRAME) WITH POSTS 2.4M APART, SUCH THAT THE FENCE LOCATION CANNOT BE ALTERED. ALL SUPPORTS AND BRACING MUST BE PLACED OUTSIDE OF THE CRZ, AND INSTALLATION MUST MINIMISE DAMAGE TO EXISTING ROOTS. (SEE DETAIL)
4. THE LOCATION OF THE TREE PROTECTION FENCING MUST BE DETERMINED BY AN ARBORIST AND DETAILED ON ANY ASSOCIATED PLANS FOR THE SITE ( E.G. TREE CONSERVATION REPORT, TREE INFORMATION REPORT, ETC). THE PLAN AND CONSTRUCTED FENCING MUST BE APPROVED BY CITY FORESTRY STAFF PRIOR TO THE COMMENCEMENT OF WORK.
5. IF THE FENCED TREE PROTECTION AREA MUST BE REDUCED TO FACILITATE CONSTRUCTION, MITIGATION MEASURES MUST BE PRESCRIBED BY AN ARBORIST AND APPROVED BY CITY FORESTRY STAFF. THESE MAY INCLUDE THE PLACEMENT OF PLYWOOD, WOOD CHIPS, OR STEEL PLATING OVER THE ROOTS FOR PROTECTION OR THE PROPER PRUNING AND CARE OF ROOTS WHERE ENCOUNTERED.

THE CITY'S TREE PROTECTION BY-LAW, 2020-340 PROTECTS BOTH CITY-OWNED TREES, CITY-WIDE, AND PRIVATELY-OWNED TREES WITHIN THE URBAN AREA. PLEASE REFER TO [WWW.OTTAWA.CA/TREEBYLAW](http://WWW.OTTAWA.CA/TREEBYLAW) FOR MORE INFORMATION ON HOW THE TREE BY-LAW APPLIES.

ACCESSIBLE FORMATS AND COMMUNICATION SUPPORTS ARE AVAILABLE, UPON REQUEST



**TREE PROTECTION SPECIFICATION**

TO BE IMPLEMENTED FOR RETAINED TREES, BOTH ON SITE AND ON ADJACENT SITES, PRIOR TO ANY TREE REMOVAL OR SITE WORKS AND MAINTAINED FOR THE DURATION OF WORK ACTIVITIES ON SITE.

SCALE: NTS

DATE: MARCH 2021

DRAWING NO.: 1 of 1



Picture 1. Portion of tree grouping A2 at 1919 Riverside Drive



Picture 2. Trees #4-7 (right to left) at 1919 Riverside Drive



Picture 3. Tree #3 at 1919 Riverside Drive



Picture 4. Tree grouping D (right) and trees #8 and 9 (left) at 1919 Riverside Drive



Picture 5. Trees #19-22 (right to left) at 1919 Riverside Drive



Picture 6. Tree grouping D at 1919 Riverside Drive





Picture 7. Trees #32-35 (right to left) at 1919 Riverside Drive



Picture 8. Tree grouping E at 1919 Riverside Drive



# LIMITATIONS OF TREE ASSESSMENTS & LIABILITY

## GENERAL

It is the policy of *IFS Associates Inc.* to attach the following clause regarding limitations. We do this to ensure that our clients are clearly aware of what is technically and professionally realistic in assessing trees for retention.

This report was carried out by *IFS Associates Inc.* at the request of the client. The information, interpretation and analysis expressed in this report are for the sole benefit and exclusive use of the client. Possession of this report or a copy thereof does not imply right of publication or use for any purpose by any other than the client to whom it is addressed. Unless otherwise required by law, neither all or any part of the contents of this report, nor copy thereof, shall be conveyed by anyone, including the client, to the public through public relations, news or other media, without the prior expressly written consent of the author, and especially as to value conclusions, identity of the author, or any reference to any professional society or institute or to any initialed designation conferred upon the author as stated in his qualifications.

This report and any values expressed herein represent the opinion of the author; his fee is in no way contingent upon the reporting of a specified value, a stipulated result, nor upon any finding to be reported. Details obtained from photographs, sketches, *etc.*, are intended as visual aids and are not to scale. They should not be construed as engineering reports or surveys. Although every effort has been made to ensure that this assessment is reasonably accurate, the tree(s) should be reassessed at least annually. The assessment presented in this report is valid at the time of the inspection only. The loss or alteration of any part of this report invalidates the entire report.

## LIMITATIONS

The information contained in this report covers only the tree(s) in question and no others. It reflects the condition of the assessed tree(s) at the time of inspection and was limited to a visual examination of the accessible portions only. *IFS Associates Inc.* has prepared this report in a manner consistent with that level of care and skill ordinarily exercised by members of the forestry and arboricultural professions, subject to the time limits and physical constraints applicable to this report. The assessment of the tree(s) presented in this report has been made using accepted arboricultural techniques. These include a visual examination of the above-ground portions of each tree for structural defects, scars, cracks, cavities, external indications of decay such as fungal fruiting bodies, evidence of insect infestations, discoloured foliage, the condition of any visible root structures, the degree and direction of lean (if any), the general condition of the tree(s) and the surrounding site, and the proximity of people and property. Except where specifically noted in the report, the tree(s) examined were not dissected, cored, probed or climbed to gain further evidence of their structural condition. Also, unless otherwise noted, no detailed root collar examinations involving excavation were undertaken.

While reasonable efforts have been made to ensure that the tree(s) proposed for retention are healthy, no warranty or guarantee, expressed or implied, are offered that these trees, or any parts of them, will remain standing. This includes other trees on or off the property not examined as part of this assignment. It is both professionally and practically impossible to predict with absolute certainty the behaviour of any single tree or groups of trees or their component parts in all circumstances, especially when within construction zones. Inevitably, a standing tree will always pose some risk. Most trees have the potential for failure in the event of root loss due to excavation and other construction-related impacts. This risk can only be eliminated through full tree removal.



Notwithstanding the recommendations and conclusions made in this report, it must be realized that trees are living organisms, and their health and vigour constantly change over time. They are not immune to changes in site conditions, or seasonal variations in the weather. It is a condition of this report that *IFS Associates Inc.* be notified of any changes in tree condition and be provided an opportunity to review or revise the recommendations within this report. Recognition of changes to a tree's condition requires expertise and extensive experience. It is recommended that *IFS Associates Inc.* be employed to re-inspect the tree(s) with sufficient frequency to detect if conditions have changed significantly.

#### ASSUMPTIONS

Statements made to *IFS Associates Inc.* in regards to the condition, history and location of the tree(s) are assumed to be correct. Unless indicated otherwise, all trees under investigation in this report are assumed to be on the client's property. A recent survey prepared by a Licensed Ontario Land Surveyor showing all relevant trees, both on and adjacent to the subject property, will be provided prior to the start of field work. The final version of the grading plan for the project will be provided prior to completion of the report. Any further changes to this plan invalidate the report on which it is based. *IFS Associates Inc.* must be provided the opportunity to revise the report in relation to any significant changes to the grading plan. The procurement of said survey and grading plan, and the costs associated with them both, are the responsibility of the client, not *IFS Associates Inc.*

#### LIABILITY

Without limiting the foregoing, no liability is assumed by *IFS Associates Inc.* for: 1) any legal description provided with respect to the property; 2) issues of title and/or ownership with respect to the property; 3) the accuracy of the property line locations or boundaries with respect to the property; 4) the accuracy of any other information provided by the client or third parties; 5) any consequential loss, injury or damages suffered by the client or any third parties, including but not limited to replacement costs, loss of use, earnings and business interruption; and, 6) the unauthorized distribution of the report.

#### INDEMNIFICATION

An applicant for a permit or other approval based on this report shall agree to indemnify and save harmless *IFS Associates Inc.* from any and all claims, demands, causes of action, losses, costs or damages that affected private landowners and/or the City of Ottawa may suffer, incur or be liable for resulting from the issuance of a permit or approval based on this report or from the performance or non-performance of the applicant, whether with or without negligence on the part of the applicant, or the applicant's employees, directors, contractors and agents.

Further, under no circumstances may any claims be initiated or commenced by the applicant against *IFS Associates Inc.* or any of its directors, officers, employees, contractors, agents or assessors, in contract or in tort, more than 12 months after the date of this report.

#### ONGOING SERVICES

*IFS Associates Inc.* accepts no responsibility for the implementation of any or all parts of the report, unless specifically requested to supervise the implementation or examine the results of activities recommended herein. In the event that examination or supervision is requested, that request shall be made in writing and the details, including fees, agreed to in advance.