#### Geotechnical Engineering

Environmental Engineering

Hydrogeology

Geological Engineering

**Materials Testing** 

**Building Science** 

Archaeological Services

# patersongroup

# **Phase I-Environmental Site Assessment**

316, 320, 324, 326 and 332 Clifton Road Ottawa, Ontario

**Prepared For** 

Insight Ottawa Realty Corporation

#### Paterson Group Inc.

Consulting Engineers 154 Colonnade Road South Ottawa (Nepean), Ontario Canada K2E 7J5

Tel: (613) 226-7381 Fax: (613) 226-6344 www.patersongroup.ca January 9, 2019

Report: PE4500-1

# TABLE OF CONTENTS

EXEC	CUTIVE SUMMARY	ii
1.0	INTRODUCTION	1
2.0	PHASE I PROPERTY INFORMATION	2
3.0	SCOPE OF INVESTIGATION	3
4.0	RECORDS REVIEW	4
	4.1 General	4
	4.2 Environmental Source Information	
	4.3 Physical Setting Sources	
5.0	INTERVIEWS	
6.0	SITE RECONNAISSANCE	
	6.1 General Requirements	
	6.2 Specific Observations at Phase I Property	14
7.0	REVIEW AND EVALUATION OF INFORMATION	
	7.1 Land Use History	
	7.2 Conceptual Site Model	21
8.0	CONCLUSIONS	24
9.0	STATEMENT OF LIMITATIONS	
10.0	REFERENCES	27

# **List of Figures**

Figure 1 - Key Plan Figure 2 - Topographic Map Drawing PE4500-1 - Site Plan Drawing PE4500-2 - Surrounding Land Use Plan

# List of Appendices

- Appendix 1 Aerial Photographs Site Photographs
- Appendix 2 MECP Freedom of Information Search MECP Well Records City of Ottawa HLUI Search TSSA Correspondence
- Appendix 3 Qualifications of Assessors

# **EXECUTIVE SUMMARY**

# Assessment

A Phase I-Environmental Site Assessment (ESA) was carried out for the properties addressed 316, 320, 324, 326 and 332 Clifton Road, in the City of Ottawa, Ontario. The purpose of the Phase I-ESA was to research the past and current use of the site and study area and to identify environmental concerns with the potential to have impacted the subject property.

Based on the available historical information sources, the Phase I Property was first developed for residential purposes between 1948 to 1953. The adjacent properties to the north, south and east were used for residential purposes, while adjacent property to the west was originally vacant, followed by use for commercial purposes (contractor yard). The property to the northeast, across Clifton Road, has been occupied by a transformer sub-station since as early as 1957. The land further to the north, on the south side of Scott Street, was occupied by commercial office space.

Paterson has filed records of site condition (RSCs) in the MECP's Environmental Site Registry for the residential and mixed-use redevelopment of the adjacent properties to the west and northwest. Based on information in our files, these properties are not considered to represent areas of potential environmental concern on the Phase I Property.

Off-site historical PCAs identified are not considered to result in APECs on the Phase I Property based on their separation distances and/or orientations with respect to the subject land.

Following the historical review, a site visit was conducted. Based on the findings of the site visit, no on-site PCAs were identified. At the time of the site visit, the current use of the adjacent and neighbouring properties within the Phase I ESA Study Area were observed from publicly accessible areas. No off-site PCAs with the potential to impact the Phase I Property were identified at the time of the site visit.

Based on the findings of the Phase I-ESA, it is our opinion that **a Phase II-ESA is not** required for the Phase I Property.

# Recommendations

Based on the ages of the subject structures (1920's through 1960's) potentially asbestos containing materials (ACMs) observed at the time of the site visit include, vinyl floor tiles, linoleum flooring, hard plaster, decorative ceiling plasters, suspended ceiling tiles, drywall joint compound, lath and plaster, and interior and exterior parging. Based

on dates of construction, lead-based paints (LBPs) may be present within the structures on older or original painted surfaces beneath newer paints. All building materials and painted surfaces were observed to be in good condition at the time of the site visit and the potential for ACMs and LBPs is not considered to represent an immediate concern.

It is our understanding that the subject structures will be demolished in conjunction with future redevelopment. Prior to any demolition activities, a designated substance survey (DSS) must be conducted for the existing structures, in accordance with Ontario Regulation 490/09 under the Occupational Health and Safety Act.

# 1.0 INTRODUCTION

At the request of Insight Ottawa Realty Corporation, Paterson Group (Paterson) conducted a Phase I-Environmental Site Assessment (Phase I-ESA) of the properties located at 316, 320, 324, 326 and 332 Clifton Road in the City of Ottawa, Ontario. The purpose of this Phase I-ESA was to research the past and current use of the site and study area to identify any environmental concerns with the potential to have impacted the subject property.

Paterson was engaged to conduct this Phase I-ESA by Mr. Jeremy Silburt of Insight Ottawa Realty Corporation. Mr. Silburt can be contacted by telephone at 613-880-5491.

This report has been prepared specifically and solely for the above noted project which is described herein. It contains all of our findings and results of the environmental conditions at this site.

This Phase I-ESA report has been prepared in general accordance with Ontario Regulation 153/04, as amended, under the Environmental Protection Act, and also complies with the requirements of CSA Z768-01. The conclusions presented herein are based on information gathered from a limited historical review and field inspection program. The findings of the Phase I-ESA are based on a review of readily available geological, historical and regulatory information and a cursory review made at the time of the field assessment. The historical research relies on information supplied by others, such as, local, provincial and federal agencies and was limited within the scope-of-work, time and budget of the project herein.

# 2.0 PHASE I PROPERTY INFORMATION

Address:	316, 320, 324, 326 and 332 Clifton Road, Ottawa, ON			
Legal Description:	Lots 18, 19, 20, 21, 22 and 23 on Registered Plan 369, City of Ottawa			
Property Identification Numbers:	04021-0044, 04021-0045, 04021-0046, 04021-0047, and 04021-00148			
Location:	The Phase I property is located on the west side of Clifton Road, north of Wilber Avenue, in the City of Ottawa. The subject site is shown on Figure 1 - Key Plan following the body of this report.			
Latitude and Longitude:	45° 23' 47" N, 75° 44' 56" W			
Site Description:				
Configuration:	Rectangular (approximate)			
Site Area:	0.29 ha (approximate)			
Zoning:	R3R – Residential Third Density Zone; Mature Neighbourhood Overly			
Current Use:	The subject property is currently occupied by 5 single- family residential dwellings.			
Services:	The Phase I Property is located in a municipally serviced area.			

# 3.0 SCOPE OF INVESTIGATION

The scope of work for this Phase I-Environmental Site Assessment was as follows:

- Determine the historical activities on the subject site and study area by conducting a review of readily available records, reports, photographs, plans, mapping, databases and regulatory agencies;
- Investigate the existing conditions present at the subject site and study area by conducting site reconnaissance;
- □ Conduct interviews with persons knowledgeable of current and historic operations on the subject property, and if warranted, neighbouring properties;
- Present the results of our findings in a comprehensive report in general accordance with the requirements of Ontario Regulation 153/04 as amended under the Environmental Protection Act, and in compliance with the requirements of CSA Z768-01;
- D Provide a preliminary environmental site evaluation based on our findings;
- □ Provide preliminary remediation recommendations and further investigative work if contamination is suspected or encountered.

# 4.0 RECORDS REVIEW

# 4.1 General

# Phase I-ESA Study Area Determination

A radius of approximately 250 m was determined to be appropriate as a Phase I ESA study area for this assignment. Properties outside the 250 m radius are not considered to have impacted the subject land, based on their significant distance from the site.

# First Developed Use Determination

The earliest aerial photograph from 1928 shows the Phase I Property was vacant, undeveloped land. The existing structures are present on a 1953 photograph, the next available photography for review. The subject site is therefore considered to have been first developed for residential purposes between 1948-1957.

# Fire Insurance Plans

Fire insurance plans (FIPs) dated 1956 and 1957 cover the Phase I Property and majority of the Phase I Study Area. According to the FIPs, the Phase I Property was occupied by the existing residences. The review of the FIPs did not identify any on-site potentially contaminating activities (PCAs).

Immediately adjacent properties to the north, south and east (across Clifton Road) were also occupied by residential dwellings, while the adjacent property to the west was occupied by a contractor's yard. Otherwise, neighbouring land use in the Phase I Study Area consisted of a combination of residential, commercial and industrial properties.

Various off-site PCAs identified during the review of FIPs include: a transformer sub-station, rail lines, coal storage locations, as well as autobody and automotive repair garages. These off-site PCAs are not considered to represent areas of potential environmental concern (APECs) on the Phase I Property based on their respective separation distances and/or orientations in relation to the subject land as well as previous work that Paterson completed on the adjacent properties to the north. The locations of the PCAs identified in the Phase I-ESA area are depicted on Drawing PE4500-2 - Surrounding Land Use Plan.

It should be noted that the contractor yard at 319 McRae Avenue, immediately west of the Phase I Property, is not considered to be a potentially contaminating activity and does not represent an area of potential environmental concern (APEC) on the Phase I Property, based on information in our files, which is further discussed in the Previous Engineering Reports Section of this report.

# **City of Ottawa Street Directories**

City directories were reviewed in approximately 10-year intervals from 1910 to 2010. The subject properties have been listed as residential properties since 1948. Neighbouring properties in the Phase I Study Area were listed primarily as residential dwellings, with some commercial or industrial land use. Potentially contaminating activities identified from the review of the City Directories are listed below in Table 1.

TABLE 1: Potentially Contaminating Activities City Directories Review Summary							
Listing	Address	Years Listed	Potentially Contaminating Activity	Represents an Area of Potential Environmental Concern			
Carson's Body Shop Gas Bar/J's Gas Bar	1976 Scott Street	1972-1992	Retail fuel outlet	No			
Westboro Motors	1976 Scott Street	2010	Automotive Service Garage	No			
Independent Coal and Lumber Co.	25 Clifton Road	1941, 1951, 1961	Bulk Coal Storage Facility	No			
Carson's Auto Body Shop	320 McRae Avenue	1959-2010	Automotive Service Garage	No			
AutoRebex	320 McRae Avenue	1999-2010	Automotive Service Garage	No			
Canadian Bank Note Company	145 Richmond Road	1990, 2000	Industrial Printing	No			
Canadian General Electric Co.	175 Richmond Road	1955, 1961	Electronics Manufacturer	No			
Guillevin International Pro Restaurant Equipment	175 Richmond Road	1980, 1990, 2000	Restaurant Equipment Manufacturers	No			
Fuller Construction	199 Richmond Road	1951, 1961, 1970	Contractors Yard	No			
Westboro Auto Imports	199 Richmond Road	1989	Automotive Service Garage	No			
Sheera Car Care	201 Richmond Road	2000	Automotive Service Garage	No			
Otto's Service Centre	225-245 Richmond Road	1961, 1970, 1980, 1989, 2000, 2010	Car Sales Lot and Automotive Service Garage	No			
Ken Workman's Shell Service Station	225 Richmond Road	1951, 1961, 1970	Retail Fuel Outlet	No			

TABLE 1: Potentially Contaminating Activities           City Directories Review Summary								
Listing	Address	Years Listed	Potentially Contaminating Activity	Represents an Area of Potential Environmental Concern				
Les Auto Body Repairs	314 Athlone Avenue	1961, 1970, 1980, 1989, 2000	Commercial Autobody Shop	No				
Brebner Manufacturing and Repairs	360 Kirkwood Avenue	2000	Manufacturer Facility	No				
Gifford Auto	359 McRae Avenue	1997, 2000	Automotive Service Garage	No				
Frappier's Garage	345 Tweedsmuir	1959	Automotive Service Garage	No				

The off-site PCAs noted above are not considered to represent areas of potential environmental concern (APECs) on the Phase I Property based on their separation distances, orientations with respect to the subject land and/or information contained in our files. The locations of the aforementioned PCAs, are depicted on Drawing PE4500-2 - Surrounding Land Use Plan.

Gervais Motors was listed at 1960 Scott Street in 1989. As further discussed in the Previous Engineering Reports section, this property is not considered to be a PCA based on information in our files and has therefore not been included in Table 1.

# Chain of Title

A Chain of Title was not obtained for the Phase I Property as the information obtained from the records review is considered to satisfy the objectives of the records review, and a title search back to the date of the first developed use would not contribute to obtaining information about the environmental condition of the Phase One Property. As previously noted, based on a review of aerial photographs and city directories, the Phase I Property is considered to have been first developed for residential purposes as early as 1948.

# Plan of Survey

Insight Ottawa Realty Corporation indicated that a survey plan of the Phase I Property is not currently available for review. The Phase I Property is shown in its current configuration on the City of Ottawa's electronic mapping site (geoOttawa).

# **Previous Engineering Reports**

Paterson has completed subsurface investigations for the following properties in the immediate vicinity of the Phase I Property: 1960 Scott Street, 319 McRae Avenue and 320 McRae Avenue. Based on the findings of the investigations at 1960 Scott Street and 319 McRae, immediately west and northwest of the Phase I Property, no environmental concerns were identified with regards to the soil located immediately adjacent to the west of the subject land. It should also be noted that the groundwater beneath these properties was determined to be in compliance with the Ministry of the Environment, Conservation and Parks (MECP) Table 7 standards for a residential land use in shallow soil conditions. Records of Site Condition have been successfully filed in the MECP's Environmental Site Registry for both 319 McRae Avenue and 1960 Scott Street.

# 4.2 Environmental Source Information

# **Environment Canada**

A search of the National Pollutant Release Inventory (NPRI) was conducted electronically on December 6, 2018. The subject site was not listed in the NPRI database. One (1) site with NPRI records was identified within the Phase I study area. This site is the Canadian Bank Note Company building located at 145 Richmond Road, approximately 130 m southeast of the Phase I Property.

The Canadian Bank Note Company includes a certificate air contaminant release form that indicates 10.891 tonnes of volatile organic compounds were released as emissions in 2010. Reports of this type appear available for this property for 2003 to 2010, however, no other details or figures were available. Based on its separation distance from the Phase I Property, this facility is not considered to represent an APEC on the subject land.

# Ontario Ministry of Environment, Conservation and Parks (MECP) Instruments

Requests were submitted to the MECP Freedom of Information office, at the time of the original Phase I site visit, for information with respect to certificates of approval, permits to take water, certificates of property use or any other similar MECP issued instruments for the sites comprising the Phase I Property. A response had not been received from the MECP at the time this report was issued. Any pertinent information will be forwarded to the client upon receipt. A copy of the MECP search request is provided in Appendix 2.

# **MECP Coal Gasification Plant Inventory**

The Ontario Ministry of Environment, Conservation and Parks document titled "Municipal Coal Gasification Plant Site Inventory, 1991" was reviewed to reference the locations of former plants with respect to the site. No coal gasification plants were identified on the Phase I Property or within the Phase I Study Area.

# **MECP Incident Reports**

Requests were submitted to the MECP Freedom of Information office for information with respect to records concerning environmental incidents, orders, offences, spills, discharges of contaminants or inspections maintained by the MECP for the sites comprising the Phase I Property, or adjacent properties. A response had not been received from the MECP at the time this report was issued. Any pertinent information will be forwarded to the client upon receipt. A copy of the MECP search request is provided in Appendix 2.

# MECP Waste Management Records

Requests were submitted to the MECP Freedom of Information office for information with respect to waste management records. A response had not been received from the MECP at the time this report was issued. Any pertinent information will be forwarded to the client upon receipt. A copy of the MECP search request is provided in Appendix 2.

# **MECP Submissions**

Requests were submitted to the MECP Freedom of Information office for information with respect to reports related to environmental conditions that have been submitted to the MECP. A response had not been received from the MECP at the time this report was issued. Any pertinent information will be forwarded to the client upon receipt. A copy of the MECP search request is provided in Appendix 2.

# MECP Waste Disposal Site Inventory

The Ontario Ministry of Environment document titled "Waste Disposal Site Inventory in Ontario, 1991" was reviewed as part of the historical research. The MECP document did not identify any landfill sites in the Phase I Study Area.

#### **MECP Brownfields Environmental Site Registry**

A search of the MECP Brownfields Environmental Site Registry (ESR) was conducted as part of this assessment for the site, neighbouring properties and the general area of the site. No Records of Site Condition (RSCs) were filed for the subject site.

Four RSCs were identified for the following properties within the Phase I study area: 309 Athlone Avenue, 1900 Scott Street, 1960 Scott Street and 319 McRae Avenue. Based on the separation distances of the properties at 309 Athlone Avenue and 1900 Scott Street with respect to the Phase I Property, in combination with the information in the ESR, these properties are not considered to represent an APEC on the subject land.

The RSC for 319 McRae Avenue, situated immediately southwest of the subject property, was filed by Paterson in December of 2014. As discussed previously, groundwater beneath this property was determined to be clean at the time of the Phase II ESA. No indications of contamination were noted along the eastern portion of the site, adjacent to the Phase I Property, at the time of the remediation.

The RSC for 1960 Scott Street, immediately northwest of the Phase I Property, was filed by Paterson in August of 2018. As noted previously, the groundwater beneath this property was also determined to be clean at the time of the Phase II ESA, and there were no indications of contamination on the southeastern portion of the site, in the vicinity of the northwestern portion of the Phase I Property, at the time of the remediation.

#### PCB Inventory

A search of the national PCB waste storage sites was conducted. No PCB waste storage sites were identified within the Phase I Study Area.

#### Areas of Natural Heritage and Significance Interest

A search for areas of natural significance and features within the Phase I study area was conducted on the web site of the Ontario Ministry of Natural Resources (MNR) on December 6, 2018. The search did not identify any provincially significant life sciences or earth sciences areas of natural heritage and scientific interest within the Phase I Study Area.

# Technical Standards and Safety Authority (TSSA)

The TSSA, Fuels Safety Branch in Toronto was contacted electronically on December 7, 2018, to inquire about current and former underground storage tanks, spills and incidents for the site and neighbouring properties. According to the TSSA response dated December 7, 2018, no records were identified. A copy of the TSSA correspondence is included in Appendix 2.

#### City of Ottawa Landfill Document

The document entitled "Old Landfill Management Strategy, Phase I-Identification of Sites, City of Ottawa", was reviewed. One landfill site was identified within the Phase I Study Area. The review of the report indicates that the landfill was located on McRae Avenue, between Scott Street and Richmond Road, served the City of Ottawa and was active prior to the 1940s. The report indicates that the waste is domestic, of unknown thickness and the footprint has not been identified.

Based on clean groundwater results beneath the adjacent properties to the northwest (1960 Scott Street) and west (319 McRae Avenue), in combination with the northerly groundwater flow direction in the area of the Phase I Property, the landfill is not considered to represent an APEC on the subject land.

# City of Ottawa Historical Land Use Inventory (HLUI)

A requisition form was sent to the City of Ottawa to request information from the City's Historical Land Use Inventory (HLUI 2005) database for the subject property. A response had not been received at the time this report was issued. A copy of the response will be forwarded to the client if it contains any pertinent information. The HLUI request form has been provided in Appendix 2.

# 4.3 Physical Setting Sources

#### Aerial Photographs

Historical air photos from the National Air Photo Library were reviewed in approximate 10-year intervals. The review period dates back to the first available air photos for the site. Based on the review, the following observations have been made:

- 1928 The Phase I Property is vacant, undeveloped land. Adjacent and surrounding lands are also vacant, while Clifton Road is present immediately to the east of the subject land. Occasional residential dwellings can be seen further to the north, east and south of the Phase I Property.
- 1953 The Phase I Property has been developed with the existing residential structures. Residential development has occurred to the north, south and east of the Phase I Property, along Clifton Road. The property to the west remains vacant. Apparent commercial or industrial development has occurred further southwest, southeast and north of the Phase I Property.
- 1958 The Phase I Property appears to remain unchanged from the previous photograph. Commercial or light-industrial activity appears to be present on the adjacent property to the west. The property to the northeast, at the southeast corner of Scott Street and Clifton Road appears to have been developed, however the land use cannot be distinguished in this photo. No other significant changes appear to have been made to the surrounding land use, since the previous photograph.
- 1976 No significant changes appear to have been made to the Phase I Property or the surrounding lands. The present-day transformer substation east of the Phase I Property can be clearly seen at the southeast corner of Scott Street and Clifton Road.
- 1984 The Phase I Property remains unchanged from the previous photograph. The adjacent property to the west now has what appears to be shipping containers on it. No other significant changes appear to have been made to the neighbouring properties.

- 1989 No significant changes appear to have been made to the Phase I Property. The adjacent property to the northwest appears to now be occupied with smaller containers over the eastern portion of the land, with what appears to be a small commercial building on the southeastern portion of the land. There appears to have been additional residential development east of the site, across Clifton Road, south of the transformer sub-station. No other significant changes appear to have occurred on the adjacent and neighbouring properties.
- 1993 The Phase I Property remains unchanged from the previous photograph. The adjacent property to the northwest has been redeveloped with a new commercial building. Otherwise, no significant changes appear to have been made to the neighbouring properties.
- 2005 (City of Ottawa website) No significant changes appear to have been made to the Phase I Property or immediately adjacent properties. Residential dwellings have been developed along West Village Private, further east of the Phase I Property.
- 2015 (City of Ottawa website) The Phase I Property remains unchanged from the previous photograph. The adjacent property to the west has been developed with a multi-storey mixed-used building. Otherwise, adjacent and neighbouring properties remain unchanged from the previous photograph.

Laser copies of selected aerial photographs reviewed are included in Appendix 1.

# **Topographic Maps**

Topographic maps were obtained from Natural Resources Canada – The Atlas of Canada website and from the City of Ottawa website. The topographic maps indicate that the regional topography generally slopes down to the north, towards the Ottawa River. The topographic map depicts the Hydro corridor on the east side of McRae Avenue and a substation on the north side of Scott Street.

Based on the topographic maps, the closest body of water to the subject site is the Ottawa River, the closest point of which is located approximately 940m northwest of the Phase I Property. An illustration of the referenced topographic map is presented on Figure 2 – Topographic Map, appended to this report.

# Physiographic Maps

The Ontario Geological Survey publication 'The Physiography of Southern Ontario, Third Edition' was reviewed as a part of this assessment. According to the publication and attached mapping, the site is situated within the Ottawa Valley Clay Plains physiographic region, described as "clay plains interrupted by ridges of rock or sand". Mapping shows the subject site as situated in an area of limestone and till plains.

# **Geological Maps**

The Geological Survey of Canada website on the Urban Geology of the National Capital Area was consulted as part of this assessment. Based on this information, the bedrock in the area of the subject site consists of interbedded limestone and dolostone of the Gull River Formation. Overburden soils are shown as glacial till, with a drift thickness on the order of 2 to 5 m. The findings of the subsurface investigations conducted by Paterson in the immediate vicinity of the Phase I Property, confirm the reported subsurface conditions.

# Water Well Records

The online interactive well record mapping system was accessed on December 6, 2018. No well records were identified for the Phase I Property. A total of 16 well records were identified within the Phase I Study Area. With the exception of two (2) domestic wells installed in 1948 and 1951, all of the wells in the area of the Phase I Property were utilized as test holes or groundwater monitoring wells.

Monitoring well records were identified for the properties addressed 1960 Scott Street, 309 Athlone Avenue, 145 Richmond Road, 160 Lanark Avenue (Mahoney Park) and further to the east along Scott Street. As previously discussed, the groundwater beneath 1960 Scott Street is clean based on information in our files. The remaining monitoring wells are not considered to represent a concern to the Phase I Property based on their separation distances of over 100m from the subject land.

# Water Bodies and Areas of Natural Significance

No water bodies or Areas of Natural Significance are present on the Phase I Property. The closest water body is the Ottawa River, located approximately 940m northwest of the subject site. No areas of natural significance are known to exist within the Phase I Study Area.

# 5.0 INTERVIEWS

Mr. Jordan Stitt, the agent from REMAX Core Realty Inc., who is representing Mr. Jeremy Silburt (the prospective buyer) was interviewed at the time of the site visit as well as via email. The subject site is currently occupied by five (5) residential dwellings constructed between 1948 to 1957. The site is current under agreement of purchase and sale for a future residential development. Mr. Stitt is not aware of any potential environment concern with regard to the subject site.

# 6.0 SITE RECONNAISSANCE

# 6.1 General Requirements

The site visits were conducted on December 13, 2018 and January 8, 2019. Weather conditions were sunny, with a temperature of approximately -14° C and -2° C, respectively. Personnel from the Environmental Department of Paterson Group conducted the site visit. In addition to the site, the uses of neighbouring properties within the Phase I-ESA Study Area were also assessed at the time of the site visit, from publicly accessible areas.

# 6.2 Specific Observations at Phase I Property

# **Buildings and Structures**

The five (5) parcels of land that make up the Phase I Property were all occupied with single-family dwellings.

316 Clifton Road is occupied by a two (2) storey single-family dwelling and a detached private garage. The dwelling was constructed circa 1953 with a poured concrete foundation, finished with a brick and stone style exterior and a peaked roof covered with shingles. The private garage is a wood frame structure with a poured slab-on-grade foundation and finished on the exterior with plywood and vinyl siding and a peaked roof covered with asphaltic shingles.

320 Clifton Road is occupied by a 2-storey residence and a detached private garage. The dwelling was constructed in 1949 with a poured concrete foundation, finished with vinyl siding exterior and a sloped shingle roof. The private garage is a wood frame structure with a poured slab-on-grade foundation and finished on the exterior with vinyl siding with a sloped shingle roof.

324 Clifton Road is occupied by a single storey dwelling and detached garage, constructed in 1953 with a poured concrete foundation, finished with a cream coloured stucco exterior and a peak covered shingle roof. The private garage is a wood frame structure with a poured slab-on-grade foundation and finished on the exterior with vinyl siding with a sloped shingle roof.

326 Clifton Road is occupied by a single-storey residence. The dwelling was constructed between 1947 to 1953 with a poured concrete foundation, finished with a white stucco exterior and a peak covered shingle roof.

332 Clifton Road is occupied by a 2-storey residence and a private garage. The dwelling was constructed in 1948 with a poured concrete foundation, finished with a red brick exterior and a peak covered shingle roof. The private garage is a wood frame structure with a poured slab-on-grade foundation and finished on the exterior with vinyl siding with a sloped shingle roof.

# Site Features

The ground surface on the residential properties largely consisted of a landscaped lot with grass and trees, and asphaltic concrete laneways and parking areas. Site topography is generally flat, sloping slightly downwards to the east. Site drainage consists primarily of sheet flow to catch basins along Clifton Road, with some infiltration occurring in areas of permeable ground surface, such as the landscaped areas.

No exterior aboveground storage tanks (ASTs) or evidence of exterior underground storage tanks (USTs) were observed at the time of the site visit. No spills, staining, stressed vegetation, or visual or olfactory evidence of contamination was noted on the exterior of the subject site during the Phase I site visit.

No underground structures, drains, pits, or sumps were observed on the exterior of the Phase I Property during the site visit. No monitoring wells, potable wells or private sewage systems were observed onsite, nor are any expected to be present, as the site is located in a municipally-serviced area.

Waste generated on site consists of domestic waste and recycling generated from each of the subject buildings. Waste and recycling is collected at the curbside by the municipality on a weekly basis.

A pole mounted transformer was noted in front of 316 Clifton Road. No signs of transformer oil staining were noted beneath the transformer.

No evidence of recent excavation was observed on the exterior of the subject property. No evidence of current or former railway or spur lines on the subject land were observed at the time of the site visit. There were no unidentified substances observed on the exterior of the Phase I Property.

The above-noted site features are shown on Drawing PE4500-1 - Site Plan.

#### Interior Assessment

A general description of the interior of each residential dwelling is provided below:

#### 316 Clifton Road

- Floor materials consist of hardwood, ceramic tiles, and vinyl tiles and poured concrete.
- □ Wall materials consist of lath and plater, gypsum boardand poured concrete.
- Ceiling materials consist of lath and plaster, several of which were finished with decorative plaster design.
- Lighting throughout the building is provided by incandescent fixtures.

The building is currently heated with natural gas-fired equipment located in the basement. Based on the age of the building (1953) in combination with observations made at the time of the site visit, it is very likely that the building was originally heated with fuel-oil, prior to conversion to natural gas. It should be noted however, that no evidence of ASTs or USTs, spills, or staining were observed in the basement.

One floor drain was observed throughout the basement level. The drain appeared to be dry. No other drains, or sumps were observed.

Chemical storage was limited to small quantities of commercially-available cleaning products and paint. All chemicals were properly stored in their original containers, with no evidence of spills or staining observed at the time of the site visit. No concerns associated with chemical storage were identified at the subject site.

Based on the date of construction, potentially asbestos-containing materials (ACMs) observed at the time of the site visit include vinyl floor tiles, drywall joint

compound, parging (interior and exterior) and plaster ceilings. Lead-based paints may also be present on older or original painted surfaces beneath newer leadfree paints. Building materials and painted surfaces were observed to be in good condition at the time of the site visit.

#### 320 Clifton Road

- Floor materials consist of hardwood, linoleum, ceramic and vinyl tile, some carpet and poured concrete (basement).
- □ Wall materials consist of lath and plater, gypsum board, and poured concrete.
- Ceiling materials consist of gypsum board and plaster.
- Lighting throughout the building is provided by incandescent fixtures.

The building was previously heated with an oil burning furnace until 2001 and replaced with a natural gas fired furnace. A sub-floor was installed in the area of where the former AST was situated. As a result, the concrete floor could not be observed at the time of the site visit. However, no odours were noted in the basement.

One floor drain was observed in the basement level. The drain appeared to be dry. No other drains, or sumps were observed at the time of the site visit.

Chemical storage was limited to small quantities of commercially-available cleaning products and paint. All chemicals were properly stored in their original containers, with no evidence of spills or staining observed at the time of the site visit. No concerns associated with chemical storage were identified on this portion of the Phase I Property.

Based on the date of construction of the dwelling (1949), potentially asbestoscontaining materials (ACMs) observed at the time of the site visit include vinyl floor tiles, drywall joint compound and plaster. Lead-based paints may also be present on older or original painted surfaces beneath newer lead-free paints. Building materials and painted surfaces were observed to be in good condition at the time of the site visit.

#### 324 Clifton Road

- Floor materials consist of vinyl tile, hardwood, ceramic tile and poured concrete.
- □ Wall materials consist of lath and plater, gypsum board, parging, and poured concrete.
- Ceiling materials consist of lath and plaster, gypsum board, wood paneling and suspended ceiling tiles.
- Lighting throughout the building is provided by incandescent fixtures.

The building is currently heated with a natural gas fired furnace. Signs of an AST were observed in the basement; a non-painted wall area outlining the shape of an AST as well as the location of the former fill and vent pipes. No odour, spills, or staining were observed on the interior of the residential dwelling. The private garage is not heated.

A sump pit was observed in the basement of the dwelling. No odour or water was noted at the time of the site visit.

Chemical storage within the dwelling was limited to small quantities of commercially-available cleaning products in the basement. All chemicals were properly stored in their original containers, with no evidence of spills or staining observed at the time of the site visit. No concerns associated with chemical storage were identified on this portion of the Phase I Property.

Based on the date of construction of the dwelling (as early as 1953), potentially asbestos-containing materials (ACMs) observed at the time of the site visit include drywall joint compound, vinyl tiles and suspended ceiling tiles. Lead-based paints may also be present on older or original painted surfaces beneath newer lead-free paints. Building materials and painted surfaces were observed to be in good condition at the time of the site visit.

#### 326 Clifton Road

- Floor materials consist of hardwood, linoleum, vinyl tile and poured concrete.
- □ Wall materials consist of lath and plater, gypsum board, parging, wood panels and poured concrete.

- Ceiling materials consist of lath and plaster and gypsum board and suspended ceiling tile.
- Lighting throughout the building is provided by incandescent fixtures.

The building was previously heated with an oil burning furnace until 2008 and replaced with a natural gas fired furnace. Signs of an AST were observed in the basement, including above ground copper wires partially parged over, and parged holes of the former vent and fill pipes. Some minor dark staining, (approximately 0.3 m in diameter) accompanied by a white ring around it, was noted where the old oil burning furnace was situated. However, it is expected that the noted stain is primarily from the water condensation of the former oil furnace (precipitation of salt on the concrete floor). No odour was accompanied by the floor stain in the basement at the time of the site visit.

No drains or sumps were observed at the time of the site visit.

No chemical storage was observed except domestic cleaning products, which were property stored in their original containers, with no evidence of spills or staining observed at the time of the site visit.

Based on the date of construction of the dwelling (approximately 1950), potentially asbestos-containing materials (ACMs) observed at the time of the site visit include vinyl floor tiles, lath and plaster, suspended ceiling tiles, drywall joint compound and plaster. Lead-based paints may also be present on older or original painted surfaces beneath newer lead-free paints. Building materials and painted surfaces were observed to be in good condition at the time of the site visit.

# 332 Clifton Road

- Floor materials consist of hardwood, ceramic tile and poured concrete.
- □ Wall materials consist of lath and plater, gypsum board, parging and poured concrete.
- Ceiling materials consist of lath and plaster and gypsum board.
- Lighting throughout the building is provided by incandescent fixtures.

The building is currently heated with a natural gas fired furnace. Based on the age of the building (1948) it is possible the building was originally heated with

fuel-oil, prior to conversion to natural gas. No odour, spills, or staining were observed in the basement.

One floor drain was observed in the basement level. The drain appeared to be dry. No other drains, or sumps were observed at the time of the site visit.

Chemical storage within the dwelling was limited to small quantities of commercially-available cleaning products. All chemicals were properly stored in their original containers, with no evidence of spills or staining observed at the time of the site visit. No concerns associated with chemical storage were identified on this portion of the Phase I Property.

Based on the date of construction of the dwelling (1948), potentially asbestoscontaining materials (ACMs) observed at the time of the site visit include gypsum board and plaster. Lead-based paints may also be present on older or original painted surfaces beneath newer lead-free paints. Building materials and painted surfaces were observed to be in good condition at the time of the site visit.

# Neighbouring Properties

An inspection of neighbouring properties was conducted from publicly accessible roadways at the time of the site inspection. Land use adjacent to the subject site was as follows:

- North Residential dwelling, followed by International Buddhist Progress Society of Ottawa;
- □ East Clifton Road, followed by single-family residences;
- South Residential condominium building roadway (Wilber Avenue), followed by single family residences;
- □ West Residential condominium building, followed by McRae Avenue.

The current use of the adjacent properties is not considered to pose an environmental concern to the subject site. Potentially contaminating activities (PCAs) within the Phase I Study Area were identified, however based on the separations distances, orientation with respect to the subject site and previous environmental work conducted by Paterson, these properties do not represent areas of potential environmental concerns (APECs). PCAs within the study area are illustrated and presented in green text on Drawing PE4500-2 – Surrounding Land Use Plan in the Figures section of this report.

# 7.0 REVIEW AND EVALUATION OF INFORMATION

# 7.1 Land Use History

The Phase I Property was vacant, until developed with the existing residential dwellings between 1948 to 1953. The Phase I Property has always been used for residential purposes.

# Potentially Contaminating Activities (PCAs)

Off-site PCAs identified within the Phase I Study Area are illustrated on Drawing PE4500-2 – Surrounding Land Use Plan in the Figures section of this report, following the text. Based on their separation distances and/or orientations with respect to the subject land, as well as previous work completed by Paterson Group, the PCAs are not considered to represent APECs on the Phase I Property.

# Areas of Potential Environmental Concern (APECs)

No APECs were identified on the Phase I Property.

# Contaminants of Potential Concern (CPCs)

No CPCs were identified on the Phase I Property.

# 7.2 Conceptual Site Model

# Geological and Hydrogeological Setting

The Geological Survey of Canada website on the Urban Geology of the National Capital Area was consulted as part of this assessment. Based on this information, the bedrock in the area of the subject site consists of interbedded limestone and dolostone of the Gull River Formation. Overburden soils are shown as glacial till, with a drift thickness on the order of 2 to 5 m.

The findings of subsurface investigations conducted by Paterson in the immediate vicinity of the Phase I Property, confirm the reported subsurface conditions. Based on groundwater level measurements taken in conjunction with the aforementioned investigations, the long-term groundwater table in the area of the Phase I Property is interpreted to be present in the bedrock layer with a flow direction toward the north.

It is possible that the groundwater flow beneath the site may be slightly influenced by the recent construction of the multi-storey buildings with at least 2 levels of underground parking on the adjacent properties to the west and northwest.

# **Buildings and Structures**

The subject site is currently occupied by five (5) residential dwellings and associated private garages. The buildings are considered to have been constructed between 1948 to 1953. No other buildings or structures are present on the Phase I Property.

# Water Bodies and Areas of Natural Significance

There are no water bodies on the subject site or within the Phase I Study Area. The nearest water body is the Ottawa River, located approximately 940 m to the northwest of the Phase I Property.

No areas of natural significance were identified on the site or in the Phase I ESA Study Area.

#### Drinking Water Wells

The online interactive well record mapping system was accessed on December 7, 2018. No potable well records were identified for the Phase I Property. Two records of domestic wells, dated 1948 and 1951, were identified for properties within the Phase I Study Area. These wells are no longer considered to be in operation as the Phase I Property and surrounding properties are municipally serviced.

# Monitoring Well Records

A total of 14 well records for test holes or groundwater monitoring wells were identified for other properties within the Phase I Study Area. Monitoring well records were identified for the properties addressed 1960 Scott Street, 309 Athlone Avenue, 145 Richmond Road, 160 Lanark Avenue (Mahoney Park) and further to the east along Scott Street. As previously discussed, the groundwater beneath 1960 Scott Street is clean based on information in our files. The remaining monitoring wells are not considered to represent a concern to the Phase I Property based on their separation distances of over 100m from the subject land.

# **Neighbouring Land Use**

Neighbouring land use in the Phase I Study Area is primarily residential with some commercial land use.

# Potentially Contaminating Activities (PCAs)

No existing on-site PCAs were identified on the Phase I Property. As noted previously, based on the findings of investigative work conducted by Paterson on the adjacent properties to the west and northwest, previously occupied by automotive service garages and/or contractor yards, these properties are not considered to be PCAs. A transformer sub-station situated to the northeast of the Phase I Property, across Clifton Road is the closest off-site PCA with respect to the Phase I Property. Based the nature of its operation in combination with its downgradient orientation and separation distance of approximately 35m, the substation is not considered to represent an APEC on the Phase I Property.

Other historical or existing off-site PCAs identified within the Phase I-ESA study area are presented on Drawing PE4500-2 – Surrounding Land Use Plan. Based on their separation distances and/or orientations with respect to the Phase I Property, the PCAs are not considered to represent APECs on the Phase I Property.

# Areas of Potential Environmental Concern (APECs) and Contaminants of Potential Concern (CPCs)

As noted above, none of the aforementioned off-site PCAs identified within the Phase I Study Area are considered to have resulted in APECs on the Phase I Property. There are no CPCs on the Phase I Property.

# Assessment of Uncertainty and/or Absence of Information

The information available for review as part of the preparation of this Phase I-ESA is considered to be sufficient to conclude that there are no PCAs in the Phase I Study Area that represent APECs on the subject site. The presence of PCAs was confirmed by a variety of independent sources, and as such, the conclusions of this report are not affected by uncertainty which may be present with respect to the individual sources.

# 8.0 CONCLUSIONS

# Assessment

A Phase I-Environmental Site Assessment (ESA) was carried out for the properties addressed 316, 320, 324, 326 and 332 Clifton Road, in the City of Ottawa, Ontario. The purpose of the Phase I-ESA was to research the past and current use of the site and study area and to identify environmental concerns with the potential to have impacted the subject property.

Based on the available historical information sources, the Phase I Property was first developed for residential purposes between 1948 to 1953. The adjacent properties to the north, south and east were used for residential purposes, while the adjacent property to the west was originally vacant, followed by use for commercial purposes (contractor yard). The property to the northeast, across Clifton Road, has been occupied by a transformer sub-station since as early as 1957. Paterson has filed records of site condition (RSCs) in the MECP's Environmental Site Registry for the residential and mixed-use redevelopment of the adjacent properties to the west and northwest. Based on information in our files, these properties are not considered to represent areas of potential environmental concern on the Phase I Property.

Off-site historical PCAs identified are not considered to result in APECs on the Phase I Property based on their separation distances and/or orientations with respect to the subject land.

Following the historical review, a site visit was conducted. No concerns were identified on the subject site. The current use of the adjacent and neighbouring properties within the Phase I ESA Study Area were observed from publicly accessible areas. No off-site PCAs with the potential to impact the Phase I Property were identified at the time of the site visit.

Based on the findings of the Phase I-ESA, it is our opinion that **a Phase II-ESA is not required for the Phase I Property.** 

# Recommendations

Based on the ages of the subject structures (late 1940's through early 1950's) potentially asbestos containing materials (ACMs) observed at the time of the site visit include, vinyl floor tiles, linoleum flooring, hard plaster, decorative ceiling plasters, suspended ceiling tiles, drywall joint compound, and interior and exterior parging. Based on dates of construction, lead-based paints (LBPs) may be

present within the structures on older or original painted surfaces beneath newer paints. All building materials and painted surfaces were observed to be in good condition at the time of the site visit and the potential for ACMs and LBPs is not considered to represent an immediate concern.

It is our understanding that the subject structures will be demolished in conjunction with future redevelopment. Prior to any demolition activities, a designated substance survey (DSS) must be conducted for the existing structures, in accordance with Ontario Regulation 490/09 under the Occupational Health and Safety Act.

# 9.0 STATEMENT OF LIMITATIONS

This Phase I-Environmental Site Assessment (ESA) report has been prepared in general accordance with O.Reg. 153/04, as amended, under the Environmental Protection Act and meets the requirements of CSA Z768-01. The conclusions presented herein are based on information gathered from a limited historical review and field inspection program. The findings of the Phase I-ESA are based on a review of readily available geological, historical and regulatory information and a cursory review made at the time of the field assessment. The historical research relies on information supplied by others, such as, local, provincial and federal agencies and was limited within the scope-of-work, time and budget of the project herein.

Should any conditions be encountered at the subject site and/or historical information that differ from our findings, we request that we be notified immediately in order to allow for a reassessment.

This report was prepared for the sole use of Insight Ottawa Realty Corporation. Permission and notification from Insight Ottawa Realty Corporation and Paterson will be required to release this report to any other party.

# Paterson Group Inc.

Mandy Witteman, M.A.Sc.

Mark S. D'Arcy, P.Eng., QPESA

#### **Report Distribution:**

Insight Ottawa Realty CorporationPaterson Group



# **10.0 REFERENCES**

# **Federal Records**

Air photos at the Energy Mines and Resources Air Photo Library. National Archives. Maps and photographs (Geological Survey of Canada surficial and subsurface mapping). Natural Resources Canada – The Atlas of Canada. Environment Canada, National Pollutant Release Inventory. PCB Waste Storage Site Inventory.

# **Provincial Records**

MECP Freedom of Information and Privacy Office. MECP Municipal Coal Gasification Plant Site Inventory, 1991. MECP document titled "Waste Disposal Site Inventory in Ontario". MECP Brownfields Environmental Site Registry. Office of Technical Standards and Safety Authority, Fuels Safety Branch. MNR Areas of Natural Significance. MECP Water Well Inventory.

# **Municipal Records**

City of Ottawa Document "Old Landfill Management Strategy, Phase I -Identification of Sites.", prepared by Golder Associates, 2004. Intera Technologies Limited Report "Mapping and Assessment of Former Industrial Sites, City of Ottawa", 1988. The City of Ottawa eMap website.

# **Local Information Sources**

Previous Engineering Reports. Personal Interviews.

# **Public Information Sources**

Google Earth. Google Maps/Street View.

# FIGURES

FIGURE 1 – KEY PLAN

FIGURE 2 – TOPOGRAPHIC MAP

DRAWING PE4500-1 – SITE PLAN

DRAWING PE4500-2 – SURROUNDING LAND USE PLAN




FIGURE 1 TOPOGRAPHIC MAP

# patersongroup.






FIGURE 2 TOPOGRAPHIC MAP

# patersongroup



autocad drawings\environmental\pe45xx\pe4500\pe4500-1 d



p:\autocad drawings\environmental\pe45xx\pe4500\pe4500-2 slup.dwg

# **APPENDIX 1**

**AERIAL PHOTOGRAPHS** 

SITE PHOTOGRAPHS







# patersongroup

AERIAL PHOTOGRAPH 1953





## patersongroup -



# patersongroup —




# patersongroup -



patersongroup -


# patersongroup

AERIAL PHOTOGRAPH 1993





\_\_\_\_patersongroup



patersongroup

## Site Photographs

PE4500

316, 320, 324, 326, 332 Clifton Road - Ottawa, ON

January 8, 2019



Photograph 1: East face of subject building addressed 316 Clifton Road, looking west.



Photograph 2: East face of subject building addressed 320 Clifton Road, looking west.

## patersongroup

## Site Photographs

316, 320, 324, 326, 332 Clifton Road - Ottawa, ON

January 8, 2019



Photograph 3: East face of subject building addressed 324 Clifton Road, looking west.



Photograph 4: East face of subject building addressed 328 Clifton Road, looking west.

PE4500

## patersongroup \_

## Site Photographs

PE4500

316, 320, 324, 326, 332 Clifton Road - Ottawa, ON

January 8, 2019



Photograph 5: East face of subject building addressed 332 Clifton Road, looking west.

## patersongroup.

## **APPENDIX 2**

MECP FREEDOM OF INFORMATION SEARCH MECP WELL RECORDS CITY OF OTTAWA HLUI SEARCH TSSA CORRESPONDENCE



Ministry of Environment and Energy

## **Freedom of Information Request**

This form is for requesting documents which are in the Ministry's files on environmental concerns related to properties. Please refer to the guide on completion and use of this form. Our fax no. is (416) 314-4285.

		Requester Data		For Minist	ry Use Only
Name, Company	Name, Mailing Address and	Email Address of Requester		FOI Request No.	Date Request Received
Mandy Witt				i of nequest no.	
Paterson G 154 Colonr	•				
Ottawa, ON					
		patersongroup.ca		🗆 ACCT 🗆 CHQ 🗆 V	'ISA/MC □ CASH
Telephone/Fax No	DS.	Your Project/Reference No.	Signature/Print /Name of Requester		
	13-226-7381 13-226-6344	PE4500	Mandy Witteman	□ CNR □ ER □ NOR □ SAC □ IEB □ EAA	
			Request Parameter		
Municipal Addres	ss / Lot, Concession, Geo	ographic Township (Municipa	l address essential for cities, towns or region	ons)	
316, 320, 3	324, 326 and 332	Clifton Road., Ottaw	a ON		
	Owner(s) and Date(s) of Ow				
Jeremy Sill					
•	Owner(s) and Date(s) of Ov	vnership			
Present/Previous	Tenant(s),(if applicable)				
Unknown					
		Sea	arch Parameters		Specify Year(s) Requested
Files older tha	an 2 years may requir	e \$60.00 retrieval cost. Th	ere is no guarantee that records responsive	e to your request will be located.	Specify real(s) Requested
Environme	ntal concerns (Ge	eneral corresponden	ce, occurrence reports, abatement	)	all
Orders					all
Spills					all
Investigatio	ons/prosecutions	Owner AND tena	nt information must be provided		all
Waste Gen	nerator number/cl	asses			all
		Certificate	s of Approval ➤ Proponent info	rmation must be provided	
			h fees in excess of \$300.00 could be orting documents are also required		
				SD	Specify Year(s) Requested
air - emission	18				1986-present
water - main	ns, treatment, ground	level, standpipes & elevate	ed storage, pumping stations (local & boost	ər)	1986-present
sewage - sa	anitary, storm, treatme	ent, stormwater, leachate &	& leachate treatment & sewage pump statio	ns	1986-present
waste wate	er - industrial discharg	jes			1986-present
waste sites	5 - disposal, landfill sit	es, transfer stations, proce	essing sites, incinerator sites		1986-present
waste syste	ems - PCB destruct	ion, mobile waste processi	ng units, haulers: sewage, non-hazardous	s & hazardous waste	1986-present
pesticides -	- licenses				1986-present


<u>pesticides</u> <u>1986-present</u> A \$5.00 non-refundable application fee, payable to the Minister of Finance, is mandatory. The cost of locating on-site and/or preparing any record is \$30.00/hour and 20 cents/page for photocopying and you will be contacted for approval for fees in excess of \$30.00.

UTM 118 1444455 - Iman	ciplate	<b>A</b> SE 30	, L	15 Nº	<b>C</b> . 39\72
19 R 0501217 31610 N 101	ONTARIO	AJE SU	Ø	10 N.	
Elev. $9 R G 2 0 0$ Basin $256$ Department of M	ll Drillers		RECE	VED	
	T 4 4		MAD 2 ]	10/22	
Lot-32. Water W	/ell	Rec	Ofd GEOLOGICAL	RRANCH	TTAWP
County or District. Oarlela Tp			DEPARTMENT (	E MINES ot	
				cres	· · · · · · · · · · · ·
	includ		180.00		•••••
Pipe and Casing Record			Pumping Test		
Casing diameter(s)	Date Developed (	Capacity	Country 2	$\varphi_{\dots\dots\dots}$	· · · · · · · · · · · · ·
Length of screen	Duration of	Test	to	ŧ	
Type of screen     Type of pump	Pumping R	ate	200. 9. kg	•••••••••••••••••	• • • • • • • • • • • •
Capacity of pump	Drawdown Static level	of completed	· · · · ·	8 #+	• • • • • • • • • • •
Depth of pump setting 2.0	Is well a gra	avel-wall typ	pe?	<u> </u>	
 	ter Record	··· ··· ·	- <b>1</b>		<b>.</b>
Kind (fresh or mineral)			Depth(s)	Kind of	No. of Feet
Quality (hard, soft, contains iron, sulphur etc.)			Wester II. 1. /	111	Water Rises
Appearance (clear, cloudy, coloured)	Clear		119 /4	Jat+	100 - th
For what purpose(s) is the water to be used?				-	110 feet
How far is well from possible source of contamination?	A		•		
What is source of contamination? Septu ter	1 1	· · · · · · · · · · · · · · · · · ·		-	
Enclose a copy of any mineral analysis that has been man	de of water	••••	• • • • • • • • • • • • • • • • • • • •	_	
Weil Log				cation of Wel	1
Drift and Bedrock Record	From	To		low show dista	
l_	0 ft.	ft.	from road and		
Blue Clay	8	5			
				61	
Black and to	50	50			
		- <b>*</b> ~			Ţ.
Bille Shale	60	125 1-	$\mathcal{L}$		land P. D+
	<u></u>		TOP	The second	plain co
			22 602		<b>a s</b>
			Mary	- AN	
		1 4			
		/	Que la la	S.Z	
			the train	S. Z.	
			12 that have	Sil Nest	·
Situation: Is well on upland, in valley, or on hillside?.		Leavel.	12 that have	Str Vest	
Drilling Firm Mullyn Bro		Leavel.	20 m tone	<u>S</u> ?? <u>Vest</u>	
Drilling Firm. Mullyn Bro Address. Wistbor R KH1 Recorded by John & Murhand	· · · · · · · · · · · · · · · · · · ·		20 pt to the	•••••••••••••••••••••••••••••••••••••••	· · · · · · · · · · · · · · · · · · ·
Drilling Firm Mullyn Bro	· · · · · · · · · · · · · · · · · · ·		12 Hours June Var Hours Land	•••••••••••••••••••••••••••••••••••••••	· · · · · · · · · · · · · · · · · · ·
Drilling Firm. Mullyn Bro Address. Wistbor R KH1 Recorded by John & Murhand	· · · · · · · · · · · · · · · · · · ·	Address .	ý	•••••••••••••••••••••••••••••••••••••••	

.

Basin 215	V 62 ONTARIO Well Driller Minos Pro			<u>15 Nº</u> CEIVI	
Department of 97 1433 Water V			DEPAR	LOUIDAL BRA RTMENT OF N	
County or Territorial District Carleton	Township	TALUA Village, Town	City.	<del>parana</del> .	· · · · · · · · · · · ·
	s	Micst			
(day) (month) (year)	or wen (excl	uding pump)	•••••	•••••••••••••••	• • • • • • • • •
Pipe and Casing Record		1	Pumping Test		
Casing diameter (s)	<ul> <li>Static leve</li> <li>Pumping 1</li> <li>Pumping r</li> <li>Duration c</li> </ul>	1 <b>2.0</b> evel <b>3.0</b> ate f test		• • • • • • • • • • • • • • • • • • • •	
V	Vater Recor				
Quality (hard, soft, contains iron, sulphur, etc.) Appearance (clear, cloudy, coloured) For what purpose(s) is the water to be used? How far is well from possible source of contamination? What is the source of contamination? Enclose a copy of any mineral analysis that has been ma		· · · · · · · · · · · · · · · · · · ·	80	hard	60
Well Log	de of water.	·····			-
Overburden and Bedrock Record	From 0 ft.	To ft.	In diagram be	tion of Well clow show distand and lot lin	
		18	dicate north	Ş	
White Lumestore		125	ory hulles		
			Frank -	Arres	selan ( Seland
			Frank P	o # 8100 4	160 from
Situation: Is well on upland, in valley, or on hillside? Drilling Firm	· · · · · · · · · · · · · · · · · · ·	Address	laguleron Ecr	.t. 2n /	<i>n</i> .2
Date		Licence Nu	mber	••••••	• • • • • • • • • •


	istry of Environment	029527	iber below)	Regulation 903	Ontario Water	II Record Resources Act
<ul> <li>All Sections must be completed of the comple</li></ul>	Form Datario only. This document is a p seted in full to avoid delays in proce ting this application can be directed hall be reported to 1/10 <sup>th</sup> of a me	essing. Further in ed to the Water V	structions and	explanations are avainent Coordinator at 4	e reference. ilable on the ba 116-235-6203	ack of this form.
Please print clearly in blue of Well Owner's Information and Image: State	r black ink only. d Location of Well Information			Ministry Use		LOT
RR#/Street Number/Name 309 A H ONC GPS Reading NAD Zong 8 3 18 Log of Overburden and Bedro	Avenue Easting 4411 <b>40</b> 502720 ock Materials (see instructions		Ja	Site/Compar of Operation: Undif	rtment/Block/Tr	act etc.
General Colour Most common mat Asphalt conc DK Brown Silty Sand Brown Sandy S Grey Limestone	terial Other Materials Mere 9 ravel	Typ 3m (5	ical Hon stallat	I Description itering Well ion and a Clust		······································
Hole Diameter	Construction	1		Test Pumping test method	t of Well Yield	Recovery
From To Centimetres	Inside Material Wall diam Material thicknes ntimetres centimet	ss	Metres To			Time Water Level min Metres
Water Record	Casing Casing Steel Fibreglass Galvanized Steel Fibreglass Plastic Concrete	0.9	1.25	(metres) Pumping rate - (litres/min) Duration of pumping hrs +min Final water level end of pumping	Level	1 2 3
Gas Salty Minerals Other: m Fresh Sulphur Gas Salty Minerals Other:	Galvanized			Recommended pump typeShallowDeep Recommended pump depthmetres	4	4
Other:	Screer	°. 1.25	4.70	Recommended pump rate. (litres/min) If flowing give rate - (litres/min) If pumping discontin- ued, give reason.	10 15 20 25 30 40	10           15           20           25           30           40
	Open hole				50 60	50 60
G.9 1.25 Bentori	pentonite slurry, neat cement slurry) etc.	Abandonment Volume Placed (cubic metres)	Indicate north by	Location of v show distances of well fro v arrow. e See Site (thached)	om road, lot line,	and building.
Cable Tool Rotary (air) Rotary (conventional) Air percuss Rotary (reverse) Boring Domestic Industrial	Diamond					
Stock     Commercia     Irrigation     Municipal     Fi     Water Supply     Recharge well     Observation well     Abandoned, insu     Test Hole     Abandoned, poor	Cooling & air condition inal Status of Well Unfinished A ufficient supply Dewatering		Audit No. Z Was the well ov package delivered	31545 vner's information ad? Yes No		55 108125 //// MM □D
	ctor/Technician Information UDUILing Ud Well Contraction Self-Sha-Folge, Oc Jr name) Well Technic Date Submitted	OVIBO Dian's Licence No.	Data Source Date Received OC I Remarks	1 2 2005   Dat	ntractor 1 e of Inspection	



	Inistry of Sector Well Tag Net Environment	winiber (Place sticker and print a	umber below)	Regulation 903	Ontario Wat		ecord
	a far a far a second a second	มาให้มากระดิษาสมกับ และมากกู้เริ่มและมาติ (1967) 	i .	- TOTALON MARIN	$a_1 = a_1 \sum_{i=1}^{n} a_i$	4.4.1 L	of
Instructions for Completing	Form as the set of the design of	and the state of the state when	houmont Plac	de ante de case de se retain for future	reference	1.05	
All Castions must be compl	f <b>Ontario</b> only. This documen bleted in full to avoid delays in	nrocessing Further ins	tructions and ex	kolanations are avai	lable on the	DACK OF L	his form.
<ul> <li>Ouestions regarding completions</li> </ul>	leting this application can be shall be reported to 1/10 <sup>th</sup> c	directed to the water w	ell Managemer	It Coordinator at 4	-10-235-020	)3.	
<ul> <li>All metre measurements s</li> <li>Please print clearly in blue of</li> </ul>	or black ink only.			Ministry Use	Only		
Well Owner's Information ar		nation	CON			LOT	
142 DICHMONL	O DOAR			Site/Compar	tmont/Blook	/Troot otc	
RR#/Street Number/Name		City/Town/Villa	LIF.	n a chuir an chuir an Chuir an chuir an chui			
GPS Reading NAD Zone	Easting Northin	g Unit Make/Moo		2 T 12 (7 2 1 <u>) 2222</u> ) 1 1 3 4 Land (T 2 1)	ferentiated rentiated, specif	Avera	ged
8 3 /2 Log of Overburden and Bed	drock Materials (see instru	ictions)					
General Colour Most common ma		rials	General D	escription		Depth From	Metres To
a the second sec				<ul> <li>Address (Construction)</li> </ul>	1997 - 1998 - 1998 - 1998 - 1998 - 1998 - 1998 - 1998 - 1998 - 1998 - 1998 - 1998 - 1998 - 1998 - 1998 - 1998 -		
		Carlos and C	ateria ad <u>ar</u>	and thin a second			
					si	- D	
	<ul> <li>The first distance of</li> </ul>	. Kentari Alin Interneti	tila prime eno	i de la transferiera de la companya	· · · ·		
	a a transformation and a second second	and an and a state of the	າວຣັບສະ ( )	Received Recting and	· · ·		
	C. A. Michael			and the second	<u> </u>	<u></u>	
			Leithad parages	e i e server i e transferencia. Al constante de la constante d		, <sup>1</sup> .	
Part of the second s	and the second second second second		<mark>¢la of 2002 - 2011.</mark> Na 1990 - 1990 - 1990	an golf ann an de Maria an Ghr ann an Anna Anna Anna Anna Anna			
na sea an an ann an Seastair			h <del>an an an</del> an	<u></u>	in the second second		
Hole Diameter		uction Record	· · · · · · · · · · · · · · · · · · ·	I es Pumping test method	t of Well Yie Draw Dow		ecovery
Depth         Metres         Diameter           From         To         Centimetres	Inside diam Material	Wall Depth thickness	MCCO		Time Water Li	evel Time	Water Level
and the second s	centimetres	centimetres From	То	Pump intake set at -	min Metre Static	es min	Metres
		Casing		metres) Pumping rate -	Level	1	š
	Steel Fibreglass			litres/min)			
Water Record	Galvanized			Duration of pumping	2	2	
Water found atMetres / Kind of Water	Steel Fibreglass	en de la companya de		hrs + min Final water level end	3	3	
m Fresh Sulphur		alt y del	2011 C 1 1 2 2 1	of pumpingmetres			
Other:	Galvanized			Recommended pump	4	4	
m Fresh Sulphur Gas Sulphur Minerals	Plastic Concrete	No.		Shallow Deep Recommended pump	5	5	
Other.	Galvanized			depthmetres Recommended pump			
☐ m ☐ Fresh ☐ Sulphur ☐ Gas ☐ Salty ☐ Minerals		Screen	A	rate. (litres/min)	10 15	<u>10</u> 15	
Gas Salty Minerals	diam Blastic Concrete	Slot No.	non an ann an an ann an Anna an Anna an Anna an Anna An Anna Anna	If flowing give rate -	20	20	
After test of well yield, water was	Galvanized	<ul> <li>TAB ( replication for the particular sector)</li> </ul>	• • • • • • • • • ∎ • • • • • • • • • •	(litres/min)	25 30	25	
Other, specify	No Ca	sing or Screen		ued, give reason.	40	40	
Chlorinated Yes No	Open hole	1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1			50	50	( 
			JL		60	60	
Plugging and Sea		to Volume Placed	In diagram below s	Location of how distances of well fr	in the second	ine, and bu	ilding.
From To	e (bentonito sidiny), near coment sidiny),	(cubic metres)	Indicate north by a			-esta azolo -	
15 25 Mont	f lary	3 Bras			1.4.4.4. 1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1		
0 15 Jones	WHAT OUT	s and gent for him is	partiti presi i s	an the second state		s i e as l	. 11 a ag
9 Parto		1	palaan Arina gewoo T		ang <sup>ar</sup> an an an a	· · · · 2	
	Constant Constants Constant d Constant Constant Alternative	and an and the second of the second		en destructionen ander metzig Erstende die State in		en en 1983. Maria de 1993	ana indra 44 ji T
Me	lethod of Construction			autor more de seconda		n Andre Sect	
Cable Tool Rotary (a	air) Diamond	Digging Other	n an an an Arrien an Arrien an Arrien an Ar	eren art <b>erkno</b> uweren.	,	t jangkaput	4.11 - 14.14
Rotary (reverse) Boring	The average of the state of the Driving	No on and the b <del>eing all and the formation</del> is	s saki terang lada	nasi waali kwali i		en Solap Longo	
	Water Use	· · · · · · · · · · · · · · · · · · ·	ande opræse Biller	esta hara a de la della de La della d		en las Ortikas	en En se fins en s
Stock Commerce	rcial 🗌 Not used		动行动的现在	ang dinan si	te Well Compl	e ted	
	al Cooling & air Final Status of Well	conditioning	Audit No. Z	28743 🎽		YYYY	MM DD
Water Supply Recharge wel	əll 🗌 Unfinişhed	Abandoned, (Other)	Was the well own	er's information Da	te Delivered	YYYY	MM DD
Observation well     Abandoned, in     Test Hole     Abandoned, p	insufficient supply Dewatering poor quality Replacement	well	package delivered?				<u> </u>
Well Contr	tractor/Technician Informatio		Data Source	Ministry Us	e Only	veri A	
Name of Mal Contractor	hllere	Contractor's Licence No.	2		<u>60</u>	164	•
Business Address (street name, numbe	et, citretc.) Out - FUX	1160	Date Received	1 2005 DD Da	te of Inspectior	י איזא	MM DD
Name of Well Technician (last name, fir	5 - p	Technician's Licence No.	Remarks		ell Record Nun	nber	
Signature of Technician/Contraction			DWC VIP	PHONE	an an ann an An Frainneach Agus An		
X		2005 11 15	2005/11	/1>		lines	
0506E (09/03)	Contractor's Copy 🔲 🛛 Mi	nistry's Copy 🔲 🛛 Well Owr	ner's Copy 🛄	Cette	formule est a	sporiibie	ən nançals

<b>Ontario</b>	Ministry of the Environment	Well Tag No. for Master A 056104	Master Well Record for Cluster Well Construction
		A056104	Regulation 903 Ontario Water Resources Act Page of

		Land Owner's Info	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~			
First Name			Name			
Mailing Ad	<u>らそ O tTA ふみ</u> dress (Street Numbe	r/Name, RR)	BLICWOR Municipali	<u>fs &amp; Sei</u>	ences	
* -	ONSTELLATIO	2		TAWA		$\frac{\text{Province}}{ON} \qquad \frac{\text{Postal Code}}{\frac{1}{2} \frac{1}{2} \frac{1}{$
Location	and Constructio	n of the Master We				
	•	t Number/Name, RR)	То	ownship		Lot Concession
	ATTACHE strict/Municipality	o plan	0:	the of The same the fatter of		
Coanty/Dis	strictivitincipanty			ty/Town/Villag	-	Province   Postal Code     S   Ontario
UTM Coord	linates Zone Easti	ng <sub>t</sub> Northing	GPS	Unit Make	Model	
NAD	8318744	2331502	794961	grai-	76	65 [Jubifferentiated, specify 30
Overb	urden and Bedroc	k Materials <i>(see inst</i>	ructions on the b	ack of this fo	orm)	Hole Details
General Colour	Most Common Material	Other Materials	General Description		(Metres)	
	1		Decomplication		To	(Centimetres)
GRY	ASPHALT	·		O	0.2	2 0 5.3 20.0
GRY	CONCLETE			0.2	0.5	5
Ben	SAND	GLAVEL LOBBL	-	0.5	3.1	
BRN GR-1	1			31		
OLY	LIMESTONE		· · · · · · · · · · · · · · · · · · ·	J.P	3.3	
<u> </u>	······································				. · · · · · ·	Water Use
		Survey and State				Public Industrial Not used Other, specify     Domestic Commercial Dewatering
		9				
	$\langle n \rangle$					Inigation Test Hole Cooling & Air Conditioning
·····	$-/3^{\dagger}$	1				Method of Construction
						Cable Tool Air Percussion Digging Rotary (Conventional) Diamond Boring
					·*****	Rotary (Reverse)     Detting     Other, specify
<u> </u>			······			Rotary (Air)  Driving
			······	·····		Status of Well
						Test Hole Abandoned, Insufficient Supply
			······································			Replacement Well     Abandoned, Poor Water Quality     Dewatering Well     Other, specify
·····	·	·····				
						No Casing and Screen Used Static Water Level Test Open Hole
		Construction Dei	ails	F	·	Yes No Metres
Inside Dian	<b>k</b>	Material	Wal		I	
(Centimeti		fibreglass, concrete, ga	alvanized) Thickn	ess From	To	Galvanized     Steel     Fibreglass     Concrete     Fibreglastic       Outside Diameter (Centimetres)     Slot No.
3,2	PLAST.	IL RIS	EL 0,2	20	2.3	Outside Diameter (Centimetres) Slot No. 3.6
		SCAL	EN 0.2	- 2.3	5.3	
			**************************************			Water found at Depth Kind of Water
		······································	·····			Metres Gas Fresh Salty Sulphur Minerals
	1					Water found at Depth Kind of Water
Death Cat a		Space/Abandonmen				Metres Gas Fresh Salty Sulphur Minerals
Depth Set a From	To	Type of Sealant U (Material and Type		Volume (Cubic I		Water found at Depth       Kind of Water         Image:
0.2	18 hr.	WITE HOL			···· ···	
<u> </u>	TOU IJENT	WITE HOL	.E <sup>p</sup> LUC		9	Disinfected Yes No. If no, provide reason: Date Master Well Completed (//yyy/mm/dd),
			······································			2007/10/15
						Cluster Information (Please also fill out the additional Cluster Well
				·····		Information for Well Construction for each parcel of land and cluster.)           Total Wells in Cluster         Please indicate Number of Cluster Well
	,					- Information Log Sheets Submitted
·						Total Wells on this Property
	, ,					Location of Well Cluster     Detailed Map must be provided as an attachment no larger than legal size
·····						(8.5" x 14"). Sketches are not allowed.
						Check box to confirm detailed map is provided as per Section 11.1 (3)
						Consent to release additional information concerning the cluster to the Director upon request
						Signature of Technician/Contractor Date (yyyy/mm/dd)
		actor and Well Tech	nician Informatio	on		
lusiness Na	me of Well Contractor			ontractor's Lice	nce No.	Master Well Owner's/Land Owner's consent to use Cluster Form



© Queen's Printer for Ontario, 2006

Ministry's Copy



Ministry of the Environment

Well Tag No. for Master Well (Print Well Tag No.)

A056104

## **Cluster Well Information for Cluster Well Construction**

Regulation 903 Ontario Water Resources Act

											Page /	of
Property Owner's Information	Service come											
	t Name	(			ress (Street No			Munici		*		
Province Prostal C	)EPARTM	<u> ゆんうて 001</u>   E-mai	ILADUCHOU	55 100 (	CONSTRU	LATI	onCles	ENT. (1 Fr	No. (inc. area	OTTAWA	-	
t –	662		<u>Carol.Houre</u>	so attai	a Pa					02424		
Cluster Well Information				30-011-100	<u> </u>				<u> </u>			BOIL TO THE DILECTOR
Address of Well Location (Street Number/Name, R	R)	Lot	Co	ncession T	ownship			County	//District/Mur	nicipality	upon request Signature of Technician/Contractor	Date (yyyy/mm/dd)
SEE ATTACHED PLAN City/Town/Village Prov	vince Po	ostal Code	GP	S Unit Make N	lodel	I Init Mor	le of Oper	ation C1100	lifferentiated	Averaged		
	tario				765	1	entiated, s		ancicialeu			
Well# UTM Coordinates on Sketch Zone Easting Northing	Full Depth of Hole (metres)	Hole Diameter	Method of Construction	Casing Material	Casing Length		erval (metres)		Static Water	Abandonment	Comments	Date of Completion
				Δ	(metres)	From	То	Sealant Used	Level (metres)	Sealant Used		(yyyy/mm/dd)
BH2 181 44 1 487516 2744	8 5.2	20.0	BORING	PLASTIC	0-2.2	2.2	-5.2	HOLGPLUG	4.0			
345 181 44171125027576	5.0	20,0	n	11	0-2.0	2.0	5.0	/ )	4.2			
346 187442213502787	7 5.1	20.0	h	4	0-2.1	2.1	5.1	4	4.1			
3410 1874424525028000		20,0	1,	4	0-2.2	2,2	5.2	4	4.3			
H 4 187441 56 95027494	, ,	20.0	<i>l</i> i	11	0-17	<b>张</b> ].7	3.1	(1	Ha-			
							31		1671			
Well Contractor and Well Technician Ir	nformation				·					I	Date 1st Well in Cluster Constructed Date Last	Well in Cluster Constructed
Business Name of Well Contractor		Bus	iness Address (St				Municipal	ity		Province	(yyyy/mm/dd) 2007/10/12 (yyyy/mm/dd	10/16
AST CONSULTING	NT	6	65 HEW	itson S.	T		THUN	OER BA	7	ON TANIO	Ministry Use Only	
Postal Code         Business Telephone           P         7         8         7         6         2	NO. (Inc. area 2 2 2	code) 929		Licence No. Bus	iness E-mail A	odress					Date Revolve2 (2/2007//dd) Date Ins	spected (yyyy/mm/dd)
Name of Well Technician (First Name, Last Name)		1 1	Well Technician's	Licence No. Date	Submitted (y)	(yy/mm/dd)	Signature			······	Audit No. Remarks	8
ALAN FINKE			2 5	4 4	OCT 2	007		C				NIZLO
1991 (11/2006)							8-m					's Printer for Optaria 2006

Ministry's Copy

	surem		the		ric 🗌 Imp	<b>erial</b> Print or Type			1	ag No. of I U/A on Drawin	·		-	ell Tag N	o.)				(Only	for Mul	ord for Well tiple Test Holes o 3 Ontario Water R	or Dewa	atering \	
Addres	s of We	II Location	n Inform n (Street N n Char mlet	iumber(s)/	Name(s), RR,	if available)	Lot(s) Provinc Onta	I	GPS U	nit Make				Haw Mode of Differentia	S C- Operatio		1 0 5 8	er Tier Municip OHcw ated XAV	c~	Land Deta	ory Attachments/A d Owner Consent Form ailed Drawing of All We son constructing the wel on request, any addition tated to any well in the v	n must be ell Locatic II, will pror nal informa well cluste	e attached. ons must be mptly submi ation in my o er that I have	e attached. nit to the custody or re constructed.
Well D Well # on Drawing		Easting	UTM Co	ordinates Northing		Hole Depth (m/ft)	Hole Diameter (cm/in)	Metho Constru		Casing Material; Diameter (cm/in)		sing 1/ft)   To		Interval /ft) To	Annul: From	ar Space (m/ft) To	Material Material:			burden/Be	of Technician/Contract edrock or erial Intervals (m/ft)		Date (yyy Static Water .evel (m/ft)	Date of Completion
#1	1	-			2731214 24731819	0 4.9~ 9 4.6~	~/ <sub>A</sub>		-	-	-		-	-	-	<u>م</u>					Bentanite D.6			2011 1102
#3	1	¥			a 735 k		N/A								<b>1</b>			Gravel	0-0.61	Bend	oùdz 0.61m-2	•43m	2.43m	2011 1102
																								~
											- 													4
Busines	s Nam	e of Well (	Contractor			ess Address (S			RR)	Municipality	·	<u> </u>		vince	or Abar	idoned (y	Cluster Cons yyy/mm/dd) ට 2	Con	e Last Well in npleted (yyyy/i	mm/dd) 🛛	Ministry Use Only Date Received (yyyy/m JAN 3 1 201		Audit No.	16367
Postal C K 7 Name o	Code R∣3 f Well 1	5	イム んてき Bus. Telep 613 3き (First Nar	phone No. 5	. Well C 6 70 Name) Well To	06 Danve Contractor's Lic 065 echnician's Lic 16	cence No.	Business Setd	ETTP-	ńsem	y <b>८</b> ७.^  Dat	e Submit		/mm/dd)	Well A Persor	<b>bando</b> Abando	ning the Well				Comments:	<u> </u>		

1991E (2011/04) © Queen's Printer for Ontario, 2011

.

Well ID Number: 7224472 Well Audit Number: *C22336* Well Tag Number: *A147202* 

This table contains information from the original well record and any subsequent updates.

## Well Location

Address of Well Location	
Township	NEPEAN TOWNSHIP
Lot	
Concession	
County/District/Municipality	OTTAWA-CARLETON
City/Town/Village	
Province	ON
Postal Code	n/a
UTM Coordinates	NAD83 — Zone 18 Easting: 441521.00 Northing: 5027205.00
Municipal Plan and Sublot Number	
Other	

#### **Overburden and Bedrock Materials Interval**

General Colour Most Common Material	Other Materials	General Description	Depth From	Depth To	
-------------------------------------	-----------------	---------------------	---------------	-------------	--

#### Annular Space/Abandonment Sealing Record

DepthDepthType of Sealant UsedVolumeFromTo(Material and Type)Placed

### Method of Construction & Well Use

Method of Construction Well Use

#### **Status of Well**

#### **Construction Record - Casing**

Inside Diameter Open Hole or material Depth Depth From To

#### **Construction Record - Screen**

Outside Diameter<sup>Material</sup> Depth Depth From To

### Well Contractor and Well Technician Information

Well Contractor's Licence Number: 6964

## **Results of Well Yield Testing**

After test of well yield, water wa	s
If pumping discontinued, give re	ason
Pump intake set at	
Pumping Rate	
Duration of Pumping	
Final water level	
If flowing give rate	
Recommended pump depth	
Recommended pump rate	
Well Production	
Disinfected?	

#### Draw Down & Recovery

Draw Down Time(min)	Draw Down Water level	Recovery Time(min)	<b>Recovery Water level</b>
SWL			
1		1	
2		2	
3		3	
4		4	
5		5	
10		10	
15		15	
20		20	
25		25	
30		30	
40		40	
45		45	
50		50	
60		60	

#### Water Details

Water Found at Depth Kind

#### **Hole Diameter**

Depth Depth From To Diameter

Audit Number: C22336

Date Well Completed: January 24, 2014

Date Well Record Received by MOE: July 24, 2014

Updated: February 2, 2018 Rate<u>Rate</u> Share<u>facebook twitter Print</u> Tags

- Environment and energy,
- Drinking water,

Well ID Number: 7240886 Well Audit Number: *Z198253* Well Tag Number: *A173740* 

This table contains information from the original well record and any subsequent updates.

## Well Location

Address of Well Location	205 LANARK AVE.
Township	NEPEAN TOWNSHIP
Lot	
Concession	
County/District/Municipality	OTTAWA-CARLETON
City/Town/Village	OTTAWA
Province	ON
Postal Code	n/a
UTM Coordinates	NAD83 — Zone 18 Easting: 441131.00 Northing: 5027480.00
Municipal Plan and Sublot Number	
Other	

#### **Overburden and Bedrock Materials Interval**

General Colour	Most Common Material	Other Materials	General Description	Depth From	Depth To
BRWN	LOAM	STNS	SOFT	0 m	1.32 m
GREY	LMSN	LYRD		1.32 m	12.19 m

#### Annular Space/Abandonment Sealing Record

	Depth To	Type of Sealant Used (Material and Type)	Volume Placed
0 m	.31 m	CONCRETE/FLUSHMOUNT	
.31 m	8.84 m	BENTONITE	
8.84 m	12.19 m	FILTER SAND	

## Method of Construction & Well Use

Method of Construction Well Use

Air Percussion

Monitoring and Test Hole

#### Status of Well

Test Hole

#### **Construction Record - Casing**

Inside	Open Hole or material	Depth	Depth
Diameter		From	To
4.03 cm	PLASTIC	0 m	9.14 m

#### **Construction Record - Screen**

Outside Depth Depth Diameter Material From To 4.82 cm PLASTIC 9.14 m 12.19 m

#### Well Contractor and Well Technician Information

Well Contractor's Licence Number: 7241

#### **Results of Well Yield Testing**

After test of well yield, water was If pumping discontinued, give reason Pump intake set at Pumping Rate Duration of Pumping Final water level If flowing give rate Recommended pump depth Recommended pump rate Well Production Disinfected?

#### Draw Down & Recovery

Draw Down Time(min)	Draw Down Water level	Recovery Time(min)	<b>Recovery Water level</b>
SWL			
1		1	
2		2	
3		3	
4		4	
5		5	
10		10	
15		15	
20		20	
25		25	
30		30	
40		40	
45		45	
50		50	
60		60	

#### Water Details

Water Found at Depth Kind

#### **Hole Diameter**

Depth From	Depth To	Diameter
0 m	1.83 m	11.43 cm
1.83 m	12.19 m	7.62 cm

Audit Number: Z198253

Date Well Completed: April 17, 2015

Date Well Record Received by MOE: May 05, 2015

Updated: February 2, 2018 Rate<u>Rate</u>

Well ID Number: 7265948 Well Audit Number: *Z229830* Well Tag Number: *A190916* 

This table contains information from the original well record and any subsequent updates.

## Well Location

160 LANARK AVENUE
NEPEAN TOWNSHIP
OTTAWA-CARLETON
Ottawa
ON
n/a
NAD83 — Zone 18 Easting: 441305.00 Northing: 5027564.00

#### **Overburden and Bedrock Materials Interval**

General Colour	Most Common Material	Other Materials	General Description	Depth From	Depth To
BRWN	SAND	FILL	SOFT	0 m	1.22 m
BRWN	SAND		SOFT	1.22 m	2.13 m
BRWN	SILT		PCKD	2.13 m	2.44 m
GREY	LMSN		PCKD	2.44 m	5.79 m

#### Annular Space/Abandonment Sealing Record

Depth From	Depth To	Type of Sealant Used (Material and Type)	Volume Placed
0 m	.31 m	FLUSHMOUNT/ CONCRETE	
.31 m	2.44 m	BENTONITE	
2.44 m	5.79 m	SAND	

#### Method of Construction & Well Use

Method of Construction	Well Use
Air Percussion	
	Monitoring and Test Hole

#### Status of Well

Monitoring and Test Hole

## **Construction Record - Casing**

Inside	Open Hole or material	Depth	Depth
Diameter		From	To
5.2 cm	PLASTIC	0 m	2.74 m

#### **Construction Record - Screen**

Outside Material Depth Depth Diameter Material Depth From To 6.03 cm PLASTIC 2.74 m 5.29 m

#### Well Contractor and Well Technician Information

Well Contractor's Licence Number: 7241

#### **Results of Well Yield Testing**

After test of well yield, water was If pumping discontinued, give reason Pump intake set at Pumping Rate Duration of Pumping Final water level If flowing give rate Recommended pump depth Recommended pump rate Well Production Disinfected?

#### Draw Down & Recovery

Draw Down Time(min)	Draw Down Water level	Recovery Time(min)	<b>Recovery Water level</b>
SWL			
1		1	
2		2	
3		3	
4		4	
5		5	
10		10	
15		15	
20		20	
25		25	
30		30	
40		40	
45		45	
50		50	
60		60	

#### Water Details

Water Found at Depth Kind

#### **Hole Diameter**

Depth From	Depth To	Diameter
0 m	2.44 m	11.43 cm
2.44 m	5.79 m	7.62 cm

Audit Number: Z229830

Date Well Completed: June 09, 2016

Date Well Record Received by MOE: July 04, 2016

Updated: February 2, 2018 Rate<u>Rate</u>

Well ID Number: 7265949 Well Audit Number: *Z229802* Well Tag Number: *A190915* 

This table contains information from the original well record and any subsequent updates.

## Well Location

Address of Well Location	160 LANARK AVENUE
Township	NEPEAN TOWNSHIP
Lot	
Concession	
County/District/Municipality	OTTAWA-CARLETON
City/Town/Village	Ottawa
Province	ON
Postal Code	n/a
UTM Coordinates	NAD83 — Zone 18 Easting: 441323.00 Northing: 5027536.00
Municipal Plan and Sublot Number	
Other	

#### **Overburden and Bedrock Materials Interval**

General Colour	Most Common Material	Other Materials	General Description	Depth From	Depth To
BRWN	LOAM		SOFT	0 m	.31 m
BRWN	SAND	GRVL	LOOS	.31 m	2.13 m
GREY	LMSN		WTHD	2.13 m	5.79 m

#### Annular Space/Abandonment Sealing Record

Depth From	Depth To	Type of Sealant Used (Material and Type)	Volume Placed
0 m	.31 m	FLUSHMONT/ CONCRETE	
.31 m	2.59 m	BENTONITE	
2.59 m	5.79 m	FILTER SAND	

#### Method of Construction & Well Use

Method of Construction Well Use

Air Percussion

Monitoring and Test Hole

#### **Status of Well**

Monitoring and Test Hole

## **Construction Record - Casing**

Inside	Open Hole or material	Depth	Depth
Diameter		From	To
5.2 cm	PLASTIC	0 m	2.74 m

#### **Construction Record - Screen**

Outside Material Depth Depth Diameter Material Depth From To 6.03 cm PLASTIC 2.74 m 5.79 m

#### Well Contractor and Well Technician Information

Well Contractor's Licence Number: 7241

#### **Results of Well Yield Testing**

After test of well yield, water was If pumping discontinued, give reason Pump intake set at Pumping Rate Duration of Pumping Final water level If flowing give rate Recommended pump depth Recommended pump rate Well Production Disinfected?

#### Draw Down & Recovery

Draw Down Time(min)	Draw Down Water level	Recovery Time(min)	<b>Recovery Water level</b>
SWL			
1		1	
2		2	
3		3	
4		4	
5		5	
10		10	
15		15	
20		20	
25		25	
30		30	
40		40	
45		45	
50		50	
60		60	

#### Water Details

Water Found at Depth Kind

#### **Hole Diameter**

Depth From	Depth To	Diameter
0 m	3.1 m	11.43 cm
3.1 m	5.79 m	7.62 cm

Audit Number: Z229802

Date Well Completed: June 09, 2016

Date Well Record Received by MOE: July 04, 2016

Updated: February 2, 2018 Rate<u>Rate</u>

Well ID Number: 7265950 Well Audit Number: *Z229801* Well Tag Number: *A190913* 

This table contains information from the original well record and any subsequent updates.

## Well Location

Address of Well Location	60 LANARK AVENUE
Township	NEPEAN TOWNSHIP
Lot	
Concession	
County/District/Municipality	OTTAWA-CARLETON
City/Town/Village	Ottawa
Province	ON
Postal Code	n/a
UTM Coordinates	NAD83 — Zone 18 Easting: 441296.00 Northing: 5027526.00
Municipal Plan and Sublot Number	
Other	

#### **Overburden and Bedrock Materials Interval**

General Colour	Most Common Material	Other Materials	General Description	Depth From	Depth To
BRWN	LOAM		SOFT	0 m	.31 m
BRWN	SAND	GRVL	LOOS	.31 m	1.22 m
GREY	LMSN		WTHD	1.22 m	4.88 m

#### Annular Space/Abandonment Sealing Record

Depth From	Depth To	Type of Sealant Used (Material and Type)	Volume Placed
0 m	.31 m	FLUSHMOUNT/ CONCRETE	
.31 m	1.62 m	BENTONITE	
1.68 m	4.88 m	FILTER SAND	

#### Method of Construction & Well Use

Method of Construction Well Use

Air Percussion

Monitoring and Test Hole

#### **Status of Well**

Monitoring and Test Hole

#### **Construction Record - Casing**

Inside	Open Hole or material	Depth	Depth
Diameter		From	To
5.2 cm	PLASTIC	0 m	1.83 m

#### **Construction Record - Screen**

Outside Material Depth Depth Diameter Material Depth From To 6.03 cm PLASTIC 1.83 m 4.88 m

#### Well Contractor and Well Technician Information

Well Contractor's Licence Number: 7241

#### **Results of Well Yield Testing**

After test of well yield, water was If pumping discontinued, give reason Pump intake set at Pumping Rate Duration of Pumping Final water level If flowing give rate Recommended pump depth Recommended pump rate Well Production Disinfected?

#### Draw Down & Recovery

Draw Down Time(min)	Draw Down Water level	Recovery Time(min)	<b>Recovery Water level</b>
SWL			
1		1	
2		2	
3		3	
4		4	
5		5	
10		10	
15		15	
20		20	
25		25	
30		30	
40		40	
45		45	
50		50	
60		60	

#### Water Details

Water Found at Depth Kind

#### **Hole Diameter**

Depth From	Depth To	Diameter
0 m	1.52 m	11.43 cm
1.52 m	4.88 m	7.62 cm

Audit Number: Z229801

Date Well Completed: June 09, 2016

Date Well Record Received by MOE: July 04, 2016

Updated: February 2, 2018 Rate<u>Rate</u>

Well ID Number: 7290746 Well Audit Number: Z256707 Well Tag Number: A190915

This table contains information from the original well record and any subsequent updates.

## Well Location

Address of Well Location	160 LANARK AVENUE
Township	OTTAWA CITY
Lot	
Concession	
County/District/Municipality	OTTAWA-CARLETON
City/Town/Village	Ottawa
Province	ON
Postal Code	n/a
UTM Coordinates	NAD83 — Zone 18 Easting: 441300.00
	Northing: 5027544.00
Municipal Plan and Sublot Number	
Other	

#### **Overburden and Bedrock Materials Interval**

General Colour Most Common Material	Other Materials	General Description	Depth From	Depth To	
-------------------------------------	-----------------	---------------------	---------------	-------------	--

#### Annular Space/Abandonment Sealing Record

Depth	Depth	Type of Sealant Used	Volume
From	To	(Material and Type)	Placed
5.79 m	0 m	GROUTED 3/8 BENTON	ITE

#### Method of Construction & Well Use

Method of Construction Well Use

#### Status of Well

Abandoned-Other

#### **Construction Record - Casing**

Inside Diameter Open Hole or material Depth Depth From To

## **Construction Record - Screen**

Outside Diameter Material Depth Depth From To

### Well Contractor and Well Technician Information

Well Contractor's Licence Number: 1558

## **Results of Well Yield Testing**

After test of well yield, water was	
If pumping discontinued, give rease	on
Pump intake set at	
Pumping Rate	
Duration of Pumping	
Final water level	
If flowing give rate	
Recommended pump depth	
Recommended pump rate	
Well Production	
Disinfected?	

#### Draw Down & Recovery

Draw Down Time(min)	Draw Down Water level	Recovery Time(min)	<b>Recovery Water level</b>
SWL			
1		1	
2		2	
3		3	
4		4	
5		5	
10		10	
15		15	
20		20	
25		25	
30		30	
40		40	
45		45	
50		50	
60		60	

#### Water Details

Water Found at Depth Kind

#### **Hole Diameter**

Depth Depth From To Diameter

Audit Number: Z256707

Date Well Completed: May 04, 2017

Date Well Record Received by MOE: July 24, 2017

Updated: February 2, 2018 Rate<u>Rate</u> Share<u>facebook twitter</u> <u>Print</u> Tags

- Environment and energy,
- Drinking water,

Well ID Number: 7290747 Well Audit Number: *Z256708* Well Tag Number: *A190916* 

This table contains information from the original well record and any subsequent updates.

## Well Location

Address of Well Location	160 LANARK AVENUE
Township	OTTAWA CITY
Lot	
Concession	
County/District/Municipality	OTTAWA-CARLETON
City/Town/Village	Ottawa
Province	ON
Postal Code	n/a
UTM Coordinates	NAD83 — Zone 18 Easting: 441294.00 Northing: 5027544.00
Municipal Plan and Sublot Number	
Other	

#### **Overburden and Bedrock Materials Interval**

General Colour Most Common Material	Other Materials	<b>General Description</b>	Depth From	Depth To	
-------------------------------------	-----------------	----------------------------	---------------	-------------	--

#### Annular Space/Abandonment Sealing Record

Depth	Depth	Type of Sealant Used	Volume
From	To	(Material and Type)	Placed
5.79 m	0 m	<b>GROUTED 3/8 BENTONITE HOLEPLU</b>	3

#### Method of Construction & Well Use

Method of Construction Well Use

#### Status of Well

Abandoned-Other

#### **Construction Record - Casing**

Inside Diameter Open Hole or material Depth Depth From To

## **Construction Record - Screen**

Outside Diameter Material Depth Depth From To

### Well Contractor and Well Technician Information

Well Contractor's Licence Number: 1558

After test of well yield, water was	
If pumping discontinued, give rease	on
Pump intake set at	
Pumping Rate	
Duration of Pumping	
Final water level	
If flowing give rate	
Recommended pump depth	
Recommended pump rate	
Well Production	
Disinfected?	

#### Draw Down & Recovery

Draw Down Time(min)	Draw Down Water level	Recovery Time(min)	<b>Recovery Water level</b>
SWL			
1		1	
2		2	
3		3	
4		4	
5		5	
10		10	
15		15	
20		20	
25		25	
30		30	
40		40	
45		45	
50		50	
60		60	

#### Water Details

Water Found at Depth Kind

#### **Hole Diameter**

Depth Depth From To Diameter

Audit Number: Z256708

Date Well Completed: May 04, 2017

Date Well Record Received by MOE: July 24, 2017

- Environment and energy,
- Drinking water,

#### Well ID

Well ID Number: 7290748 Well Audit Number: Z256705 Well Tag Number: A190913

This table contains information from the original well record and any subsequent updates.

#### Well Location

Address of Well Location	160 LANARK AVENUE
Township	OTTAWA CITY
Lot	
Concession	
County/District/Municipality	OTTAWA-CARLETON
City/Town/Village	Ottawa
Province	ON
Postal Code	n/a
UTM Coordinates	NAD83 — Zone 18 Easting: 441302.00 Northing: 5027549.00
Municipal Plan and Sublot Number	
Other	

#### **Overburden and Bedrock Materials Interval**

General Colour Most Common Material	Other Materials	<b>General Description</b>	Depth From	Depth To	
-------------------------------------	-----------------	----------------------------	---------------	-------------	--

#### Annular Space/Abandonment Sealing Record

Depth	Depth	Type of Sealant Used	Volume
From	To	(Material and Type)	Placed
5.79 m	0 m	<b>GROUTED 3/8 BENTONITE HOLEPLUG</b>	3

#### Method of Construction & Well Use

Method of Construction Well Use

#### **Status of Well**

Abandoned-Other

#### **Construction Record - Casing**

Inside Diameter Open Hole or material Depth Depth From To

#### **Construction Record - Screen**

Outside Diameter Material Depth Depth From To

#### Well Contractor and Well Technician Information

Well Contractor's Licence Number: 1558

After test of well yield, water was	
If pumping discontinued, give rease	on
Pump intake set at	
Pumping Rate	
Duration of Pumping	
Final water level	
If flowing give rate	
Recommended pump depth	
Recommended pump rate	
Well Production	
Disinfected?	

#### Draw Down & Recovery

Draw Down Time(min)	Draw Down Water level	Recovery Time(min)	<b>Recovery Water level</b>
SWL			
1		1	
2		2	
3		3	
4		4	
5		5	
10		10	
15		15	
20		20	
25		25	
30		30	
40		40	
45		45	
50		50	
60		60	

#### Water Details

Water Found at Depth Kind

#### **Hole Diameter**

Depth Depth From To Diameter

Audit Number: Z256705

Date Well Completed: May 04, 2017

Date Well Record Received by MOE: July 24, 2017

- Environment and energy,
- Drinking water,

#### Well ID

Well ID Number: 7290749 Well Audit Number: Z256709 Well Tag Number: A155785

This table contains information from the original well record and any subsequent updates.

#### Well Location

Address of Well Location	160 LANARK AVENUE
Township	OTTAWA CITY
Lot	
Concession	
County/District/Municipality	OTTAWA-CARLETON
City/Town/Village	OTTAWA
Province	ON
Postal Code	n/a
UTM Coordinates	NAD83 — Zone 18 Easting: 441276.00 Northing: 5027574.00
Municipal Plan and Sublot Number	
Other	

#### **Overburden and Bedrock Materials Interval**

General Colour Most Common Material	Other Materials	<b>General Description</b>	Depth From	Depth To	
-------------------------------------	-----------------	----------------------------	---------------	-------------	--

#### Annular Space/Abandonment Sealing Record

Depth	Depth	Type of Sealant Used	Volume
From	To	(Material and Type)	Placed
7.92 m	0 m	<b>GROUTED 3/8 BENTONITE HOLEPLU</b>	3

#### Method of Construction & Well Use

Method of Construction Well Use

#### **Status of Well**

Abandoned-Other

#### **Construction Record - Casing**

Inside Diameter Open Hole or material Depth Depth From To

#### **Construction Record - Screen**

Outside Diameter Material Depth Depth From To

#### Well Contractor and Well Technician Information

Well Contractor's Licence Number: 1558

After test of well yield, water was	
If pumping discontinued, give rease	on
Pump intake set at	
Pumping Rate	
Duration of Pumping	
Final water level	
If flowing give rate	
Recommended pump depth	
Recommended pump rate	
Well Production	
Disinfected?	

#### Draw Down & Recovery

Draw Down Time(min)	Draw Down Water level	Recovery Time(min)	<b>Recovery Water level</b>
SWL			
1		1	
2		2	
3		3	
4		4	
5		5	
10		10	
15		15	
20		20	
25		25	
30		30	
40		40	
45		45	
50		50	
60		60	

#### Water Details

Water Found at Depth Kind

#### **Hole Diameter**

Depth Depth From To Diameter

Audit Number: Z256709

Date Well Completed: May 05, 2017

Date Well Record Received by MOE: July 24, 2017

- Environment and energy,
- Drinking water,

#### Well ID

Well ID Number: 7265890 Well Audit Number: *C26623* Well Tag Number: *A200790* 

This table contains information from the original well record and any subsequent updates.

#### Well Location

Address of Well Location	
Township	NEPEAN TOWNSHIP
Lot	
Concession	
County/District/Municipality	OTTAWA-CARLETON
City/Town/Village	
Province	ON
Postal Code	n/a
UTM Coordinates	NAD83 — Zone 18 Easting: 441274.00 Northing: 5027306.00
Municipal Plan and Sublot Number	
Other	

#### **Overburden and Bedrock Materials Interval**

General Colour Most Common Material	Other Materials	General Description	Depth From	Depth To	
-------------------------------------	-----------------	---------------------	---------------	-------------	--

#### Annular Space/Abandonment Sealing Record

DepthDepthType of Sealant UsedVolumeFromTo(Material and Type)Placed

#### Method of Construction & Well Use

Method of Construction Well Use

#### **Status of Well**

#### **Construction Record - Casing**

Inside Diameter Open Hole or material Depth Depth From To

#### **Construction Record - Screen**

Outside Diameter<sup>Material</sup> Depth Depth From To

#### Well Contractor and Well Technician Information

Well Contractor's Licence Number: 7328

After test of well yield, water was	
If pumping discontinued, give reas	son
Pump intake set at	
Pumping Rate	
Duration of Pumping	
Final water level	
If flowing give rate	
Recommended pump depth	
Recommended pump rate	
Well Production	
Disinfected?	

#### Draw Down & Recovery

Draw Down Time(min)	Draw Down Water level	Recovery Time(min)	<b>Recovery Water level</b>
SWL			
1		1	
2		2	
3		3	
4		4	
5		5	
10		10	
15		15	
20		20	
25		25	
30		30	
40		40	
45		45	
50		50	
60		60	

#### Water Details

Water Found at Depth Kind

#### **Hole Diameter**

Depth Depth From To Diameter

Audit Number: C26623

Date Well Completed: May 06, 2016

Date Well Record Received by MOE: July 04, 2016

- Environment and energy,
- <u>Drinking water</u>,

## patersongroup

#### **Consulting Engineers**

154 Colonnade Road South Orlaws: Orlaws Caroda: M20 705 Tel: (613) 226-7381 Fax: (613) 226-6344

> Centestrate Chighteenna Environmental Chighteering mytroposipay Georoposi Chighteering Materials Choling Building Solance Archaeoloposi Services

www.patersongroup.ca

December 3, 2018 File: PE4500-HLUI

City of Ottawa 110 Laurier Avenue W Ottawa, Ontario K1P 1J1

Subject:

Authorization Letter, HLUI Search Phase I-Environmental Site Assessment 316, 320, 324, 326 and 332 Clifton Road Ottawa, Ontario

Dear Sir or Madame,

Please consider this letter as confirmation that Paterson Group has been retained to conduct a Phase I-Environmental Site Assessment at the aforementioned property.

With this letter, the property owner authorizes the City of Ottawa and other regulatory bodies to release, to Paterson Group, information requested for the purpose of completing an environmental assessment of the property.

Name of Company/Property Owner:

Name of Representative:

Authorization of Representative:

Date:

	)
Insight Ottawa Balty Corp Jeremy Silburt	

1/8/2019

Docusigned by: Jury Silburt DABC6A0F00534A7...

#### **Mandy Witteman**

From:	Public Information Services < publicinformationservices@tssa.org>
Sent:	December-07-18 11:36 AM
То:	Karyn Munch
Subject:	RE: Search Request - PE4500

Good morning Karyn,

Thank you for your request for confirmation of public information.

We confirm that there are no records in our database of any fuel storage tanks at the subject addresses.

For a further search in our archives please complete our release of public information form found at <u>https://www.tssa.org/en/about-tssa/release-of-public-information.aspx? mid =392</u> and email the completed form to <u>publicinformationservices@tssa.org</u> or through mail along with a fee of \$56.50 (including HST) per location. The fee is payable with credit card (Visa or MasterCard) or with a Cheque made payable to TSSA.

Although TSSA believes the information provided pursuant to your request is accurate, please note that TSSA does not warrant this information in any way whatsoever.

Enjoy your weekend!

Kind regards,

Sarah



#### Sarah Quibell | Public Information Agent

Facilities 345 Carlingview Drive Toronto, Ontario M9W 6N9 Tel: +1-877-682-8772 | Fax: +1-416-231-6183 | E-Mail: <u>squibell@tssa.org</u> www.tssa.org

From: Karyn Munch <KMunch@Patersongroup.ca> Sent: December 7, 2018 11:06 AM To: Public Information Services <publicinformationservices@tssa.org> Subject: Search Request - PE4500

Good morning,

Could you please search your files for the following properties in the City of Ottawa:

316, 320, 324, 326, 327, 328, 329, 332, 342 Clifton Road 185 Wilbur Avenue

Thank-you very much.

Best Regards,

Karyn Munch, P.Eng.



154 Colonnade Road South Ottawa, Ontario, K2E 7J5 Tel: (613) 226-7381 Ext. 217 Fax: (613) 226-6344 Email: <u>kmunch@patersongroup.ca</u>

This electronic message and any attached documents are intended only for the named recipients. This communication from the Technical Standards and Safety Authority may contain information that is privileged, confidential or otherwise protected from disclosure and it must not be disclosed, copied, forwarded or distributed without authorization. If you have received this message in error, please notify the sender immediately and delete the original message.

## **APPENDIX 3**

**QUALIFICATIONS OF ASSESSORS** 

### Mandy Witteman, E.I.T.

# patersongroup

Geotechnical Engineering

Environmental Engineering

Hydrogeology

Geological Engineering

**Materials Testing** 

**Building Science** 

Archaeological Services

#### POSITION

Environmental Engineer

#### EDUCATION

Carleton University, M.A.Sc., Environmental Engineering, 2013 Carleton University, B.Eng., Environmental Engineering, 2008

#### **MEMBERSHIPS & AWARDS**

Alberta Professional Engineers and Geoscience Association NSERC Industry R&D Scholarship

#### **EXPERIENCE**

2018 – Present **Paterson Group Inc.** Consulting Engineers Geotechnical and Environmental Division Environmental Engineer

2014 – 2015

Thurber Engineering Limited Oil Sand Tailings Group Tailings Engineer

2014 – 2013

**Carleton University** Department of Civil & Environmental Engineering Research Engineer

2013 - 2009 Carleton University Department of Civil & Environmental Engineering Research Assistant and Teachers Assistant

2008 – 2009 SLR Consulting Limited Contaminated Sites Junior Environmental Engineer

### Mark S. D'Arcy, P. Eng.

# patersongroup

Geotechnical Engineering

Environmental Engineering

Hydrogeology

Geological Engineering

**Materials Testing** 

**Building Science** 

Archaeological Services

#### POSITION

Associate and Supervisor of the Environmental Division Senior Environmental/Geotechnical Engineer

#### **EDUCATION**

Queen's University, B.A.Sc.Eng, 1991 Geotechnical / Geological Engineering

#### **MEMBERSHIPS**

Ottawa Geotechnical Group Professional Engineers of Ontario

#### **EXPERIENCE**

1991 to Present **Paterson Group Inc.** Associate and Senior Environmental/Geotechnical Engineer Environmental and Geotechnical Division Supervisor of the Environmental Division

#### SELECT LIST OF PROJECTS

Mary River Exploration Mine Site - Northern Baffin Island Agricultural Supply Facilities - Eastern Ontario Laboratory Facility – Edmonton (Alberta) Ottawa International Airport - Contaminant Migration Study - Ottawa Richmond Road Reconstruction - Ottawa Billings Hurdman Interconnect - Ottawa Bank Street Reconstruction - Ottawa Environmental Review - Various Laboratories across Canada - CFIA Dwyer Hill Training Centre - Ottawa Nortel Networks Environmental Monitoring - Carling Campus - Ottawa Remediation Program - Block D Lands - Kingston Investigation of former landfill sites - City of Ottawa Record of Site Condition for Railway Lands - North Bay Commercial Properties - Guelph and Brampton Brownfields Remediation - Alcan Site - Kingston Montreal Road Reconstruction - Ottawa Appleford Street Residential Development - Ottawa Remediation Program - Ottawa Train Yards Remediation Program - Bayshore and Heron Gate Gladstone Avenue Reconstruction - Ottawa Somerset Avenue West Reconstruction - Ottawa