

P.O. BOX 13593, STN. KANATA, OTTAWA, ON K2K 1X6 TELEPHONE: (613) 838-5717

WEBSITE: WWW.IFSASSOCIATES.CA

URBAN FORESTRY & FOREST MANAGEMENT CONSULTING

December 16, 2022

Rohit Communities Ontario Inc. 15 Fitzgerald Rd Ottawa, ON K2H 9G1 Attn: Adil Kodian

# RE: TREE CONSERVATION REPORT FOR 3430 CARLING AVENUE, OTTAWA

This Tree Conservation Report (TCR) was prepared by IFS Associates Inc. on behalf of Rohit Communities Ontario Inc. in support of the proposed redevelopment of 3430 Carling Avenue in Ottawa. The need for this report is related to trees protected under the City of Ottawa's Tree Protection By-law (By-law no. 2020-340). In this instance, this TCR reflects the proposed demolition of the existing commercial building and construction of two separate 6-storey apartment buildings with 262 below-grade parking spaces.

Under the Tree Protection By-law, a TCR is required for all plans of subdivision, site plan control applications, common elements condominium applications, and vacant land condominium applications where there is a tree of 10 cm in diameter at breast height (DBH) or greater on site and/or if there is a tree on an adjacent site that has a critical root zone (CRZ) extending onto a development site. The CRZ is calculated as DBH x 10 cm. Trees of any size on adjacent city lands must also be documented in a TCR. A "tree" is defined in the by-law as any species of woody perennial plant, including its root system, which has reached or can reach a minimum height of at least 450 cm at physiological maturity.

The approval of this TCR by the City of Ottawa and the issuing of a permit by them authorize the removal of approved trees. Importantly, although this report may be used to support the application for a tree removal permit, it does not by itself constitute permission to remove trees or begin site clearing activities. No such work should occur before a tree removal permit is issued authorizing the injury or destruction of a tree in accordance with the bylaw. Further, the removal of any trees shared with or fully on neighbouring properties will first require written permission of the adjacent landowner.

The inventory in this report details the assessment of all individual trees and hedges on and shared with the subject property. No trees were located on city land directly adjacent to the subject property. One hedge and three individual pine trees conflict with the proposed construction and so are slated for removal. They are all located fully on the subject property. All other trees on the subject and adjacent private properties will be preserved, unless noted otherwise. Field work for this report was completed in July 2021 and December 2022.



## TREE SPECIES, CONDITION, SIZE AND STATUS

Table 1 on pages 3 and 4 details the species, condition, size (diameter), ownership and status of the individual trees found on or shared with the subject property. Each of these trees is referenced by the numbers plotted on the tree conservation plan on page 5 this report. Pictures 1 through 7 on pages 7 to 10 of this report show selected trees and hedges.

#### PROVINCIAL REGULATIONS

Provincial regulations are applicable to trees on private property. In particular, the Endangered Species Act (2007) mandates that tree species on the Species at Risk in Ontario (SARO) list be identified. Butternut (*Juglans cinerea*) is present in Eastern Ontario and is listed as threatened on the SARO. Because of this it is protected from harm. No trees of this species were identified on the subject property or nearby adjacent properties.

## TREE PRESERVATION AND PROTECTION MEASURES

Preservation and protection measures intended to mitigate damage during construction will be applied for the trees to be retained. The following measures are the minimum required by the City of Ottawa to ensure tree survival during and following construction:

- 1. As per the City of Ottawa's tree protection barrier specification (see page 6), erect a fence as close as possible to the CRZ of the tree(s).
- 2. Do not place any material or equipment within the CRZ of the tree(s).
- 3. Do not attach any signs, notices or posters to any tree.
- 4. Do not raise or lower the existing grade within the CRZ without approval.
- 5. Tunnel or bore instead of trenching within the CRZ of any tree.
- 6. Do not damage the root system, trunk or branches of any tree.
- 7. Ensure that exhaust fumes from all equipment are NOT directed towards any tree's canopy.

<sup>1</sup> critical root zone (CRZ) is established as being 10 centimetres from the trunk of a tree for every centimetre of DBH. The CRZ is calculated as DBH x 10 cm.

This report is subject to the attached Limitations of Tree Assessments and Liability to which the reader's attention is directed.

Please do not hesitate to contact the undersigned with any questions concerning this report.

Yours,

Andrew K. Boyd, B.Sc.F, R.P.F. (#1828) Certified Arborist #ON-0496A and TRAQualified

Consulting Urban Forester

IFS ASSOCIATES

Table 1. Species, condition, size (diameter) and status of trees located on or shared with 3430 Carling Avenue

Table 1	Species, condition, size (diameter) and status of trees located on or shared with 3430 Carling Avenue					
Tree	Tree species	Condition	DBH <sup>1</sup>	Owner	Age class, tree condition notes & <b>preservation status</b> (to be removed or	
No.		$(VP \rightarrow E)$	(cm)	-ship	preserved and protected)	
1	Eastern white	Fair	15 &	Private	Mature individual tree within hedge; double-stemmed from grade; fair crown	
	cedar (Thuja		27		density, growth increment and needle colour; native species; <b>to be removed</b>	
	occidentalis)				(conflicts with underground parking)	
2	Eastern white	Fair	<10	Private	Immature hedge; fair crown density, growth increment and needle colour;	
	cedar (Thuja				competing ash (Fraxinus spp.), Siberian elm (Ulmus pumila) and linden (Tilia	
	occidentalis)				spp.) growth diminishing condition; <b>to be removed</b> (conflicts with underground	
					parking)	
3	White elm	Poor	17	Shared	Mature; central stem with five competing leaders at 2m from grade – topped in	
	(Ulmus				past; dead due to Dutch elm disease (Ophiostoma novo-ulmi); native species; to	
	americana)				be removed (dead)	
4	Black walnut	Good	26 &	Shared	Mature; double-stemmed at 0.3m from grade; western stem topped at 3m due to	
	(Juglans nigra)		31		overhead Hydro lines; native species; to be preserved and protected	
5	Eastern white	Fair	15	Private	Maturing hedge; fair crown density, growth increment and needle colour; heavy	
	cedar (Thuja		avg.		vine (Vitas spp.) and Norway maple (Acer platanoides) growth diminishing	
	occidentalis)				condition; to be preserved and protected (except in selected areas of diminished	
					condition where solid fencing will be installed for snow storage/containment)	
6	Eastern white	Good	15	Private	Maturing hedge; good crown density, growth increment and needle colour; <b>to be</b>	
	cedar (Thuja		avg.		preserved and protected	
	occidentalis)					
7	Eastern white	Poor	<10	Private	Immature hedge; poor crown density, growth increment and needle colour; very	
	cedar (Thuja				heavy vine growth greatly diminishing condition; to be preserved and protected	
	occidentalis)					
8	Eastern white	Good	12	Private	Maturing hedge; good crown density, growth increment and needle colour; to be	
	cedar (Thuja		avg.		fully preserved and protected	
	occidentalis)					
9	Austrian pine	Poor	25	Private	Mature; poor crown density, growth increment and needle colour; heavily	
	(Pinus nigra)				divergent and asymmetric towards northeast; strong sweep in main stem at 4.5m;	
					introduced species; to be removed (conflicts with construction)	





Table 1. Species, condition, size (diameter) and status of trees located on or shared with 3430 Carling Avenue

Tree	Tree species	Condition	DBH <sup>1</sup>	Owner	Age class, tree condition notes & <b>preservation status</b> (to be removed or
No.		$(VP \rightarrow E)$	(cm)	-ship	preserved and protected)
10	Austrian pine	Fair	46	Private	Mature; fair crown density, growth increment and needle colour; moderately
	(Pinus nigra)				divergent and asymmetric towards southeast; co-dominant stems at 3m; to be
					removed (conflicts with construction)
11	Austrian pine	Good	54 (at	Private	Mature; good crown density, growth increment and needle colour; moderately
	(Pinus nigra)		1m)		divergent and asymmetric towards southwest; co-dominant stems at 1.5m; to be
					removed (conflicts with construction)

diameter at breast height, or 1.4m from grade (unless otherwise indicated); average diameters indicate multi-stemmed trees, hedges







**Ottawa** 

TREE PROTECTION BARRIER SPEC.

DATE: MARCH 2019

DRAWING NO.: 1 of 1



Picture 1. Cedar hedge #2 at 3430 Carling Avenue (cedar tree #1 is on the far right and shared dead elm #3 on left)



Picture 2. Cedar hedge #5 at 3430 Carling Avenue



Picture 3. Tree #4, shared black walnut at 3430 Carling Avenue





Picture 4. Cedar hedge #6 at 3430 Carling Avenue



Picture 5. Cedar hedge #7 at 3430 Carling Avenue





Picture 6. Cedar hedge #8 at 3430 Carling Avenue



Picture 7. Austrian pines #9 (right background), 10 and 11 (left to right) at 3430 Carling Avenue

# LIMITATIONS OF TREE ASSESSMENTS & LIABILITY

#### GENERAL

It is the policy of *IFS Associates Inc.* to attach the following clause regarding limitations. We do this to ensure that our clients are clearly aware of what is technically and professionally realistic in assessing trees for retention.

This report was carried out by *IFS Associates Inc.* at the request of the client. The information, interpretation and analysis expressed in this report are for the sole benefit and exclusive use of the client. Possession of this report or a copy thereof does not imply right of publication or use for any purpose by any other than the client to whom it is addressed. Unless otherwise required by law, neither all or any part of the contents of this report, nor copy thereof, shall be conveyed by anyone, including the client, to the public through public relations, news or other media, without the prior expressly written consent of the author, and especially as to value conclusions, identity of the author, or any reference to any professional society or institute or to any initialed designation conferred upon the author as stated in his qualifications.

This report and any values expressed herein represent the opinion of the author; his fee is in no way contingent upon the reporting of a specified value, a stipulated result, nor upon any finding to be reported. Details obtained from photographs, sketches, *etc.*, are intended as visual aids and are not to scale. They should not be construed as engineering reports or surveys. Although every effort has been made to ensure that this assessment is reasonably accurate, the tree(s) should be reassessed at least annually. The assessment presented in this report is valid at the time of the inspection only. The loss or alteration of any part of this report invalidates the entire report.

#### LIMITATIONS

The information contained in this report covers only the tree(s) in question and no others. It reflects the condition of the assessed tree(s) at the time of inspection and was limited to a visual examination of the accessible portions only. *IFS Associates Inc.* has prepared this report in a manner consistent with that level of care and skill ordinarily exercised by members of the forestry and arboricultural professions, subject to the time limits and physical constraints applicable to this report. The assessment of the tree(s) presented in this report has been made using accepted arboricultural techniques. These include a visual examination of the above-ground portions of each tree for structural defects, scars, cracks, cavities, external indications of decay such as fungal fruiting bodies, evidence of insect infestations, discoloured foliage, the condition of any visible root structures, the degree and direction of lean (if any), the general condition of the tree(s) and the surrounding site, and the proximity of people and property. Except where specifically noted in the report, the tree(s) examined were not dissected, cored, probed or climbed to gain further evidence of their structural condition. Also, unless otherwise noted, no detailed root collar examinations involving excavation were undertaken.

While reasonable efforts have been made to ensure that the tree(s) proposed for retention are healthy, no warranty or guarantee, expressed or implied, are offered that these trees, or any parts of them, will remain standing. This includes other trees on or off the property not examined as part of this assignment. It is both professionally and practically impossible to predict with absolute certainty the behaviour of any single tree or groups of trees or their component parts in all circumstances, especially when within construction zones. Inevitably, a standing tree will always pose some risk. Most trees have the potential for failure in the event of root loss due to excavation and other construction-related impacts. This risk can only be eliminated through full tree removal.

Notwithstanding the recommendations and conclusions made in this report, it must be realized that trees are living organisms, and their health and vigour constantly change over time. They are not immune to changes in site conditions, or seasonal variations in the weather. It is a condition of this report that *IFS Associates Inc.* be notified of any changes in tree condition and be provided an opportunity to review or revise the recommendations within this report. Recognition of changes to a tree's condition requires expertise and extensive experience. It is recommended that *IFS Associates Inc.* be employed to re-inspect the tree(s) with sufficient frequency to detect if conditions have changed significantly.

## **ASSUMPTIONS**

Statements made to *IFS Associates Inc*. in regards to the condition, history and location of the tree(s) are assumed to be correct. Unless indicated otherwise, all trees under investigation in this report are assumed to be on the client's property. A recent survey prepared by a Licensed Ontario Land Surveyor showing all relevant trees, both on and adjacent to the subject property, will be provided prior to the start of field work. The final version of the grading plan for the project will be provided prior to completion of the report. Any further changes to this plan invalidate the report on which it is based. *IFS Associates Inc*. must be provided the opportunity to revise the report in relation to any significant changes to the grading plan. The procurement of said survey and grading plan, and the costs associated with them both, are the responsibility of the client, not *IFS Associates Inc*.

#### LIABILITY

Without limiting the foregoing, no liability is assumed by *IFS Associates Inc.* for: 1) any legal description provided with respect to the property; 2) issues of title and/or ownership with respect to the property; 3) the accuracy of the property line locations or boundaries with respect to the property; 4) the accuracy of any other information provided by the client or third parties; 5) any consequential loss, injury or damages suffered by the client or any third parties, including but not limited to replacement costs, loss of use, earnings and business interruption; and, 6) the unauthorized distribution of the report.

#### INDEMNIFICATION

An applicant for a permit or other approval based on this report shall agree to indemnify and save harmless *IFS Associates Inc.* from any and all claims, demands, causes of action, losses, costs or damages that affected private landowners and/or the City of Ottawa may suffer, incur or be liable for resulting from the issuance of a permit or approval based on this report or from the performance or non-performance of the applicant, whether with or without negligence on the part of the applicant, or the applicant's employees, directors, contractors and agents.

Further, under no circumstances may any claims be initiated or commenced by the applicant against *IFS Associates Inc.* or any of its directors, officers, employees, contractors, agents or assessors, in contract or in tort, more than 12 months after the date of this report.

#### ONGOING SERVICES

*IFS Associates Inc.* accepts no responsibility for the implementation of any or all parts of the report, unless specifically requested to supervise the implementation or examine the results of activates recommended herein. In the event that examination or supervision is requested, that request shall be made in writing and the details, including fees, agreed to in advance.