

May 15, 2024

2317916 Ontario Inc. 2081 Merivale Road, Unit 1300 Ottawa, ON K2G 1G9 E-mail: hairdoc@gmail.com

Attention: Dr. Hussain Rahal *Owner*

Re: Amendment Letter – Phase Two Environmental Site Assessment 47 Beechwood Avenue, 5 Springfield Road, and 12 Douglas Avenue, Ottawa, Ontario Pinchin File: 321299.001

As requested, Pinchin Ltd. (Pinchin) is pleased to offer the following comments and amendments with respect to the following document prepared by the City of Ottawa: *Phase 2 Pre-Consultation: Meeting Feedback for the Proposed Zoning By-Law Amendment Application and Site Plan Control Application – 47 Beechwood Ave, 12 Douglas Ave, and 5 Springfield Rd* (File No. PC2023-0238) for the above-noted Site.

It is Pinchin's understanding that the Phase 2 Pre-Consultation Meeting Feedback identified two concerns with respect to the Phase Two Environmental Site Assessment (ESA) report that Pinchin prepared for the Site, dated August 3, 2023. These comments included:

Item 4.2. The Phase One ESA reported the historical presence of two dry cleaners within the building located at the southwest corner of the property, which required further investigation. Three monitoring wells were installed onsite to address the potential impacts by the former dry cleaners. According to the Phase Two ESA, the local groundwater water flow direction is reported towards west. Therefore, based on the site plans, neither of the installed monitoring wells are located downgradient of the potentially contaminating activity (dry cleaners) and thus may be incapable of capturing a potential groundwater may be required.

Item 4.3. In addition, the following general comments can be offered:

Based on the available information, soil contamination exists on-Site, which requires completion of remedial activities prior to constructing new structures on-Site. The Phase Two ESA needs to be updated with a remediation report appended upon completion of the remedial activities as per the O. Reg. 153/04 requirements and submitted for review / records.



• Due to the proposed land use change to a more sensitive use (i.e. commercial to residential), filing a Record of Site Condition (RSC) is required prior to a building permit issuance for constructing new structures on-Site.

With respect to Item 4.2, Pinchin recognizes that the groundwater flow from the July 26, 2023 groundwater monitoring event calculated that the local groundwater flow direction was towards the west, as reported in the Phase Two ESA report. However, the groundwater monitoring data from July 7, 2023 indicated that the groundwater flow direction was to the east/southeast, which could indicate that groundwater impacts from the former potential on-Site dry cleaners would have been captured by monitoring well MW4. The groundwater flow direction and contours from July 7, 2023 are shown in the attached Figure 1. Pinchin recognizes that groundwater flow direction is subject to seasonal and climatic variations, and can also be impacted by underground utilities, and as such, recommends continuing to monitor the groundwater elevations on-Site to further confirm the groundwater flow direction. In the interim, Pinchin has prepared a work plan and cost estimate to install a new groundwater monitoring well adjacent to the west property boundary to address the City of Ottawa's concern.

With respect to Item 4.3, Pinchin acknowledges that soil contamination exists on-Site which requires completion of remedial activities prior filing an RSC. Pinchin will work with the Client to complete the required soil remedial activities, potentially during redevelopment activities, and update the Phase Two ESA report in accordance with Ontario Regulation 153/04 to ensure that an RSC can be filed for the Site.

We trust that the information provided herein is sufficient for your present needs. Should you have any questions or concerns regarding the contents of this letter, please contact the undersigned.

Yours truly,

Pinchin Ltd.

Prepared by:

Alicia mont

Alicia McDonald, P.Eng., QP_{ESA} Senior Project Manager 613.840.6147 <u>amcdonald@pinchin.com</u> Reviewed by:

Jood Matter

Scott Mather, P.Eng., QP_{ESA} Director, Eastern Ontario 613.851.4098 <u>smather@pinchin.com</u>

Encl.: Figure 1 – Groundwater Elevations and Inferred Groundwater Flow Direction (July 7, 2023) J:\321000s\0321299.000 RAHAL,VariousSites,OTT,ON,EDR,SA1&RSC\0321299.001 RAHAL,VariousSites,OTT,ON,EDR,SA2&RSC\Deliverables\321299.001 Phase Two ESA Amendment Letter Beechwood Springfield Douglas May 2024.docx Template: Master Letter Template, January 24, 2023



199	1200	15 M		Λ		
				Ň		
				LEGEND		
			8.	SITE BOUNDAR'	ł	
			20	SITE BUILDING		
				FORMER BUILD	NG	
					ELL	
			76.5			
				GROUNDWATER	R CONTOUR LINES	
			6.3	GROUNDWATEF	R FLOW DIRECTION	
		1000	100	(xxx.xx) GROUNDWATEF	RELEVATION	
			5			
			1			
			877			
			18			
			14			
			25%			
			200			
			de			
			2			
			60			
	6/2 635			LEGEND IS COLOUR DEPENDENT. NON-COLOUR COPIES MAY ALTER		
	0		226	INTERPRETATION.		
	× 1		1			
			6.00	PINC		
	10					
			*			
			10.20		TWO	
	1997 C C C C C C C C C C C C C C C C C C		PHASE TWO ENVIRONMENTAL SITE ASSESSMENT			
			CLIENT NAME: 1101600 ONTARIO INC.			
			A. A	47 BEECHWOOD AVENUE, 5 SPRINGFIELD ROAD, AND 12 DOUGLAS		
				ROAD, OTTAWA, ONTARIO		
				FIGURE NAME: GROUNDWATER ELEVATION AND		
				INFERRED GROUNDWATER FLOW DIRECTION (JULY 7, 2023)		
				PROJECT NUMBER: 321299.001	SCALE: AS SHOWN	
		1.00		DRAWN BY: KL	REVIEWED BY:	
5	10		20 m	DATE: MAY 2024	FIGURE NUMBER:	
	•			IVIAT ZUZ4	1	