

TREE
CONSERVATION
REPORT
349 Danforth

Tree Conservation Report submitted as Partial Requirements for a Site Plan Control Application, June 25, 2021

Prepared by: Dendron Forestry Services



www.dendronforestry.ca 613.805.WOOD (9663) info@dendronforestry.ca

# **Tree Conservation Report V2.0**

## **Submitted as part of Site Plan Control Application**

Address: 349 Danforth

**Date:** June 25, 2021

Prepared by: Astrid Nielsen, RPF, ISA Certified Arborist ®

**Prepared for:** Fernando Matos, Ottawa Carleton Construction Group

fernando@ottawacarletonconstruction

Site Visit: October 7, 2020

## Introduction

This Tree Conservation Report (TCR) has been prepared for Fernando Matos of Ottawa Carleton Construction Group, as partial requirements for the Site Plan Control Application submitted to the City of Ottawa. It replaces the original TCR prepared by Dendron dates October 8, 2020. The report has been updated to reflect new ownership information for tree #4 – it has been confirmed by an updated survey dated June 23, 2021, that the tree is fully on the subject property.

The objectives of this Tree Conservation Report are:

- To describe all trees over 10 cm on the site, recording their species, size, and current health condition
- To evaluate the impact of the trees by the proposed development and what the recommended action is (retain or protect)
- To provide recommendations on how to mitigate damage to retained trees during construction

## **Current Vegetation**

The following is an inventory of all trees 10 cm or greater on the property and adjacent property that will be impacted by development.



www.dendronforestry.ca 613.805.WOOD (9663) info@dendronforestry.ca

## Tree Inventory

Tree <sup>1</sup>	Species	Diameter at breast height (dbh)	Ownership <sup>2</sup>	Condition	Action
1	Showy mountain- ash ( <i>Sorbus</i> decora)	14 cm	Private	Good	Proposed removal to accommodate new building
2	American elm (Ulmus americana)	11 cm	Private	Good	Proposed removal to accommodate new building
3	American elm (Ulmus americana)	10 cm	Private	Fair	Proposed removal to accommodate new building
4	American elm (Ulmus americana)	22 cm	Private	Good	Proposed removal to accommodate new building

<sup>&</sup>lt;sup>1</sup> Please refer to the attached grading plan for tree numbers. Note that the Tree Disclosure map includes a tree layer added to the grading plan (in pdf format) provided by the client. This layer includes only information about the trees and the original grading plan is not altered in this process.

## **Proposed Development and Conserved Vegetation**

The proposed development at this site will be a 3-story mixed use building with a footprint that will encompass almost of the extent of the entire lot. The trees that are currently onsite have seeded naturally and are not well placed to accommodate the proposed development and the level of construction activity and excavation that will take place on this site. To accommodate the proposed development, removal of these tree is recommended.

Please note that a **Tree Permit** from the City of Ottawa Planning, Infrastructure and Economic Development Department is required for the removal of any trees onsite.

<sup>&</sup>lt;sup>2</sup>Ownership of the tree in this report is based on the information provided and should not be used as a determination of ownership. For ownership disputes, a survey should be relied on.



www.dendronforestry.ca 613.805.WOOD (9663) info@dendronforestry.ca

The undersigned personally inspected the property and issues associated with this report on Oct. 7, 2020. On Behalf of Dendron Forestry Services,





Astrid Nielsen, MFC, RPF (Registered Professional Forester)
ISA Certified Arborist ®, ON-1976
ISA Tree Risk Assessment Qualified
Principal, Dendron Resource Surveys
<u>Astrid.nielsen@dendronforestry.ca</u>
(613) 805-9663 (WOOD)



Dendron Forestry Services www.dendronforestry.ca 613.805.WOOD (9663) info@dendronforestry.ca



Figure 1: Tree 1 - showy mountain ash to be removed



Dendron Forestry Services www.dendronforestry.ca 613.805.WOOD (9663) info@dendronforestry.ca



Figure 2: American elms (trees 2-4) growing along the side of the building - to be removed



www.dendronforestry.ca 613.805.WOOD (9663) info@dendronforestry.ca

### Intended Use of the Report

This Information Report was carried out by Dendron Forestry Services (hereafter Dendron) at the request of the Client. The information, interpretation and analysis contained within this Report is to be used solely for the purposes outlined within this Report. This Report is for the exclusive use of the Client.

### **Limitations of this Repor**

This Report is based on the circumstances and observations as they existed at the time of the site inspection of the Client's Property and the trees situate thereon by Dendron and upon information provided by the Client to Dendron. The opinions in this Report are given based on observations made and using generally accepted professional judgment, however, because trees and plants are living organisms and subject to change, damage and disease, the results, observations, recommendations, and analysis as set out in this Report are valid only as at the date any such testing, observations and analysis took place and no guarantee, warranty, representation or opinion is offered or made by Dendron as to the length of the validity of the results, observations, recommendations and analysis contained within this Report As a result the Client shall not rely upon this Report, save and except for representing the circumstances and observations, analysis and recommendations that were made as at the date of such inspections. It is recommended that the trees discussed in this Report should be re-assessed periodically.

### **Further Services**

Neither Dendron nor any assessor employed or retained by Dendron for the purpose of preparing or assisting in the preparation of this Report shall be required to provide any further consultation or services to the Client, save and except as already carried out in the preparation of this Report and including, without limitation, to act as an expert witness or witness in any court in any jurisdiction unless the Client has first made specific arrangements with respect to such further services, including, without limitation, providing the payment of the Report's regular hourly billing fees.

Dendron accepts no responsibility for the implementation of all or any part of the Report, unless specifically request to examine the implementation of such activities recommended herein. In the event that inspection or supervision of all or part of the implementation is request, that request shall be in writing and the details agreed to in writing by both parties.

### Assumptions

The Client is hereby notified and does hereby acknowledge and agree that where any of the facts and information set out and referenced in this Report are based on assumptions, facts or information provided to Dendron by the Client and/or third parties and unless otherwise set out within this Report, Dendron will in no way be responsible for the veracity or accuracy of any such information. Further, the Client acknowledges and agrees that Dendron has, for the purposes of preparing their Report, assumed that the Property, which is the subject of this Report is in full compliance with all applicable federal, provincial, municipal and local statutes, regulations, by-laws, guidelines and other related laws. Dendron explicitly denies any legal liability for any and all issues with respect to non-compliance with any of the above-referenced statutes, regulations, bylaws, guidelines and laws as it may pertain to or affect the Property to which this Report applies.

### **Professional Responsibility**

In carrying out this Report, Dendron and any Assessor appointed for and on behalf of Dendron to perform and carry out the Report has exercised a reasonable standard of care, skill and diligence as would be customarily and normally provided in carrying out this Report. While reasonable efforts have been made to ensure that the trees recommended for retention are healthy, no guarantees are offered, or implied, that these trees, or all parts of them will remain standing. It is professionally impossible to predict with absolute certainty the behaviour of any single tree or group of trees, or all their component parts, in all given circumstances. Inevitably, a standing tree will always pose some risk. Most trees have the potential to fall, lean, or otherwise pose a danger to property and persons in the event of adverse weather conditions, and this risk can only be eliminated if the tree is removed.


Without limiting the foregoing, no liability is assumed by Dendron for:

- a) any legal description provided with respect to the Property;
- b) issues of title and or ownership respect to the Property;
- c) the accuracy of the Property line locations or boundaries with respect to the Property; and
- d) the accuracy of any other information provided to Dendron by the Client or third parties;
- e) any consequential loss, injury or damages suffered by the Client or any third parties, including but not limited to replacement costs, loss of use, earnings and business interruption; and
- f) the unauthorized distribution of the Report.

Further, under no circumstance may any claims be initiated or commenced by the Client against Dendron or any of its directors, officers, employees, contractors, agents or Assessors, in contract or in tort, more than 12 months after the date of this Report.

### General

Any plans and/or illustrations in this Report are included only to help the Client visualize the issues in this Report and shall not be relied upon for any other purpose. This report is best viewed in colour. Any copies printed in black and white may make some details difficult to properly understand. Dendron accepts no liability for misunderstandings due to a black and white copy of the report.




Protection Fencing Area



client in pdf format. This layer refers to the trees only, and the original Servicing and Grading plan has not been altered in the process.



Version 2.0, June 25, 2021 For more information, please contact info@dendronforestry.ca



Critical Root Zone

Note that the tree layer has been added to the original Servicing and Grading plan supplied by the client in pdf format. This layer refers to the trees only, and the original Servicing and Grading plan has not been altered in the process.



Tree Conservation Report – 349 Danforth

Tree layer prepared by Dendron Forestry Services

Version 2.0, June 25, 2021

For more information, please contact info@dendronforestry.ca