TREE CONSERVATION REPORT

2046-2050 Scott Street

Tree Conservation Report submitted as Partial Requirements for a Site Plan Control Application

Astrid Nielsen, Registered Professional Forester, ISA Certified Arborist[®], ON-1976



Preliminary Tree Conservation Report

Submitted as part of Site Plan Control Application

Address:	2046 – 2050 Scott Street
Date:	January 15, 2021
Prepared by:	Astrid Nielsen, RPF, ISA Certified Arborist ®
Prepared for:	Jakub Ulak, President, Surface Developments, jakub@surfacedevelopments.com
Site Visit:	May 4, 2020

Introduction

This Tree Conservation Report v2.0 replaces the Preliminary Tree Conservation Report that was prepared by Dendron Forestry Services dated May 4, 2020. The objectives of this Tree Conservation Report are:

- To describe all trees over 10 cm on the site, recording their species, size, and current health condition
- To evaluate the impact of the trees by the proposed development and what the recommended action is (retain or protect)
- To provide recommendations on how to mitigate damage to retained trees during construction

Current Vegetation

The following is an inventory of all trees 10 cm or greater on the property and adjacent property that will be impacted by development. It also includes Distinctive Trees (30 cm or greater) on adjacent properties whose Critical Root Zone extend within the area of excavation.

These trees have been identified on the Tree Conservation Report Map. Note that no trees, except for 4 and 5 were included on the grading plan, and their locations have been estimated.



Tree Inventory

Tree ¹	Species	Diameter at breast height (dbh)	Critical Root Zone (m) ²	Ownership	Condition	Action
1	Manitoba maple (<i>Acer negundo</i>)	15 cm	1.5 m	Private	Poor; topped by hydro	Proposed removal; in conflict with proposed development
2	American elm (<i>Ulmus</i> <i>americana</i>)	49 cm	5 m	Private	Good/fair; restricted and compromised rooting zone	Proposed removal; in conflict with proposed development
3	American elm (<i>Ulmus</i> <i>americana</i>)	18 cm	2 m	Private	Good/fair; restricted and compromised rooting zone	Proposed removal; in conflict with proposed development
4	Siberian elm (<i>Ulmus pumila</i>)	60 cm	6 m	Private	Fair; multi- stem with included bark	Proposed removal; in conflict with proposed development
5	Manitoba maple (<i>Acer negundo</i>)	44 cm	4 m	Private	Good	Proposed removal; in conflict with proposed development
6	Manitoba maple (<i>Acer negundo</i>)	14	1.5 m	Private	Fair	Proposed removal; in conflict with proposed development
7	Ash (<i>Fraxinus</i> spp.)	42 cm	n/a	Private	Dead	Remove
8	Freeman maple (<i>Acer freemanii</i>)	30 cm	3 m	City; right-of-way in front of 295 Ashton	Fair; multiple cankers along the trunk and crown dieback	Proposed removal; in conflict with proposed development
9	Pyramidal cedar clump	10, 10, 5, 5 cm (estimate)	1 m	City; right of way in front of 301 Ashton	Good	Proposed removal; replace with a



						larger tree
10	Crab apple (<i>Malus spp</i>)	15 cm (estimate)	1.5 m	Private – rear yard of 301 Ashton	Good	Proposed removal; in conflict with proposed development
11	Lilac (Syringa reticula)	Multi- stemmed; 7 stems 10-15 cm (estimate)	2 m	Private – rear yard of 301 Ashton	Good	Proposed removal; in conflict with proposed development

¹ Please refer to the attached map for tree numbers. Note that the map includes a tree layer added to the survey or site plan (in pdf format) provided by the client. This layer includes only information about the trees and the original plan is not altered in this process. Also note that all locations have been estimated except for 4 and 5 which were included in the survey. ² Critical Root Zone is an area around the trunk with a radius equivalent to 10 times the diameter of the trunk

Proposed Development and Conserved Vegetation

The trees along the existing fence in the rear of 2046 Scott and 295 Ashton are all privately-owned and are in the footprint of the proposed 30-storey building. All of these trees have seeded naturally, and several are considered non-native, invasive species. However, these species can withstand harsh urban environments and provide shade and other benefits where other native species may not survive. Because their location is not compatible with the new building, removal is recommended.

Tree no. 8 is a Freeman maple that is in fair condition. The main stem has several cankers, some of which have sealed over. There is also some crown dieback, possibly caused by root damage when the adjacent soft surface was converted to asphalt about 5 years ago (see Google Street view for reference). Given the poor health of this tree, it is not recommended that it be incorporated into the new development.

The trees on the 301 Ashton property include the clump of cedar in the front along with two small trees in the rear yard, a crab apple and lilac tree. Note that this yard was not accessed, and the size, health and species of these trees have been estimated through a 2-m high fence. All the trees on this property lie within the footprint of the underground garage and, therefore, removal is requested.

A Tree Permit from the City of Ottawa is required prior to the removal of any of the trees identified in this report.



The undersigned personally inspected the property and issues associated with this report on May 4, 2020. On Behalf of Dendron Forestry Services,





Astrid Nielsen, MFC, RPF (Registered Professional Forester) ISA Certified Arborist[®], ON-1976 ISA Tree Risk Assessment Qualified Principal, Dendron Resource Surveys <u>Astrid.nielsen@dendronforestry.ca</u>



Figure 1: Trees no. 1-3: American elms and Manitoba maple to be removed



Dendron Forestry Services www.dendronforestry.ca 613.805.WOOD (9663) info@dendronforestry.ca




Figure 2: Trees 4 to 7: Siberian elm, Manitoba maple and ash (dead) to be removed



Dendron Forestry Services www.dendronforestry.ca 613.805.WOOD (9663) info@dendronforestry.ca



Figure 3: Tree no. 8 - City-owned Freeman maple to be removed



Intended Use of the Report

This Information Report was carried out by Dendron Forestry Services (hereafter Dendron) at the request of the Client. The information, interpretation and analysis contained within this Report is to be used solely for the purposes outlined within this Report. This Report is for the exclusive use of the Client.

Limitations of this Report

This Report is based on the circumstances and observations as they existed at the time of the site inspection of the Client's Property and the trees situate thereon by Dendron and upon information provided by the Client to Dendron. The opinions in this Report are given based on observations made and using generally accepted professional judgment, however, because trees and plants are living organisms and subject to change, damage and disease, the results, observations, recommendations, and analysis as set out in this Report are valid only as at the date any such testing, observations and analysis took place and no guarantee, warranty, representation or opinion is offered or made by Dendron as to the length of the validity of the results, observations, recommendations and analysis contained within this Report As a result the Client shall not rely upon this Report, save and except for representing the circumstances and observations, analysis and recommendations that were made as at the date of such inspections. It is recommended that the trees discussed in this Report should be re-assessed periodically.

Further Services

Neither Dendron nor any assessor employed or retained by Dendron for the purpose of preparing or assisting in the preparation of this Report shall be required to provide any further consultation or services to the Client, save and except as already carried out in the preparation of this Report and including, without limitation, to act as an expert witness or witness in any court in any jurisdiction unless the Client has first made specific arrangements with respect to such further services, including, without limitation, providing the payment of the Report's regular hourly billing fees.

Dendron accepts no responsibility for the implementation of all or any part of the Report, unless specifically request to examine the implementation of such activities recommended herein. In the event that inspection or supervision of all or part of the implementation is request, that request shall be in writing and the details agreed to in writing by both parties.

Assumptions

The Client is hereby notified and does hereby acknowledge and agree that where any of the facts and information set out and referenced in this Report are based on assumptions, facts or information provided to Dendron by the Client and/or third parties and unless otherwise set out within this Report, Dendron will in no way be responsible for the veracity or accuracy of any such information. Further, the Client acknowledges and agrees that Dendron has, for the purposes of preparing their Report, assumed that the Property, which is the subject of this Report is in full compliance with all applicable federal, provincial, municipal and local statutes, regulations, by-laws, guidelines and other related laws. Dendron explicitly denies any legal liability for any and all issues with respect to non-compliance with any of the above-referenced statutes, regulations, bylaws, guidelines and laws as it may pertain to or affect the Property to which this Report applies.

Professional Responsibility

In carrying out this Report, Dendron and any Assessor appointed for and on behalf of Dendron to perform and carry out the Report has exercised a reasonable standard of care, skill and diligence as would be customarily and normally provided in carrying out this Report. While reasonable efforts have been made to ensure that the trees recommended for retention are healthy, no guarantees are offered, or implied, that these trees, or all parts of them will remain standing. It is professionally impossible to predict with absolute certainty the behaviour of any single tree or group of trees, or all their component parts, in all given circumstances. Inevitably, a standing tree will always pose some risk. Most trees have the potential to fall, lean, or otherwise pose a danger to property and persons in the event of adverse weather conditions, and this risk can only be eliminated if the tree is removed.


Without limiting the foregoing, no liability is assumed by Dendron for:

- a) any legal description provided with respect to the Property;
- b) issues of title and or ownership respect to the Property;
- c) the accuracy of the Property line locations or boundaries with respect to the Property; and
- d) the accuracy of any other information provided to Dendron by the Client or third parties;
- e) any consequential loss, injury or damages suffered by the Client or any third parties, including but not limited to replacement costs, loss of use, earnings and business interruption; and
- f) the unauthorized distribution of the Report.


Further, under no circumstance may any claims be initiated or commenced by the Client against Dendron or any of its directors, officers, employees, contractors, agents or Assessors, in contract or in tort, more than 12 months after the date of this Report.

General

Any plans and/or illustrations in this Report are included only to help the Client visualize the issues in this Report and shall not be relied upon for any other purpose. This report is best viewed in colour. Any copies printed in black and white may make some details difficult to properly understand. Dendron accepts no liability for misunderstandings due to a black and white copy of the report.



Note that the tree layer has been added to the original site plan supplied by the client in pdf format. This layer refers to the trees only, and the original site plan has not been altered in the process.



Tree Conservation Repor 2046-2050 Scott Tree layer prepared by Dendron Forestry Services Version 2.0, January 15, 2021 For more information, please contact info@dendronforestry.ca

	ZÖNING BY-LAW 2008-250 TM (103) / R4G SITE AREA 1,351.54 m, m. 14,539 m, f. TM (103) ZÖNING REQUIREMENT BUILDING HEIGHT TM (105) - 18 m, / R4G - 11 m, AMENTY AREA - Bm* PER LINIT (364 units) 2,124 m, m. FRONT YARD SETBACK - TM (103) 40 m, INTERIOR YARD SETBACK - R4G 4.0 m, INTERIOR YARD SETBACK - R4G 1.5 m, / 2.5 m, / 6.0 m, INTERIOR YARD SETBACK - R4G 1.5 m, / 2.5 m, / 6.0 m, INTERIOR YARD SETBACK - R4G 1.0 m, INDRCAPE AREA - ABUTTING REB. 1.0 m, PROJECT STATISTICS 63.40 m, emil BUILDING HEIGHT B2.0 m	CONDESIONS TO THE ARCHITECT. ALL CONTRACTORS MUST COMPLY WITH ALL PERTINENT CODES AND EY-LAWS. THIS DRAWING MAY NOT BE USED FOR CONSTRUCTION UNTIL SIGNED BY THE ARCHITECT. DO NOT BCALE DRAWINGS. COPYRIGHT RESERVED. NOTATION SYMBOLS: (D) INDICATES DRAWING NOTES, LISTED ON EACH SHEET. (D) INDICATES ASSEMBLE TYPE, REFER TO TYPICAL ASSEMBLIES SCHEDUAL. (D) INDICATES ASSEMBLE TYPE, REFER TO TYPICAL ASSEMBLIES SCHEDUAL. (D) INDICATES ASSEMBLE TYPE, REFER TO TYPICAL ASSEMBLIES SCHEDUAL. (D) INDICATES DOCK TYPE, REFER TO DOOR SCHEDULE AND DETAILS ON ASSO SERIES. (D) INDICATES DOCK TYPE, REFER TO DOOR SCHEDULE AND DETAILS ON ASSO SERIES. (D) INDICATES DOCK TYPE, REFER TO DOOR	
	REAR YARD SETBACK - ANGLEAR PLANE () 45" 74.5 m H. REAR YARD SETBACK 7.5 m TOWER PLOOR PLATE AREA 735.3 cq. m. 8,112 sq. k STANDARD PARQING SPACE 2.6m X 8.2m SMALL CAR PARKING SPACE 2.4m X 4.0m	DETAIL CROSS REFERENCE PAGE	
	GROSS BUILDING FLOOR AREA ETT286 22880 DEFNITION UNG PARSONG LEVELS 005 eq. m. 000 aq. f. UNG PARSONG LEVELS 005 eq. m. 000 aq. f. 005 eq. m. 000 aq. f. SROUND FLOOR 3 # 1.2864 eq. m. 2 # 13,860 rg. ft. 2,636.8 eq. m. 2 # 13,860 rg. ft. 2nd & 3nd FLOOR 3 # 1.2864 eq. m. 2 # 13,860 rg. ft. 27,208 aq. ft. 6h FLOOR 3 # 1.085.7 eq. m. 3 # 1.085.7 eq. m. 3 # 13,850 rg. ft. 22,654 aq. ft. 8h & 6h FLOOR 3 # 1.085.7 eq. m. 3 # 10,820 rg. ft. 22,654 aq. ft. 9h FLOOR 3 # 1.085.7 eq. m. 3 # (13,927) rg. ft. 22,654 aq. ft. 9h FLOOR 3 # 1.085.7 eq. m. 3 # (13,927) rg. ft. 22,654 aq. ft. 9h FLOOR 3 # 1.085.7 eq. m. 3 # (13,927) rg. ft. 22,654 aq. ft. 9h FLOOR 3 # 1.085.7 eq. m. 3 # (13,927) rg. ft. 32,654.4 rg. m. 8,036 sq. ft. 9h FLOOR 4 # # 600.7 ms. m. 8,036 sq. ft. 36,836 sq. ft. 36,836 sq. ft. 9h ft Som FLOOR 9 # # 500.07 ms. m. 100,040 st. ft. 30,936 sq. ft. 100,040 st. ft. 900 ft qq. m. 100,040 st. ft. 000.05 qq. m. 000.5 qq. m.		
	TOTAL AREA ABOVE GRADE 20,862.0 as, n. 221,220 as, n. 22512 as, n		
	CAR PARKING REQUIRED RESIDENCE - 0.6 PER DWELLING UNIT 154		÷
	VESITOR -0.1 PER UNIT SSS UNITS) 174	3 REVIBED PROJECT DEBIGN Mar. 30, 20 2 ISSUED FOR PUBLIC MEETING Jan. 27, 23 1 ISSUED FOR ZONING AMENDMENT Jan. 21, 20	
	VISITOR -0.1 PER UNIT (363 UNITS) 30 TOTAL 204 BICYCLE PARKING REGUIRED RESIDENCE -0.5 PER UNIT (363 UNITS) COMMERCIAL RETAIL -1.0 PER 2800P OF BJFA	No. DESCRIPTION DATE	
ĪD.	TOTAL 176 PROVIDED BELOW GRADE LEVEL 293 GROUND FLOOR 0 TOTAL 292		
-	AMENITY SPACE 700.0 mp. m. AT GRADE EXTENSICA SIDE YARDS - 700.0 mp. m. PRATE BALCONES - 1,130.0 mp. m. 4th FLOOR - PRIMATE EXTENSICA - 197.0 mp. m. 7th FLOOR - PRIMATE EXTENSICA - 590.0 mp. m. 7th FLOOR - EXTENSICA - 3,107.0 mp. m. 7th FLOOR - EXTENSICA - 1,650.0 mp. m. 7th FLOOR - EXTENSICA - 1,650.0 mp. m.	RODERICKLAHEY A R C H I T E C T I N C 56 Eeech Street Oftawa, Ontario K'S 3J6 t6'3.724.9932 f6'3.724.1209 www.rtderick.ahey.ca	
-	REQUIRED COMMUNAL (g . 50% = 1,069 m; m.	2046 SCOTT STREET	
	LOT COVERAGE PAVED BURFACE = 22.0 mp. nL 0.0% BUILDING FOOTPRINT = 1,051.1 mp. nL 465.0% LANDSCAPE OPEN SPACE = 859.0 mp. nL 34.2% TOTAL = 2,512.1 mp. nL 100.0%		×
-		DHAMAN: CHECKED: R.V. K.R. RCALE: HEET No. 1:125 РИСЛЕСТ No. 1928	
	enti 1828 Site Plan 2020 04 10.dwg port — 2046-2050 Sc	Plan No.: #	ם

IT IS THE RESPONSIBILITY OF THE APPROPRIATE CONTRACTOR TO CHECK AND VERIFY ALL DIMENSION ON SITE AND TO REPORT ALL ERRORS AND/OR CMISSIONS TO THE ARCHITECT.

PROJECT INFORMATION