


13. Ensure that mulch is pulled back a min. distance of 75mm from base of tree trunk.

NAASCAR INC. & AD **INVESTMENTS**



T.L. Mak Engineering Consultants Ltd. 1455 Youville Drive, Suite 218 Ottawa, ON. K1C 6Z7

LEGEND




- SOIL VOLUME AREA PROPOSED DECIDUOUS TREE



PROPOSED SHRUBS / ORNAMENTAL GRASSES



PROPOSED WOOD MULCH





PROPOSED BOULDER

EXISTING TREE TO REMAIN

TREE PROTECTION FENCE

__o___o_ 2.4m Ht. NOISE BARRIER FENCE

PROPOSED 2.1m Ht. WOOD SCREEN FENCE

10				
9				
8				
7				
6				
5				
4	REVISED PER CITY COMMENTS	02/27/2025	ML	JL
3	ISSUED FOR DISCUSSION AND REVIEW	01/13/2025	WF	JL
2	REVISED PER CITY COMMENTS	11/20/2024	ML	JL
1	ISSUED FOR DISCUSSION AND REVIEW	04/26/2024	ML	JL
Nο	Issue	Date	DR	CK

JAMES B. LENNOX & ASSOCIATES INC. LANDSCAPE **ARCHITECTS** 3332 CARLING AVE. OTTAWA, ONTARIO K2H 5A8 Fax. 1(866) 343-3942

PROPOSED LOW-RISE APARTMENTS 609, 611,

TREE CONSERVATION REPORT & LANDSCAPE PLAN



AS SHOWN TART DATE

FEBRUARY 2024 ROJECT NO.

24MIS2408

RAWING NO.

