



June 11, 2025

Wagdy Hassanin
Barrhaven Islamic Center - Muslim Association of Canada
3971 Greenbank Road
Ottawa, ON K2C 3H2
Email: whassanin@ottawa.macnet.ca

Re: OTT-25002603-A0 Geotechnical Desk Top Review
Barrhaven Islamic Center - Muslim Association of Canada
3971 Greenbank Road, Ottawa, Ontario

EXP Services Inc. (EXP) is pleased to present the results of a desk review of inferred geotechnical condition at the Barrhaven Islamic Centre (BIC) site situated at 3971 Greenbank Road, Ottawa, ON. The purpose of this review is to establish the subsurface condition that may be underlying the site for general information purposes. This information is not intended to be used for the design of any structures or development at the site.

Available reports reviewed comprised of Phase II ESA report completed at the site in by Franz Environmental Limited in 2002 as well geotechnical investigations completed by others in the general area of the site..

A review of available information revealed the site to be likely underlain by compact to dense silty sand to sand extending to depths of at least 8 m below grade. The groundwater at the site is expected to be at a depth of 4 to 6 m below the existing ground surface

As indicated above, this letter should be used for general information and a detailed geotechnical investigation is required for any proposed development or construction at the site.

. Should you have any questions, please do not hesitate to contact this office.

Sincerely,

EXP Services Inc.

A handwritten signature in black ink, appearing to read "Ismail Taki".

Ismail Taki, M. Eng., P.Eng.
Manager – Geotechnical Services
Earth and Environment