


REMOVE DAMAGED OR OBJECTIONABLE BRANCHES. FOLLOW PROPER HORTICULTURAL PRACTICE. PLANTING BED AROUND SHRUBS. COVER ENTIRE BED WITH 75mm DEPTH WOODCHIP MULCH. PULL BACK MULCH FROM BASE OF SHRUBS. ENSURE THAT MULCH COVERS ALL EXPOSED SOIL. TAPER TO BLEND NATURALLY WITH FINISHED GRADE.



APPROVED

By Adam Brown at 2:18 pm, Feb 18, 2025



ADAM BROWN

MANAGER, DEVELOPMENT REVIEW RURAL PLANNING, DEVELOPMENT & BUILDING SERVICES DEPARTMENT, CITY OF OTTAWA

KEY	QTY.	BOTANICAL NAME	COMMON NAME	SIZE	CONDITION	REMARKS
TRE	EES					
HB HL LL RE RO WS	5 7 7 1 1 3	Celtis occidentalis Gleditsia triacanthos 'Draves' Larix laricina Acer rubrum Quercus rubra Picea glauca	Hackberry Street Keeper Honey Locust Tamarack Red Maple Red Oak White Spruce	60mm ø 60mm ø 15 gallon pot 15 gallon pot 15 gallon pot 15 gallon pot	B&B B&B Potted Potted Potted Potted	
SHF	RUB	S				
DW FR	43	Cornus sericea	Red Osier Dogwood	800mm ht.	Potted / bare root	
EB	43 14 32	Cornus sericea Sambucus racemosa Rhus aromatica	Red Osier Dogwood Red Elderberry Fragrant Sumac	800mm ht. 800mm ht. 600mm ht.	Potted / bare root Potted / bare root Potted	
DW EB FS NB	14	Sambucus racemosa	Red Elderberry	800mm ht.	Potted / bare root	1200 mm o.c. 1200 mm o.c. 1500 mm o.c.
EB FS NB	14 32 13	Sambucus racemosa Rhus aromatica	Red Elderberry Fragrant Sumac Nannyberry	800mm ht. 600mm ht.	Potted / bare root Potted	1200 mm o.c.
EB FS NB	14 32 13	Sambucus racemosa Rhus aromatica Viburnum lentago	Red Elderberry Fragrant Sumac Nannyberry	800mm ht. 600mm ht.	Potted / bare root Potted	1200 mm o.c.

KEY	QTY.	BOTANICAL NAME	COMMON NAME	SIZE	CONDITION	REMARK
TD						
IK	EES					
ΑI	*	Alnus incana	Speckled Alder	50-100mm DBH	Good	See Plan
AN	*	Acer negundo	Manitoba Maple	100-200mm DBH	Good	See Plan
AR	1	Acer rubrum	Red Maple	250mm DBH	Fair	See Plan
AS	7	Acer saccharum	Sugar Maple	100-800mm DBH	Dead-Good	See Plan
FR	*	Fraxinus sp.	Ash	100-499mm DBH	Dead-Good	See Plan
MA	*	Malus sp.	Crabapple	100-300mm DBH	Fair-Good	See Plan
PP	6	Picea pungens 'Glauca'	Colorado Blue Spruce	300mm DBH	Good	See Plan
PD	*	Populus deltoides	Eastern Cottonwood	100-450mm DBH	Poor-Good	See Plan
SR	2	Syringa reticulata	Japanese Tree Lilac	300mm DBH	Good	See Plan
SA	*	Salix sp.	Willow	100-350mm DBH	Poor-Good	See Plan
TA	*	Tilia americana	Basswood	100-900mm DBH	Dead-Good	See Plan
TO	1	Thuja occidentalis	Eastern White Cedar	3x300mm DBH	Poor	See Plan
UA	*	Ulmus americana	American Elm	100-300mm DBH	Dead-Good	See Plan

GENERAL NOTES:

1. It is the responsibility of the appropriate contractor or official to report any errors, omissions or discrepancies on this plan with actual site conditions to the Landscape Architect before proceeding with construction.

2. The contractor is to notify all utility companies and authorities prior to any excavation and ascertain locations of underground services.

3. The contractor is to reinstate all areas and items damaged as a result of construction activity.

4. The contractor is to comply with all pertinent codes and by-laws.

5. The contractor is to maintain a positive surface run-off throughout the entire construction period.

6. The Landscape Architect is not responsible for subsurface conditions.

7. The contractor is to identify all existing trees to remain on site with the Landscape Architect prior to construction.

8. The contractor is to stake the proposed location of all plant material in conjunction with the Landscape Architect prior to excavation.

9. Minimum distances for selected deciduous trees are as follows: Building Foundations 7.5m Sidewalks 1.5m

Public Streets 2.5m

Underground Infrastructure 2.0m

10. All trees within 1m of underground utility trenches are to be excavated by hand.

11. Remove all protective wrapping from tree trunks after installation.

12. Staking of trees shall only be performed if necessary. 13. Ensure that mulch is pulled back a min. distance of 75mm from base of tree trunk.

HINDU TEMPLE OF OTTAWA CARLETON

4835 BANK STREET, OTTAWA, ONTARIO K1X 1G6 Tel : (613) 613.822.1531

CONSULTANTS

ARCHITECTS: **VECTOR DESIGN** ARCHITECTS

Tel: (613) 613.421.9806

14 STRATHBURY STREET, OTTAWA, ONTARIO K2G 5N8

LRL ASSOCIATES LTD.

5430 CANOTEK RD, GLOUCESTER ON K1J 9G2

LEGEND

GROUP OF EXISTING TREES TO

EXISTING TREE TO REMAIN

BE REMOVED

GROUP OF EXISTING TREES TO

EXISTING TREE TO BE REMOVED

PROPOSED DECIDUOUS TREE

PROPOSED CONIFEROUS TREE

PROPOSED SHRUBS/ PERENNIALS/ ORNAMENTAL GRASSES

PROPOSED NON-IRRIGATED SPORTS FIELD SEED MIXTURE

PROPOSED ONTARIO SEED COMPANY LTD. CREEK BANK SEED MIXTURE

PROPOSED RIVERSTONE MULCH

PROPOSED RIP-RAP (REFER TO

PROPOSED PRECAST CONCRETE

CIVIL DRAWING)

PROPOSED TREE PROTECTION

	FENCE							
7	FILE NUMBER FORMAT REVISED	06/10/2024	ML	JL				
6	FILE NUMBER REVISED	06/05/2024	ML	JL				
5	REVISED PER NEW SITE PLAN	09/30/2022	ML	JL				
4	REVISED PER CITY COMMENTS	06/10/2022	ML	JL				
3	REVISED PER CITY COMMENTS	08/25/2021	ML	JL				
2	REVISED PER CITY COMMENTS	01/27/2021	ML	JL				
1	ISSUED FOR SITE PLAN CONTROL	03/11/2020	ML	JL				

Date DR C JAMES B. LENNOX & ASSOCIATES INC. **ARCHITECTS** LANDSCAPE OTTAWA, ONTARIO K2H 5A8 3332 CARLING AVE. Tel. (613) 722-5168 Fax. 1(866) 343-3942

PROPOSED ASSEMBLY HALL - HINDU TEMPLE

4835 BANK STREET, OTTAWA ON

TREE CONSERVATION REPORT &



SCALE AS SHOWN START DATE AUGUST 2019

ROJECT NO. 19MIS1974

PROJECT NORTH

DRAWING NO.