

11. Remove all protective wrapping from tree trunks after installation.

13. Ensure that mulch is pulled back a min. distance of 75mm from base of tree trunk.

12. Staking of trees shall only be performed if necessary.

Conseil des écoles publiques de l'Est de l'Ontario

## grc architects

CIVIL ENGINEERS:



5430 Canotek Road | Ottawa, ON, K1J 9G2 www.lrl.ca | (613) 842-3434

Callon Dietz INCORPORATED ONTARIO LAND SURVEYORS CARLETON PLACE LONDON NORTH BAY requests@callondietz.com callondietz.com

LEGEND PROPOSED CONCRETE PROPOSED PAVERS PROPOSED SOD PROPOSED DECIDUOUS TREE PROPOSED CONIFEROUS TREE PROPOSED SHRUBS/PERENNIALS PROPOSED CONIFEROUS TREE PROPOSED CONIFEROUS TREE


PROPERTY LINE

TAMES D. LENNOV & ASSOCIATES INC.				
No.	Issue	Date MM/DD/YY	DR	С
1	ISSUED FOR DISCUSSION AND REVIEW	12/13/2024	ML	J
2	REVISED AS PER ARCHITECTS COMMENTS	01/24/2025	CAT	J
3	ISSUED FOR DISCUSSION AND REVIEW	01/29/2025	ML	J
4	ISSUED FOR 66% REVIEW	01/31/2025	ML	J
				_

JAMES B. LENNOX & ASSOCIATES INC. LANDSCAPE **ARCHITECTS** 3332 CARLING AVE. OTTAWA, ONTARIO K2H 5A8 Tel. (613) 722-5168 Fax. 1(866) 343-3942

PROPOSED HIGH SCHOOL- ESP ORLEANS SUD 2405 MER BLEUE ROAD, OTTAWA ON

TREE CONSERVATION REPORT & LANDSCAPE PLAN



SCALE

AS SHOWN TART DATE OCTOBER 2024

ROJECT NO.

LOT SIZE ARCH-D

DRAWING NO.

\*DENOTES NUMEROUS

25 | 1

Acer saccharum

Picea glauca

Populus deltoides

Populus deltoides

Rhamnus cathartica

Sugar Maple

White Spruce

120mm DBH

390mm DBH GOOD

Eastern Cottonwood | 100-150mm DBH | GOOD

Common Buckthorn | 2x120mm DBH | GOOD

Eastern Cottonwood 800mm DBH

GOOD

To be removed 2405 Mer Bleue Road

Tree is in good condition

Tree is in good condition

Hedgerow is in good condition

Tree is in good condition- invasive species

Tree is in good condition- can be hazardous at this size