ARCADIS

**IBI GROUP** 

ARCADIS IBI GROUP 500–333 Preston Street Ottawa ON K1S 5N4 Canada tel 613 225 1311 fax 613 225 9868 ibigroup.com

## Memorandum

To/Attention	Vincent Denomme	Date	May 9, 2023
From	Lindsay Jackson	Project No	140253
сс	Alex Zeller		
Subject	Walkley & Conroy Tree Conservation Report Comment Response Table		

Mr. Denomme,

As a part of our works for the Tree Conservation Report for Project Number 140253, we have been asked to provide answers to the comments from the City of Ottawa Staff. We have provided you with a comment response table for comments number 9 and 10 (**Table 1**), as well as a table outlining the rationale for the removal, or possibility of retention for trees identified by the City of Ottawa (**Table 2**).

## Table 1: City of Ottawa Comment Response Table

9. Tree Removal in the area identified as "Additional lands owned by the applicant" in the Planning and Design Brief will not be approved through this Site Plan Control application. Tree removal will be considered at the time of the future development's Site Plan Control application. Please update the TCR showing the trees in this area as retained.	We have obtained an update Site Plan and have updated our figures to reflect the update. Trees that are not within the Subject Property or are not expected to be impacted by the works associated with the property development have been removed from the mapping and the inventory table to avoid any confusion. Any trees that are within this area, and whose critical root zone conflicts with development have been identified.
10. There are 266 trees identified for removal with the reasoning presented in the TCR being they are mostly non-native and invasive species. Non-native species can serve an important function in the urban forest. Removal because a tree is non-native is not justified. Retention solutions for healthy trees in suitable locations must be sought. Please consider retention strategies for trees where feasible with a focus on exploring options for tree #s 1, 99, 110, 221-224,225, 229, 231,234,237, 239, 245 – 247, 248-250, 254, 253.	Retention strategies have been explored for the following trees: 1, 99, 110, 221-224,225, 229, 231,234,237, 239, 245 – 247, 248-250, 254, 253. Please see Table 2 for provided tree-specific rational in relation to the provided Site Plan.

Trees ID #4	Lindated Otta Dian above that this term
Tree ID #1	Updated Site Plan shows that this tree can be
	retained. Tree protection fencing will be
	required to protect the CRZ as it borders the
	property line.
Tree ID #99	Updated Site Plan places this tree within the
	proposed park block. As there is no detailed
	design available for the proposed park, the
	tree can be retained. Tree removal details for
	the park will occur at the detailed design
	stage, and trees identified by the City should
	be considered for incorporation in the design.
Tree ID #110	Updated Site Plan places this tree within the
	footprint of a home and is not suitable for
	retention. Tree is to be removed.
Tree ID #221-224	Updated Site plan identifies this section of
	trees as retainable. Tree protection fencing
	will be required to protect the CRZ.
Tree ID #225	Updated Site Plan shows that this tree can be
	retained. Tree protection fencing will be
	required to protect the CRZ as it borders the
	property line.
Tree ID #229	Updated Site Plan shows that this tree can be
	retained. Tree protection fencing will be
	required to protect the CRZ as it borders the
	property line.
Tree ID #231	Updated Site Plan shows that this tree cannot
	be retained as it is within a road right-of-way.
Tree ID #234	Updated Site Plan shows that this tree cannot
	be retained as it is within a road right-of-way.
Tree ID #237	Updated Site Plan shows that this tree cannot
	be retained as it is within a road right-of-way.
Tree ID #239	Updated Site Plan shows that this tree cannot
	be retained as it is within a road right-of-way.
Tree ID #245-248	Updated Site Plan shows that this tree can be
	retained. Tree protection fencing will be
	required to protect the CRZ.
Tree ID #249	Updated Site Plan shows that this tree cannot
	be retained as it is within a parking lot.
Tree ID #250	Updated Site Plan shows that this tree cannot
	be retained as it is within a parking lot.
Tree ID #253	Updated Site Plan shows that this tree cannot
	be retained as it is within a parking lot.
Tree ID #254	Updated Site Plan shows that this tree cannot
	be retained as it is within a parking lot.
	be retained as it is within a parking lot.

## Table 2: Trees Identified as Potentially Retainable by the City of Ottawa