



PROPOSED PLANT LIST						QTY. KEY
KEY	qty.	BOTANICAL NAME	COMMON NAME	SIZE	CONDITION	REMARKS
TREES						
* AM	8	Acer x freemanii 'Armstrong'	Armstrong Maple	50mm cal.	B&B	Proposed on private property
* SB	3	Amelanchier canadensis	Shadblow Serviceberry	50mm cal.	B&B	Proposed on city property
* SF	3	Amelanchier laevis 'JFS-ARB'	Spring Flurry Serviceberry	50mm cal.	B&B	Proposed on city property
SHRUBS						
AH	18	Hydrangea arborescens 'Annabelle'	Annabelle Hydrangea	1 gallon pot	Potted	Space 1000mm o.c.
* DW	12	Cornus sericea	Red Osier Dogwood	800mm ht.	Potted	Space 1200mm o.c.
* JH	9	Juniperus horizontalis	Creeping Juniper	600mm spr.	Potted	Space 800mm o.c.
RR	18	Rosa rugosa	Rugosa Rose	800mm ht.	Potted	Space 1000mm o.c.
SE	21	Sorbaria sorbifolia 'Sem'	Sem False Spirea	600mm ht.	Potted	Space 1000mm o.c.
ORNAMENTAL GRASSES						
KF	13	Calamagrostis 'Karl Foerster'	Karl Foerster Grass	250mm pot.	Potted	Space 800mm o.c.

*NATIVE TO ONTARIO. ALL SHRUBS AND ORNAMENTAL GRASSES ARE PROPOSED ON PRIVATE PROPERTY



EXISTING TREE LIST

QTY
KEY

KEY	QTY.	BOTANICAL NAME	COMMON NAME	SIZE	CONDITION	REMARKS	OWNERSHIP	COMMENTS
1	1	<i>Acer saccharum</i>	Sugar Maple	460mm DBH	DEAD	To remain	NCC	Tree is dead with 0% leaf canopy
2	1	<i>Fagus grandifolia</i>	American Beech	350mm DBH	GOOD	To be removed	City of Ottawa	Tree is in good condition
3	1	<i>Fagus grandifolia</i>	American Beech	3x400mm DBH	GOOD	To be removed	1146 Snow Street	3 stemmed tree is in good condition
4	1	<i>Fraxinus spp.</i>	Ash	350mm DBH	DEAD	To remain	NCC	Tree is dead with 0% leaf canopy
5	1	<i>Populus tremuloides</i>	Trembling Aspen	350mm DBH	GOOD	To remain	NCC	Tree is in good condition
6	1	<i>Populus tremuloides</i>	Trembling Aspen	400mm DBH	DEAD	To remain	NCC	Tree is dead and has fallen over
7	1	<i>Rhamnus cathartica</i>	Common Buckthorn	100mm DBH	GOOD	To remain	NCC	Tree is in good condition- invasive species
8	1	<i>Acer rubrum</i>	Red Maple	170mm DBH	GOOD	To remain	NCC	Tree is in good condition
9	1	<i>Tilia americana</i>	Basewood	300mm DBH	GOOD	To remain	NCC	Tree is in good condition
10	1	<i>Rhamnus cathartica</i>	Common Buckthorn	3x100mm DBH	GOOD	To remain	NCC	Tree is in good condition- invasive species
11	1	<i>Populus tremuloides</i>	Trembling Aspen	400mm DBH	GOOD	To remain	NCC	Tree is in good condition
12	1	<i>Ostrya virginiana</i>	Ironwood	200mm DBH	GOOD	To remain	NCC	Tree is in good condition
13	1	<i>Populus tremuloides</i>	Trembling Aspen	180mm DBH	GOOD	To remain	NCC	Tree is in good condition
14	1	<i>Populus tremuloides</i>	Trembling Aspen	170mm DBH	GOOD	To remain	NCC	Tree is in good condition
15	1	<i>Pinus strobus</i>	White Pine	300mm DBH	GOOD	To remain	521 Burleigh private	Tree is in good condition- size and location estimated
16	1	<i>Ulmus americana</i>	American Elm	150mm DBH	GOOD	To remain	521 Burleigh private	Tree is in good condition- size and location estimated
17	1	<i>Pinus strobus</i>	White Pine	300mm DBH	GOOD	To remain	521 Burleigh private	Tree is in good condition- size and location estimated
18	1	<i>Picea pungens</i>	Colorado Spruce	150mm DBH	GOOD	To remain	517 Burleigh private	Tree is in good condition- size and location estimated
19	1	<i>Picea glauca</i>	White Spruce	400mm DBH	GOOD	To remain	1142 Snow Street	Tree is in good condition- size and location estimated

PLOT SIZE ARCH-D