#### Geotechnical Engineering

Environmental Engineering

Hydrogeology

Geological Engineering

**Materials Testing** 

**Building Science** 

Archaeological Studies

# patersongroup

## **Phase I Environmental Site Assessment**

Vacant Property - Oak Ridge Gate Subdivision Chinon Place at Breezewood Street Ottawa, Ontario

#### **Prepared For**

Ashcroft Homes

#### Paterson Group Inc.

Consulting Engineers 154 Colonnade Road South Ottawa (Nepean), Ontario Canada K2E 7J5

Tel: (613) 226-7381 Fax: (613) 226-6344 www.patersongroup.ca December 6, 2017

Report: PE2326-2

#### TABLE OF CONTENTS

EXEC	UTIV	E SUMMARY	.ii
1.0	INTR	ODUCTION	1
2.0	PHAS	SE I PROPERTY INFORMATION	2
3.0	SCO	PE OF INVESTIGATION	3
4.0	RECO	DRDS REVIEW	4
	4.1	General	4
	4.2	Environmental Source Information	5
	4.3	Physical Setting Sources	
5.0	INTE	RVIEWS	9
6.0	SITE	RECONNAISSANCE	9
	6.1	General Requirements	9
	6.2	Specific Observations at Phase I Property	9
7.0	REVI	EW AND EVALUATION OF INFORMATION 1	1
		Land Use History 1	
	7.2	Conceptual Site Model1	1
8.0		CLUSION 1	
9.0		EMENT OF LIMITATIONS 1	
10.0	REFE	RENCES 1	5

#### **List of Figures**

Figure 1 - Key Plan Figure 2 - Topographic Map Drawing PE2326-2 - Site Plan Drawing PE2326-3 - Surrounding Land Use Plan

#### **List of Appendices**

- Appendix 1 Plan of Survey Aerial Photographs Site Photographs
- Appendix 2 MOECC Freedom of Information Search Request City of Ottawa HLUI Request TSSA Correspondence MOECC Water Well Records
- Appendix 3 Qualifications of Assessors

## **EXECUTIVE SUMMARY**

## Assessment

A Phase I – Environmental Site Assessment was carried out for the vacant piece of land just west of the Chinon Place and Breezewood Street intersection, in the City of Ottawa, Ontario. The property does not have a civic address. The purpose of this environmental assessment was to research the past and current use of the subject site and adjacent properties and identify any environmental concerns with the potential to impact the subject property.

Based on a review of historical sources, the subject property appears to have never been developed. No historical potentially contaminating activities (PCAs) were identified on the Phase I property. Surrounding properties have historically been used for agricultural purposes, with large scale residential development occurring in the early 2000's. A bus depot was constructed west of the subject site in the late 1980s and was identified by the TSSA as having two (2) USTs. The bus depot is considered a PCA but due to the distance and cross-gradient orientation with respect to the subject site, this PCA is not considered to have resulted in an APEC on the subject property.

Following the historical review, a site visit was conducted. The subject property currently exists as a vacant lot of land with grass, shrubs and small tree coverage. No environmental concerns were identified on the subject site at the time of the site visit.

The surrounding land use consisted primarily of residential properties, with some under construction light commercial property further to the south and a hydro corridor further to the north. The former bus depot to the west is considered a PCA because of the two (2) expired USTs reported by the TSSA to be onsite. However, due to the distance and cross-gradient orientation with respect to the subject site, this PCA is not considered to have resulted in an APEC on the subject property.

Based on the results of this Phase I - Environmental Site Assessment, it is our opinion that a Phase II - Environmental Site Assessment is not required for the property.

## **1.0 INTRODUCTION**

At the request of Ashcroft Homes, Paterson Group (Paterson) conducted a Phase I - Environmental Site Assessment (Phase I ESA) on the vacant land (no civic address) located west of the Chinon Place and Breezewood Street intersection, in the City of Ottawa, Ontario. The purpose of this Phase I ESA was to research the past and current use of the site and study area and to identify any environmental concerns with the potential to have impacted the subject property.

Paterson was engaged to conduct this Phase I ESA by Ms. Keiran Watson of Ashcroft Homes. Ms. Watson can be reached by telephone at (613) 226-7266.

This report has been prepared specifically and solely for the above noted project which is described herein. It contains all of our findings and results of the environmental conditions at this site.

This Phase I ESA report has been prepared in general accordance with the requirements of Ontario Regulation 153/04 as amended by O.Reg. 269/11 (Environmental Protection Act), and also complies with the requirements of CSA Z768-01. The conclusions presented herein are based on information gathered from a limited historical review and field inspection program. The findings of the Phase I ESA are based on a review of readily available geological, historical and regulatory information and a cursory review made at the time of the field assessment. The historical research relies on information supplied by others, such as local, provincial and federal agencies and was limited within the scope-of-work, time and budget of the project herein.

## 2.0 PHASE I PROPERTY INFORMATION

Address:	No civic address for the property.					
Legal Description:	Part 3, Part of Lot A, Concession 9, (Geographic Township of Cumberland) in the City of Ottawa, Ontario.					
Property Identification Number (PIN):	14526-0650					
Location:	The subject site is located on the east side of Trim Road, approximately 230 m north of Valin Street.					
Latitude and Longitude:	45° 28' 29" N, 75° 27' 26" W					
Site Description:						
Configuration:	Rectangular					
Site Area:	8,960 m <sup>2</sup> (approximate)					
Zoning:	DR – Development Reserve					
Current Use:	The subject site is vacant, grassed land.					
Services:	The subject site is situated in an area that is municipally serviced.					

## 3.0 SCOPE OF INVESTIGATION

The scope of work for this Phase I – Environmental Site Assessment was as follows:

- Determine the historical activities on the subject site and study area by conducting a review of readily available records, reports, photographs, plans, mapping, databases and regulatory agencies;
- Investigate the existing conditions present at the subject site and study area by conducting site reconnaissance;
- Conduct interviews with persons knowledgeable of current and historic operations on the subject property, and if warranted, neighbouring properties;
- Present the results of our findings in a comprehensive report in general accordance with the requirements of Ontario Regulation 269/11 amending O.Reg. 153/04 made under the Environmental Protection Act and in compliance with the requirements of CSA Z768-01;
- Provide a preliminary environmental site evaluation based on our findings;
- Provide preliminary remediation recommendations and further investigative work if contamination is suspected or encountered.

## 4.0 RECORDS REVIEW

#### 4.1 General

#### Phase I ESA Study Area Determination

A radius of approximately 250 m was determined to be appropriate as a Phase I ESA study area for this assignment. Properties outside the 250 m radius are not considered to have impacted the subject land, based on their significant distance from the site.

#### First Developed Use Determination

Based on a review of historically available information, the Phase I property does not appear to have ever been developed, although it has been used for agricultural purposes in the past.

#### National Archives

Fire insurance plans are not available for the Phase I study area.

Directories were reviewed at the National Archives for the subject site and properties within the Phase I study area, from 1984 through 2011. The area surrounding the subject site has been listed as residential and commercial since at least 1996. No environmental concerns were noted in the City directories with respect to the use of the subject site.

#### Plan of Survey

A plan of survey was prepared by the City of Ottawa and dated February 12, 2003. The plan depicts the subject site in its current configuration but has an outdated PIN number. Trim Road has been realigned since 2003 and now borders the western property boundary of the subject site. A copy of the plan is included in Appendix 1.

#### **Previous Environmental Reports**

Paterson conducted a previous Phase I ESA in conjunction with a geotechnical project for the subject property in June 2011. At that time, no environmental concerns were identified on the subject site or neighbouring properties. A total of three (3) boreholes were drilled as part of the geotechnical project, and the subsurface material was found to be predominantly firm to stiff native silty-clay. No sub-surface impacts were observed during the drilling program.

#### City of Ottawa Historic Land Use Inventory (HLUI) Database

A request for information from the City's Historic Land Use Inventory (HLUI 2005) database for the subject property was submitted to the City of Ottawa. The response from the City had not been received at the time of issuance of this report.

#### 4.2 Environmental Source Information

#### Environment Canada

A search of the National Pollutant Release Inventory (NPRI) was conducted electronically on November 29, 2017. The subject site and Phase I study area were not listed in the NPRI database.

#### PCB Inventory

A search of national PCB waste storage sites was conducted. No PCB waste storage sites are located within the Phase I study area.

#### Ontario Ministry of Environment and Climate Change (MOECC) Instruments

A request was submitted to the MOECC Freedom of Information office for information with respect to certificates of approval, permits to take water, certificates of property use or any other similar MOECC issued instruments for the site. At the time of issuing this report, a response from the MOECC had not been received.

#### **MOECC Coal Gasification Plant Inventory**

The Ontario Ministry of Environment and Climate Change document titled "Municipal Coal Gasification Plant Site Inventory, 1991" was reviewed to reference the locations of former plants with respect to the site. No coal gasification plants were identified in the Phase I study area

#### MOECC Incident Reports

A request was submitted to the MOECC Freedom of Information office for information with respect to records concerning environmental incidents, orders, offences, spills, discharges of contaminants or inspections maintained by the MOECC for the site or adjacent properties. At the time of issuing this report, a response from the MOECC had not been received.

#### **MOECC Waste Management Records**

A request was submitted to the MOECC Freedom of Information office for information with respect to waste management records. At the time of issuing this report, a response from the MOECC had not been received.

#### **MOECC Submissions**

A request was submitted to the MOECC Freedom of Information office for information with respect to reports related to environmental conditions for the property. At the time of issuing this report, a response from the MOECC had not been received.

#### **MOECC Brownfields Environmental Site Registry**

A search of the MOECC Brownfields Environmental Site Registry was conducted as part of this assessment for the site, neighbouring properties and the Phase I study area. No Records of Site Condition (RSCs) were filed for the subject site or properties within the Phase I study area.

#### **MOECC Waste Disposal Site Inventory**

The Ontario Ministry of Environment and Climate Change document titled "Waste Disposal Site Inventory in Ontario, 1991" was reviewed as part of the historical research. This document includes all recorded active and closed waste disposal sites, industrial manufactured gas plants and coal tar distillation plants in the Province of Ontario. No records were listed for the subject site or for properties within the Phase I study area.

#### Areas of Natural Significance

A search for areas of natural significance and features within the Phase I study area was conducted on the web site of the Ontario Ministry of Natural Resources (MNR) on November 29, 2017. No areas of natural significance were identified on the subject site or within the Phase I study area.

#### Technical Standards and Safety Authority (TSSA)

The TSSA, Fuels Safety Branch in Toronto was contacted electronically on November 29, 2017 to inquire about current and former underground storage tanks, spills and incidents for the site and neighbouring properties. According to the TSSA, two (2) expired underground fuel tanks are present at 1830 Trim Road, the former bus depot to the west of the subject site. The TSSA correspondence is attached under Appendix 2.

#### City of Ottawa Landfill Document

The document entitled "Old Landfill Management Strategy, Phase I – Identification of Sites, City of Ottawa", was reviewed. No landfill sites were identified within the Phase I study area.

#### 4.3 Physical Setting Sources

#### Aerial Photographs

Historical air photos from the National Air Photo Library were reviewed in approximate ten (10) year intervals. The review period dates to the first available air photos for the site. The following observations have been made:

- 1945 The subject site and surrounding properties appear to be used for agricultural purposes. Scattered farmsteads are present in the general area of the subject site.
- 1973-85 No apparent changes have been made to the subject site or majority of surrounding properties. The property to the south appears to have been developed with a residential dwelling.
- 1990 No apparent changes have been made to the subject site or surrounding properties to the north, east and south. A bus depot is present west of the subject site, on the opposite side of Trim Road.
- 1994 No apparent changes have been made to the subject site or surrounding properties to the east and south. To the north and west of the subject site, excavation activities for the construction of a large municipal drainage ditch are underway.
- 2005 (City of Ottawa website) No apparent changes have been made to the subject site or surrounding properties to the south and west. To the east and south, and further to the north and west of the subject site, significant residential development is present. To the north, grassed areas and walking paths appear to be present.
- 2017 (City of Ottawa website) No apparent changes have been made to the subject site or surrounding properties to the east, west and south. Trim Road appears to have been realigned north of the subject site and further north residential properties are present.

Laser copies of selected aerial photographs reviewed are included in Appendix 1.

#### **Topographic Maps**

Topographic information was obtained from Natural Resources Canada – The Atlas of Canada website. The topographic maps indicate that the elevation of the subject site is approximately 85 m ASL, and that the regional topography in the general area of the site slopes downward to the north-northeast, towards Cardinal Creek. An illustration of the referenced topographic map is presented on Figure 2 – Topographic Map, appended to this report.

#### Physiographic Maps

A Physiographic Map was reviewed from the Natural Resources Canada – The Atlas of Canada website, as a part of this assessment. According to the publication and mapping, the site is situated within the St. Lawrence Lowlands, Till Plains (Drumlinized) physiographic region. According to the mapping description provided: "The lowlands are plain-like areas that were all affected by the Pleistocene glaciations and are therefore covered by surficial deposits and other features associated with the ice sheets." The subject site is in the Central St. Lawrence Lowland, "where the land is rarely more than 150 m above sea level, except for the Monteregion Hills, which consist of intrusive igneous rocks.

#### Geological Maps

The Geological Survey of Canada website on the Urban Geology of the National Capital Area was consulted as part of this assessment. Based on this information, bedrock in the area of the site consists of interbedded limestone and dolostone of the Gull River Formation. Overburden consists of clay and silt offshore marine sediments, with a drift thickness on the order of 25 to 50 m.

#### Water Well Records

A search of the MOECCs web site for all drilled well records within 250 m of the subject site was conducted on November 29, 2017. Based on the search results, three (3) water well records were identified in the Phase I study area. Newer developments within the Phase I study area are municipally serviced.

#### Water Bodies and Areas of Natural Significance

Cardinal Creek is the closest significant water body, at approximately 500 m to the northeast of the subject site. No creeks, streams, lakes or other water bodies were identified in the Phase I study area. No areas of natural significance were identified within the Phase I study area.

## 5.0 INTERVIEWS

#### Ashcroft Homes – Planner

Ms. Kieran Watson of Ashcroft Homes was interviewed via email. Ms. Watson provided the 2003 plan of survey and stated that the property has no municipal address. Ms. Watson stated that the property was purchased by Ashcroft Homes approximately 10 years ago and that she was uncertain as to who the previous property owners were. Ms. Watson was not aware of any environmental concerns with the subject site or surrounding properties.

## 6.0 SITE RECONNAISSANCE

#### 6.1 General Requirements

The site assessment was conducted on November 30, 2017. Weather conditions were overcast, with a temperature of approximately 0°C. Personnel from the Environmental Department of Paterson Group conducted the site visit. In addition to the site, the uses of neighbouring properties within the Phase I study area were also assessed at the time of the site visit.

#### 6.2 Specific Observations at Phase I Property

#### **Buildings and Structures**

The subject site is a vacant lot of land. No buildings or structures exist on the subject property. A depiction of the subject site is shown on Drawing PE2326-2 – Site Plan, in the Figures section of this report.

#### Site Features

The subject site is not developed and exists as a vacant lot of land with grass, shrubs and small tree coverage.

#### **Underground Utilities**

The subject site has no underground utilities.

#### Waste Materials

Minor amounts of non-hazardous municipal solid waste and compostable material was present on the subject site at the time of the site visit. These items are not considered an environmental concern.

#### Storage Tanks

No storage tanks were present on the subject site at the time of the site visit.

#### **Drains, Pits and Sumps**

No drains, pits or sumps were present on the subject site at the time of the site visit.

#### Unidentified Substances

No unidentified substances were present on the subject site at the time of the site visit.

#### Hazardous Building Materials

No hazardous building materials were present on the subject site at the time of the site visit.

#### Phase I Study Area

An inspection of the neighbouring properties was conducted from publicly accessible roadways at the time of the site inspection. Land use adjacent to the subject site was as follows:

- □ North Residential properties, followed by Mondavi Street;
- □ South Residential property, followed by Trim Road;
- □ East Residential properties, followed by Breezewood Street;
- □ West Trim Road, followed by a former bus depot.

The bus depot to the west of the subject site has been closed since 2014. A TSSA search request from 2011 identified two (2) active underground storage tanks (USTs) to be present at the depot. The TSSA search request sent as part of this current ESA, identified two (2) expired USTs. Based on aerial photographs, the likely location of the USTs on the bus depot property is approximately 220 m from the subject site. Based on this significant distance, the USTs are not considered to result in an APEC on the subject site. Property use within the Phase I study area is presented on Drawing PE2326-3 – Surrounding Land Use Plan.

## 7.0 REVIEW AND EVALUATION OF INFORMATION

#### 7.1 Land Use History

The subject site appears to have never been developed and currently exists as a vacant lot of land. The subject site has previously been used for agricultural purposes.

#### Potentially Contaminating Activities (PCAs)

Potentially Contaminating Activities (PCAs) were not identified on the subject site. The TSSA identified two (2) expired USTs at the former bus depot to the west of the subject site. These USTs are considered to be a PCA.

#### Areas of Potential Environmental Concern (APECs)

Based on the distance and cross-gradient location with respect to the subject site, the identified former bus depot (offsite) PCA is not considered to represent an Area of Potential Environmental Concern (APECs) on the subject site.

#### **Contaminants of Potential Concern (CPCs)**

No contaminants of concern (CPCs) were identified on the Phase I property.

#### 7.2 Conceptual Site Model

#### **Existing Buildings and Structures**

The subject site is a vacant lot of land. No buildings or structures exist on the subject property.

#### Geological and Hydrogeological Setting

The subject site is located in an area of offshore marine sediments of clay and silt. Groundwater flow is expected to reflect site topography and flow in a north-easterly direction.

#### Water Bodies

The closest water body is Cardinal Creek, located approximately 500 m northeast of the subject site. There are no water bodies on the subject site or within the Phase I study area.

#### Areas of Natural Significance

No areas of natural significance were identified within the Phase I study area.

#### Water Wells

A search of the MOECC's web site for all drilled well records within 250 m of the subject site was conducted on November 29, 2017. Based on the search results, no wells were located on the subject site. Three (3) potable well records were identified within the Phase I study area. Newer developments within the Phase I study area receive full municipal services.

#### Neighbouring Land Use

Neighbouring land use in the Phase I study area is primarily residential, with a former bus depot to the west, some light commercial use further to the south and a hydro corridor further to the north. The residential properties consist of duplex dwellings and row housing. The bus depot was identified by the TSSA as having two (2) expired USTs on the property, and is considered to be a PCA. The light commercial property is currently under development and the ground surface of the hydro corridor has walking paths. Neighbouring land use does not pose an environmental concern to the subject site.

# Potentially Contaminating Activities and Areas of Potential Environmental Concern

As per Section 7.1 of this report, the former bus depot to the west of the subject site was the only PCA identified within the Phase I study area. Based on the distance and cross-gradient orientation with respect to the subject site, the bus depot PCA is not considered to have resulted in an APEC on the subject site.

#### **Contaminants of Potential Concern**

No CPCs were identified on the subject site.

#### Assessment of Uncertainty and/or Absence of Information

The information available for review as part of the preparation of this Phase I ESA is considered to be sufficient to conclude that there are no APECs on the subject site. The presence of a PCA was confirmed by a variety of independent sources, and as such, the conclusions of this report are not affected by uncertainty which may be present with respect to the individual sources.

## 8.0 CONCLUSION

## Assessment

A Phase I – Environmental Site Assessment was carried out for the property west of the Chinon Place and Breezewood Street intersection, in the City of Ottawa, Ontario. The property does not have a civic address. The purpose of this environmental assessment was to research the past and current use of the subject site and adjacent properties and identify any environmental concerns with the potential to impact the subject property.

Based on a review of historical sources, the subject property appears to have never been developed. No historical potentially contaminating activities (PCAs) were identified on the Phase I property. Surrounding properties have historically been used for agricultural purposes, with large scale residential development occurring in the early 2000's. A bus depot was constructed west of the subject site in the late 1980s and was identified by the TSSA as having two (2) USTs. The bus depot is considered a PCA but due to the distance and cross-gradient orientation with respect to the subject site, this PCA is not considered to have resulted in an APEC on the subject property.

Following the historical review, a site visit was conducted. The subject property currently exists as a vacant lot of land with grass, shrubs and small tree coverage. No environmental concerns were identified on the subject site at the time of the site visit.

The surrounding land use consisted primarily of residential properties, with some under construction light commercial property further to the south and a hydro corridor further to the north. The former bus depot to the west is considered a PCA because of the two (2) expired USTs reported by the TSSA to be onsite. However, due to the distance and cross-gradient orientation with respect to the subject site, this PCA is not considered to have resulted in an APEC on the subject property.

Based on the results of this Phase I - Environmental Site Assessment, it is our opinion that a Phase II - Environmental Site Assessment is not required for the property.

## 9.0 STATEMENT OF LIMITATIONS

This Phase I - Environmental Site Assessment report has been prepared in general accordance with O.Reg. 153/04 as amended by O.Reg. 269/11, and meets the requirements of CSA Z768-01. The conclusions presented herein are based on information gathered from a limited historical review and field inspection program. The findings of the Phase I ESA are based on a review of readily available geological, historical and regulatory information and a cursory review made at the time of the field assessment. The historical research relies on information supplied by others, such as, local, provincial and federal agencies and was limited within the scope-of-work, time and budget of the project herein.

Should any conditions be encountered at the subject site and/or historical information that differ from our findings, we request that we be notified immediately in order to allow for a reassessment.

This report was prepared for the sole use of Ashcroft Homes. Permission and notification from Ashcroft and Paterson will be required to release this report to any other party.

Paterson Group Inc.

L

Greg van Loenen, B.Eng.

Mark S. D'Arcy, P.Eng., QPESA

#### **Report Distribution:**

- Ashcroft Homes (1 copy)
- Paterson Group Inc. (1 copy)



#### **10.0 REFERENCES**

#### **Federal Records**

Air photos at the Energy Mines and Resources Air Photo Library. National Archives. Maps and photographs (Geological Survey of Canada surficial and subsurface). Natural Resources Canada – The Atlas of Canada. Environment Canada, National Pollutant Release Inventory. PCB Waste Storage Site Inventory.

#### **Provincial Records**

MOECC Freedom of Information and Privacy Office. MOECC Municipal Coal Gasification Plant Site Inventory, 1991. MOECC document titled "Waste Disposal Site Inventory in Ontario". MOECC Brownfields Environmental Site Registry. Office of Technical Standards and Safety Authority, Fuels Safety Branch. MNR Areas of Natural Significance. MOECC Water Well Inventory. Chapman, L.J., and Putnam, D.F., 1984: 'The Physiography of Southern

Ontario, Third Edition', Ontario Geological Survey Special Volume 2.

#### **Municipal Records**

City of Ottawa Document "Old Landfill Management Strategy, Phase I -Identification of Sites", prepared by Golder Associates, 2004. The City of Ottawa Historical Land Use Inventory. Intera Technologies Limited Report "Mapping and Assessment of Former Industrial Sites, City of Ottawa", 1988. The City of Ottawa eMap website.

#### **Local Information Sources**

Plan of Survey, prepared by the City of Ottawa, February 2003. Personal Interviews.

#### **Public Information Sources**

Google Earth. Google Maps/Street View.

# FIGURES

FIGURE 1 – KEY PLAN

FIGURE 2 – TOPOGRAPHIC MAP

DRAWING PE2326-2 – SITE PLAN

DRAWING PE2326-3 – SURROUNDING LAND USE PLAN

#### 33 Monday $\mathcal{G}_{1}$ Lugione St Ver Charles Ferrace SITE 57 Nood St. Demander Rue Gent Qu<sup>3</sup>ic Hills Crescent Tim Rd Brasseut Crescen Pine Vista Valin Luesby Crescent **Vafa** 57 Inne Provence Ave Mulder Ave Celeste May Pure Joy M Soully Way Venus Me Ballantyne Of 30 Innes Rd Salzburg Dr 2 30 Lucile Solia Ave Crescent Janet Way Millen

FIGURE 1 KEY PLAN

# patersongroup






FIGURE 2 TOPOGRAPHIC MAP

# patersongroup -



# utocad drawings\environmental\pe23xx\pe2326\pe2326-1.d




'autocad drawings\environmental\pe23xx\pe2326\pe2326-2.

# **APPENDIX 1**

PLAN OF SURVEY

**AERIAL PHOTOGRAPHS** 

SITE PHOTOGRAPHS







# patersongroup -




# patersongroup -




patersongroup \_\_\_\_




patersongroup -



# patersongroup -



# patersongroup \_\_\_\_



# patersongroup -

#### Site Photographs



Part of Lot A, Concession 9, Geographic Township of Cumberland



Photograph 1: View of the subject site, facing east. Trim Road is present in the foreground. The subject site is currently vacant grassed land.



Photograph 2: View of the subject site, facing northeast. The subject site is flanked to the north and east by newer residential properties.

# patersongroup

#### Site Photographs



Part of Lot A, Concession 9, Geographic Township of Cumberland



Photograph 3: View of the subject site, facing southwest. The east portion of the subject site was observed to have some tree clippings and minor amount of non-hazardous solid waste present.



Photograph 4: View of the subject site, facing northwest. The east portion of the site was also noted to have two (2) fill piles present.

# patersongroup

# **APPENDIX 2**

MOECC FREEDOM OF INFORMATION SEARCH REQUEST

CITY OF OTTAWA HLUI REQUEST

**TSSA CORRESPONDENCE** 

**MOECC WATER WELL RECORDS** 



Ministry of Environment and Energy

## **Freedom of Information Request**

This form is for requesting documents which are in the Ministry's files on environmental concerns related to properties. Please refer to the guide on completion and use of this form. Our fax no. is (416) 314-4285.

Requester Data			For Ministry Use Only			
Name, Company Name, Mailing Address and Email Address of Requester			FOI Request No.			
Greg van Loenen		FOI Request No.				
Paterson Group Inc. 154 Colonnade Road		Fee Paid				
Ottawa, ON K2E 7J5				UISA/MC CASH		
Email address: gvanloenen@	patersongroup.ca					
<sup>Telephone/Fax Nos.</sup> Tel. 613-226-7381 Fax 613-226-6344	Your Project/Reference No. PE2326	Signature/Print /Name of Requester Greg van Loenen	□ CNR □ ER □ NOR □ SWR □ WCR □ SAC □ IEB □ EAA □ EMR □ SWA			
		Request Parameters	5			
Municipal Address / Lot, Concession, Geograp	hic Township (Municipal add	ress essential for cities, towns or regions)				
Part of Lot A, Concession 9,	, Geographic Townsh	ip of Cumberland				
Present Property Owner(s) and Date(s) of Ow	nership					
Ashcroft Homes						
Previous Property Owner(s) and Date(s) of Ov	vnersnip					
Present/Previous Tenant(s),(if applicable)						
Files older than 2 years may require	Search Parameters Files older than 2 years may require \$60.00 retrieval cost. There is no guarantee that records responsive to your request will be located. Specify Year(s) Requested					
Environmental concerns (General correspondence, occurrence reports, abatement) all						
Orders				all		
Spills				all		
Investigations/prosecutions	► Owner AND tena	nt information must be provided		all		
Waste Generator number/cl	asses			all		
	Certificate	s of Approval > Proponent infor	mation must be provided			
		h fees in excess of \$300.00 could be orting documents are also required		pes and years to be searched. Specify pe e.g. maps, plans, reports, etc.		
			SD	Specify Year(s) Requested		
air - emissions				1986-present		
water - mains, treatment, ground	level, standpipes & elevate	d storage, pumping stations (local & booste	er)	1986-present		
sewage - sanitary, storm, treatme	ent, stormwater, leachate &	leachate treatment & sewage pump station	าร	1986-present		
waste water - industrial discharg	ges			1986-present		
waste sites - disposal, landfill sit	es, transfer stations, proce	ssing sites, incinerator sites		1986-present		
waste systems - PCB destruct	1986-present					
pesticides - licenses				1986-present		

A \$5.00 non-refundable application fee, payable to the Minister of Finance, is mandatory. The cost of locating on-site and/or preparing any record is \$30.00/hour and 20 cents/page for photocopying and you will be contacted for approval for fees in excess of \$30.00.

Office Use Only							
Application Number:	Ward Number:	Application Receiv	ed: (dd/mm/yyyy):				
Client Service Centre Staff:		Fee Received:	\$				



## **Historic Land Use Inventory**

**Application Form** 

#### **Notice of Public Record**

All information and materials required in support of your application shall be made available to the public, as indicated by Section 1.0.1 of *The Planning Act*, R.S.O. 1990, C.P.13.

#### **Municipal Freedom of Information and Protection Act**

Personal information on this form is collected under the authority the *Planning Act*, RSO 1990, c. P. 13 and will be used to process this application. Questions about this collection may be directed by mail to Manager, Business Support Services, Planning Infrastructure and Economic Development Department, 110 Laurier Avenue West, Ottawa, K1P 1J1, or by phone at (613) 580-2424, ext. 24075

	Background Information						
*Site Address or Location:	Part 3, Part of Lot A, Concession 9, Geographic Township of Cumberland (City of Ottawa), ON.						
	* Mandatory Field						

#### **Applicant/Agent Information:**

Name:	Paterson Group							
Mailing Address:	154 Colonnade Rd South, Ottawa, C	DN						
Telephone: 613-226-7381		Email Address:	gvanloenen@patersongroup.ca					
Registered Property Owner Information:								
Name:	Jame: Ashcroft Homes (1070280 Ontario Inc.)							
Mailing Address:	18 Antares Drive, Ottawa, ON							
Telephone: 613-226-7266		Email Address:	kwatson@ashcrofthomes.ca					

	Site Details							
Legal Description and PIN:	Part of Lot A, Concession 9; (Geographic Township of Cumberland) City of Ottawa. PIN: 14526-0650							
What is the land currently used for?	Vacant							
<b>OR</b> Lot	Lot frontage:mLot depth:mLot area: $m^2$ ORLot area: (irregular lot)8,960 $m^2$ Does the site have Full Municipal Services:YesNo							
	Required Fees							
Please don't hesitate to visit <u>the Historic Land Use Inventory</u> website more information. Fees must be paid in full at the time of application submission.								
Planning Fee \$100.00								

Submittal Requirements

The following are required to be submitted with this application:

- 1. Consent to Disclose Information: Consultants and other third parties may make requests for information on behalf of an individual or corporation. However, if the requester is not the owner of the property, the requester must provide the City of Ottawa with a 'consent to disclose information' letter, signed by the property owner. This will authorize the City of Ottawa to release any relevant information about the property or its owner(s) to the requester. Consent for disclosure is required in the event that personal information or proprietary company information is found concerning the property and its owner. All consents must clearly indicate the name of the property owner as well as the name of the requester, and must be signed and dated.
- 2. Disclaimer: Requesters must read and understand the conditions included in the attached disclaimer and submit a signed disclaimer to the City of Ottawa's Planning, Infrastructure and Economic Development Department. This disclaimer is related to the Historic Land Use Inventory and must be received by the City of Ottawa, signed and dated by the requestor, before the process can begin.
- 3. A site plan or key plan of the property, its location and particular features.
- 4. Any significant dates or time frames that you would like researched.

#### Disclaimer For use with HLUI Database

CITY OF OTTAWA ("the City") is the owner of the Historical Land Use Inventory ("HLUI"), a database of information on the type and location of land uses within the geographic area of Ottawa, which had or have the potential to cause contamination in soil, groundwater or surface water.

The City, in providing information from the HLUI, to	Paterson Group	("the Requester") does so only under the following

conditions and understanding:

- The HLUI may contain erroneous information given that such records and sources of information may be flawed. Changes in municipal addresses over time may have introduced error in such records and sources of information. The City is not responsible for any errors or omissions in the HLUI and reserves the right to change and update the HLUI without further notice. The City does not, however, make any commitment to update the HLUI. Accordingly, all information from the HLUI is provided on an "as is" basis with no representation or warranty by the City with respect to the information's accuracy or exhaustiveness in responding to the request.
- 2. City staff will perform a search of the HLUI based on the information given by the Requester. City staff will make every effort to be accurate, however, the City does not provide an assurance, guarantee, warranty, representation (express or implied), as to the availability, accuracy, completeness or currency of information which will be provided to the Requester. The HLUI in no way confirms the presence or absence of contamination or pollution of any kind. The information provided by the City to the Requester is provided on the assumption that it will not be relied upon by any person whatsoever. The City denies all liability to any such persons attempting to rely on any information provided from the HLUI database.
- 3. The City, its employees, servants, agents, boards, officials or contractors take no responsibility for any actions, claims, losses, liability, judgments, demands, expenses, costs, damages or harm suffered by any person whatsoever including negligence in compiling or disseminating information in the HLUI.
- 4. Copyright is reserved to the City.
- 5. Any use of the information provided from the HLUI which a third party makes, or any reliance on or decisions to be based on it, are the responsibilities of such third parties. The City, its employees, servants, agents, boards, officials or contractors accept no responsibility for any damages, if any, suffered by a third party as a result of decisions made as a result of an information search of the HLUI.
- 6. Any use of this service by the Requestor indicates an acknowledgement, acceptance and limits of this disclaimer.
- 7. All information collected under this request and all records provided in response to this request are subject to the provisions of the Municipal Freedom of Information and Protection of Privacy Act, R.S.O. 1990, c. M.56, as amended.

Signed: Dated (dd/mm/yyyy): 29/11/2017 Per: Greg van Loenen (Please print name) Title: Environmental Consultant

#### **Greg van Loenen**

From:	Ruchi Chohan <rchohan@tssa.org> on behalf of Public Information Services <publicinformationservices@tssa.org></publicinformationservices@tssa.org></rchohan@tssa.org>
Sent:	December-01-17 2:00 PM
То:	Greg van Loenen
Subject:	RE: Records Search request for 1869 Trim Road, Ottawa

Hello Greg,

Thank you for your inquiry.

I have searched the below noted address (addresses) and I have located the following record:

1830 Trim Rd, Orleans has record of 2 expired underground fuel tanks

For a more detailed report including underground fuel storage tank details and copies of all inspection reports, please submit your request in writing to Public Information Services via e-mail (<u>publicinformationservices@tssa.org</u>) or through mail along with a fee of \$56.50 (including HST) per location. The fee is payable with credit card (Visa or MasterCard) or with a cheque made payable to TSSA.

Although TSSA believes the information provided pursuant to your request is accurate, please note that TSSA does not warrant this information in any way whatsoever.

Thank you and have a good day!

Ruchi

From: Greg van Loenen [mailto:GvanLoenen@Patersongroup.ca]
Sent: November 29, 2017 12:04 PM
To: Public Information Services <publicinformationservices@tssa.org>
Subject: Records Search request for 1869 Trim Road, Ottawa

Good afternoon,

Could you please complete a search of your records for underground/aboveground storage tanks, historical spills or other incidents/infractions for the following addresses for properties located in the City of Ottawa, ON:

1825 Trim Road

1830 Trim Road

1869 Trim Road

200 Prive de la Sittelle

226 Prive de la Sittelle

Thank you,

Regards,

Greg van Loenen, B.Eng. Environmental Consultant

Paterson Group Inc. T: 613-226-7381 C: 613-978-1181

This electronic message and any attached documents are intended only for the named recipients. This communication from the Technical Standards and Safety Authority may contain information that is privileged, confidential or otherwise protected from disclosure and it must not be disclosed, copied, forwarded or distributed without authorization. If you have received this message in error, please notify the sender immediately and delete the original message.

(🕅 Ontario	Ministry of the Environment	y Number (	14477		Well Record
Instructions for Comple		14571	unananut waanangee	Regulation 903 Ontari	o Water Resources Act page of
<ul> <li>For use in the Provinc</li> <li>All Sections must be c</li> </ul>	e of Ontario only. This docume ompleted in full to avoid delays	ent is a permanent le	er instructions and	l explanations are available o	n the back of this form.
<ul> <li>Questions regarding do</li> <li>All metre measureme</li> <li>Please print clearly in the second seco</li></ul>	ompleting this application can b ints shall be reported to 1/10 <sup>th</sup>	e directed to the Wat • of a metre.	er Well Managen	nent Coordinator at 416-23 Ministry Use Only	5-6203.
	n and Location of Well Info	rmation MUN	GAIL CO	DN CON	
Ottania	Carleton	Cira	mhala	nd	Q
RR#/Street Number/Name	rim Rd		Millage Lans		
8 3	Easting North 8 464367 50 Bedrock Materials (see inst	35991 N	Model Mode	of Operation: Undifferentiated,	
General Colour Most comm			Genera	I Description	Depth Metres From To
Grav	e				30.531.1
3					
			· · · · · · · · · · · · · · · · · · ·		
·				· · · · · · · · · · · · · · · · · · ·	
Hole Diameter Depth Metres Diameter		truction Record Wall Depth	Metres	I i diriping toot motion a	Down Recovery
From To Centimeter	centimetres	thickness centimetres From	То	Subpump min	ater Level     Time     Water Level       Metres     min     Metres       7,94     7,94
	Steel Fibreglass	Casing		(metres) Level / Pumping rate - 1	7.93 1 7.70
Water Record Water found Kind of Water	- IS.88 Plastic Concrete Galvanized	-48 0	30.8	Duration of pumping 2	94 2 7.70
at Metres				Final water level end 3 of pumping metres	3
	Steel Fibreglass		• .	Recommended pump 4 type. Shallow Deep Recommended pump 5	5
Gas Salty Minera	Galvanized	Screen		deptb2//metres Recommended pump 10	10
Gas Salty Minera	ats Outside Steel Fibreglass	Slot No.		rate. (litres/min) 15 If flowing give rate - 20	15 20
After test of well yield, water was Clear and sediment free Other, specify	Galvanized	Casing or Screen	- 	(litres/min) 25 If pumping discontin- ued, give reason. 40	25 30 40
Chlorinated Yes No	Open hole	30	2 31-1	50	50 50 60 1-70
	Sealing Record Annula type (bentonite slurry, neat cement slurry	Note Volume Placed	In diagram below	Location of Well w show distances of well from road	, lot line, and building.
From Io	tonite slurry	(cubic metres)	Indicate north by	•	of TN
				300' Trim 1350' Inr	
		*			reordi
	Method of Construction ary (air) Diamond	Digging	-		
Rotary (cohventional)	percussion Jetting ing Driving Water Use	Other			
Stock	ustrial			A APAN Date Well (	Completed
Irrigation Mur Water Supply Recharg	Final Status of Well	air conditioning		14538 22	204 DO18
Observation well Abandor Test Hole Abandor	ned, insufficient supply Dewatering ned, poor quality Replaceme Contractor/Technician Informati	ent well	package delivere	Ministry Use Only	Sec.
Name of Well Contractor	illing Coltd"	Vell Contractor's Licence No		Contractor	1118
Businese dcress (street name h		Vell Technician's Licence No	Date Received	0 8 2004   DD Date of Insp Well Recor	
Signature of Jechnician/Contract	Shannon		e		534760
X 10-10-10-10-10-10-10-10-10-10-10-10-10-1	Contractor's Copy 🗋 N	Ainistry's Copy & Well	Swner's Copy		est disponible en français

	ma			NVIRONMENT Resources Ac	ct.	319/	$\mathcal{P}$	<u>2</u>
		ATER V	WEL	L R	ECOR	D /6	k j	<u>2</u> K. (. <b>3</b>
Ontario	1. PRINT ONLY IN S	SPACES PROVIDED ECT BOX WHERE APPLICABLE		1515855	150	LL Čgi	V	<b></b>
COUNTY OR DIS		township, Borough. cit			CON., BLOCK, TRACT. S	URVEY ETC.		LOT 25-27
Car	1 AT ON	s 1		Ont		DATE COMPL		48-53
		035	Navan. $500$	0285	4 26 L			
	LC		N AND BEDRO	26 DCK MATERIAL	30 31			
GENERAL COL	OUR COMMON MATERIAL	OTHER MA	ATERIALS		GENERAL DESCRIPTIO	N	FROM	TO
yello	-						0 18	18 98
blue grey	clay gravel						98	105
grey	limestone						105	110
					194			
		JAW						
		13						
· ·		/ <b>C</b> -9	<b>[</b> ]					
			<b>y</b>					
	2018505 11 0.09	8305 010	5211	0110215				
	WATER RECORD	51 CASING &			54 SIZE(S) OF OPENING (SLOT NO.)	31-33 DIAMET	ER 34-38	75 80 LENGTH 39-40
WATER FOUND FEET	KIND OF WATER	INSID DIAM. MATERIAL INCHES		DEPTH - FEET	MATERIAL AND TYPE		INCHES DEPTH TO TOP OF SCREEN	FEET 41-44 80
0110	2 SALTY 4 MINERAL	10-11 X STEEL 2 GALVANIZED 3 CONCRETE	<sup>12</sup> 188 C	) <b>p106</b> <sup>13-16</sup>	S			FEET
20-23	2 SALTY 4 MINERAL	4 □ OPEN HOLE 17-18 1 □ STEEL	19	20-23	61 PLUGO	MATERIAL AND	TYPE ICEM	ENT GROUT. PACKER, ETC.)
25-28	2 SALTY 4 MINERAL	2 🗋 GALVANIZED 3 🗍 CONCRETE 4 🗍 OPEN HOLE			10-13 14-17			·
30-33	2 SALTY 4 MINERAL 1 FRESH 3 SULPHUR 34.60	24-25 1 🗋 STEEL 2 🗍 GALVANIZED 3 🗌 CONCRETE	26	27-30	18-21 22-25 26-29 30-33	80	-	
	2 SALTY 4 MINERAL	4 OPEN HOLE	PUMPING	] [		OF WELI		
	IC WATER LEVEL 25	GPN 01 H	5-16 00 17-18 oursMINS.		GRAM BELOW SHOW DIST	ANCES OF WELL		AND
	EL PUMPING 19-21 22-24 15 MINUTES 26-2	30 MINUTES 45 MINUTE 24 29-31	RECOVERY 55 60 MINUTES 32-34 35-37			F	1	NA.
	IG, 38-41 PUMP INTAKE		FEET 015 FEET		SC 1	<b>The Control of Control of Sol</b> Control of Sol Control of S	ander franker i Maria i si	j/
AP	GPM . IDED PUMP TYPE RECOMMENDED		D 46-49		2 P		, A	Y
50-53	HALLOW DEEP SETTING	2 30 FEET RATE OC	010 gpm		· //	λ.	7	
FINA		5 🗌 ABANDONED, INS LL 6 🗌 ABANDONED, POC	,		J B is N			
STAT OF W	ELL 4 RECHARGE WELL	7 UNFINISHED		¥	× I.Skin J	1 30/	, general da se	
- WAT	ER 1 3 I IRRIGATION	5 🗌 COMMERCIAL 6 🗋 MUNICIPAL 7 🔲 PUBLIC SUPPLY		, <b>m</b> . 4	na na anna an tao anna an taonachta anna an tao anna ann ann			
USI	E V 4 🗆 INDUSTRIAL	8  COOLING OR AIR CON	IDITIONING OT USED					
METH					317	NAL	ALN3	
		E) 8 D JETTING 9 DRIVING		DRILLERS REMARKS	e.	L	MIN.	
	well convencion		LICENCE NUMBER		58 CONTRACTOR 1504	59-62 DATE RECEIVED	8 03 7	7 63-68 80
ADDRESS				AINO BS			3031	
	DRILLER OR BORER	JI TEGHS JUHU	LICENCE NUMBER	D RENAKS:	1(		.	295
Signatu	Bourgeois RE OF CONTRATOR	SUBMISSION DATE	<u>8 y</u> 76	OFFICE		C\$\$.\$8		WI
M	INISTRY OF THE ENV			L.,	<u></u>	<u> </u>	FORM	7 MOE 07-091

011 \6. 31G/	6 S	507		un gera - onnadas - segnisation (°1224) 1995 - Jack Martinet, segnisation (*1224)	
UTM0 1 1 8 2 41641 1118 E			1512776	56 <sup>51</sup> N	• <u>5</u> 73
15 R 501315161/15 N			3 9	1 13	
Elev. $5 \mathbb{R}$ $0 + 2 + 8 + 5$			tention Act 1057	e examinado	a 🚺 🔪
Basin 215 The Ontario	Water Kesou	rces Comm	ission Act, 1957	TUBERS STOR	s sem "
	CR WE	LL I	RECORI	)	
			Village, Town or		5 h h
County or District Russell					
ана стана (т. 1997). Спорта на стана стана (т. 1997). Спорта на стана стана стана (т. 1997).			pleted March. (day	month Ottawa	
		dress	21 WIICH DU		
Casing and Screen Record				nping Test	
Inside diameter of casing		1	vel		
Total length of casing 94'			mping rate7		
Type of screen			g level <sup>2</sup> n of test pumping		
Length of screen			n of test pumping clear or cloudy at o		
Depth to top of screen	2"		nended pumping		
Diameter of finished hole		1	pumping level of		
Well Log				ter Record	
			Depth(s) at which	No. of feet	Kind of water
Overburden and Bedrock Record	From ft.	To ft.	water(s) found	water rises	(fresh, salty, sulphur)
Blue Clay	0'	90'			
Gravel	<u> </u>	94'	94'	76'	Fresh
			-	-	
					1
For what purpose(s) is the water to be used?			Loca	tion of Well	$\mathcal{N}$
Domestic			In diagram below		
Is well on upland, in valley, or on hillside?	Up	1	road and lot line	. Indicate north	by arrow.
	_			ANADA	Ne
Drilling Firm			TRANS		
				OLD 17	
Address	••••••			<u></u>	
					ş
Licence Number				Ċ	
Name of Driller Gerard Charbonneau Orleans Ont		· · · · · · · · · · · · · · · · · · ·	3	····	KONARÞ
Address			N	n N	ARÞ
Date				" B	32
Gerard Charbonne	-				X 33
Signature of Licensed Drilling Contractor	r)		50	A	
			CHARTE	pr12	No.
Form 5 15M-58-4149			ICHIM"	CS	5.58
c · · ·				•	

# **APPENDIX 3**

**QUALIFICATIONS OF ASSESSORS** 

## Mark S. D'Arcy, P. Eng.

# patersongroup

Geotechnical Engineering

Environmental Engineering

Hydrogeology

Geological Engineering

**Materials Testing** 

**Building Science** 

Archaeological Services

#### POSITION

Associate and Supervisor of the Environmental Division Senior Environmental/Geotechnical Engineer

#### EDUCATION

Queen's University, B.A.Sc.Eng, 1991 Geotechnical / Geological Engineering

#### **MEMBERSHIPS**

Ottawa Geotechnical Group Professional Engineers of Ontario

#### **EXPERIENCE**

1991 to Present **Paterson Group Inc.** Associate and Senior Environmental/Geotechnical Engineer Environmental and Geotechnical Division Supervisor of the Environmental Division

#### SELECT LIST OF PROJECTS

Mary River Exploration Mine Site - Northern Baffin Island Agricultural Supply Facilities - Eastern Ontario Laboratory Facility – Edmonton (Alberta) Ottawa International Airport - Contaminant Migration Study - Ottawa Richmond Road Reconstruction - Ottawa Billings Hurdman Interconnect - Ottawa Bank Street Reconstruction - Ottawa Environmental Review - Various Laboratories across Canada - CFIA Dwyer Hill Training Centre - Ottawa Nortel Networks Environmental Monitoring - Carling Campus - Ottawa Remediation Program - Block D Lands - Kingston Investigation of former landfill sites - City of Ottawa Record of Site Condition for Railway Lands - North Bay Commercial Properties - Guelph and Brampton Brownfields Remediation - Alcan Site - Kingston Montreal Road Reconstruction - Ottawa Appleford Street Residential Development - Ottawa Remediation Program - Ottawa Train Yards Remediation Program - Bayshore and Heron Gate Gladstone Avenue Reconstruction - Ottawa Somerset Avenue West Reconstruction - Ottawa

## Greg van Loenen, B. Eng.

#### Geotechnical Engineering

Environmental Engineering

Hydrogeology

Geological Engineering

**Materials Testing** 

**Building Science** 

Archaeological Services

#### POSITION

**Environmental Consultant** 

#### **EDUCATION**

Carleton University, B.Eng., 2015 Environmental Engineering

St. Lawrence College, 2008 Environmental Technician

#### **EXPERIENCE**

2016 to Present **Paterson Group Inc.** Environmental and Geotechnical Division Environmental Consultant

2015 to 2016 **Kanellos Consulting Inc.** Environmental Consultant

Summers 2013 & 2014 **GFL Environmental Inc.** Environmental Technician

2008 to 2011, summer 2012 **Petroleum Enviro Services (Div. of ASM Corrosion Control)** Environmental Consultant

#### SELECT LIST OF PROJECTS

Nortex Industrial Site - Soil and Groundwater Remediation - Kingston, ON Contaminated Soil and Groundwater Sampling - Various sites - Eastern ON Designated Substance Surveys and Reports - Various sites - Eastern ON Mould Sampling, Assessments and Reports - Various sites - Eastern ON Surcharge and Settlement Surveys - Ottawa, ON Tank Site Remediation Program - Various sites - Alberta Tank Installation Drawings (PTMAA) - Various sites - Alberta

# patersongroup