Geotechnical Engineering

Environmental Engineering

Hydrogeology

Geological Engineering

Materials Testing

Building Science

Archaeological Services

patersongroup

Phase I Environmental Site Assessment

1655 Carling Avenue Ottawa, Ontario

Prepared For

Surface Developments

Paterson Group Inc.

Consulting Engineers 154 Colonnade Road South Ottawa (Nepean), Ontario Canada K2E 7J5

Tel: (613) 226-7381 Fax: (613) 226-6344 www.patersongroup.ca October 11, 2019

Report: PE4229-1



TABLE OF CONTENTS

EXE	CUTIV	/E SUMMARY	i	
1.0	INTR	ODUCTION	1	
2.0	PHAS	SE I PROPERTY INFORMATION	2	
3.0	SCOPE OF INVESTIGATION			
4.0	RECORDS REVIEW		4	
	4.1	General	4	
	4.2	Environmental Source Information	6	
	4.3	Physical Setting Sources	10	
5.0	INTE	RVIEWS	12	
6.0	SITE RECONNAISSANCE			
	6.1	General Requirements	13	
	6.2	Specific Observations at the Phase I Property	13	
7.0		EW AND EVALUATION OF INFORMATION		
		Land Use History		
	7.2	Conceptual Site Model	17	
8.0	CON	CLUSIONS	19	
9.0	STAT	EMENT OF LIMITATIONS	21	
10.0	RFFF	FRENCES	22	

List of Figures

Figure 1 - Key Plan

Figure 2 - Topographic Map

Drawing PE4229-1 - Site Plan

Drawing PE4229-2 – Surrounding Land Use Plan

List of Appendices

Appendix 1 Aerial Photographs

Appendix 2 MECP Freedom of Information Request

City of Ottawa HLUI application

Water Well Records TSSA Correspondence

Appendix 3 Qualifications of Assessors



EXECUTIVE SUMMARY

Assessment

Paterson Group was retained by Surface Developments to conduct a Phase I Environmental Site Assessment (Phase I-ESA) of 1655 Carling Avenue, in the City of Ottawa, Ontario. The purpose of this Phase I – Environmental Site Assessment was to research the past and current use of the site and study area and to identify any environmental concerns with the potential to have impacted the subject properties.

The subject site comprised a vacant/agricultural plot until 1956 when the subject site was developed for the Aladdin Motel. In 1987 this changed to the West Park Motor Inn until 1992 when the motel was demolished. On demolition, an AST located in the basement was found to have leaked. This tank represents an APEC on the subject site. Previous investigations by Paterson and others have found the subject site to be impacted by hydrocarbons including PHCs, BTEX and PAHs.

The lands surrounding the subject site were historically used for residential, north of carling Avenue and were commercial in use, south of Carling Avenue. Several PCAs have been identified including several retail fuel outlets, a UST at the neighbouring 1619 Carling Avenue, Minutemen Press Printers, the Sheridan Equipment property and various muffler and auto service centres. Of these, 1619 Carling Avenue and 1607 Carling Avenue (Shell retail fuel outlet) were considered to be up gradient and therefore identified as APECs. USTs are known to have leaked at both properties in the past.

Following the historical review, a site visit was conducted. The site is currently used as a parking lot. No further PCAs or APECS were identified.

The following Areas of Potential Environmental Concern (APECs) were identified with regard to the subject site;

Former AST in the basement of the historical motel which leaked;
Former UST located at 1619 Carling Avenue;
Former and current USTs located at 1607 Carling Avenue (Shell retail fuel outlet).

Recommendations

Based on the results of the Phase I - Environmental Site Assessment, it is our opinion that a Phase II - Environmental Site Assessment is required for the subject site.



1.0 INTRODUCTION

At the request of Surface Developments, Paterson Group (Paterson) conducted a Phase I Environmental Site Assessment (Phase I ESA) for 1655 Carling Avenue, in the City of Ottawa, Ontario. The purpose of this Phase I ESA was to research the past and current use of the site and study area and to identify any environmental concerns with the potential to have impacted the subject property.

Paterson was engaged to conduct this Phase I ESA by Mr. Jakub Ulak of Surface Developments whose offices are located at 88 Spadina Avenue, Ottawa.

This report has been prepared specifically and solely for the above noted project which is described herein. It contains all our findings and results of the environmental conditions at this site.

This Phase I-ESA report has been prepared in general accordance with the requirements of Ontario Regulation 153/04, as amended under the Environmental Protection Act, and also complies with the requirements of CSA Z768-01. The conclusions presented herein are based on information gathered from a limited historical review and field inspection program. The findings of the Phase I - ESA are based on a review of readily available geological, historical and regulatory information and a cursory review made at the time of the field assessment. The historical research relies on information supplied by others, such as local, provincial and federal agencies and was limited within the scope-of-work, time and budget of the project herein.

Report: PE4229



2.0 PHASE I PROPERTY INFORMATION

Address: 1655 Carling Avenue, Ottawa, Ontario.

Property Identification

Number:

04012-0101

Location: The subject site is located on the north side of Carling

Avenue, around 75 m west of the intersection

between Carling Avenue and Churchill Avenue, in the

City of Ottawa Ontario.

Latitude and Longitude: 45° 22' 48" N, 75° 44' 54" W;

Site Description:

Configuration: Rectangular.

Site Area: 0.35ha (approximate).

Zoning: AM10 – Arterial Main-street.

Current Use: The subject site is currently a gravel-surfaced parking

lot.

Services: The subject site is located in a municipally serviced

area.

Report: PE4229



3.0 SCOPE OF INVESTIGATION

The scope of work for this Phase I – Environmental Site Assessment was as follows:

- Determine the historical activities on the subject site and study area by conducting a review of readily available records, reports, photographs, plans, mapping, databases and regulatory agencies;
- Investigate the existing conditions present at the subject site and study area by conducting site reconnaissance;
- Conduct interviews with persons knowledgeable of current and historic operations on the subject property, and if warranted, neighbouring properties;
- Present the results of our findings in a comprehensive report in general accordance with the requirements of Ontario Regulation 269/11 amending O.Reg. 153/04 made under the Environmental Protection Act and in compliance with the requirements of CSA Z768-01;
- Provide a preliminary environmental site evaluation based on our findings;
- Provide preliminary remediation recommendations and further investigative work if contamination is suspected or encountered.

Report: PE4229 October 11, 2019



4.0 RECORDS REVIEW

4.1 General

Phase I-ESA Study Area Determination

A radius of approximately 250 m was determined to be appropriate as a Phase I ESA study area for this assignment. Properties outside the 250 m radius are not considered to have impacted the subject land, based on their significant distance from the site.

First Developed Use Determination

Based on the available sources, including previous engineering reports, the property appears to have been first developed in 1956 as a motel.

Fire Insurance Plans

Fire insurance plans (FIP) from 1925 and 1956 were reviewed for the subject site and surrounding area.

The 1925 FIP shows the subject site and lands immediately north, east and west are vacant. No Potentially Contaminating Activities (PCAs) are identified in the subject area.

In the 1956 FIP, the subject site is labelled as the Aladdin Motel with four separate buildings shown. The lands immediately north of the subject site are developed with apartment blocks, while to the west of the subject site, a commercial building (Sheridan Equipment Ltd.; bulldozers, etc.) is identified. Three corners of the intersection between Carling Avenue and Churchill Avenue were occupied by retail fuel outlets; 1607 Carling Avenue occupies the northwest corner, 1596 Carling Avenue the southeast corner and 1599 Carling Avenue the northeast corner. The Sheridan Equipment property is hot considered to represent an Area of Potential Environmental Concern (APEC) given the westward groundwater flow direction (discussed later in this report). The retail fuel outlets located at the corners of the intersection between Carling Avenue and Churchill Avenue are considered to be PCAs with the nearest RFO at 1607 Carling Avenue also comprising an Area of Potential Environmental Concern (APEC).

City of Ottawa Street Directories

City directories at the National Archives were reviewed at around 10-year intervals, from 1949 to 2011 as part of the Phase I ESA.

Report: PE4229

Ottawa, ON



A summary of Potentially Contaminating Activities on the site and in the Phase I study area is provided in the table below.

Table 1: City Directories – Potentially Contaminating Activities (PCA) in Phase I Study Area			
Address	Listed Activity (years listed)	Distance / Orientation from site	APEC (Y/N)
1621 Carling Avenue and 1607 Carling Avenue	Shell Canada Products (2010) 7/11 Food and Gas Bar (1980-1988) Otto's Service Station (1970) White Rose Service Station (1955)	30m east	Yes
1659 Carling Avenue	Minutemen Press Printers (1988)	30m west	No
1650 Carling Avenue	Turpin Saturn, Saab, Isuzu sales and service (2000)	40m south	No
1604 Carling Avenue	Richards Texaco Service Station (1970) Moreland's Texaco Service Station (1960) Ouderkirk service Station (1955)	85m east	No
1666 Carling Avenue	Turpin Pontiac, Buick, GMC sales and service (1980-2000)	100m southwest	No
1688 Carling Avenue	Mister Muffler (2000) Custom Muffler Ltd. (1980)	160m southwest	No

The directories first record the street addresses of 1655 as being occupied by the Aladdin Motel in 1957.

The retail fuel outlets (RFOs) at civic addresses 1621 Carling Avenue and 1607 Carling Avenue (Shell RFO) are the same property, located at the northwest corner of the intersection between Carling Avenue and Churchill Avenue. It is not clear if this represents an error in the records or if an address adjustment was made, however from this point onwards the Shell retail fuel outlet will be referred to by the current address, 1607 Carling Avenue.

Of the PCAs listed in Table 1, only 1607 Carling Avenue is considered to represent a potential APEC. Minutemen Press Printers, located at 1659 Carling Avenue, is believed to have been a 'copy shop' and not a main printing operation for the company. The remaining off-site PCAs do not represent an environmental concern given their separation distance and/or cross or down gradient location from the subject site.

Report: PE4229



4.2 Environmental Source Information

Environment and Climate Change Canada

A search of the National Pollutant Release Inventory (NPRI) was conducted electronically on October 1, 2019. The subject site was not listed in the NPRI database. One record of pollutant release was listed in the database, relating to Saputo Foods Ltd., located 250m south of the subject property. The Inventory describes the disposal of 17.35 tonnes of "Nitrate ion". This inventory item is not considered to represent an environmental concern on the subject site.

PCB Inventory

A search of national PCB waste storage sites was conducted. No PCB waste storage sites were identified on the subject site or within a 250m radius.

Ontario Ministry of Environment (MECP) Instruments

A request was submitted to the MECP Freedom of Information office for information with respect to certificates of approval, permits to take water, certificates of property use or any other similar MECP issued instruments for the site. At the time of issuance of this report, a response had not been received. A copy of the response will be forwarded to the client, should it contain any pertinent information.

MECP Coal Gasification Plant Inventory

The Ontario Ministry of Environment document titled "Municipal Coal Gasification Plant Site Inventory, 1991" was reviewed to reference the locations of former plants with respect to the site. No coal gasification plants were identified within the Phase I study area.

MECP Incident Reports

A request was submitted to the MECP Freedom of Information office for information with respect to records concerning environmental incidents, orders, offences, spills, discharges of contaminants or inspections maintained by the MECP for the site or adjacent properties. At the time of issuance of this report, a response had not been received. A copy of the response will be forwarded to the client, should it contain any pertinent information.



MECP Waste Management Records

A request was submitted to the MECP Freedom of Information office for information with respect to waste management records. At the time of issuance of this report, a response had not been received. A copy of the response will be forwarded to the client, should it contain any pertinent information.

MECP Submissions

A request has been submitted to the MECP Freedom of Information office for information with respect to reports related to environmental conditions. At the time of issuance of this report, a response had not been received. A copy of the response will be forwarded to the client, should it contain any pertinent information.

MECP Brownfields Environmental Site Registry

A search of the MECP Brownfields Environmental Site Registry was conducted as part of this assessment for the site, neighbouring properties and the general area of the site. No Record of Site Condition (RSC) was found for the subject site or neighbouring properties.

MECP Waste Disposal Site Inventory

The Ontario Ministry of Environment document titled "Waste Disposal Site Inventory in Ontario, 1991" was reviewed as part of the historical research. This document includes all recorded active and closed waste disposal sites, industrial manufactured gas plants and coal tar distillation plants in the Province of Ontario. No waste disposal sites were identified within the Phase I study area.

Areas of Natural Significance Interest (ANSI)

A search for areas of natural significance and features within the Phase I study area was conducted on the web site of the Ontario Ministry of Natural Resources (MNR) on October 1, 2019. The search did not reveal any natural features or areas of natural significance within the Phase I study area.

Technical Standards and Safety Authority (TSSA)

The TSSA, Fuels Safety Branch in Toronto, was contacted on October 1, 2019, to inquire about current and former underground storage tanks, spills and incidents for the subject and neighbouring properties. No records were found for the subject site.



The response returned information for 1607 Carling Avenue, a retail fuel outlet currently operated by Shell. The property is reported to have three active liquid fuel tanks and a facility recorded. Six expired instances are also noted.

At least one tank at 1607 Carling Avenue is known to have leaked historically. These tanks represent a PCA and APEC.

City of Ottawa Landfill Document

The document entitled "Old Landfill Management Strategy, Phase I – Identification of Sites, City of Ottawa", was reviewed. No former waste disposal sites were located within the Phase I study area.

City of Ottawa Historical Land Use Inventory

A search of the City's Historical Land Use Inventory (HLUI 2005) database for the subject property was conducted as part of the Phase I ESA. At the time of issuance of this report, a response had not been received. A copy of the response will be forwarded to the client, should it contain any pertinent information.

Previous Engineering Reports

The following reports were reviewed prior to conducting this assessment:

□ "Phase I and II - Environmental Site Assessment, Former Aladdin Motel, 1655 Carling Avenue, Ottawa, Ontario", prepared by John D. Paterson & Associates Ltd., dated September 26, 1994.

A former heating oil underground storage tank (UST) located at 1619 Carling Avenue was known to have leaked. The UST was located approximately 4m to 5m east of the eastern boundary of the subject site. The Phase I and II ESA was completed to assess whether the shallow soils on the subject site had been impacted. Two boreholes were completed. Vapour readings indicated the soils had not been impacted. No further investigation was recommended.

□ "PE1472-FAX.01 Phase II - Environmental Remediation Cost Estimate, 1655 Carling Avenue, Ottawa, Ontario", prepared by Paterson Group, dated November 5, 2008.

Paterson completed a Phase II ESA comprising fifteen (15) test pits and six (6) boreholes, four (4) of which were installed with groundwater monitoring wells. Soil testing was completed to assist in delineating the PHC and BTEX contamination ahead of estimating the cost of remediation.



□ "Technical Review of Various Reports by Golder Associates Ltd. 1655 Carling Avenue, Ottawa, Ontario" prepared by Kollaard Associates, dated December 14, 2015

Kollaard Associates undertook a technical review of several reports completed by Golder Associates between September 2001 and March 2006. The review concluded that six (6) wells were installed in boreholes drilled across three phases of investigation and supplemented by numerous test pits and test trenches.

Across several investigations, Golder determined the groundwater to be flowing in a generally west and northwest direction.

Hydrocarbon contamination (PAH, TPH gas diesel and TPH heavy oil), in excess of the standards of the time, was identified in soil samples tested. Soil impacted with PHC and PAH concentrations exceeding the applicable standards was generally located across the eastern half of the Phase I Property. Groundwater across the eastern third of the subject site was also found to be impacted but no applicable standards were available at the time. The source of the contamination was believed to be the former UST located at 1619 Carling Avenue and former above ground storage tanks (AST) located in the basement of the former Aladdin Motel/West Park Motor Inn motel at 1655 Carling Avenue. Golder reportedly undertook a magnetic survey anomaly investigation and concluded no USTs were present.

Kollaard Associates noted that no works were known to have occurred at the property between 2006 and their assessment of 2015 and recommended an updated Phase I and II ESA be completed to identify any environmental concerns that may have occurred in the interim and confirm the levels of contamination.

"Limited Groundwater Sampling and Testing of Existing Boreholes Technical Review of Various Reports by Golder Associates Ltd. 1655 Carling Avenue, Ottawa, Ontario" prepared by Kollaard Associates, dated December 14, 2015

Kollaard Associates visited the subject site with the intention of sampling and testing the groundwater so as to confirm the levels of contamination present. Four (4) wells were located, three installed by Golder Associates and one (1) by another company. No free product was detected however a strong hydrocarbon odour was noted in one or more wells. The results exceeded the applicable standards in all four samples tested PHC. Two samples also exceeded the applicable standards for selected PAH contaminants.

Report: PE4229



Chain of Title

Based on a review of the City Directories, aerial photographs and previous engineering reports, the Phase I Property has seen very limited development other than the construction and demolition of the motel. Chain of Title information was not ordered as it was deemed that the other information from the records review would satisfy the objectives of the records search and that the information provided in a Chain of Title would not contribute additional environmental information relevant to the Phase LESA.

4.3 Physical Setting Sources

Aerial Photographs

Historical air photos from the National Air Photo Library were reviewed in approximate ten (10) year intervals. The review period dates back to the first available air photos for the site. Based on the review, the following observations have been made:

The subject site is a vacant parcel of possibly agricultural land, bound on the southern side by Carling Avenue. The surrounding lands appear to be agricultural in use with fields and occasional agricultural buildings present.

The site is occupied by the Aladdin Motel at this time. The buildings occupy the majority of the subject site. The surrounding area generally comprises residential land however a commercial property (a possible garage or car sales centre) located south of the subject site fronts onto Carling Avenue. Retail fuel outlets can be seen at the northwest, northeast and southeast corners of the intersection between Carling Avenue and Churchill Avenue. To the west of the subject site, a property labelled in the 1956 FIP as "Sheridan Equipment Ltd.; bulldozers, etc." can be seen.

No significant changes appear to have been made to the subject site.

To the east of the subject site, a commercial building (Hakim Optical) has been constructed.

No significant changes appear to have been made to the subject site. The Sheridan Equipment property, west of the subject site, has been developed into a strip mall of commercial shops.



1999	The motel buildings have been demolished with the subject site used as a parking lot at this time. The motel is known to have been demolished in 1992. The retail fuel outlets located at the northeast and southeast corners of the intersection between Carling Avenue and Churchill Avenue can no longer be identified. Commercial development has continued on the properties fronting on to Carling Avenue, particularly south and west of the subject site.
2002	No significant changes appear to have been made to the subject site or surrounding area.
2011	No significant changes appear to have been made to the subject site. Commercial development has continued south of Carling Avenue with the demolition of a building (known to have previously been a bank) at the southwest corner of the intersection between Carling Avenue and Churchill Avenue and the construction of a Canadian Time Superstore and pizza restaurant.
2017	No significant changes appear to have been made to the subject site or surrounding area.

Laser copies of selected aerial photographs reviewed are included in Appendix 1.

Topographic Maps

Topographic maps were obtained from Natural Resources Canada - The Atlas of Canada website. The topographic maps indicate that the subject site and surrounding area are generally flat-lying with a possibly slight downwards slope to the west. An illustration of the referenced topographic map is present in Figure 2 - Topographic Map following the body of this report.

Physiographic Maps

A Physiographic Map was reviewed from the Natural Resources Canada - The Atlas of Canada website. According to this physiographic map, the site is located in the St. Lawrence Lowlands. According to the mapping description provided: "The lowlands are plain-like areas that were all affected by the Pleistocene glaciations and are therefore covered by surficial deposits and other features associated with the ice sheets." The subject site is located in the Central St. Lawrence Lowland, "where the land is rarely more than 150 m above sea level, except for the Monteregian Hills, which consist of intrusive igneous rocks".



Geological Maps

The Geological Survey of Canada website on the Urban Geology of the National Capital Area was consulted as part of this assessment. Based on the information from NRCAN, bedrock in the area of the site consists of limestone, dolostone, shale, arkose, sandstone of the Ottawa Group. Based on the maps, the thickness of overburden is anticipated to be around 2 m and consists of fine-textured glaciomarine deposits. Groundwater is expected to be encountered in the bedrock at around 2m to 3m below the existing ground level.

Water Well Records

A search of the MECP's web site for all drilled well records within 250 m of the subject site was conducted on October 3, 2019. The search identified 100 records in the subject area. Of these, six (6) are records of water supply wells dating from 1949 and 1960. The remainder of the wells consisted of observation and monitoring well records, the majority of which detail monitoring wells located at the former RFO at 1599 Carling Avenue.

No wells were depicted as being on the subject site however the nearest recorded well to the subject site detailed the potable water supply well for the Aladdin Motel and dated from 1956.

Given the municipally supplied area and age of the wells, all private water wells are assumed to be obsolete.

The well records indicate a surficial clay overburden of around 4 feet (1.2m) depth, overlying limestone bedrock.

Water Bodies and Areas of Natural Significance

There are no water bodies or areas of natural and scientific interest, on the subject site or within the study area.

5.0 INTERVIEWS

Given the wealth of information from the previous investigations at the property, an interview was not conducted as it was not considered to add any significant detail to the understanding of the properties' use or environmental condition.



6.0 SITE RECONNAISSANCE

6.1 General Requirements

The site assessment was conducted on October 8, 2019. Weather conditions were clear, with a temperature of approximately 16°C. Mr. Philip Price from the Environmental Department of Paterson Group conducted the site visit. In addition to the site, the uses of neighbouring properties within the Phase I study area were also assessed at the time of the site reconnaissance.

6.2 Specific Observations at the Phase I Property

Site Features

The subject site operates as a parking lot, surfaced with gravel. Surface water infiltrates directly into the ground and drains to catch basins on Carling Avenue. Adjacent properties are approximately at grade with respect to the subject site. No structures were noted on the subject site.

Below Ground Structures

Given the historic presence of buildings on the site, relict structures may be encountered, including foundations, basement slabs and abandoned utilities.

Potable Water Source

The phase I study area is municipally serviced.

Potential Environmental Concerns

■ Underground Utilities


The site may be served by electrical and sewer utilities with numerous catch located along Carling Avenue.

□ Ground Surface

The ground surface across the majority of the subject site consists of gravel. No signs of staining or stressed vegetation were noted on the subject site.

□ Railway Lines

No railway lines were observed on the subject site or within the Phase I ESA study area.





	Polycl	nlorinated Biphenyls (PCBs)
	No trar	nsformers or sources of PCBs were identified on-site.
	Unide	ntified Substances
		were no unidentified substances on the subject property at the time assessment.
	Waste	Storage and Disposal
	No wa	ste generation or storage was noted on the subject site.
Othe	r Poteni	tial Environmental Concerns
	Storag	e Tanks
	No fue	ls or chemical storage was noted on the subject site.
	Waste	water Drainage
	Waste	water drains into the City of Ottawa sewer system.
Neig	hbourin	g Properties
acce	ssible ro	n of the neighbouring properties was conducted from publicly adways at the time of the site inspection. Land use adjacent to the as as follows:
	lorth -	Residential multi-tenant apartment buildings (including private storage garages) followed by Tillbury Avenue with further Residential land use beyond.
□ S	South -	Carling Avenue followed by commercial land (including a car dealership, restaurant and superstore) with parking lots and further commercial land beyond.
□ E	ast -	Vacant land followed by a retail fuel outlet followed by Churchill Avenue.
□ V	Vest -	Commercial retail land (including restaurants and service and health providers), followed by Coal Avenue.
		thin the Phase I study area is shown on Drawing PE4229-2 -

Report: PE4229 October 11, 2019

Ottawa, ON



7.0 REVIEW AND EVALUATION OF INFORMATION

7.1 Land Use History

The following table indicates the current and past uses of the site dating back to the first developed use of the site.

Table 2: Land Use History			
Time Period	Land Use	Potentially Contaminating Activities	Areas of Potential Environmental Concern
Prior to 1956	Vacant / Agricultural	None	No
1956 - 1987	Aladdin Motel	AST located in the Basement that is	Yes
1987 - 1992	West Park Motor Inn motel	known to have leaked	res
1992 - present	Gravel surface parking lot	None	No

Potentially Contaminating Activities (PCAs)

From the previous engineering reports, the former motel on-site is known to have had a heating oil AST located in the basement that is known to have leaked. This represents an APEC on the subject land. Petroleum hydrocarbon (PAH, TPH gas diesel and TPH heavy oil) contamination has previously been identified in the soils and groundwater at the subject site.

Twelve (12) additional PCAs outside of the subject property but within the Phase I study area were identified. These comprise the various RFOs located at the intersection between Carling Avenue and Churchill Avenue, the UST located at the 1619 Carling Avenue property, Minutemen Press Printers, the Sheridan Equipment property and various automotive service garages. The majority of these PCAs are not considered to represent APECs based on their separation distance from the subject site and/or their down- or cross-gradient location from the Phase I property. However, the 1619 Carling Avenue property and the RFO located at 1607 Carling Avenue do represent APECs on the subject property. The off-site PCAs and APECs are shown on Drawing PE4229-1 Site Plan and Drawing PE4229-2 Surrounding Land Use Plan.

Report: PE4229



Areas of Potential Environmental Concern (APEC)

Table 3: Areas of Potential Environmental Concern					
APEC	Location of APEC with respect to Phase I Property	PCA	Location of PCA (on-site or off- site)	Contaminants of Potential Concern	Media Potentially Impacted (Groundwater, Soil, and/or Sediment)
AST located in the basement of the former motel	The central portion of the site	Item 28 - Gasoline and Associated Products Storage in Fixed Tanks	On-site	PHCs, BTEX, PAH	Soil/ Groundwater
Former UST located at 1619 Carling Avenue (Hakim Optical)	Eastern portion of the site	Item 28 - Gasoline and Associated Products Storage in Fixed Tanks	On-site	PHCs, BTEX, PAH	Groundwater
Former and current USTs located at 1607 Carling Avenue (Shell RFO)	Eastern portion of the site	Item 28 - Gasoline and Associated Products Storage in Fixed Tanks	On-site	PHCs, BTEX, PAH	Groundwater

Contaminants of Potential Concern (CPC)

Based on the APECs, the following Contaminants of Potential Concern (CPCs) have been identified:

- Petroleum Hydrocarbons Fractions 1 through 4 (PHCs F₁-F₄) this suite of parameters encompasses gasoline (Fraction 1), diesel and fuel oil (Fraction 2), and heavy oils and grease (Fractions 3 and 4). PHCs F₁-F₄ were selected as CPCs for the Phase I property due to the former and current on and off-site fuel tanks.
- Benzene, Toluene, Ethylbenzene, and Xylenes (BTEX) were selected as CPCs for the Phase I property due to the former and current on and off-site fuel tanks.

Report: PE4229



Polycyclic Aromatic Hydrocarbons (PAHs) were selected as CPCs for the Phase I property as they have previously been recorded in excess of the applicable site standards.

7.2 Conceptual Site Model

Geological and Hydrogeological Setting

Based on the information from NRCAN, bedrock in the area of the site consists of limestone, dolostone, shale, arkose, sandstone of the Ottawa Group. Based on the maps, the thickness of overburden is anticipated to be around 2 m and consists of glacial till. Groundwater is expected to be encountered in the bedrock at around 2 m to 3 m below the existing ground level.

Contaminants of Potential Concern

As per Section 7.1 of this report, CPCs identified on the subject site include PHCs, BTEX and PAHs.

Existing Buildings and Structures

The subject site is not occupied by any buildings.

Water Bodies

There are no water bodies on the subject property or within the Phase I ESA study area.


Areas of Natural Significance

There are no areas of natural and scientific interest on the subject property or within the Phase I ESA study area

Drinking Water Wells

The subject site is located within a municipally supplied area, drinking water wells are not considered to be present within the Phase I ESA study area. Records of 100 water wells, dating from 1949 to 2016, were found in the study area.

One well is recorded on-site and details the water supply well, dated 1956, related to the Aladdin Motel. The nearest off-site wells were recorded monitoring and observation wells at the RFO addressed 1607 Carling Avenue.





Given the municipally supplied area and age of the wells, all private water wells are assumed to be obsolete.

Neighbouring Land Use

Neighbouring land use in the Phase I study area consists of residential and commercial properties. Land use is shown on Drawing PE4229-2 Surrounding Land Use Plan.

Potentially Contaminating Activities and Areas of Potential Environmental Concern

As per Section 7.1 of this report, Potentially Contaminating Activities and Areas of Potential Environmental Concern were identified within the Phase I ESA study area. The off-site PCAs and APECs are shown on Drawing PE4229-1 Site Plan and Drawing PE4229-2 Surrounding Land Use Plan.

Assessment of Uncertainty and/or Absence of Information

The information available for review as part of the preparation of this Phase I ESA is considered to be sufficient to conclude that there are areas of potential environmental concern on the subject site. The presence of potentially contaminating activities was confirmed by a variety of independent sources, and as such, the conclusions of this report are not affected by uncertainty which may be present with respect to the individual sources.



8.0 CONCLUSIONS

Assessment

Paterson Group was retained by Surface Developments to conduct a Phase I Environmental Site Assessment (Phase I-ESA) of 1655 Carling Avenue, in the City of Ottawa, Ontario. The purpose of this Phase I – Environmental Site Assessment was to research the past and current use of the site and study area and to identify any environmental concerns with the potential to have impacted the subject properties.


The subject site comprised a vacant/agricultural plot until 1956 when the subject site was developed for the Aladdin Motel. In 1987 this changed to the West Park Motor Inn until 1992 when the motel was demolished. On demolition, an AST located in the basement was found to have leaked. This tank represents an APEC on the subject site. Previous investigations by Paterson and others have found the subject site to be impacted by hydrocarbons including PHCs, BTEX and PAHs.

The lands surrounding the subject site were historically used for residential, north of carling Avenue and were commercial in use, south of Carling Avenue. Several PCAs have been identified including several retail fuel outlets, a UST at the neighbouring 1619 Carling Avenue, Minutemen Press Printers, the Sheridan Equipment property and various muffler and auto service centres. Of these, 1619 Carling Avenue and 1607 Carling Avenue (Shell retail fuel outlet) were considered to be up gradient and therefore identified as APECs. USTs are known to have leaked at both properties in the past.

Following the historical review, a site visit was conducted. The site is currently used as a parking lot. No further PCAs or APECS were identified.

The following Areas of Potential Environmental Concern (APECs) were identified with regard to the subject site;

Former AST in the basement of the historical motel which leaked;
Former UST located at 1619 Carling Avenue;
Former and current USTs located at 1607 Carling Avenue (Shell retail fuel
outlet).





Recommendations

Based on the results of the Phase I - Environmental Site Assessment, it is our opinion that a Phase II - Environmental Site Assessment is required for the subject site.



9.0 STATEMENT OF LIMITATIONS

This Phase I - Environmental Site Assessment report has been prepared in general accordance with O.Reg. 153/04 as amended, and meets the requirements of CSA Z768-01. The conclusions presented herein are based on information gathered from a limited historical review and field inspection program. The findings of the Phase I - ESA are based on a review of readily available geological, historical and regulatory information and a cursory review made at the time of the field assessment. The historical research relies on information supplied by others, such as, local, provincial and federal agencies and was limited within the scope-of-work, time and budget of the project herein.

Should any conditions be encountered at the subject site and/or historical information that differ from our findings, we request that we be notified immediately in order to allow for a reassessment.

This report was prepared for the sole use of Surface Developments. Permission and notification from the above noted party and Paterson will be required to release this report to any other party.

Paterson Group Inc.

Philip Price, BSc. FGS

Mark S. D'Arcy, P.Eng.

M.S. D'ARCY 90377839

Report Distribution:

- Surface Developments
- Paterson Group



10.0 REFERENCES

Federal Records

Air photos at the Energy Mines and Resources Air Photo Library.

National Archives.

Maps and photographs (Geological Survey of Canada surficial and subsurface mapping).

Natural Resources Canada - The Atlas of Canada.

Environment Canada, National Pollutant Release Inventory.

PCB Waste Storage Site Inventory.

Provincial Records

MECP Freedom of Information and Privacy Office.

MECP Municipal Coal Gasification Plant Site Inventory, 1991.

MECP document titled "Waste Disposal Site Inventory in Ontario".

MECP Brownfields Environmental Site Registry.

Office of Technical Standards and Safety Authority, Fuels Safety Branch.

MNR Areas of Natural Significance.

MECP Water Well Inventory.

Municipal Records

The City of Ottawa Historical Land Use Inventory.

The City of Ottawa geoOttawa website.

Local Information Sources

Personal Interviews.

Public Information Sources

Google Earth.
Google Maps/Street View
Bing Maps

FIGURES

FIGURE 1 – KEY PLAN

FIGURE 2 – TOPOGRAPHIC MAP

DRAWING PE4229-1 - SITE PLAN

DRAWING PE4229-2 – SURROUNDING LAND USE PLAN



FIGURE 1 KEY PLAN






FIGURE 2 TOPOGRAPHIC MAP





APPENDIX 1



AERIAL PHOTOGRAPH 1928













AERIAL PHOTOGRAPH 2002

patersongroup ____



AERIAL PHOTOGRAPH 2011



AERIAL PHOTOGRAPH 2017

APPENDIX 2

MECP FREEDOM OF INFORMATION SEARCH
CITY OF OTTAWA HLUI RESPONSE
WATER WELL RECORDS
TSSA CORRESPONDENCE



Freedom of Information Request

This form is for requesting documents which are in the Ministry's files on environmental concerns related to properties. Please refer to the guide on completion and use of this form. Our fax no. is (416) 314-4285.

completion and dee of the let	• • • • • • • • • • • • • • • • •	0/011 =001				
Requester Data		For Ministry Use Only				
Name, Company Name, Mailing Address and Email Address of Requester			FOI Request No.			
Philip Price			i Oi Nequest No.			
Paterson Group Inc. 154 Colonnade Road		Fee Paid				
Ottawa, ON K2E 7J5				VISA/MC □ CASH		
Email address: pprice@pate	rsongroup.ca	T				
Telephone/Fax Nos.	□ CNR □ ER □ NO	DR □ SWR □ WCR				
Tel. 613-226-7381 Fax 613-226-6344	PE4229	Philip Price				
	<u> </u>	Request Parameter	s			
Municipal Address / Lot, Concession, Ge	ographic Township (Municipal	l address essential for cities, towns or region				
1655 Carling Avenue, Ottav PIN - 04012-0101	wa, Ontario					
Present Property Owner(s) and Date(s) of Ov	vnership					
Surface Developments						
Previous Property Owner(s) and Date(s) of O	wnership					
Present/Previous Tenant(s),(if applicable)						
Search Parameters Files older than 2 years may require \$60.00 retrieval cost. There is no guarantee that records responsive to your request will be located. Specify Year(s) Requested						
Environmental concerns (General correspondence, occurrence reports, abatement) all				all		
Orders				all		
Spills all						
	Investigations/prosecutions ➤ Owner AND tenant information must be provided all					
Waste Generator number/classes			all			
	Certificate	s of Approval > Proponent info	rmation must be provided			
1985 and prior records are searched manually. Search fees in excess of \$300.00 could be incurred, depending on the types and years to be searched. Specify Certificates of Approval number(s) (if known). If supporting documents are also required, mark SD box and specify type e.g. maps, plans, reports, etc.						
	Specify Year(s) Requested					
air - emissions 1986-present						
water - mains, treatment, ground level, standpipes & elevated storage, pumping stations (local & booster)				1986-present		
Sewage - sanitary, storm, treatment, stormwater, leachate & leachate treatment & sewage pump stations				1986-present		
waste water - industrial discharges				1986-present		
waste sites - disposal, landfill sites, transfer stations, processing sites, incinerator sites 1986-prese				1986-present		
waste systems - PCB destruc	waste systems - PCB destruction, mobile waste processing units, haulers: sewage, non-hazardous & hazardous waste 1986-present					
pesticides - licenses	1986-present					

A \$5.00 non-refundable application fee, payable to the Minister of Finance, is mandatory. The cost of locating on-site and/or preparing any record is \$30.00/hour and 20 cents/page for photocopying and you will be contacted for approval for fees in excess of \$30.00.

0026 (05/02) Page 1 of 1

	Office Use C	Only	
Application Number:	Ward Number:	Application Received: (dd/mm/yyyy):	
Client Service Centre Staff:		Fee Received: \$	



Historic Land Use Inventory

Application Form

Notice of Public Record

All information and materials required in support of your application shall be made available to the public, as indicated by Section 1.0.1 of *The Planning Act*, R.S.O. 1990, C.P.13.

Municipal Freedom of Information and Protection Act

Personal information on this form is collected under the authority the *Planning Act*, RSO 1990, c. P. 13 and will be used to process this application. Questions about this collection may be directed by mail to Manager, Business Support Services, Planning Infrastructure and Economic Development Department, 110 Laurier Avenue West, Ottawa, K1P 1J1, or by phone at (613) 580-2424, ext. 24075

Background Information							
*Site Address or Location:	1655 Carling Avenue						
	* Mandatory Field						
Applicant/Agent	information:						
Name:	Paterson Group						
Mailing Address:	154 Colonnade Road South, Ottaw	154 Colonnade Road South, Ottawa, ON, K2E 7J5					
Telephone:	613-226-7381	Email Address:	pprice@patersongroup.ca				
Registered Prope	rty Owner Information:	Same as abo	ve				
Name:	Surface Developments						
Mailing Address:	88 Spadina Avenue, Ottawa, ON, K	172C1					
Telephone:	613 255 5507	Email Address:	Jakub@surfacedevelopments.com				

	Site Details
Legal Description and PIN:	1655 Carling Avenue, Ottawa, Ontario PIN: 04012-0101
What is the land currently used for?	Vacant / Parking lot
	e: m Lot depth: m Lot area: m² area: (irregular lot) 3,458
	Required Fees
Please don't hesitat more information.	e to visit <u>the Historic Land Use Inventory</u> website Fees must be paid in full at the time of application submission.
Planning Fee	\$105.00
	Submittal Requirements

The following are required to be submitted with this application:

- 1. Consent to Disclose Information: Consultants and other third parties may make requests for information on behalf of an individual or corporation. However, if the requester is not the owner of the property, the requester must provide the City of Ottawa with a 'consent to disclose information' letter, signed by the property owner. This will authorize the City of Ottawa to release any relevant information about the property or its owner(s) to the requester. Consent for disclosure is required in the event that personal information or proprietary company information is found concerning the property and its owner. All consents must clearly indicate the name of the property owner as well as the name of the requester, and must be signed and dated.
- 2. Disclaimer: Requesters must read and understand the conditions included in the attached disclaimer and submit a signed disclaimer to the City of Ottawa's Planning, Infrastructure and Economic Development Department. This disclaimer is related to the Historic Land Use Inventory and must be received by the City of Ottawa, signed and dated by the requestor, before the process can begin.
- 3. A site plan or key plan of the property, its location and particular features.
- 4. Any significant dates or time frames that you would like researched.

Disclaimer For use with HLUI Database

CITY OF OTTAWA ("the City") is the owner of the Historical Land Use Inventory ("HLUI"), a database of information on the type and location of land uses within the geographic area of Ottawa, which had or have the potential to cause contamination in soil, groundwater or surface water.

The City, in providing information from the HLUI, to	Paterson Group	("the Requester") does so only under the following
conditions and understanding:		

- The HLUI may contain erroneous information given that such records and sources of information may be flawed. Changes in
 municipal addresses over time may have introduced error in such records and sources of information. The City is not responsible
 for any errors or omissions in the HLUI and reserves the right to change and update the HLUI without further notice. The City
 does not, however, make any commitment to update the HLUI. Accordingly, all information from the HLUI is provided on an "as
 is" basis with no representation or warranty by the City with respect to the information's accuracy or exhaustiveness in
 responding to the request.
- 2. City staff will perform a search of the HLUI based on the information given by the Requester. City staff will make every effort to be accurate, however, the City does not provide an assurance, guarantee, warranty, representation (express or implied), as to the availability, accuracy, completeness or currency of information which will be provided to the Requester. The HLUI in no way confirms the presence or absence of contamination or pollution of any kind. The information provided by the City to the Requester is provided on the assumption that it will not be relied upon by any person whatsoever. The City denies all liability to any such persons attempting to rely on any information provided from the HLUI database.
- The City, its employees, servants, agents, boards, officials or contractors take no responsibility for any actions, claims, losses, liability, judgments, demands, expenses, costs, damages or harm suffered by any person whatsoever including negligence in compiling or disseminating information in the HLUI.
- 4. Copyright is reserved to the City.
- 5. Any use of the information provided from the HLUI which a third party makes, or any reliance on or decisions to be based on it, are the responsibilities of such third parties. The City, its employees, servants, agents, boards, officials or contractors accept no responsibility for any damages, if any, suffered by a third party as a result of decisions made as a result of an information search of the HLUI.
- 6. Any use of this service by the Requestor indicates an acknowledgement, acceptance and limits of this disclaimer.
- 7. All information collected under this request and all records provided in response to this request are subject to the provisions of the Municipal Freedom of Information and Protection of Privacy Act, R.S.O. 1990, c. M.56, as amended.

Signed:	
Dated (dd/mm/yyyy): 04/10/2019	
Per: Philip Price	
(Please print name)	
Title: Environmental Engineer	
Company: Paterson Group	


UIM 118 Z 41411141210E 9 R 5101215121815 N

Elev. 1912 0121510

Basin | 2 | 5 | 1 | 1



The Water-well Drillers Act, 1954 Department of Mines



TX7~+~~ TX7~11


·	v alei.	- vv e	:11	Vecor		
County or Territorial District	allon	Town	nship	, Village, Town or	ity Ollar	-
			7q J	v. Village, Town or Ci Village, Town or Ci dress	len moi	t L
(day)	(month)	(year)				
Pipe and Casing		(year)			Pumping Test	
			1	401		
Casing diameter(s)5				atic level	0 Y.PH_	***************************************
Length(s) Type of screen			P11	mning level 65	//	
Length of screen			l .	ration of test	<u>L</u>	***************************************
Well Log			<u>!</u>		Water Record	
Overburden and Bedrock Record	From ft.	To ft.		Depth(s) at which water(s) found	No. of feet water rises	Kind of wate (fresh, salty or sulphur)
Play	1.	41	,	250'	210.	Just
						
Limestone	4'	250	0-			
For what purpose(s) is the water	to be used?	1		La	cation of Well	
motel use	<i>"</i>			In diagram below		f well from
Is water clear or cloudy?		- Oh.		road and lot line	. Indicate north	by arrow.
Is well on upland, in valley, or or	hillside?				N	
Drilling firm Muse	agh.	,,				3
Address 639 Rawa	n wood	lue				
July	wa	a				
Name of Driller	1 argu	·····		alladi	in 1. Mi	4 3
Audico				mal	Se par	2 3
Licence Number				90'bre 1	Ju Jua	
I certify that the statements of fact				PA	- (i)	
			•	1 our	glice.	*
Date april mm	eaghn				W	P
	sign a ture of License	ee		Welaw	a //use	, ,

Form 5

5 Carling Luc.

♥ Ontario	Ministry of the Environment Well Tag Number (Place sto	(ckerand print number below) Well Record Regulation 903 Ontario Water Resources Act
Instructions for Complet	ting Form Well abandor	nmend page of _2
 For use in the Province All Sections must be or Questions regarding or All metre measureme Please print clearly in b 	e of Ontario only. This document is a permane ompleted in full to avoid delays in processing. In ompleting this application can be directed to the onts shall be reported to 1/10th of a metre.	ent legal document. Please retain for future reference. Further instructions and explanations are available on the back of this form. e Water Well Management Coordinator at 416-235-6203. Ministry Use Only MUN CON LOT LOT
GPS Reading NAD Z	one Easting Northing Unit	//Town/Village Site/Compartment/Block/Tract etc. t Make/Model Mode of Operation: Undifferentiated Averaged Differentiated, specify
General Colour Most commo		General Description Depth Metres
		From To
		0 3.40
Remov	e monitoring well, over	dull + backfill borehole with ce. as per Hin Rog 503
Hole Diameter	Construction Record	Test of Well Yield
Depth Metres Diameter		Depth Metres Pumping test method Draw Down Recovery
From To Centimetre	s diam Material thickness	Time Water Level Time Water Level
0 3.90 20	centimetres	From To min Metres min Metres Pump intake set at - Static
	Casing	(metres) Level
·	Steel Fibreglass	Pumping rate - 1 1 (litres/min)
	Plastic Concrete	
Water Record Water found Kind of Water	Galvanized	Duration of pumping 2 2
at Metres / Tille of Water	Steel Fibreglass	Final water level end 3 3
m Fresh Sulphu		of pumping metres
Other:	Galvanized	Recommended pump 4 4
	Steel Fibre glass	type. Shallow Deep
Gas Salty Mineral	S Plastic Concrete	Recommended pump 5 5 5 depth.
Other:	Galvanized	nede
m Fresh Sulphu		l roto
Gas Salty Mineral	diam Steel Floregiass Slot No.	(litres/min) 15 15 15 If flowing give rate - 20 20
After test of well yield, water was	Plastic Concrete	(litres/min) 25 25
Clear and sediment free	Galvanized	If pumping discontinued, give reason.
Other, specify	No Casing or Screen	40 40
Chlorinated Yes	Open hole	50 50
		60 60
	Sealing Record Annular space Abando	
From To	ype (bentonite slurry, neat cement slurry) etc. (cubic met	
0 39 Ben	trute concert dense, 40 H	K9 D
		Please see attached site plan
	Method of Construction	
Cable Tool Rotar		ging
Rotary (conventional) Air pe	arcussion ☐ Jetting ☐ 🦪 in a priving	DA CALL
	Water Use	
Domestic Indus	trial Public Supply Oth	her
	nercial Not used	LD-ta-Mall Completed
Irrigation Munic	cipal Cooling & air conditioning Final Status of Well	Audit No. z 50491 Date Well Completed
Water Supply Recharge		
Observation well Abandone	d, insufficient supply Dewatering	package delivered? Yes Woo 2004 09114
	d poor quality Replacement well	Ministry Use Only
	/ Well Contractor's Licence	
GOORGE DOWNINGES	Help Dulling Ltd 1844	
Business Address (street name, nur	mber, city etc.)	Date Received TYYYY 7 MM DD Date of Inspection YYYY MM DD DD DD DD DD DD DD DATE OF INSPECTION YYYY MM DD
Name of Well Technician (last name	hilfo yur (a Night VC, Joy) jirst name) Well Technician's Ligen	nce No. Remarks Well Record Number
Douming Bruce	72131	
Signature of Technician/Contractor	Date Submitted yyyy	(A) (P)
0506E (09/03)		Well Owner's Copy ☐ Cette formule est disponible en français
` '	,,	<u> </u>





OCT 17 2006

Philip Price

From: Public Information Services <publicinformationservices@tssa.org>

Sent: October-01-19 4:35 PM

To: Philip Price

Subject: RE: TSSA Records Search, PE4229 - Ottawa, ON

Good afternoon,

Thank you for your request for confirmation of public information.

I have searched the below noted addresses and I have located the following record:

Inst Numb	Context -T	Address	Ţ	City 📑	Provin(*	Postal Co	Inststatusnan 🔼
9951570	FS Facility	1607 CARLING AVE		OTTAWA	ON	K2A 1C4	EXPIRED
10381941	FS Facility	1607 CARLING AVE		OTTAWA	ON	K2A 1C4	EXPIRED
64492365	FS Facility	1607 CARLING AVE		OTTAWA	ON	K2A 1C4	Active
11113291	FS Liquid Fuel Tank	1607 CARLING AVE		OTTAWA	ON	K2A 1C4	EXPIRED
11113319	FS Liquid Fuel Tank	1607 CARLING AVE		OTTAWA	ON	K2A 1C4	EXPIRED
11113349	FS Liquid Fuel Tank	1607 CARLING AVE		OTTAWA	ON	K2A 1C4	EXPIRED
11113379	FS Liquid Fuel Tank	1607 CARLING AVE		OTTAWA	ON	K2A 1C4	EXPIRED
11457764	FS Liquid Fuel Tank	1607 CARLING AVE		OTTAWA	ON	K2A 1C4	Active
11457777	FS Liquid Fuel Tank	1607 CARLING AVE		OTTAWA	ON	K2A 1C4	Active
11457783	FS Liquid Fuel Tank	1607 CARLING AVE		OTTAWA	ON	K2A 1C4	Active

For a further search in our archives, or for copies of documents, please complete our release of public information form found at https://www.tssa.org/en/about-tssa/release-of-public-information.aspx? mid =392 and email the completed form to publicinformationservices@tssa.org or through mail along with a fee of \$56.50 (including HST) per location. The fee is payable with credit card (Visa or MasterCard) or with a Cheque made payable to TSSA.

Although TSSA believes the information provided pursuant to your request is accurate, please note that TSSA does not warrant this information in any way whatsoever.



Sherees Thompson | Public Information Agent

Facilities
345 Carlingview Drive
Toronto, Ontario M9W 6N9
Taly 14 446 724 2363 | Favy

Tel: +1-416-734-3363 | Fax: +1-416-231-6183 | E-Mail: <u>sthompson@tssa.org</u>

www.tssa.org







From: Philip Price < PPrice@Patersongroup.ca>

Sent: October 1, 2019 1:29 PM

To: Public Information Services <publicinformationservices@tssa.org>

Subject: TSSA Records Search, PE4229 - Ottawa, ON

Good Afternoon,

Could you please conduct a search of your records for underground storage tanks, historical spills and other incidents/infractions for the following addresses for properties located in Ottawa, Ontario:

1607 Carling Avenue 1619 Carling Avenue 1638 Carling Avenue 1640 Carling Avenue 1655 Carling Avenue 1657 Carling Avenue

358 Tillbury Ave 364 Tillbury Ave 370 Tillbury Ave 376 Tillbury Ave

Thank you very much,

Philip Price

patersongroup

solution oriented engineering over 60 years servicing our clients

154 Colonnade Road South Ottawa, Ontario, K2E 7J5 Tel: (613) 226-7381 Ext. 250

Cell: (343) 999 7255

This electronic message and any attached documents are intended only for the named recipients. This communication from the Technical Standards and Safety Authority may contain information that is privileged, confidential or otherwise protected from disclosure and it must not be disclosed, copied, forwarded or distributed without authorization. If you have received this message in error, please notify the sender immediately and delete the original message.

APPENDIX 3

QUALIFICATIONS OF ASSESSORS

Philip Price BSc. FGS

patersongroup

POSITION

Intermediate Environmental Scientist

EDUCATION

Kingston University, London, England, BSc (Hons), 2005 Geology

Environmental Engineering

EXPERIENCE

2018 - Present:

Paterson Group Inc. Consulting Engineers Environmental Division

Intermediate Environmental Scientist

Geotechnical Engineering

2016 - 2018

Harrison Group Environmental Ltd.

Consulting Engineers

Senior Environmental Engineer

2013 - 2016

Harrison Group Environmental Ltd.

Materials Testing Quality Control

Consulting Engineers Environmental Engineer

2009 - 2011

AP Geotechnics Ltd.
Consulting Engineers
Geotechnical Engineer

Building Sciences

2006 - 2009

Harrison Group Environmental Ltd.

Consulting Engineers

Junior Environmental Engineer

SELECT LIST OF PROJECTS

Hydrogeology

Remediation Supervision – Residential Development, Arnprior Remediation Supervision – Residential Development, Ottawa Remediation Supervision – Commercial Development, Ottawa Phase I & II ESA – Commercial Development, Bells Corners, Ottawa Groundwater Monitoring and Sampling – Various Location, Ottawa Phase I ESA – Various Locations, Ontario

Archaeological Services

Mark S. D'Arcy, P. Eng.

patersongroup

Geotechnical Engineering

Environmental Engineering

Hydrogeology

Geological Engineering

Materials Testing

Building Science

Archaeological Services

POSITION

Associate and Supervisor of the Environmental Division Senior Environmental/Geotechnical Engineer

EDUCATION

Queen's University, B.A.Sc.Eng, 1991 Geotechnical / Geological Engineering

MEMBERSHIPS

Ottawa Geotechnical Group Professional Engineers of Ontario

EXPERIENCE

1991 to Present

Paterson Group Inc.

Associate and Senior Environmental/Geotechnical Engineer Environmental and Geotechnical Division Supervisor of the Environmental Division

SELECT LIST OF PROJECTS

Mary River Exploration Mine Site - Northern Baffin Island Agricultural Supply Facilities - Eastern Ontario

Laboratory Facility – Edmonton (Alberta)

Ottawa International Airport - Contaminant Migration Study - Ottawa

Richmond Road Reconstruction - Ottawa

Billings Hurdman Interconnect - Ottawa

Bank Street Reconstruction - Ottawa

Environmental Review - Various Laboratories across Canada - CFIA

Dwyer Hill Training Centre - Ottawa

Nortel Networks Environmental Monitoring - Carling Campus - Ottawa

Remediation Program - Block D Lands - Kingston

Investigation of former landfill sites - City of Ottawa

Record of Site Condition for Railway Lands - North Bay

Commercial Properties - Guelph and Brampton

Brownfields Remediation - Alcan Site - Kingston

Montreal Road Reconstruction - Ottawa

Appleford Street Residential Development - Ottawa

Remediation Program - Ottawa Train Yards

Remediation Program - Bayshore and Heron Gate

Gladstone Avenue Reconstruction – Ottawa

Somerset Avenue West Reconstruction - Ottawa