Geotechnical Engineering

**Environmental Engineering** 

**Hydrogeology** 

Geological Engineering

**Materials Testing** 

**Building Science** 

Archaeological Services

# patersongroup

# **Phase I Environmental Site Assessment**

1500 Merivale Road Ottawa, Ontario

# **Prepared For**

Osmington Incorporated

# Paterson Group Inc.

Consulting Engineers 154 Colonnade Road South Ottawa (Nepean), Ontario Canada K2E 7J5

Tel: (613) 226-7381 Fax: (613) 226-6344 www.patersongroup.ca August 1, 2017

Report: PE4001-1



## **TABLE OF CONTENTS**

EXE(	CUTIV	'E SUMMARY	ii
1.0	INTF	RODUCTION	1
2.0	PHA	SE I PROPERTY INFORMATION	2
3.0	SCO	PE OF INVESTIGATION	3
4.0	REC	ORDS REVIEW	4
	4.1	General	4
	4.2	Environmental Source Information	8
	4.3	Physical Setting Sources	12
5.0	INTE	RVIEWS	15
6.0	SITE	RECONNAISSANCE	15
	6.1	General Requirements	15
	6.2	Specific Observations at Phase I Property	15
7.0	REV	IEW AND EVALUATION OF INFORMATION	17
		Land Use History	
	7.2	Conceptual Site Model	20
8.0	CON	ICLUSIONS	24
9.0	STA	TEMENT OF LIMITATIONS	25
10.0	REF	ERENCES	26

# **List of Figures**

Figure 1 - Key Plan

Figure 2 - Topographic Map

Drawing PE4001-1 - Site Plan

Drawing PE4001-2 - Surrounding Land Use Plan

# **List of Appendices**

Appendix 1 Chain of Title

Plan of Survey Aerial Photographs Site Photographs

Appendix 2 MOECC Freedom of Information Response

City of Ottawa HLUI Search Results

TSSA Correspondence MOECC Well Records

Appendix 3 Qualifications of Assessors



# **EXECUTIVE SUMMARY**

#### **Assessment**

Paterson Group was retained by Osmington, to conduct a Phase I Environmental Site Assessment (ESA) of the property addressed 1500 Merivale Road, in the City of Ottawa, Ontario. The purpose of this Phase I ESA was to research the past and current use of the site and study area and to identify any environmental concerns with the potential to have impacted the subject property.

The results of the historical research indicated that the subject property was developed for residential purposes prior to 1945 and redeveloped for commercial purposes sometime in the 1950s. Several garages and commercial operations, including a dry cleaner, occupied the southern portion of the property. These former activities are potentially contaminating activities (PCAs) which represent areas or an area of potential environmental concern (APECs) on the Phase I Property.

Fourteen off-site historical PCAs were identified within the Phase I ESA study area. Four of which represent an APEC to the subject site, the former and current garages and service stations located at 1480, 1482 Merivale Road, the former and existing service station at 1377 Clyde Avenue, and the former printers at 1783 Clyde Avenue. The garages, services stations, and printers are considered to have the potential to impact the soil and groundwater quality of the subject site.

One PCA representing an APEC was identified on the subject site at the time of the assessment. The Midas automotive service garage located at 1380 Merivale Road. At the time of the assessment Paterson was not provided access to the property and was only able to evaluate the operations from a distance. Two offsite PCAs representing APECs were identified at the time of the site visit. Automotive service garages at 1377 Clyde Avenue and 1486 Merivale Road are considered to represent APECs to the subject site.

# Conclusion

Based on the results of this Phase I ESA, it is our opinion that a Phase II Environmental Site Assessment is required for the property.

August 1, 2017 Page ii



# 1.0 INTRODUCTION


At the request of Osmington Incorporated (Osmington), Paterson Group (Paterson) conducted a Phase I Environmental Site Assessment (Phase I ESA) of the property addressed 1500 Merivale Road, in the City of Ottawa, Ontario. The purpose of this Phase I ESA was to research the past and current use of the site and study area and to identify any environmental concerns with the potential to have impacted the subject property.

Paterson was engaged to conduct this Phase I ESA by Ms. Hilary Vaillancourt of Osmington. The offices of Osmington are located at 141 Adelaide Street West, Suite 601, Toronto, Ontario. Ms. Vaillancourt can be reached by telephone at (416) 306-3073.

This report has been prepared specifically and solely for the above noted project which is described herein. It contains all of our findings and results of the environmental conditions at this site.

This Phase I-ESA report has been prepared in general accordance with the requirements of Ontario Regulation 153/04 as amended by O.Reg. 269/11, and also complies with the requirements of CSA Z768-01. The conclusions presented herein are based on information gathered from a limited historical review and field inspection program. The findings of the Phase I - ESA are based on a review of readily available geological, historical and regulatory information and a cursory review made at the time of the field assessment. The historical research relies on information supplied by others, such as, local, provincial and federal agencies and was limited within the scope-of-work, time and budget of the project herein.

August 1, 2017 Page 1





# 2.0 PHASE I PROPERTY INFORMATION

Address: 1500 Merivale Road, Ottawa, Ontario. Parcel contains

lots addressed as 1490 Merivale Road and 1380

Baseline Road

Legal Description: Part of Lots 18, 19, 20, and 21, Registered Plan 30,

City of Ottawa, Ontario.

Property Identification

Number(s): 04686-0027 and 04686-0007

Location: The subject site is bound by Clyde Avenue and

commercial properties to the West, commercial properties and Merivale Road to the South and East, and commercial properties and Baseline Road to the North. The subject site is shown on Figure 1 - Key

Plan following the body of this report.

Latitude and Longitude: 45° 21′ 38″ N, 75° 44′ 13″ W.

**Site Description:** 

Configuration: Irregular

Site Area: 6.21 hectares (approximate)

Zoning: AM – Arterial Main Street

Current Use: The property is mostly vacant with an automotive

service garage (1380 Baseline Road) along the north property line and parking areas in the southwest

corner.

Services: The subject site is located in a municipally serviced

area.

August 1, 2017 Page 2



# 3.0 SCOPE OF INVESTIGATION

e scope of work for this Phase I – Environmental Site Assessment was as lows:
Determine the historical activities on the subject site and study area by conducting a review of readily available records, reports, photographs, plans, mapping, databases and regulatory agencies;
Investigate the existing conditions present at the subject site and study area by conducting site reconnaissance;
Conduct interviews with persons knowledgeable of current and historic operations on the subject property, and if warranted, neighbouring properties;
Present the results of our findings in a comprehensive report in general accordance with the requirements of Ontario Regulation 269/11 amending O.Reg. 153/04 made under the Environmental Protection Act and in compliance with the requirements of CSA Z768-01;
Provide a preliminary environmental site evaluation based on our findings;
Provide preliminary remediation recommendations and further investigative work if contamination is suspected or encountered



# 4.0 RECORDS REVIEW

## 4.1 General

# Phase I-ESA Study Area Determination

A radius of approximately 250 m was determined to be appropriate as a Phase I ESA study area for this assignment. Properties outside the 250 m radius are not considered to have impacted the subject land, based on their significant distance from the site.

# **First Developed Use Determination**

Based on the city directories, air photo research, fire insurance plans and a chain of title, it is our interpretation that the subject property was first developed prior to 1945 for residential purposes. The property switched to commercial and community use starting in the 1950s.

## **Fire Insurance Plans**

Fire Insurance Plans (FIPs), dated 1956, were reviewed for the Phase I Property and Phase I study area.

Based on the 1956 FIPs, the Phase I ESA Property was previously occupied by the following:

C.J.O.H. TV station (1500 Merivale Road);
Restaurant (1476 Merivale Road);
Commercial businesses with Underground Storage Tank (UST) (1464, 1466,
1468 Merivale Road);
M.H. Rhodes Limited, Timing device manufacturing and machine shop (8, 10
Kimway Crescent);
Transport Office with UST (1490 Merivale Road);
Capri Restaurant (1488 Merivale Road);
Bethany Baptist Church (1366 Baseline Road)
Several other unidentified buildings;

Multiple PCAs resulting in APECs on the subject site were identified on the Phase I ESA Property in the 1956 FIPs, as shown below in Table 1. The 1956 FIPs identified several onsite and offsite PCAs within the Phase I study area. The PCAs identified on the 1956 FIPs are shown on Drawing PE4001-2 Surrounding

August 1, 2017 Page 4

Ottawa, Ontario



Land Use Plan. The on-site and off-site PCAs which are considered to represent an APEC to the subject property are shown in Table 1.

Table 1							
Fire Insurance Plans							
Potentially Contain	minating Activities re	sulting in an APEC					
Civic Address	Potential Environmental Concern (Y / N)						
1956 FIP							
1468 Merivale Road	UST located on south side of store	Onsite	Υ				
1490 Merivale Road	UST located adjacent to a transport office	Onsite	Y				
1504 Merivale Road	Auto Service Garage with UST	Offsite, Adjacent South	Υ				
1383 Clyde Avenue	Former IBM Printers	Offsite, Adjacent West	Y				
8 Kimway Crescent	Machine Shop	Onsite	Υ				
10 Kimway Crescent	Manufacturing	Onsite	Υ				

The above noted PCAs are all considered to represent APECs on the subject site. Several other PCAs were identified during a review of the FIPs, however based on the separation distance and the inferred groundwater flow direction the remaining PCAs, as identified on the FIPs, are not considered to represent APECs on the subject site.

# **City of Ottawa Street Directories**

As part of the Phase I ESA, city directories at the National Archives were reviewed in approximate 10 year intervals from 1943 through 2011.

Listings for the subject site show the property as various commercial uses primarily for recording and broadcasting purposes on 1500 Merivale Road. Portions of the property appear to be listed as a church or residential use at one time. Only one municipal address currently listed on the subject site is identified to be an APEC, 1380 Baseline Road where the current Midas service garage is located.

Neighbouring properties within the Phase I study area were used primarily for commercial purposes, with several institutional or residential properties. Several PCAs are identified in the study area, however based on the separation distance these PCAs are not considered to represent an APEC on the Phase I ESA

August 1, 2017 Page 5



property. Areas of Potential Environmental Concern identified within the Phase I study area are summarized in Table 2.

Table 2 City Directories Potentially Contaminating Activities resulting in an APEC							
Address Listed Activity (years listed) Distance / Potent Orientation from Environm Site Concern (							
1377 Clyde Avenue	Frisby Tire Co (1975-2011)	Offsite – Adjacent West	Y				
1383 Clyde Avenue	Tabulating Card Plant (1965)	Offsite – Adjacent West	Y				
1486 Merivale Road	Swans Garage (1984-2005) Midas Muffler (1984)	Offsite – Adjacent South	Y				
1480 Merivale Road	Fraser Fuels (1965)	Offsite – Adjacent South	Y				

These PCAs/APECs have been identified in the FIPs, with the exception of the Frisby Tire automotive service centre.

Other PCAs identified in the city directories are not considered to represent APECs on the Phase I Property based on their separation distances from the Phase I Property and the redevelopment of the Phase I ESA Study Area.

#### Chain of Title

Paterson verified the current land title for the subject properties with Read Abstracts Limited.

According to the chain of title dated June 20, 2017 the property is divided into parts of four separate lots (Lots 18, 19, 20, and 21) on Plan 30. The properties were owned by a series of private individuals until the 1950s when commercial interests started buying portions of the site. The properties were consolidated in approximately 2008 to form two separate PINs. The current owner of the subject site is listed as 1455251 Ontario Inc.

Three (3) PCAs were identified during a review of the chain of title; Lot 19 was leased Honeywell Controls Limited in 1960 and subsequently leased to Imperial Oil Limited in 1968, Lot 20 was owned by Armstrong Construction and Equipment Limited in the late 1950s, and Lot 21 was owned by McColl Frontenac Oil Company Limited for a period in the late 1950s. These PCAs are considered to have been identified during the reviews of other information sources. Based on



the size of the lots it is not possible to identify the exact locations using only the Chain of Title. The exact locations of these PCAs are considered to have been identified using the other historical sources. The use of parts of the subject site by these owners or leaseholders are considered to represent APECs to the subject site.

No other PCAs were identified during a review of the chain of title.

# **Engineering Reports**

Paterson reviewed several reports for the subject site. A summary of the reports is provided below:

□ "Phase I Environmental Site Assessment, 1468, 1476, 1476A, 1478, 1490, 1492 and 1500 Merivale Road and 1366, 1380 and 1386 Baseline Road, Ottawa, Ontario", prepared by Pinchin Environmental Limited (Pinchin), November, 2012.

Pinchin completed a Phase I ESA on the subject site in November 2012. Pinchin identified fifteen (15) APECs on the subject site. The APECs include known areas of groundwater impacts along with potentially impacted areas throughout the subject site. Based on the historical research and the site visit Pinchin determined that a Phase II ESA should be conducted for the subject site prior to the submission of a record of site condition (RSC).

□ "Phase II Environmental Site Assessment, Merivale and Baseline Road, Ottawa, Ontario", prepared by Pinchin, January 2014.

Based on the recommendations made in the Phase I ESA and the presence of fifteen APECs on the subject site, a Phase II ESA was conducted between March 2013 and January 2014. 63 boreholes were advanced on the subject site, 35 of which were instrumented with a groundwater monitoring well. Soil sampling from the borehole program identified soil exceedances for VOCs, Metals, PHCs, and PAHs. Multiple groundwater samples exceeded the MOECC Table 3 Standards for VOCs and PHCs. No exceedances of the MOECC Table 3 Standards were identified for Metals or PAHs in the groundwater.

□ "Phase I-II – Environmental Site Assessment, 1490 Merivale Road, Ottawa, Ontario", prepared by Paterson, February 10, 2005.

Paterson completed a Phase I-II ESA for the property addressed as 1490 Merivale Road. The field program included advancing 4 boreholes on the subject site to assess a former UST and the adjacent garage building. Three soil



samples were submitted for analytical testing of PHCs. No concentrations were identified above the method detection limits in any of the analysed soil samples. No groundwater samples were submitted for analytical testing as part of the Phase II ESA program.

# **Survey Plan**

A Surveyor's Real Property Report, prepared by Annis, O'Sullivan, Vollebekk Ltd. and dated February 14, 2012, was reviewed as part of this assessment. The subject site is shown in its current configuration. A two storey brick building is shown as present along Baseline Road. No other structures are identified on the plan. A copy of the plan is provided in Appendix I.

## 4.2 Environmental Source Information

#### **Environment Canada**

A search of the National Pollutant Release Inventory (NPRI) was conducted electronically on May 30, 2017. The Phase I Property was not listed in the NPRI database. No records of pollutant release were listed in the database for the subject site or properties located within the Phase I Study Area.

# PCB Inventory

A search of national PCB waste storage sites was conducted. No PCB sites were identified within the Phase I ESA Study area.

# Ontario Ministry of Environment and Climate Change (MOECC) Instruments

A request was submitted to the MOECC Freedom of Information office for information with respect to certificates of approval, permits to take water, certificates of property use or any other similar MOECC issued instruments for the site. At the time of issuance of this report, a response had not been received from the MOECC. A copy of the response will be forwarded onto the client if it contains any pertinent information

# **MOECC Coal Gasification Plant Inventory**

The Ontario Ministry of Environment document titled "Municipal Coal Gasification Plant Site Inventory, 1991" was reviewed to reference the locations of former plants with respect to the site. No coal gasification plants were identified within 1 km of the subject site.



# **MOECC Incident Reports**

A request was submitted to the MOECC Freedom of Information office for information with respect to records concerning environmental incidents, orders, offences, spills, discharges of contaminants or inspections maintained by the MOECC for the site or adjacent properties. At the time of issuance of this report, a response had not been received from the MOECC. A copy of the response will be forwarded onto the client if it contains any pertinent information

# **MOECC Waste Management Records**

A request was submitted to the MOECC Freedom of Information office for information with respect to waste management records. Applicable information of current and historical waste storage locations, waste generators and waste receivers pursuant to Ontario Regulation 347 was considered in this review. At the time of issuance of this report, a response had not been received from the MOECC. A copy of the response will be forwarded onto the client if it contains any pertinent information

#### **MOECC Submissions**

A request was submitted to the MOECC Freedom of Information office for information with respect to reports related to environmental conditions that have been submitted to the MOECC. At the time of issuance of this report, a response had not been received from the MOECC. A copy of the response will be forwarded onto the client if it contains any pertinent information.

# **MOECC Brownfields Environmental Site Registry**

A search of the MOECC Brownfields Environmental Site Registry was conducted as part of this assessment for the site, neighbouring properties and the general area of the site. No Records of Site Condition (RSCs) have been filed for the Phase I Property. One (1) RSC was identified in the Phase I ESA Study Area. The RSC is filed for 1357 Baseline Road, approximately 30m to the north of the subject site. The property is now developed with a retail complex. No concerns were identified during a review of the RSC filing and the current use of the RSC site.

#### **MOECC Waste Disposal Site Inventory**

The Ontario Ministry of Environment document titled "Waste Disposal Site Inventory in Ontario, 1991" was reviewed as part of the historical research. This document includes all recorded active and closed waste disposal sites, industrial manufactured gas plants and coal tar distillation plants in the Province of Ontario.

August 1, 2017 Page 9





There are no active or closed waste disposal sites or former manufactured gas or coal tar distillation plans within the Phase I ESA study area.

# **Areas of Natural Significance (ANSIs)**

A search for areas of natural significance and features within the Phase I study area was conducted on the web site of the Ontario Ministry of Natural Resources (MNR) on May 30, 2017. The search did not reveal any natural features or ANSIs within the Phase I study area.

# **Technical Standards and Safety Authority (TSSA)**

The TSSA, Fuels Safety Branch in Toronto was contacted electronically on June 1, 2017 to inquire about current and former underground storage tanks, spills and incidents for the site and neighbouring properties. No records are listed in the TSSA registry for the Phase I Property. Two properties within the Phase I ESA study area were identified during the search;

- □ 1460 Merivale Road, the adjacent property to the east, is identified as having 2 active underground tanks. Based on the aerial photos of the property, the tanks are located approximately 170m to the east of the subject site. Due to the separation distance, the USTs are not considered to represent an APEC on the subject site.
- □ 1432 Baseline Road, located approximately 35m to the west of the subject site. The TSSA registry indicates that there are 4 active USTs on the subject site. The USTs are located approximately 70m to the west of the subject site. Due to the separation distance and the inferred downgradient location the USTs are not considered to represent an APEC to the subject site.

A copy of the TSSA correspondence is included in Appendix 2.

# City of Ottawa Landfill Document

The document entitled "Old Landfill Management Strategy, Phase I – Identification of Sites, City of Ottawa", was reviewed. Based on this document, there are no former landfills within the Phase I ESA study area.

#### **Former Industrial Sites**

The report entitled "Mapping and Assessment of Former Industrial Sites, City of Ottawa" was also reviewed. The Phase I ESA property is not part of the former City of Ottawa boundaries and information for the subject site is not available. Part of the Phase I ESA Study area lies within the former City of Ottawa

Ottawa, Ontario



boundaries and no former industrial sites were identified in the Phase I ESA Study area.

# City of Ottawa Historical Land Use Inventory (HLUI)

A search of the City of Ottawa's Historical Land Use Inventory (HLUI) database was conducted in 2012 as part of the Pinchin investigation. A review of this search is included below. The HLUI search identified nine (9) activities associated with the Phase I Property, as well as 27 activities associated with properties within the Phase I Study Area. The HLUI search results for the subject site and any information resulting in an APEC are summarized in Table 3.

Table 3: City of Ottawa Historical Land Use Inventory (HLUI) Search Results						
Address	Listed Activity (years listed)	Approximate Distance / Orientation from site	Potential Environmental Concern (Y/N)			
1464 Merivale Road	Patton's Cleaners (1960-1980)	On-site	Y			
8 Kimway Cresent	Unnamed Machine Shop (1965)	On-site	Υ			
1504 Merivale Road	Bradley's Texaco Service Station (1960-1980)	Off-site, adjacent south	Y			
1490 Merivale Road	Hume's Transport (1956-1965)	On-site	Υ			
1380 Baseline Road	Midas Auto Service Experts (2001-2005)	On-site	Y			
1377 Clyde Avenue	Frisby Tire (1970-2005)	Offsite, adjacent west	Υ			
1383 Clyde Avenue	IBM (1965-1966)	Offsite, adjacent west	Y			
1486 Merivale Road	William S. Burnside (1960-2005) Swan's Garage (2001-2005)	Offsite, adjacent south	Y			
1480 Merivale Road	Fraser Fuels Limited (1970-1980)	Offsite, adjacent south	Y			
Note: Listed activities with more than one address but identified as the same location are listed as one						

Note: Listed activities with more than one address but identified as the same location are listed as one location.

As discussed in previous sections, on-site PCAs representing APECs on the Phase I Property include the on-site cleaners, the former retail fuel outlet, the former transportation company, and the existing Midas Auto Service garage.



Four off-site PCAs are considered to represent an APEC on the Phase I Property, one printers (IBM), two garages (Frisby Tire, William S. Burnside/Swan's Garage) and a fuel distributer (Fraser Fuels Limited), are considered to represent APECs on the Phase I Property. Several other PCAs were identified in the HLUI search, however these PCAs are not considered to represent APECs on the Phase I ESA property based on separation distance. Only the PCAs resulting in an APEC are listed in the above table.

It should be noted that civic addresses have changed over the years and those listed above may not currently exist. The respective distances of the above noted activities from the RSC property were determined using FIPs and the City of Ottawa electronic mapping website.

#### **ERIS Search**

As part of their Phase I-ESA completed in 2012 Pinchin completed an ERIS search for the subject site and a 250m radius surrounding the property. The ERIS search identified a total of 348 mappable records for the subject site and the surrounding 250 m radius. A total of 8 records were available for the subject site. The records available for the subject site consist of six water well information system records, one borehole record, and one certificate of approval for a restaurant. The majority of the records for the surrounding area are for water well records with multiple waste generators and TSSA records also identified.

The water well records identified for the subject site are considered to be either decommissioned drinking water wells or monitoring wells. The onsite records are not considered to represent PCAs on the subject site. The information contained in the offsite records is also present in several other sources and no additional information about the nature of the operations was produced in the ERIS report.

# 4.3 Physical Setting Sources

# **Aerial Photographs**

Historical air photos from the National Air Photo Library were reviewed in approximate ten (10) year intervals. The review period dates back to the first available air photos for the site. Based on the review, the following observations have been made:

1945

The Phase I Property appears to be mostly vacant with only some small buildings along Merivale Road. The majority of the surrounding properties appear to be vacant or agricultural with



	some residential properties along the major roadways. Baseline Road and Merivale Road are present in approximately their current configuration.
1955	No significant changes appear to have been made to the subject site. The surrounding area has started to be developed with residential properties.
1965	The subject site has been redeveloped with multiple commercial buildings. The adjacent properties have also been developed with commercial uses. Residential development continues along Merivale Road and Clyde Avenue.
1975	No significant changes appear to have been made to the subject site. A suspected gas bar is present to the west of the subject site, along Baseline Road. The development of surrounding properties continues with several additional commercial structures visible.
1988	No significant changes appear to have been made to the subject site. The development of surrounding properties continues with several additional commercial and office structures visible.
1999	No significant changes appear to have been made to the subject site. The development of surrounding properties continues with several additional commercial and office structures visible.
2007	(City of Ottawa) Several of the buildings along Kimway Cresent have been demolished. Kimway Crescent appears to no longer be in use. No significant changes have been made to the remainder of the subject site or the neighbouring properties.
2014	(City of Ottawa) All the buildings on the subject site have now been demolished with the exception of the Midas building along Baseline Road. No significant changes have been made to the neighbouring properties.

Laser copies of selected aerial photographs reviewed are included in Appendix 1.

# **Topographic Maps**

Topographic maps were obtained from Natural Resources Canada – The Atlas of Canada website and from the City of Ottawa website. The topographic maps indicate that the local topography in the immediate vicinity of the site slopes



gently downward to the south, while the regional topography generally slopes down to the northwest, toward the Ottawa River.

According to the maps, the nearest water body is the Rideau River, located approximately 2.6 km to the southeast of the Phase I Property. An illustration of the referenced topographic map is presented on Figure 2 – Topographic Map, appended to this report

# **Physiographic Maps**

A Physiographic Map was reviewed from the Natural Resources Canada – The Atlas of Canada website. According to this physiographic map, the site is located in the St. Lawrence Lowlands. According to the mapping description provided: "The lowlands are plain-like areas that were all affected by the Pleistocene glaciations and are therefore covered by surficial deposits and other features associated with the ice sheets." The subject site is located in the Central St. Lawrence Lowland, which is generally less than 150 m above sea level.

# **Geological Maps**

The Geological Survey of Canada website on the Urban Geology of the National Capital Area was consulted as part of this assessment. Based on this information, bedrock in the area of the site consists of interbedded limestone and dolomite of the Gull River Formation. Overburden is reported to consist of Glacial Till of depths ranging from 0-10 m.

#### **Water Well Records**

Well records for all drilled wells within the Phase I study area were reviewed on the MOECC website. Based on the results of the well records search, there are approximately 33 well records for the Phase I Property. Over 300 well records were observed for properties within 250 m of the subject land.

The well records observed onsite appear to relate to the Phase II ESA completed by Pinchin as well as several historical drinking water well records. Several of the drinking water well records are considered to be improperly located on the MOECC website and are not located on the subject site. Based on the Phase I ESA site visit, there are no drinking water wells located on the subject site.

Several historical drinking water well records are present at the residential subdivision to the west of the subject site, across Clyde Avenue. It is suspected that these drinking water wells have been decommissioned and are no longer present as the area is serviced by municipal drinking water.



Based on a review of the well records, there was no new information contained in the online water well database that poses a significant environmental concern to the subject site.

# **Water Bodies and Areas of Natural Significance**

No water bodies are present within the Phase I study area. The Rideau River is the closest significant water body and is present approximately 2.6km southeast of the Phase I Property. No areas of natural significance are known to exist within the Phase I study area.

# 5.0 INTERVIEWS

# **Property Owner Representative**

Ms. Hilary Vaillancourt was interviewed as part of the Phase I ESA process. Ms. Vaillancourt was able to provide all the information which Osmington had on file for the subject site, including previous reports and survey documents. Ms. Vaillancourt did not know of any additional information relating to the subject site which was not provided in the reports or documents. Ms. Vaillancourt indicated that the Midas property will not allow Paterson to access the site for the purposes of a Phase I ESA site visit.

# 6.0 SITE RECONNAISSANCE

# 6.1 General Requirements

A representative from the Environmental Department of Paterson Group conducted a site visit on June 13, 2017. Weather conditions were overcast with a temperature of approximately 25°C. At the time of the site visit, the neighbouring properties within the Phase I study area were also observed from publicly accessible areas.

# 6.2 Specific Observations at Phase I Property

## **Buildings and Structures**

The Phase I Property is currently vacant with the exception of two areas, a parking lot near the intersection of Merivale Road and Clyde Road, and a single storey brick building along Baseline Road. The subject site is covered in gravel, asphalt or vegetated. Two building foundations were identified, one along Merivale Road and a second along the former alignment of Kimway Crescent. A



fire hydrant and several light standards were visible in the area of Kimway Crescent.

No other structures were present on the Phase I Property at the time of the site visit.

# **Underground Utilities**

Underground utilities are expected to be present on the subject site in the area of the existing building. Any utilities relating to the former buildings or roadway are expected to have been decommissioned and are no longer in use.

#### Site Features

The subject property is being used as a parking lot, automotive service garage, or is vacant. The majority of the site is currently vacant and either covered in asphalt or vegetation.

No evidence of current or former railway or spur lines was observed on the exterior of the subject property at the time of the site visit. There were no unidentified substances observed on the exterior of the Phase I Property at the time of the site visit.

The Phase I ESA study area is serviced with municipal water. There were no potable wells observed on the Phase I Property or on other properties within the Phase I study area, at the time of the site visit.

The above-noted site features are shown on Drawing PE4001-1 - Site Plan.

#### Fill Material

Fill material was identified during Phase-II ESA completed by Pinchin. The fill material generally consisted of sand and gravel material. The fill material was located in the northwest portion of the property, evaluated by Pinchin and is considered to represent an APEC on the subject site.

# **Neighbouring Properties**

An inspection of the neighbouring properties was conducted from publicly accessible roadways at the time of the site inspection. Land use adjacent to the Phase I Property was as follows:

□ North –Commercial properties (including an automotive service garage) and Baseline Road followed by commercial (retail) and office spaces;





South - Garage,	radio station	and restaurant	properties	followed by	/ Merivale
Road and comme	ercial propertie	es;			

- ☐ East Commercial properties (grocery store) followed by retail fuel outlet and other commercial properties;
- □ West Commercial properties (retail stores and service garage) followed by Clyde Avenue.

The automotive service garages identified at 1377 Clyde Avenue and 1486 Merivale Road are considered to represent APECs on the subject site. The reminding PCAs identified during the inspection of neighbouring properties are not considered to represent APECs due to the separation distance.

Land use within the Phase I study area (250 m radius) is primarily used for residential and commercial purposes with some institutional land use. Several off-site PCAs were identified at the time of the site visit, however none of which are considered to represent an APEC to the subject site. Surrounding land use is shown on Drawing PE4001-2 – Surrounding Land Use Plan.

# 7.0 REVIEW AND EVALUATION OF INFORMATION

# 7.1 Land Use History

The following table outlines the general ownership and land use dating back to the first developed use of the Phase I Property.

Table 4 - Land Use History – 1500 Merivale Road							
Year	Name of Owner	Description of Property Use	Property Use	Other Observations from Aerial Photos, FIPs, etc.			
Plan 30 registe	ered August 16, 18	370 (Ordnance Lai	nds) by The Crow	n			
1870 - 1952	Sold in parcels to various individuals	Residential and agricultural	Agricultural and Residential	1945 Aerial photos show the properties as having few buildings and agricultural fields.			
1952 - 2008	Owned by various corporations and individuals	Commercial	Commercial	1956 FIPs show the property as being primarily commercial.			
2008-2015	Owned by Osmington Inc.	Commercial	Commercial	2008 Aerial photo shows several buildings present on the property			

August 1, 2017 Page 17



Table 4 - Land Use History – 1500 Merivale Road							
Year	Name of Owner	Description of Property Use	Property Use	Other Observations from Aerial Photos, FIPs, etc.			
Plan 30 registe	ered August 16, 18	370 (Ordnance Lai	nds) by The Crow	n			
2015- Present	Owned by 1455251 Ontario Inc.	Commerical	Commercial	2014 Aerial photo shows no buildings present on the property with the exception of the Midas building along Baseline.			

# Potentially Contaminating Activities and Areas of Potential Environmental Concern

Potentially contaminating activities (PCAs) considered to result in areas of potential environmental concern (APECs) on the Phase I Property, are described in Table 5 below and shown in red on Drawing PE4001-1 – Site Plan. Off-site PCAs are shown on Drawing PE4001-2 – Surrounding Land Use Plan.

Additional PCAs identified within the Phase I study area were not considered to represent APECs on the Phase I Property based on their respective separation distances and/or their inferred down-gradient or cross-gradient orientations with respect to the Phase I Property. PCAs are shown in green on Drawing PE4001-2.

Table 5								
Areas of Potential Environmental Concern								
Area of Potential of Potential Environmental Concern Concern with respect to Phase I Property		Potentially Contaminating Activity	Location of PCA (on-site or off- site)	Contaminants of Potential Concern	Media Potentially Impacted (Groundwater, Soil, and/or Sediment)			
APEC 1: Automotive Service Center	Northcentral portion of the Phase I Property	Item 52, Table 2, O.Reg.153/04 as amended by O.Reg.269/11 ("Storage, maintenance, fuelling and repair of equipment, vehicles and material used to maintain transportation systems")	On-site	VOCs, PHCs (F <sub>1</sub> -F <sub>4</sub> )	Soil and Groundwater			



Table 5						
Areas of Pote Area of Potential Environmental Concern	ential Environm Location of Area of Potential Environmental Concern with respect to Phase I Property	Potentially Contaminating Activity	Location of PCA (on-site or off- site)	Contaminants of Potential Concern	Media Potentially Impacted (Groundwater, Soil, and/or Sediment)	
APEC2: Fill Material	Central portion of the Phase I Property	Item 30, Table 2, O.Reg.153/04 as amended by O.Reg.269/11 (Importation of Fill Material of Unknown Quality)	On-site	Metals, PAHs	Soil and Groundwater	
APEC3: Machine Shop	Central-East portion of the Phase I Property	Other	On-site	VOCs, PHCs (F <sub>1</sub> -F <sub>4</sub> )	Soil and Groundwater	
APEC4: Drycleaners and UST	Southeastern portion of the Phase I Property	Item 37, Table 2, O.Reg.153/04 as amended by O.Reg.269/11 (Operation of Dry Cleaning Equipment), Item 28, Table 2, O.Reg.153/04 as amended by O.Reg.269/11 (Gasoline and Associated products in fixed tanks)	On-site On-site	VOCs, PHCs (F <sub>1</sub> -F <sub>4</sub> )	Soil and Groundwater	
APEC5: Garage and Service Station	Southeastern portion of the Phase I Property	Item 52, Table 2, O.Reg.153/04 as amended by O.Reg.269/11	On-site	VOCs, PHCs (F <sub>1</sub> -F <sub>4</sub> )	Soil and Groundwater	
APEC6: Garage and Service Station	Adjacent to the south	Item 52, Table 2, O.Reg.153/04 as amended by O.Reg.269/11	Off-site	VOCs, PHCs (F <sub>1</sub> -F <sub>4</sub> )	Soil and Groundwater	
APEC7: Garage and Service Station	Adjacent to the south	Item 52, Table 2, O.Reg.153/04 as amended by O.Reg.269/11	Off-site	VOCs, PHCs (F <sub>1</sub> -F <sub>4</sub> )	Soil and Groundwater	



Table 5					
Areas of Potential Environmental Concern					
Area of Potential Environmental Concern	Location of Area of Potential Environmental Concern with respect to Phase I Property	Potentially Contaminating Activity	Location of PCA (on-site or off- site)	Contaminants of Potential Concern	Media Potentially Impacted (Groundwater, Soil, and/or Sediment)
APEC8: Automotive service station and Transportation office UST	Southcentral portion of the Phase I Property	Item 52, Table 2, O.Reg.153/04 as amended by O.Reg.269/11 Item 28, Table 2, O.Reg.153/04 as amended by O.Reg.269/11	On-site	VOCs, PHCs (F <sub>1</sub> -F <sub>4</sub> )	Soil and Groundwater
APEC9: Former fuel oil UST and retail fuel outlet	Southwestern portion of the Phase I Property	Item 52, Table 2, O.Reg.153/04 as amended by O.Reg.269/11 Item 28, Table 2, O.Reg.153/04 as amended by O.Reg.269/11	On-site	VOCs, PHCs	Soil and Groundwater
APEC 10: Former Printers	Adjacent to the west	Other	Off-site	VOCs	Soil and Groundwater
APEC11 Automotive Service Garage	Adjacent to the west	Item 52, Table 2, O.Reg.153/04 as amended by O.Reg.269/11	Off Site	VOCs, PHCs (F <sub>1</sub> -F <sub>4</sub> )	Soil and Groundwater
APEC 12 Former Gas Bar and Garage	Adjacent to the west	Item 52, Table 2, O.Reg.153/04 as amended by O.Reg.269/11	Off-site	VOCs, PHCs	Soil and Groundwater

# **Contaminants of Potential Concern (CPCs)**

Based on the PCAs identified above, CPCs present on or beneath the Phase I Property include volatile organic compounds (VOCs), petroleum hydrocarbons (PHCs), polycyclic aromatic hydrocarbons (PAHs), and metals.

# 7.2 Conceptual Site Model

# **Geological and Hydrogeological Setting**

The Geological Survey of Canada website on the Urban Geology of the National Capital Area was consulted as part of this assessment. Based on this information, bedrock in the area of the site consists of interbedded limestone and



dolomite of the Gull River Formation. Overburden is reported to consist of Glacial Till of depths ranging from 0-10m.

The regional and surrounding topography slopes to the south and the west. The local groundwater flow beneath the Phase I Property is inferred to be in a south east direction.

#### **Contaminants of Potential Concern**

As noted above, the CPCs identified in this Phase I ESA included VOCs, PHCs, PAHs and metals. CPCs may be encountered in the soil or groundwater in the vicinity of the historical on-site automotive service garages, underground storage tanks, reported cleaners and offsite retail fuel outlets. Potential mechanisms of contaminant transport within the groundwater system include advection, dispersion, and diffusion.

# **Existing Buildings and Structures**

One building is present on the subject site, along Baseline Road. The building currently operates as a Midas automotive repair garage. No access was provided to the Midas building or property. Two old building foundations are present on the subject site. The foundations are present along Merivale Road and the former alignment of Kimway Crescent. Several light standards are also present along Kimway Crescent.

Pavement structures are present in large portions of the site, as well as abandoned utilities. These structures are considered to be shallow.

#### **Water Bodies**

No water bodies are present within the Phase I study area. The Rideau River is the closest significant water body and is present approximately 2.6km southeast of the Phase I Property

## Areas of Natural Significance

No areas of natural significance were identified on the Phase I Property or in the Phase I study area.

## **Drinking Water Wells**

No drinking water wells are located on the Phase I Property or expected within the Phase I study area.



# **Groundwater Monitoring Wells**

Multiple groundwater monitoring wells were identified on the Phase I ESA property. The monitoring wells are primarily clustered in two locations, near the intersection of Merivale Road and Clyde Avenue and near the intersection of Merivale Road and Kimway Cresent. Several other monitoring wells are present throughout the site in areas where an APEC was previously identified by Pinchin.

Over 300 entries in the well records database were identified. To the west of the site, across Clyde Avenue, the residential subdivision appears to have been at one time been on private well systems. It is our understanding that the subdivision is currently on municipal water and the private wells are no longer in use. No potable water wells are considered to be present within the Phase I study area.

# **Neighbouring Land Use**

Neighbouring land use in the Phase I study area is primarily commercial and residential with occasional community or institutional uses. Land use is shown on Drawing PE4001-2 - Surrounding Land Use Plan.

# Potentially Contaminating Activities and Areas of Potential Environmental Concern

Eleven PCA's representing APECs on the subject site were identified during the historical research.

Six automotive repair shops and service stations located throughout the Phase I Property.			
Former dry cleaner in the southeast corner of the Phase I Property.			
Fill material in select areas of the subject site.			
Former printers to the west of the Phase I ESA property.			
Machine shop located in the central area of the Phase I ESA property			
Former fuel oil UST near the southwestern portion of the Phase I ESA			

Additional PCAs were identified within the Phase I study area, however these activities were not considered to represent APECs on the Phase I Property based on their respective separation distances, and inferred orientations down or cross-gradient with respect to the Phase I Property.

property



# **Assessment of Uncertainty and/or Absence of Information**

The information available for review as part of the preparation of this Phase I ESA is considered to be sufficient to conclude that there are areas of potential environmental concern on the subject site resulting from current and historical uses of the subject site and neighbouring properties. The presence of potentially contaminating activities was confirmed by a variety of independent sources. The conclusions of this report are not affected by uncertainty which may be present with respect to the individual sources.



# 8.0 CONCLUSIONS

#### **Assessment**

Paterson Group was retained by Osmington, to conduct a Phase I Environmental Site Assessment (ESA) of the property addressed 1500 Merivale Road, in the City of Ottawa, Ontario. The purpose of this Phase I ESA was to research the past and current use of the site and study area and to identify any environmental concerns with the potential to have impacted the subject property.

The results of the historical research indicated that the subject property was developed for residential purposes prior to 1945 and redeveloped for commercial purposes sometime in the 1950s. Several garages and commercial operations, including a dry cleaner, occupied the southern portion of the property. These former activities are potentially contaminating activities (PCAs) which represent areas or an area of potential environmental concern (APECs) on the Phase I Property.

Fourteen off-site historical PCAs were identified within the Phase I ESA study area. Four of which represent an APEC to the subject site, the former and current garages and service stations located at 1480, 1482 Merivale Road, the former and existing service station at 1377 Clyde Avenue, and the former printers at 1783 Clyde Avenue. The garages, services stations, and printers are considered to have the potential to impact the soil and groundwater quality of the subject site.

One PCA representing an APEC was identified on the subject site at the time of the assessment. The Midas automotive service garage located at 1380 Merivale Road. At the time of the assessment Paterson was not provided access to the property and was only able to evaluate the operations from a distance. Two offsite PCAs representing APECs were identified at the time of the site visit. Automotive service garages at 1377 Clyde Avenue and 1486 Merivale Road are considered to represent APECs to the subject site.

# Recommendations

Based on the results of this Phase I ESA, it is our opinion that a Phase II Environmental Site Assessment is required for the property.



# 9.0 STATEMENT OF LIMITATIONS

This Phase I Environmental Site Assessment report has been prepared in general accordance with O.Reg. 153/04 as amended by O.Reg. 269/11, and meets the requirements of CSA Z768-01. The conclusions presented herein are based on information gathered from a limited historical review and field inspection program. The findings of the Phase I - ESA are based on a review of readily available geological, historical and regulatory information and a cursory review made at the time of the field assessment. The historical research relies on information supplied by others, such as, local, provincial and federal agencies and was limited within the scope-of-work, time and budget of the project herein.

Should any conditions be encountered at the subject site and/or historical information that differ from our findings, we request that we be notified immediately in order to allow for a reassessment.

This report was prepared for the sole use of Osmington Inc. Permission and notification from Osmington Inc. and Paterson will be required to release this report to any other party.

POFESSION

M.S. D'ARCY

Paterson Group Inc.

Michael Beaudoin, P.Eng.

Mark S. D'Arcy, P.Eng. QPESA

**Report Distribution:** 

□ Osmington Incorporated (6 copies)

□ Paterson Group (1 copy)



# 10.0 REFERENCES

#### **Federal Records**

Air photos at the Energy Mines and Resources Air Photo Library.

National Archives.

Maps and photographs (Geological Survey of Canada surficial and subsurface mapping).

Natural Resources Canada - The Atlas of Canada.

Environment Canada, National Pollutant Release Inventory.

PCB Waste Storage Site Inventory.

#### **Provincial Records**

MOECC Freedom of Information and Privacy Office.

MOECC Municipal Coal Gasification Plant Site Inventory, 1991.

MOECC document titled "Waste Disposal Site Inventory in Ontario".

MOECC Brownfields Environmental Site Registry.

Office of Technical Standards and Safety Authority, Fuels Safety Branch.

MNR Areas of Natural Significance.

MOECC Water Well Inventory.

# **Municipal Records**

City of Ottawa Document "Old Landfill Management Strategy, Phase I - Identification of Sites.", prepared by Golder Associates, 2004.

Intera Technologies Limited Report "Mapping and Assessment of Former Industrial Sites, City of Ottawa", 1988.

City of Ottawa Historical Land Use Inventory (HLUI) database

The City of Ottawa eMap website.

#### **Local Information Sources**

Chain of Title obtained through Read Abstracts Limited, October 17, 2016. Topographical Plan, prepared by Annis, O'Sullivan, Vollebekk Ltd., January 21, 2016.

Personal Interviews.

Previous Engineering Reports.

#### **Public Information Sources**

Google Earth.

Google Maps/Street View.


# **FIGURES**

FIGURE 1 – KEY PLAN


FIGURE 2 – TOPOGRAPHIC MAP

**DRAWING PE4001-1 - SITE PLAN** 

DRAWING PE4001-2 – SURROUNDING LAND USE PLAN





# FIGURE 1 KEY PLAN



# FIGURE 2 TOPOGRAPHIC MAP

patersongroup \_





# **APPENDIX 1**

**CHAIN OF TITLE** 

**PLAN OF SURVEY** 

**AERIAL PHOTOGRAPHS** 

**SITE PHOTOGRAPHS** 



# **READ Abstracts Limited**

331 Cooper Street, Suite 300, Ottawa, Ontario K2P 0A4
Email: search@readsearch.com

Tel.: 613-236-0664 Fax: 613-236-3677

# **ENVIRONMENTAL SEARCH**

June 20, 2017

Paterson Group

Attn: Michael Beaudoin

## BRIEF DESCRIPTION OF LAND:

1500 Merivale Road, Ottawa Part of Lots 18, 19, 20, 21, Plan 30

PIN: 04686-0027 04686-0007

LAST REGISTERED OWNER: 1455251 ONTARIO INC.

## CHAIN OF TITLE:

Plan 30 registered August 16, 1870 (Ordnance Lands) By The Crown

#### **Lot 21**

Patent Registered May 13, 1870 From The Crown to Robert Stewart

Patent Registered March 9, 1875 From The Crown to James Stewart

Deed NP7232 registered June 20, 1896 From James Stewart to James Stewart Jr.

Deed NP23402 registered March 31, 1916 From James Stewart Jr. to Robert Stewart

Deed NP31634 registered November 16, 1917 From Robert Stewart to James R. Stewart

Deed 338949 registered October 18, 1955

From Estate of James R. Stewart to Frederick W. Stewart

Deed 338950 registered October 18, 1955

From Estate of James R. Stewart to Frederick W. Stewart

Deed 344853 registered April 11, 1956

From Estate of James R. Stewart to Frederick W. Stewart

Deed 344854 registered April 11, 1956

From Frederick W. Stewart to L. A. Mckinley Agencies Limited

Deed 344855 registered April 11, 1956

From L. A. Mckinley Agencies Limited to McColl-Frontenac Oil Company Limited

Deed 348677 registered July 11, 1956

From L. A. Mckinley Agencies Limited to Norman F. McKee

Deed 352187 registered October 12, 1956

From McColl-Frontenac Oil Company Limited to Highway Realties Limited

Lease 352188 registered October 12, 1956

Highway Realties Limited to McColl-Frontenac Oil Company

Deed 365519 registered November 1, 1957

From Norman F. McKee to Bellite Products Limited

Deed 411990 registered September 21, 1960

From Bellite Products Limited to Jarlaw investments Limited

Lease 419311 registered February 23, 1961

From Jarlaw Investments Limited to Bushnell T.V. Co. Limited

Expropriation 685847 registered February 26, 1976

By The Regional Municipality of Ottawa-Carleton

Deed 696793 registered September 24, 1976

From Jarlaw Investments Limited to Bushnell Communications Limited

Deed NS70186 registered October 15, 1979

From The Regional Municipality of Ottawa-Carleton to Bushnell Communications Limited

Lease NS212910 registered October 5, 1983

From Bushnell Communications Limited to Telesat Canada

Deed N341500 registered June 24, 1986

From Bushnell Communications Ltd. To Bushnell Communications Ltd.

Deed N436835 registered May 6, 1988

From Bushnell Communications Ltd. To Nation's Capital Television Inc.

#### **Lot 19**

Patent registered May 13, 1870 From The Crown to David West

Patent registered August 9, 1873 From The Crown to David West

Deed NP1316 registered September 11, 1874 From David West to Thomas Shillington

Deed NP4042 registered October 14, 1875 From Thomas Shillington to George Emiley

Deed NP6323 registered October 9, 1879 From George Emiley to Robert E. Nelson and Robert J. Mulaugh

Deed NP6325 registered October 12, 1879 From George Emiley to John MacDonald

Deed NP6705 registered February 28, 1880 From john McDonald to George Cowan

Deed NP10257 registered March 9, 1885 From George Cowan to William H. Stapleton

Deed NP14069 registered September 21, 1889 From William H. Stapleton to William L. Scott

Deed NP15611 registered March 1, 1982 From William L. Scott to Robert G. Foster

Deed NP34249 registered December 10, 1920 From Robert G. Foster to Christopher Withens

Deed NP62843 registered August 2, 1949 From Christopher Withens to Donald Fraser and Hazel Fraser

Deed 303787 registered September 8, 1952 From Donald Fraser and Hazel Fraser to Donald M. Thomson

Deed 306468 registered December 4, 1952 From Donald M. Thomson to Church Extension Board of the Baptist Convention

Deed 326315 registered October 7, 1954 Robert E. Nelson and Robert J. Mulaugh to Donald Fraser and Hazel Fraser

Deed 382373 registered December 29, 1958 From Church Extension Board of the Baptist Convention of Ontario and Quebec to Trustees of Bethany Baptist Church

Deed 404092 registered April 13, 1960

From Donald Fraser and Hazel Fraser to Ernest B. Warsiner

Lease 407928 registered July 6, 1960

From Ernest B. Warsiner to Honeywell Controls Limited

Deed 407931 registered July 6, 1960

From Ernest B. Warsiner to Canada Life Assurance Company

Deed 412046 registered September 21, 1960

From Donald Fraser and Hazel Fraser to Albert Miller, in trust

Deed 417556 registered January 9, 1961

From Albert Miller, in trust to M. H. Rhodes Inc.

Deed 487571 registered December 15, 1964

From Donald Fraser and hazel Fraser to R. E. de Champlain Company Limited

Deed 537848 registered January 30, 1968

From R. E. de Champlain Company Limited to Hubert Renaud

Lease 548523 registered September 20, 1968

From Hubert Renaud to Imperial Oil Limited

Deed 591745 registered June 1, 1971

From R. E. de Champlain Company Limited to Hubert Renaud

Deed 640495 registered October 2, 1973

From Hubert Renaud to Jarlaw Investments Limited

Deed 642371 registered October 31, 1973

From the Canad life Assurance Company to Jarlaw Investments Limited

Deed 654578 registered June 10, 1974

From Donald Fraser and Hazel Fraser to Jarlaw Investments Limited

Deed 696793 registered September 24, 1976

From Jarlaw Investments Limited to Bushnell Communications Limited

Deed N341500 registered June 24, 1986

From Bushnell Communications Ltd. To Bushnell Communications Ltd.

Deed N436835 registered May 6, 1988

From Bushnell Communications Ltd. To Nation's Capital Television Inc.

Deed N478830 registered March 10, 1989

From Baptist Convention of Ontario to The Trustees of Bethany Church

Deed N478831 registered March 10, 1989 From The Trustees of Bethany Church to Nation's Capital Television Inc.

#### **Lot 18**

Patent registered May 13, 1870 From The Crown to David West

Patent registered August 9, 1873 From The Crown to David West

Deed NP1316 registered September 11, 1874 From David West to Thomas Shillington

Deed NP4026 registered October 6, 1875 From Thomas Shillington to Thomas Robertson

Mortgage NP4027 registered October 6, 1875 From Thomas Robertson to Thomas Shillington

Assignment of Mortgage NP6326 registered April 15, 1879 From Thomas Shillington to R. A. Bradley

Foreclosure NP6327 registered April 15, 1879 From R. A. Bradley to Thomas Shillington

Deed NP6679 registered January 28, 1880 From Thomas Shillington to George Cowan

Deed NP10257 registered March 9, 1885 From George Cowan to William H. Stapleton

Deed NP14069 registered September 21, 1889 From William H. Stapleton to William L. Scott

Deed NP15611 registered March 1, 1982 From William L. Scott to Robert G. Foster

Deed NP34249 registered December 10, 1920 From Robert G. Foster to Christopher Withens

Deed NP62843 registered August 2, 1949 From Christopher Withens to Donald Fraser and Hazel Fraser

Deed 326315 registered October 7, 1954 Robert E. Nelson and Robert J. Mulaugh to Donald Fraser and Hazel Fraser

Deed 654578 registered June 10, 1974 From Donald Fraser and Hazel Fraser to Jarlaw Investments Limited Deed 696793 registered September 24, 1976 From Jarlaw Investments Limited to Bushnell Communications Limited

Deed N341500 registered June 24, 1986 From Bushnell Communications Ltd. To Bushnell Communications Ltd.

Deed N436835 registered May 6, 1988 From Bushnell Communications Ltd. To Nation's Capital Television Inc.

#### Lot 20

Patent registered June 17, 1872 From The Crown to Mary P. Brown

Deed NO1425 registered June 5, 1873 From Mary P. Brown to Joseph McGaw

Deed NP2026 registered June 5, 1873 From Mary P. Brown to Joseph McGaw

Deed NP2027 registered June 5, 1873 From Joseph McGaw to Mary P. Brown

Deed NP15585 registered February 2, 1892 From Joseph McGraw to A. L. McGaw

Deed NP15586 registered February 2, 1892 From Andrew McGaw to William G. McCullaough

Deed NP18929 registered April 25, 1901 From William G. McCullaough to Caroline McDonald

Deed NP19060 registered October 16, 1901 From William G. McCullaough to Joseph Burton

Deed NP23966 registered December 165, 1910 From William G. McCullaough to John H. McCullaough

Deed NP24769 registered October 4, 1911 From Caroline McDonald to William R. Jackson

Mortgage NP27750 registered January 28, 1914 From John H. McCullaough to Agnes Kinnaird

Vesting Order NP30350 registered May 16, 1916 To Agnes Kinnaird

Deed NP50244 registered May 1943 From William Jackson and Ada Smith to George and Margaret Pettes Deed NP50973 registered May 15, 1943 From estate of Agnes Kinnaird to Jason M. Kirkland

Tax Deed NP51335 registered May 3, 1944 Corporation of the Township of Nepean to George Taylor

Deed NP51336 registered May 3, 1944 From George Taylor to Margaret Lavis

Deed NP51706 registered June 22, 1944 From Jason M. Kirkland to Richard and Harriot Williams

Deed NP52809 registered May 31, 1945 From George and Margaret Pettes to Adam Baker

Deed NP53000 registered Jun 28, 1945 From Adam baker to Annie E. Lahoise

Deed NP56595 registered June 30, 1946 From Richard and Harriot Williams to Thomas B. Hoggan

Deed NP58555 registered November 29, 1947 From Richard and Harriot Williams to Margaret Hoggan

Deed NP58556 registered November 29, 1947 From Richard and Harriot Williams to Victor Clark

Proabte 288754 registered February 15, 1951 From Victor Clark to Gertrude McGee

Deed 289076 registered February 28, 1951 From Richard and Harriot Williams to Thomas and Theresa Williams

Deed 302286 registered July 9, 1952 From Thomas and Theresa Williams to Redmond J. McGuire

Deed 310761 registered May 13, 1953 From Estate of Richard Williams to Harriot Williams

Deed 331990 registered April 14, 1955 From Margaret Lavis to Ellen N. Armstrong

Deed 344687 registered April 5, 1956 From Gertrude McGee to Humes Transport Limited

Deed 375104 registered July 23, 1958 From Ellen N. Armstrong to Armstrong Construction & Equipment Ltd.

Deed 375329 registered July 30, 1958

From Armstrong Construction & Equipment Ltd. to Ellen Armstrong

Lease 380438 registered November 12, 1958 From Ellen Armstrong to Bank of Montreal

Assignment of Lease 383393 registered January 23, 1959

From Armstrong Construction & Equipment Ltd. to North American life Assurance Company

Deed 383370 registered January 23, 1959

From Ellen Armstrong to Armstrong Construction & Equipment Ltd.

Deed 383852 registered February 4, 1959

From Annie Lahoise to Armstrong Construction & Equipment Ltd.

Deed 384082 registered February 11, 1959

From Armstrong Construction & Equipment Ltd. to Ellen Armstrong

Deed 394632 registered Septemebr 16, 1959

From Ellen Armstrong to Armstrong Construction & Equipment Ltd.

Lease 394639 registered September 16, 1959

From Armstrong Construction & Equipment Ltd. to North American life Assurance Company

Deed 397292 registered November 3, 1959

From North American life Assurance Company to Ellen Armstrong

Deed 422102 registered April 21, 1961

From Armstrong Construction & Equipment Ltd. to Ellen Victoria Limited

Deed 422104 registered April 21, 1961

From Ellen Armstrong to Ellen Victoria Limited

Lease 448187 registered August 23, 1962

From Ellen Armstrong to Ellen Victoria Limited

Lease 448198 registered August 23, 1962

From Ellen Victoria Limited to North American life Assurance Company

Lease 448623 registered August 31, 1962

From Ellen Victoria Limited to North American life Assurance Company

Deed 470804 registered December 30, 1963

From Humes Transport Limited to Hume Bros. Investments Limited

Deed 489889 registered February 18, 1965

From Armstrong Construction & Equipment Ltd. to Ellen Victoria Limited

Deed 500625 registered October 1, 1965

From Redmond McGuire to Walter and Frederick Stanger

Deed 800797 registered October 5, 1965

From Margaret Hoggan to Romeo, Samuel and Phillip Nesralla

Deed 560474 registered June 23, 1969

From Hume Bros. investments Limited to Extendicare (Canada) ltd.

Deed 560538 registered June 24, 1969

From Extendicare (Canada) ltd. to Jarlaw Investments Limited

Deed 560588 registered June 25, 1969

From Walter and Frederick Stanger to Jarlaw Investments Limited

Deed 560729 registered June 25, 1969

From Hariiot Williams to Jarlaw Investments Limited

Deed 560730 registered June 16, 1969

From Romeo, Samuel, and Phillip Nesralla to Jarlaw Investments Limited

Deed 586450 registered January 22, 1971

From Jarlaw Investments Limited to Frank Parreca

Deed 696793 registered September 24, 1976

From Jarlaw Investments Limited to Bushnell Communications Limited

Deed NS8116 registered March 22, 1978

From Ellen Victoria Limited to Frank Parreca

Deed N341500 registered June 24, 1986

From Bushnell Communications Ltd. To Bushnell Communications Ltd.

Deed N346203 registered July 22, 1986

From Frank Porreca to Walter Krepski and Alfred Friedman

Deed N436835 registered May 6, 1988

From Bushnell Communications Ltd. To Nation's Capital Television Inc.

Agreement to Lease N436835 registered May 9, 1988

From Bushnell Communications Ltd. to Her Majesty The Queen (Ontario)

Deed N461654 registered October 21, 1988

From Walter Krepski and Alfred Friedman to 785779 Ontario Ltd.

Lease N659162 registered May 18, 1993

From 785779 Ontario Ltd. to 1024202 Ontario Ltd.

Part Lots 18, 19, 20, 21 (PIN 0027)

Name Change OC822986 registered February 8, 2008

From Nation's Capital Television Incorporated to CTV Inc.

Deed OC823573 registered February 11, 2008 From CTV Inc. to Osmington Inc.

Deed OC1679520 registered may 7, 2015 From Osmington Inc. to 1455251 Ontario Inc.

### Part Lot 20 (PIN 0007)


Deed N461654 registered October 21, 1988 From Walter Krepski and Alfred Friedman to 785779 Ontario Ltd.

Power of Sale LT1080077 registered March 3, 1997 From Canada Trustco Mortgage Company to 1213389 Ontario Inc.

Deed OC434826 registered February 18, 2005 From 1213389 Ontario Inc. to 2056967 Ontario Inc.

Deed OC746025 registered July 18, 2007 From 2056967 Ontario Inc. to Osmington Inc.

Deed OC1679520 registered may 7, 2015 From Osmington Inc. to 1455251 Ontario Inc.



SURVEYOR'S REAL PROPERTY REPORT
PART 1 Plan of
PART OF LOTS 18, 19, 20 and 21
REGISTERED PLAN 30
CITY OF OTTAWA

Surveyed by Annis, O'Sullivan, Vollebekk Ltd.

Scale 1:750

30 22.5 15 7.5 0 15 30 Metres

Metric

DISTANCES SHOWN ON THIS PLAN ARE IN METRES AND

### Surveyor's Certificate

I CERTIFY THAT :

 This survey and plan are correct and in accordance with the Surveys Act, the Surveyors Act, the Land Titles Act and the regulations made under them.
 The survey was completed on the 10th day of February, 2012.

CAN BE CONVERTED TO FEET BY DIVIDING BY 0.3048

Fel-14/12 Mbely

PART 2
THIS PLAN MUST BE READ IN CONJUNCTION WITH SURVEY REPORT DATED: FEBRUARY 14, 2012

ANNIS, O'SULLIVAN, VOLLEBEKK LTD. grants to
\_\_\_Osmington Inc.
\_\_\_("The Client"), their solicitors,
mortgagees, and other related parties, permission to use original, signed, sealed
copies of the Surveyor's Real Property Report in transactions involving The Client.

# Notes & Legend

Survey Monument Planted Survey Monument Found Short Standard Iron Bar Iron Bar Cut Cross Round Iron Bar Spike & Washer Short Standard Iron Bar (0.3 Long) Iron Bar (0.3 Long) Annis, O'Sullivan, Vollebekk Ltd. Plan 4R-25160 Plan 4R-13596 Plan 4R-11425 Plan 5R-10060 Plan 5R-3629 Plan 4R-942 (1287) Plan, December 4, 2007 (Ref.281-07) Light Standard Chain Link Fence Concrete Retaining Wall


ASSOCIATION OF ONTARIO LAND SURVEYORS
PLAN SUBMISSION FORM

1825376

THIS PLAN IS NOT VALID UNLESS IT IS AN EMBOSSED ORIGINAL COPY ISSUED BY THE SURVEYOR In accordance with Regulation 1026, Section 29 (3).

Bearings are grid bearings, derived from southerly limit of Part 1, Plan 4R-25160, shown to be N60°28'50"W thereon and are referred to the Central Meridian of Zone 9 of the Ontario Coordinate System, Longitude 76°30' West (MTM NAD-83) Original.






# AERIAL PHOTOGRAPH 1945

patersongroup \_\_\_



# AERIAL PHOTOGRAPH 1955

patersongroup \_\_\_\_




AERIAL PHOTOGRAPH 1965

patersongroup \_\_\_\_



AERIAL PHOTOGRAPH 1975



AERIAL PHOTOGRAPH 1988



AERIAL PHOTOGRAPH 1999



Photograph 1: Looking from Merivale Road, along the former Kimway Crescent alignment. The foundation of a former service station is shown on the left of the photo.



Photograph 2: At the intersection of Kimway Crescent and Merivale Road, looking northeast.



Photograph 3: Former building along Kimway Crescent.



Photograph 4: East side of property, near the end of Kimway Crescent. Looking north at the loading bays of the Loblaws building.



Photograph 5: View south, looking towards the radio station and intersection of Merivale Road and Clyde Avenue.



Photograph 6: Looking north along Clyde Avenue, showing Frisby Tire and other commercial businesses along Clyde Avenue.

1500 Merivale Road, Ottawa, ON

June 13, 2017



Photograph 7: Existing Midas building along Baseline Road

# **APPENDIX 2**

MOECC FREEDOM OF INFORMATION RESPONSE

CITY OF OTTAWA HLUI SEARCH RESULTS

TSSA CORRESPONDENCE

MOECC WELL RECORDS

Ministry of the Environment and Climate Change

Freedom of Information and Protection of Privacy Office

12th Floor 40 St. Clair Avenue West Toronto ON M4V 1M2 Tel: (416) 314-4075 Fax: (416) 314-4285

Ministère de l'Environnement et de l'Action en matière de changement climatique

Bureau de l'accès à l'information et de la protection de la vie privée

12° étage 40, avenue St. Clair ouest Toronto ON M4V 1M2 Tél.: (416) 314-4075 Téléc.: (416) 314-4285



May 30, 2017

Michael Beaudoin Paterson Group Inc 154 Colonnade Road Ottawa, ON K2E 7J5

Dear Michael Beaudoin:

RE: Freedom of Information and Protection of Privacy Act Request Our File # A-2017-03813, Your Reference PE4001

The Ministry is in receipt of your request made pursuant to the Freedom of Information and Protection of Privacy Act and has received your payment in the amount of \$5.00 (non-refundable application fee), along with your \$30.00 deposit.

The search is being conducted on the following: 1500 Merivale Rd and 1366 Baseline Rd, Ottawa. If there is any discrepancy please contact us immediately.

You may expect a reply or additional communication as your request is processed. For your information, the Ministry charges for search, copying and preparation time.

If you have any questions regarding this matter, please contact Jeneska Abano at jeneska.abano@ontario.ca.

Yours truly,

Janet Dadufalza

FOI Manager



File Number: C10-01-12-0169

July 17, 2012

Mike Kosiw Pinchin Environmental Ltd. 555 Legget Drive, Suite 1001 Kanata, ON K2K 2X3

Sent via email [mkosiw@pinchin.com]

Dear Mr. Kosiw,

Re: Information Request – Pinchin Project No. 75040 1468, 1476, 1476A, 1478, 1490, 1492, 1500 Merivale Road & 1366, 1380, 1386 Baseline Road, Ottawa, Ontario ("Subject Properties")

#### **Internal Department Circulation**

The Infrastructure Services and Community Sustainability Department has the following information in response to your request for information regarding the Subject Properties:

• The Disposals and Environmental Remediation Branch notes that the Subject Properties are within 500m of former landfill East side of Merivale Road North of Baseline Road (Ur-43) that was jointly owned by the City of Ottawa and others. A data gap analysis was conducted on the City-owned portion of this former landfill to identify any potential human health risks associated with the site's current land use, however none were identified.

#### Search of Historical Land Use Inventory

This acknowledges receipt of the signed Disclaimer regarding your request for information from the City's Historical Land Use Inventory (HLUI 2005) database for the Subject Properties.

A search of the HLUI database revealed the following information:

 There are 9 activities associated with the Subject Properties: Activity Numbers 10972, 13738, 13954, 15041, 1608, 2519, 3173, 6913 & 9212.

The HLUI database was also searched for activity associated with properties located within 50m of the Subject Properties. The following information was revealed:

Shaping our future together Ensemble, formons notre avenir City of Ottawa Infrastructure Services and Community Sustainability Department Planning and Growth Management Branch

110 Laurier Avenue West, 4th Floor Ottawa, ON K1P 1J1 Tel: (613) 580-2424 ext. 14743 Fax: (613) 560-6006 www.ottawa.ca Ville d'Ottawa Services d'infrastructure et Viabilité des collectivités Direction de l'approbation des demandes d'aménagement et d'infrastructure

110, avenue Laurier Ouest, 4e étage Ottawa (Ontario) K1P 1J1 Tél.: (613) 580-2424 ext. 14743 Télèc: (613) 560-6006 www.oltawa.ca



There are 27 activities associated with properties located within 50m of the Subject Properties: Activity Numbers 8086, 12936, 1695, 5819, 7279, 2870, 6068, 7009, 1608, 2519, 12866, 13435, 6773, 6032, 12843, 13384, 10972, 9324, 10873, 11136, 1585, 11449, 4810, 528, 6383, 149 & 7540.

Please note that Activity Numbers 10972, 13954, 15041, 1608, 9324, 10873 & 1585 have a PIN Certainty of "2". This identifier acknowledges that there is some uncertainty about the exact location of the land use activity and that the activity may or may not have been located on the Subject Properties or on certain properties within 50m of the Subject Properties. All database entries with a PIN Certainty of "2" require independent verification as to their precise location.

A site map has been included to show the location of the Subject Properties as well as the location of all the activities noted above, including the HLUI database's location of the Activity Numbers with a PIN Certainty of "2".

Please note, as per the HLUI Disclaimer, that the information contained in the HLUI database has been compiled from publicly available records and other sources of information. The HLUI may contain erroneous information given that the records used as sources of information may be flawed. For instance, changes in municipal addresses over time may introduce error. Accordingly, all information from the HLUI database is provided on an "as is" basis with no representation or warranty by the City with respect to the information's accuracy or exhaustiveness in responding to the request.

Furthermore, the HLUI database and the results of this search in no way confirm the presence or absence of contamination or pollution of any kind. This information is provided on the assumption that it will not be relied upon by any person for any purpose whatsoever. The City of Ottawa denies all liability to any persons attempting to rely on any information provided from the HLUI database.

Please note that in responding to your request, the City of Ottawa does not guarantee or comment on the environmental condition of the Subject Properties. You may wish to contact the Ontario Ministry of Environment for additional information.

If you have any further questions or comments, please contact Dilys Huang at 613-580-2424 ext. 14743 or HLUI@ottawa.ca

Sincerely,

Michael J. Boughton, MCIP, RPP

Acting Program Manager


Moughten

Development Review (Suburban Services) - West Infrastructure Services and Community Sustainability

MB/DH

Attach: 34

cc: File no. C10-01-12-0169





CITY OF OTTAWA HLUI ID: \_\_6790K3 Report:

RPTC\_OT\_DEV0122

Run On:

16 Jul 2012 at: 16:17:20

AREA (Square Metres): 4790.459

Study Year 2005 PIN 046870188

Multi-NAIC

Multiple Activities

Activity ID:

12936

Multiple PINS:

Ν

PIN Certainty:

1

Previous Activity ID(s):

Related PINS:

046870188

Name:

SKYNEY COMPUTING

Address:

1390 CLYDE AVENUE, NEPEAN

Facility Type:

Electrical and Electronic Machinery, Equipment and Supplies, Wholesale

Comments 1: Comments 2:

Generator Number: Storage Tanks: HL References 1:

HL References 2:

HL References 3: 2001 Employment Survey

NAICS

SIC

443120

0

Company Name

Year of Operation

SKYNEY COMPUTING

c. 2001

Page 1 of 1



Report: Run On: RPTC\_OT\_DEV0122

HLUI ID: \_\_679BPQ

16 Jul 2012 at: 16:11:43

AREA (Square Metres): 62322.830

Study Year 2005

PIN 039980087

Multi-NAIC

**Multiple Activities** 

Activity ID:

8086

Multiple PINS:

Ν

PIN Certainty:

1

Previous Activity ID(s):

Related PINS:

039980087

Name:

OTTAWA-CARLETON DISTRICT SCHOOL BOARD - LAURENTIAN HIGH SCHOOL

Address:

1357 BASELINE ROAD, OTTAWA

Facility Type:

Elementary and Secondary Education

Comments 1:

LAURENTIAN HIGH SCHOOL

Comments 2:

Generator Number: ON0375213

Storage Tanks:

HL References 1:

HL References 2:

HL References 3:

2000 PID

NAICS

SIC

611110

0

Company Name	Year of Operation
OTTAWA-CARLETON DISTRICT SCHOOL BOARD - LAURENTIAN HIGH SCHOOL	c. 2003
OTTAWA-CARLETON DISTRICT SCHOOL BOARD - LAURENTIAN HIGH SCHOOL	c. 2000
OTTAWA-CARLETON DISTRICT SCHOOL BOARD - LAURENTIAN HIGH SCHOOL	c. 2005
LAURENTIAN HIGH SCHOOL	c. 2005



Report:

RPTC\_OT\_DEV0122

AREA (Square Metres): 11049.724

HLUI ID: 6790K2

Run On:

16 Jul 2012 at: 16:17:41

Study Year 2005

PIN 046870134 Multi-NAIC

**Multiple Activities** 

Activity ID:

1695

Multiple PINS:

N

PIN Certainty:

Previous Activity ID(s):

Related PINS:

046870134

Name:

BLEEKER PROFESSIONAL A/V SYST

Address:

1400 CLYDE AVENUE,

Facility Type:

Photographic Equipment and Musical Instruments and Supplies, Wholesale

Comments 1: Comments 2:

Generator Number:

Storage Tanks:

HL References 1: HL References 2:

HL References 3:

2005 Select Phone

NAICS

SIC

443110

0

414130

0

Company Name

Year of Operation

**DEWAR'S AUDIO** 

c. 2001

BLEEKER PROFESSIONAL A/V SYST

c. 2005

BLEEKER PROFESSIONAL A/V SYST



HLUI ID: \_\_679F6Y

Report:

RPTC\_OT\_DEV0122

Run On:

16 Jul 2012 at: 16:15:02

Study Year 1998

PIN 046860001

Multi-NAIC

**Multiple Activities** 

Activity ID:

5819

Multiple PINS:

AREA (Square Metres): 2713.262

Ν

PIN Certainty:

1

Previous Activity ID(s): 3628

Related PINS:

046860001

Name:

GARY'S SERVICE STATION

Address:

1432 BASELINE ROAD, OTTAWA

Facility Type:

Motor Vehicle Repair Shops

Comments 1:

- property is on the SE corner of Baseline & Clyde

Comments 2:

Generator Number:

Storage Tanks:

1 UST - gasoline

HL References 1:

M.1960, M.1966, M.1970, M.1980; FIP1965-434-40146; SC98

HL References 2: HL References 3:

NAICS	SIC	
811119	635	
811199	633	
B11121	635	
447110	633	
811112	635	
447190	633	

#### Company Name

Year of Operation

Erler's Service Station

c. 1960-1966

Gary's Service Station

c. 1970

BP Gas Self Serve

c. 1980

Petro Canada Service Station



HLUI ID: \_\_679F6Y

Report:

RPTC\_OT\_DEV0122

Run On:

16 Jul 2012 at: 16:15:02

Study Year 1998

PIN 046860001 Multi-NAIC

**Multiple Activities** 

Activity ID:

7279

Multiple PINS:

AREA (Square Metres): 2713.262

N

PIN Certainty:

1

Previous Activity ID(s):

Related PINS:

046860001

Name:

IMPERIAL OIL - PRODUCTS & CHEMICAL DIVISION

Address:

1422 BASELINE ROAD, OTTAWA

Facility Type:

Gasoline Service Stations

Comments 1:

Comments 2:

Generator Number: ON9681915

Storage Tanks:

HL References 1:

HL References 2:

HL References 3:

2003 PID

NAICS

SIC

447190

0

447110

0

**Company Name** 

Year of Operation

PETRO-CANADA PRODUCTS INC.

c. 2005

IMPERIAL OIL - PRODUCTS & CHEMICAL DIVISION

c. 2003

PETRO-CANADA PRODUCTS INC.



Report:

RPTC\_OT\_DEV0122

Run On: HLUI ID: \_\_679G4I

16 Jul 2012 at: 16:15:20

AREA (Square Metres): 11408.155

Study Year 1998

PIN 046860002

Multi-NAIC

**Multiple Activities** 

Activity ID:

2870

Multiple PINS:

PIN Certainty:

1

Previous Activity ID(s): 1846, 2661

Related PINS:

046860002

Name:

CANADIAN TIRE GAS BAR

Address:

1400 BASELINE ROAD, OTTAWA

Facility Type:

Gasoline Service Stations

Comments 1:

- associated Canadian Tire store, with onsite auto repiar garages, closed in 1998

Comments 2:

Generator Number:

Storage Tanks:

HL References 1:

M.1960, M.1970, M.1980; SC98

HL References 2:

HL References 3:

NAICS	SIC	
447110	633	
811121	635	
811119	635	
447190	633	
811112	635	
811199	633	

#### Company Name

Year of Operation

Canadian Tire Corp. Associate Store

c. 1970-1998

Canadian Tire Gas Bar

c. 1980-1999



Report:

RPTC\_OT\_DEV0122

HLUI ID: \_\_670HI9

Run On:

16 Jul 2012 at: 16:16:38

AREA (Square Metres): 58350.316

Study Year

PIN 046860027

Multi-NAIC

**Multiple Activities** 

Activity ID:

10972

Multiple PINS:

Υ

PIN Certainty:

2

Previous Activity ID(s): 3044

Related PINS:

046860011

Name:

PATTON'S CLEANERS

Address:

1464 MERIVALE ROAD, OTTAWA

Facility Type:

Laundries and Cleaners

Comments 1: Comments 2:

Generator Number:

Storage Tanks:

HL References 1:

M.1960, M.1970, M.1980

HL References 2: HL References 3:

NAICS

SIC

812330

972

812310

972

561740

972

812320

972

**Company Name** 

Year of Operation

Patton's Cleaners

c. 1970

MAP Report Ver: 1



HLUI ID: \_\_670HI9

AREA (Square Metres): 58350.316

Report:

RPTC\_OT\_DEV0122

Run On:

16 Jul 2012 at: 16:16:38

Study Year

1998

PIN 046860027 Multi-NAIC

Multiple Activities

Activity ID:

13738

Multiple PINS:

Ν

PIN Certainty:

1

Previous Activity ID(s):

Related PINS:

046860027

Name:

VALBERG IMAGING INC.

Address:

1500 MERIVALE ROAD, NEPEAN

Facility Type:

Photographers

Comments 1:

Comments 2:

Generator Number:

Storage Tanks: HL References 1:

HL References 2:

HL References 3:

2001 Employment Survey

NAICS

SIC

541920

0

Company Name

Year of Operation

VALBERG IMAGING INC.



HLUI ID: \_\_670HI9

AREA (Square Metres): 58350.316

Report:

RPTC\_OT\_DEV0122

Run On:

16 Jul 2012 at: 16:16:38

Study Year

1998

PIN 046860027

Multi-NAIC

**Multiple Activities** 

**Activity ID:** 

13954

Multiple PINS:

PIN Certainty:

2

Previous Activity ID(s): 5337

Related PINS:

046860027

Name:

UNNAMED MACHINE SHOP

Address:

8 KIMWAY CRESCENT, OTTAWA

Facility Type:

Machine Shop Industry

Comments 1:

Comments 2:

Generator Number:

Storage Tanks:

HL References 1:

FIP1965-435-49486,vol4

HL References 2: HL References 3:

NAICS SIC 336350 308 333619 308 308 332710 308 336310

Company Name

Year of Operation

Unnamed Machine Shop



CITY OF OTTAWA HLUI ID: \_\_670HI9

RPTC\_OT\_DEV0122

Report: Run On:

16 Jul 2012 at: 16:16:38

AREA (Square Metres): 58350.316

Study Year 1998

PIN 046860027 Multi-NAIC

Multiple Activities

Activity ID:

15041

Multiple PINS:

Ν

PIN Certainty:

2

Previous Activity ID(s): 5338

Related PINS:

046860027

Name:

R.H. Rhodes (Canada) Ltd.

Address:

10 KIMWAY CRES, OTTAWA

Facility Type:

Timing device manufacturing

Comments 1:

Comments 2:

Generator Number:

Storage Tanks:

HL References 1:

FIP1965-435-49486, vol4; M.1965

HL References 2: HL References 3:

NAICS

SIC

391

Company Name

Year of Operation

R.H. Rhodes (Canada) Ltd.



HLUI ID: 670HI9

AREA (Square Metres): 58350.316

Report:

RPTC\_OT\_DEV0122

Run On:

16 Jul 2012 at: 16:16:38

Study Year 1998 PIN 046860027 Multi-NAIC

Multiple Activities

Activity ID:

1608

Multiple PINS:

Y

PIN Certainty:

2

....

Previous Activity ID(s): 3046, 3527

Related PINS:

046860026

Name:

BRADLEY'S TEXACO SERVICE STATION

Address:

1504 MERIVALE ROAD, OTTAWA

Facility Type:

Gasoline Service Stations

Comments 1:

Comments 2:

Generator Number:

Storage Tanks:

One UST

HL References 1:

FIP1965-436-49486,vol 4, FIP1965-437-49486, M.1960, M.1964, M.1965, M.1967, M.1970, M.1980; BEP-J-1961

(Cityview Newsletters)

HL References 2:

HL References 3:

NAICS	SIC	
811121	635	
811199	633	
447110	633	
447190	633	
811119	635	
811112	635	

#### Company Name

Year of Operation

Fraser Fuels Ltd.

c. 1970

Bradley's Texaco Service Station

c. 1964-1970

Bell's Gas Bar

c. 1980

Fraser Power Gasoline Service Station

c. 1965-1970

Cityview Texaco Service Station



HLUI ID: \_\_670HI9

Report: RPTC\_OT\_DEV0122

Run On:

16 Jul 2012 at: 16:16:38

AREA (Square Metres): 58350.316

Study Year 1998

PIN 046860027

Multi-NAIC

**Multiple Activities** 

Activity ID:

2519

Multiple PINS:

Ν

PIN Certainty:

Previous Activity ID(s): 4416

Related PINS:

046860027

Name:

NATION'S CAPITAL TELEVISION INC.

Address:

1500 MERIVALE ROAD, NEPEAN

Facility Type:

Telecommunication Broadcasting Industries

Comments 1:

CJOH-TV

Comments 2:

Generator Number: ON1540500

Storage Tanks:

HL References 1:

M.1965; FIP1965-434-49486

HL References 2:

HL References 3:

2000 PID

NAICS

SIC

515120

481

515110 515120 481

Company Name

Year of Operation

C.J.O.H. TV Station

c. 1965-1999

CJOHTV

c. 2001

NATION'S CAPITAL TELEVISION INC.

c. 2000

NATION'S CAPITAL TELEVISION INC.



Report: Run On: RPTC\_OT\_DEV0122

HLUI ID: \_\_670HI9

16 Jul 2012 at: 16:16:38

Study Year

1998

PIN 046860027

Multi-NAIC

Multiple Activities

Activity ID:

3173

Multiple PINS:

AREA (Square Metres): 58350.316

N

PIN Certainty:

1

Previous Activity ID(s):

Related PINS:

046860027

Name:

CARLETON PRODUCTIONS INTL INC.

Address:

1500 MERIVALE ROAD,

Facility Type:

Motion Picture Laboratories and Video Production Facilities

Comments 1:

Comments 2:

Generator Number:

Storage Tanks:

HL References 1:

HL References 2:

HL References 3:

2005 Select Phone

NAICS

SIC

512110

0

Company Name

Year of Operation

ROCKPIG PRODUCTIONS

c. 2001

CARLETON PRODUCTIONS INTL INC.



HLUI ID: \_\_670HI9

AREA (Square Metres): 58350.316

Report:

RPTC\_OT\_DEV0122

Run On:

16 Jul 2012 at: 16:16:38

Study Year 1998

PIN 046860027 Multi-NAIC

**Multiple Activities** 

Activity ID:

6913

Multiple PINS:

Y

PIN Certainty:

1

Previous Activity ID(s): 2505

Related PINS:

046860007

Name: Address: HUME'S TRANSPORT LIMITED MERIVALE ROAD, OTTAWA

Facility Type:

Truck Transport Industries

Comments 1:

A transport company shown on FIP1965 at 1490 Merivale Rd.

Comments 2:

1490 to 1492

Generator Number:

Storage Tanks:

1 (one) Under Ground Storage Tank (Gasoline)-FIP 1965

HL References 1:

M.1965; FIP1965-435-49486, vol4; BEP-G

HL References 2: HL References 3:

NAICS	SIC
484121	456
484239	456
484232	456
484233	456
484223	456
484231	456
488490	456
562110	456
484222	456
484110	456
484122	456
484221	456
484229	456

Company Name

Year of Operation

Hume's Transport Ltd.

c. 1956-1965



HLUI ID: \_\_670HI9

Report:

RPTC\_OT\_DEV0122

Run On:

16 Jul 2012 at: 16:16:38

Study Year

1998

PIN 046860027

Multi-NAIC

**Multiple Activities** 

Activity ID:

9212

Multiple PINS:

AREA (Square Metres): 58350.316

N

PIN Certainty:

1

Previous Activity ID(s):

Related PINS:

046860027

Name:

MIDAS AUTO SVC EXPERTS

Address:

1380 BASELINE ROAD,

Facility Type:

Motor Vehicles, Wholesale

Comments 1:

Comments 2:

Generator Number:

Storage Tanks:

HL References 1:

HL References 2:

HL References 3:

2005 Select Phone

NAICS

SIC

811111

0

Company Name

Year of Operation

MIDAS AUTO SVC EXPERTS

c. 2001

MIDAS AUTO SVC EXPERTS



## CITY OF OTTAWA HLUI ID: \_\_679FGJ

Report:

RPTC\_OT\_DEV0122

Run On:

16 Jul 2012 at: 16:23:10

Study Year 1998 PIN 046860004

Multi-NAIC

Multiple Activities

Activity ID:

7009

Multiple PINS:

AREA (Square Metres): 4282.817

M

PIN Certainty:

1

Previous Activity ID(s): 4415

Related PINS:

046860004

Name:

IBM

Address:

1383 CLYDE AVENUE, NEPEAN

Facility Type:

Commercial Printing Industries

Comments 1:

- printed tabulating cards (key punch) - dye room noted

Comments 2:

Generator Number:

Storage Tanks:

HL References 1:

M.1966; FIP1965-434-49486

HL References 2: HL References 3:

NAICS	SIC
323115	281
325920	379
323116	281
325520	379
323114	281
323119	281
325910	379

## **Company Name**

Year of Operation

IBM

c. 1965-1966



HLUI ID: \_\_679FPU

Report:

RPTC\_OT\_DEV0122

Run On:

16 Jul 2012 at: 16:27:11

Study Year 1998

PIN 046860008

Multi-NAIC

**Multiple Activities** 

Activity ID:

12866

Multiple PINS:

AREA (Square Metres): 1443.428

Ν

PIN Certainty:

Previous Activity ID(s): 3528

Related PINS:

046860008

Name: Address: WILLIAM S BURNSIDE (CANADA)

1486 MERIVALE ROAD, NEPEAN Motor Vehicle Repair Shops

Facility Type:

Comments 1:

Comments 2:

Generator Number:

Storage Tanks:

M.1960, M.1970, M.1980

**HL References 1: HL References 2:** 

HL References 3:

2005 Property Assessment

NAICS	SIC
811119	635
811119	0
811111	0
811112	0
811121	635
811112	635
811121	0
811199	0

## Company Name

Year of Operation

WILLIAM S BURNSIDE (CANADA)

c. 2005

Super Muffler-Super Trransmission



HLUI ID: \_\_679FPU

Report:

RPTC\_OT\_DEV0122

Run On:

16 Jul 2012 at: 16:27:11

Study Year

1998

PIN 046860008

Multi-NAIC

**Multiple Activities** 

Activity ID:

13435

1

Multiple PINS:

AREA (Square Metres): 1443.428

N

PIN Certainty:

Previous Activity ID(s):

Related PINS:

046860008

Name:

SWAN'S GARAGE

Address:

1486 MERIVALE ROAD,

Facility Type:

Motor Vehicles, Wholesale

Comments 1:

Comments 2:

Generator Number:

Storage Tanks:

HL References 1:

HL References 2:

HL References 3:

2005 Select Phone

NAICS

SIC

811111

0

Company Name

Year of Operation

SWAN'S GARAGE

c. 2005

SWAN'S GARAGE



HLUI ID: \_\_679FPU

Report:

RPTC\_OT\_DEV0122

Run On:

16 Jul 2012 at: 16:27:11

Study Year

1998

PIN 046860008

Multi-NAIC

Multiple Activities

Activity ID:

6773

Multiple PINS:

AREA (Square Metres): 1443.428

PIN Certainty:

1

Previous Activity ID(s):

Related PINS:

046860008

Name:

HOSIE & BROWN ELECTRIC LIMITED

Address:

1486 MERIVALE ROAD,

Facility Type:

Mechanical Specialty Work

Comments 1: Comments 2:

Generator Number:

Storage Tanks:

HL References 1: HL References 2:

HL References 3:

2001 Employment Survey

NAICS

SIC

238210

0

Company Name

Year of Operation

HOSIE & BROWN ELECTRIC LIMITED



Report: Run On: RPTC\_OT\_DEV0122

HLUI ID: \_\_679FP0

16 Jul 2012 at: 16:27:47

AREA (Square Metres): 1466.101

Study Year 1998 PIN 046860009 Multi-NAIC

Multiple Activities

Activity ID:

6032

Multiple PINS:

N

PIN Certainty:

1

1143.

Previous Activity ID(s): 5551

Related PINS:

046860009

Name:

FRASER FUELS LIMITED

Address:

1480 MERIVALE ROAD, NEPEAN

Facility Type:

Motor Vehicle Repair Shops

Comments 1:

Comments 2:

Generator Number:

Storage Tanks:

HL References 1:

M.1960, M.1970, M.1980

HL References 2: HL References 3:

NAICS	SIC	
811199	633	
811121	635	
811119	635	
447110	633	
B11112	635	
447190	633	

Company Name

Year of Operation

Fraser Fuels Ltd.

c. 1970

MAP Report Ver: 1 Page 1 of 1



CITY OF OTTAWA HLUI ID: \_\_679BNA Report:

RPTC\_OT\_DEV0122

Run On:

16 Jul 2012 at: 16:28:34

AREA (Square Metres): 8530.346

Study Year 2005 PIN 046860012

Multi-NAIC

Multiple Activities

Activity ID:

12843

Multiple PINS:

N

PIN Certainty:

1

Previous Activity ID(s): 4612

Related PINS:

046860012

Name:

SUNYS PETROLEUM INC.

Address:

1460 MERIVALE ROAD,

Facility Type:

Gasoline Service Stations

Comments 1: Comments 2:

Generator Number:

Storage Tanks:

1 UST - gasoline

HL References 1:

M.1964, M.1965, M.1966, M.1967; FIP1965-433-49486; SC98

HL References 2:

HL References 3:

2005 Select Phone

NAICS	SIC
447190	633
447190	0
811199	633
447110	633
447110	0

## Company Name

Year of Operation

Unnamed Service Station

c. 1964-1967

SUNYS PETROLEUM INC.

c. 2005

Sunys Petroleum Inc.

c. 1998

SUNYS PETROLEUM INC.



HLUI ID: \_\_679BNA

Report:

RPTC\_OT\_DEV0122

Run On:

16 Jul 2012 at: 16:28:34

Study Year

2005

PIN 046860012

Multi-NAIC

Activity ID:

13384

Multiple PINS:

AREA (Square Metres): 8530.346

N

PIN Certainty:

Previous Activity ID(s):

Related PINS:

046860012

Name:

THE DRY CLEANER

Address:

1460 MERIVALE ROAD, NEPEAN

Facility Type:

Laundries and Cleaners

Comments 1:

Comments 2:

Generator Number:

Storage Tanks:

HL References 1:

HL References 2:

HL References 3:

2001 Employment Survey

NAICS

SIC

812320

0

Company Name

Year of Operation

THE DRY CLEANER



HLUI ID: \_\_679GDG

Report:

RPTC\_OT\_DEV0122

Run On:

16 Jul 2012 at: 16:32:04

Study Year 1998

PIN 046840060

Multi-NAIC

**Multiple Activities** 

Activity ID:

9324

Multiple PINS:

AREA (Square Metres): 29000.002

N

PIN Certainty:

2

Previous Activity ID(s): 7022

Related PINS:

046840060

Name:

MINTO

Address:

MERIVALE ROAD, NEPEAN

Facility Type:

Other Utility Industries n.e.c.

Comments 1:

- private snow dump Type B - snow can come from anywhere, rezoning process completed.

Comments 2:

Generator Number:

Storage Tanks:

**HL References 1:** 

City of Nepean, Planning Dept.-1/25/99

HL References 2:

HL References 3:

NAICS	SIC
562920	499
221330	499
221320	499
562990	499
562210	499

**Company Name** 

Year of Operation

Minto

c. 1996

Page 1 of 1 MAP Report Ver: 1



CITY OF OTTAWA HLUI ID: \_\_670HE2

Report:

RPTC\_OT\_DEV0122

Run On:

16 Jul 2012 at: 16:32:48

AREA (Square Metres): 966.309

Study Year

PIN 046850039

Multi-NAIC

**Multiple Activities** 

Activity ID:

10873

Multiple PINS:

Υ

PIN Certainty:

2

Previous Activity ID(s): 4613

Related PINS:

046850038

Name:

PARKWAY PAVING

Address:

1489 MERIVALE ROAD, NEPEAN

Facility Type:

Highway and Heavy Construction

Comments 1: Comments 2:

Generator Number:

Storage Tanks:

HL References 1:

SC98

HL References 2: HL References 3:

NAICS SIC 238390 421 238990 421

238910

412

Company Name

Year of Operation

Parkway Paving



HLUI ID: \_\_670HE2

Report:

RPTC\_OT\_DEV0122

Run On:

16 Jul 2012 at: 16:32:48

Study Year 1998

PIN 046850039

Multi-NAIC

**Multiple Activities** 

Activity ID:

11136

Multiple PINS:

AREA (Square Metres): 966.309

N

PIN Certainty:

1

Previous Activity ID(s): 6788

Related PINS:

046850048

Name:

PRODUCTIVE PRINTING

Address:

1489 MERIVALE ROAD, NEPEAN

Facility Type:

Platemaking, Typesetting and Bindery Industry

Comments 1:

ARMSTRON PLAZA, SUITE 102

Comments 2:

Generator Number: ON1674600

Storage Tanks:

HL References 1:

PID1994

HL References 2:

HL References 3:

2000 PID

NAICS	SIC
323119	281
323120	282
812921	282
323114	281
323120	0
323115	281
812921	0
323116	281

## Company Name

Year of Operation

PRODUCTIVE PRINTING

c. 2000

Productive Printing

c. 1994

Page 2 of 3



HLUI ID: \_\_670HE2

Report:

RPTC\_OT\_DEV0122

Run On:

16 Jul 2012 at: 16:32:48

Study Year

PIN 046850039 Multi-NAIC

**Multiple Activities** 

Activity ID:

1585

2

Multiple PINS:

AREA (Square Metres): 966.309

V

Previous Activity ID(s): 6268

.

PIN Certainty: Related PINS:

046850038

Name:

BELLMAN FUEL OIL AND EQUIPMENT LIMITED

Address:

1489 MERIVALE ROAD, NEPEAN

Facility Type:

Petroleum Products, Wholesale

Comments 1:

Comments 2:

Generator Number:

Storage Tanks:

HL References 1:

BEP-J-City View Newsletters

HL References 2: HL References 3:

NAICS SIC 238220 424 412110 511 454310 511 419120 511

**Company Name** 

Year of Operation

Bellman Fuel Oil and Equipment Ltd.



HLUI ID: \_\_679AC2

Report:

RPTC\_OT\_DEV0122

Run On:

16 Jul 2012 at: 16:34:19

Study Year

1998 2005 PIN

046850039 046850048 Multi-NAIC

Y

**Multiple Activities** 

Y

Activity ID:

11449

Multiple PINS:

AREA (Square Metres): 4162.422

N

PIN Certainty:

1

Previous Activity ID(s):

Related PINS:

046850048

Name:

POL VIDEO PRODUCTION

Address:

1489 MERIVALE ROAD, NEPEAN

Facility Type:

Motion Picture Laboratories and Video Production Facilities

Comments 1: Comments 2:

Generator Number:

Storage Tanks:

HL References 1:

HL References 2: HL References 3:

2001 Employment Survey

NAICS

SIC

512110

0

Company Name

Year of Operation

POL VIDEO PRODUCTION



HLUI ID: \_\_679AC2

AREA (Square Metres): 4162.422

Report:

RPTC\_OT\_DEV0122

Run On:

16 Jul 2012 at: 16:34:19

Study Year

1998 2005 PIN

046850039 046850048 Multi-NAIC

Y

**Multiple Activities** 

Ÿ

Activity ID:

4810

Multiple PINS:

N

PIN Certainty:

1

Previous Activity ID(s):

Related PINS:

046850048

Name:

**EVERYTHING IN WOOD** 

Address:

1489 MERIVALE ROAD, NEPEAN

Facility Type:

Leather and Allied Products Industries

Comments 1:

Comments 2:

Generator Number:

Storage Tanks:

HL References 1:

HL References 2:

HL References 3:

2001 Employment Survey

NAICS

SIC

321999

0

Company Name

Year of Operation

**EVERYTHING IN WOOD** 



HLUI ID: \_\_679AC2

RPTC\_OT\_DEV0122

Report: Run On:

16 Jul 2012 at: 16:34:19

AREA (Square Metres): 4162.422

Study Year

1998 2005 PIN

046850039 046850048 Multi-NAIC

**Multiple Activities** 

Activity ID:

528

Multiple PINS:

N

PIN Certainty:

1

Previous Activity ID(s):

Related PINS:

046850048

Name:

ADAM'S PHOTO

Address:

1489 MERIVALE ROAD, NEPEAN

Facility Type:

Camera and Photographic Supply Stores

Comments 1:

Comments 2:

Generator Number:

Storage Tanks:

HL References 1:

HL References 2:

HL References 3:

2001 Employment Survey

NAICS

SIC

443130

0

Company Name

Year of Operation

ADAM'S PHOTO



CITY OF OTTAWA HLUI ID: \_\_679AC2

RPTC\_OT\_DEV0122

Report: Run On:

16 Jul 2012 at: 16:34:19

AREA (Square Metres): 4162.422

Study Year

1998 2005 PIN

046850039 046850048 Multi-NAIC

**Multiple Activities** 

Activity ID:

6383

Multiple PINS:

Ν

PIN Certainty:

1

Previous Activity ID(s):

Related PINS:

046850048

Name:

HARD TOP PAVING

Address:

1489 MERIVALE ROAD,

Facility Type:

Industrial Construction (Other Than Buildings)

Comments 1:

Comments 2:

Generator Number:

Storage Tanks:

HL References 1:

HL References 2:

HL References 3:

2005 Select Phone

NAICS

SIC

237310

0

Company Name

Year of Operation

HARD TOP PAVING



HLUI ID: \_\_679FVJ

Report:

RPTC\_OT\_DEV0122

Run On:

16 Jul 2012 at: 16:35:37

Study Year

1998

PIN 046850038

Multi-NAIC

Multiple Activities

Activity ID:

149

1

Multiple PINS:

AREA (Square Metres): 1811.995

N

PIN Certainty:

Previous Activity ID(s):

Related PINS:

046850038

Name:

APL COMMUNICATIONS LIMITED

Address:

1493 MERIVALE ROAD,

Facility Type:

Motion Picture Laboratories and Video Production Facilities

Comments 1:

Comments 2:

Generator Number:

Storage Tanks:

HL References 1:

HL References 2:

HL References 3:

2005 Select Phone

NAICS

SIC

512110

0

Company Name

Year of Operation

BASELINE COMMUNICATIONS INC.

c. 2001

APL COMMUNICATIONS LIMITED



HLUI ID: \_\_679FVJ

Report:

RPTC\_OT\_DEV0122

Run On:

16 Jul 2012 at: 16:35:37

AREA (Square Metres): 1811.995

Study Year 1998

PIN 046850038 Multi-NAIC

**Multiple Activities** 

Activity ID:

7540

Multiple PINS:

Ν

PIN Certainty:

Previous Activity ID(s): 2026

Related PINS:

046850038

Name: Address: LA BRECQUES SHELL STATION 1493 MERIVALE ROAD, NEPEAN

Facility Type:

Motor Vehicle Repair Shops

Comments 1:

Comments 2:

Generator Number:

Storage Tanks:

1 UST - gasoline

HL References 1:

M.1960, M.1965, M.1967, M.1970, M.1980; FIP1965-435-49487, vol 4

HL References 2: HL References 3:

NAICS	SIC
811112	635
447110	633
811121	635
811199	633
447190	633
811119	635

## Company Name

Year of Operation

La Brecques Shell Station

c. 1965-1970



HLUI ID: \_\_679F5L

Report:

RPTC\_OT\_DEV0122

Run On:

16 Jul 2012 at: 16:22:48

Study Year

PIN 046860003

Multi-NAIC

Multiple Activities

Activity ID:

6068

Multiple PINS:

AREA (Square Metres): 2540.229

Ν

PIN Certainty:

1

nampie i mo.

. .

Previous Activity ID(s): 2662

Related PINS:

046860003

Name:

FRISBY TIRE CO. (1974) / JIM FRISBY HOLDINGS LTD

Address:

1377 CLYDE AVENUE, NEPEAN

Facility Type:

Motor Vehicles, Wholesale

Comments 1:

Comments 2:

Generator Number:

Storage Tanks:

HL References 1:

M.1960, M.1970, M.1980; SC98

HL References 2:

HL References 3:

MAICC

2005 Property Assessment

NAICS	SIC
811112	0
339110	159
811119	635
326210	151
811112	635
322220	159
326290	159
811111	0
811121	635
811199	0
339990	159
811119	0
811121	0

## **Company Name**

Year of Operation

FRISBY TIRE CO. (1974) / JIM FRISBY HOLDINGS LTD

Frisby Tire Co. (1974)

c. 2005

c. 1970-1998

## **Michael Beaudoin**

From: Ruchi Chohan <rchohan@tssa.org> on behalf of Public Information Services

<publicinformationservices@tssa.org>

Sent:June-09-17 12:41 PMTo:Michael BeaudoinSubject:RE: 1500 Merivale Road

Hello Michael.

Thank you for your inquiry.

I have searched the below noted address (addresses) and I have located the following record:

1460 Merivale Rd, Ottawa has record of 2 active underground fuel tanks

1432 Baseline Rd, Ottawa has record of 4 active underground fuel tanks

For a more detailed report including underground fuel storage tank details and copies of all inspection reports, please submit your request in writing to Public Information Services via e-mail (<a href="mailto:publicinformationservices@tssa.org">public Information Services via e-mail (<a href="publicinformationservices@tssa.org">public Information Services@tssa.org</a>) or through with a fee of \$56.50 (including HST) per location. The fee is payable with credit card (Visa or MasterCard) or with a cheque made payable to TSSA.

Although TSSA believes the information provided pursuant to your request is accurate, please note that TSSA does not warrant this information in any way whatsoever.

Thank you and have a good day!

Ruchi

From: Michael Beaudoin [mailto:MBeaudoin@Patersongroup.ca]

Sent: Thursday, June 01, 2017 10:23 AM

To: Public Information Services < publicinformationservices@tssa.org >

Subject: 1500 Merivale Road

#### Good Morning

Could you please complete a search of your records for underground/aboveground storage tanks, historical spills or other infractions for the following address(es) for properties located in the City of Ottawa, ON

1383 Clyde Avenue 1460, 1480, 1486, 1500 Merivale Road 1357, 1366, 1384, 1432 Baseline Road

Michael Beaudoin, P.Eng

# patersongroup

## **Solution Oriented Engineering**

154 Colonnade Road South Ottawa - Ontario - K2E 7J5

Tel: (613) 226-7381 Fax: (613) 226-6344

This electronic message and any attached documents are intended only for the named recipients. This communication from the Technical Standards and Safety Authority may contain information that is privileged, confidential or otherwise protected from disclosure and it must not be disclosed, copied, forwarded or distributed without authorization. If you have received this message in error, please notify the sender immediately and delete the original message.

UTM | 1 | 8 | 4 | 4 | 2 | 3 | 9 | 10 | E | S|R | 5|0 | 2 | 2 | 9 | 2 | 5 | N Elev. | 4|R | 0|3|| 10 |





JAN 22 1957

15 Nº GEOLOGICAL BRANCH

AUEPAREMENT OF MINES

Basin 25		Department		nes	Andrew Stranger Stranger	
	•			Recor	10	PEAN
County or Territorial District	HEP A AND	Tow				
			ı Vil	lage, Town or (	City)	•••••••••••••••••••••••••
(day)	(month)	(year)				•
Pipe and Casing		(3041)	· · · · · · · · · · · · · · · · · · ·		Pumping Test	
Casing diameter(s)			Statio	lovel 22	1	
Length(s)	••••••••••••••••••		Pump	ing rate 3	50 GPH	
Type of screen	•••••••••••		Pump	ing level	100	
Length of screen		••••••••	Durat	ion of test	Z HOURS	***************************************
Well Log					Water Record	
Overburden and Bedrock Record	From ft.	To ft.		Depth(s) at which water(s) found	No. of feet water rises	Kind of water (fresh, salty, or sulphur)
5/67		20	_			
LIMESTONE	20	/30			70	PRACTI
		-				
				-		
			_			· · · · · · · · · · · · · · · · · · ·
	· · · · · · · · · · · · · · · · · · ·	l	l			0
For what purpose(s) is the water to				Loc	ation of Well	B
Is water clear or cloudy?					show distances of	
Is well on upland, in valley, or on hi			roa	d and lot line.	Indicate north	by arrow.
Drilling firm W. Mohou G. Uni.	· · · · · · · · · · · · · · · · · · ·					IN
Address 5/MCEWAA	f	**********				
•••••	*****		4	1EBIUAL	É	And the second second
Name of Driller				TEOL TO		
Address 51 MCLWAN	***********************		And the second second	150	,	
Licence Number 6	********************	•••••			< 35 × 3	
I certify that the for					100	
statements of fact are	e true.					
Date Aug 5 h M No hage	hold.				1/3	
/ Signat	ture of Licensee	·			11 2	
<b>V</b>					1100	

orm 5

18 Z 44412131810 E | 5|R | 5|0 |2|3 |0|8|0 | N Ontario Water Resources Commission Act

JU15 4 NO.

GROUND WATER BRANCH

ONTARIO WATER

Elev. 4 R 013110
------------------

# RECOR

				•• — — · · · · · · · · · · · · · · · · ·	<i></i>
Dania la	or District				C177
Basin 1	or District			Township Village, Town or Cit	y Olly Tlow
County	Of District				
~	MBF	Lot	35	Date completed 22 Jun	a 1961


	dress. 1480	Merivale	M., City Vi	
Casing and Screen Record			ng Test	-
Inside diameter of casing	1			
Total length of casing.	1 -			
Type of screen			npties	
Length of screen	Duration of test	pumping	45 Tixutes	
Depth to top of screen	Water clear or o	cloudy at end o	of testeloudy	
Diameter of finished hole	Recommended	G.P.M.		
	with pump sett	ing of <b>265</b>	feet belo	w ground surfac
Well Log			Wate	r Record
Overburden and Bedrock Record	From ft.	To ft.	Depth(s) at which water(s) found	Kind of water (fresh, salty, sulphur)
Clay & Boulders	••	28		
Grey Limestens	28 '	265 '	265 '	fresh
For what purpose(s) is the water to be used? NPR 14/10/6  Beauty-parler, Drive-in Restaurant etc.  Is well on upland, in valley, or on hillside? Upland	In diagr	am below sho	n of Well w distances of we ndicate north by	

Licence Number. 226 Name of Driller or Borer. J. Meere

Date 22 Pune 1

Form 7 15M Sets 60-5930

OWRC COPY



UTM 1 1 2 4 4 4 1 2 1 3 1 7 5 E 3 1 G S b    S   S   O   2   3   O   7   O   N    Elev.   Y   R   O   3     D   WATER WE		Act	150L NO. ONTARIO RESOURCES (	196 <b>638</b>
Basin 25 County or District	Township, Village, Vil	own or City	Stay Thou	The same of the sa
Con. A-RF Lot 35	Date completed	27 June	1961	year)
	ldress 1480 1			
Casing and Screen Record		Pumpin	g Test	
Inside diameter of casing	Static level	10 !	1	
Total length of casing	Test-pumping ra			
Type of screen	Pumping level			•
Length of screen	Duration of test p	oumping	1 Neur & 15	<u> Minutes</u>
Depth to top of screen	Water clear or cle	oudy at end of	f testelendy.	
Diameter of finished hole	Recommended p	oumping rate	<b>.5</b>	G.P.M
	with pump settin	g of 190	feet belo	ow ground surfac
Well Log			Wate	r Record
Overburden and Bedrock Record	From ft.	To ft.	Depth(s) at which water(s) found	Kind of water (fresh, salty, sulphur)
Clay & Boulders	281	28'	200 '	fresh
Grey Limostene				
- 1.DR 1/16//		Location	of Well	1
For what purpose(s) is the water to be used? UPK 26/10/6/.  Becaty-perlor, Brive-in Bestaurant etc			v distances of we	ell from
			dicate north by	
Is well on upland, in valley, or on hillside?			ال ح	
Drilling or Boring Firm Rair. Phillips Drilling. Co	<b>554.</b> ,	· .		
A11		•	7	
Address. <b>Stans</b>		. /	17 %	
Licence Number	MERI	VALE	Ŭ Re	PAD.
Name of Driller or Borer		75'	<u> </u>	-> 0
Address Kare		\\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\	100	200
Date		<del></del>		20
Res l. VI.		30	<b>o</b> '	
(Signature of Licensed Drilling or Boying Contractor)	N N			12
Form 7 15M Sets 60-5930				
OWRC COPY			* ***	<i>e</i> (3

Ministry of

Well Ta	AO56689	nber below)
IA	056689	

	W	ell	Rec	COI	rd
Regulation 903 O.	ntario Wai	ter Re	sour	ces.	Act

instructio	ons for Co	ompie	ting Form		100	000	2/	İ

		tile Eliviloi	ment		<u> </u>	· <del></del>	Regulation 90	3 Onta	rio Wate	r Res	ources A
Instruction	s for Completin	na Form		A050	5685	F			ı	page	of
	-	_					コ Please retain for futu	re refe			
<ul><li>All Sect</li></ul>	tions <b>must</b> be cor	npleted in 1	full to avoid dela	vs in process	ina. Further	instructions an	d explanations are av	ailable	on the ba	ack o	f this form
Questio	ons regarding cor <b>re measuremen</b> i	npleting thi	is application ca	n be directed	to the Wat	ter Well Help [	Desk (Toll Free) at	1-888-	396-935	5.	
<ul><li>Please</li></ul>	print clearly in blu	ie or black	ink only.	o or a metr	е		Ministry Us	e Only	,		
	r's Information			formation	MUN	С	ON			LOT	
First Name	~ · · · · · · ·	Last Nam	e_	N N	/ailing Addre	ss (Street Numb	er/Name, RR,Lot,Cond	cession	<i>s</i> ) ~		
7100	CTON 6	1 U ME		NAL	<u> </u>	-212-	LEGGET		BRO.	-	
County/Distric	E TON		TOWNSHIP/ORLY/TO	own/Village		rovince Posta	al Code LW 364	phone	Number	(includ	de area coc
Address of We	ell Location (County	/District/Mu			ownship	Jillano   &Co	Lot		Conce	ession	<u> </u>
1490	MERRIVIAL	ELD	CARLE	NOTE	OTTA	WA -	200		Conoc	,55101	
RR#/Street No	umber/Name	rettles	7		City/Town/V		Site/Compa	artmen	t/Block/Tr	act et	łc.
GPS Reading	MERRIUALE NAD ZOR		a No	uthing	677A	Andel Mode	of Operation; Und	H. C			
	8 3   1 &	3 49	2326 was	023212	Unit Make/N	GIN WO		differentia erentiate	ated 🔪 ed, specify _	Aver	ageo
Log of Ove	rburden and Be	edrock Ma	aterials (see in:	structions)							
General Colour	r Most common	material		/laterials		Genera	al Description		Dep Fro		Metres To
BEN	FILL		SAND SILT SILT		6	SOSE - ENSE JET			6	3	0-6
BRN	CLAY		611		7	5 NS			0	<i>b i</i>	1.8
605	e can			-	-	1 = 7			0-	33	
6-7	CCMX		716/	W.4		201			1,0	13	3-6
						William I	MARA				
Hole	Diameter		Con	struction Red	ord		Too	t of W	ell Yield		
	Metres Diameter	Inside				N.A. A.	Pumping test method		w Down	ГВ	Recovery
From	To Centimetres	Inside diam	Material	Wall thickness	Depth	Metres	Fumping test method				Water Lev
0 3	3.66 11,43	centimetres		centimetres	From	То		min	Metres	min	
2	0.00 /.//			Casing			Pump intake set at - (metres)	Static Level			
			Steel Fibrėglas:	s			Pumping rate -	1		1	
		3.81	Plastic Concrete	0-25	0	2113	(litres/min)				
	r Record	0.01	Galvanized			- 6110	Duration of pumping	2		2	
Water found at Metres /	/ Kind of Water		Steel Fibreglass	s			hrs + min				
m	Fresh Sulphur Salty Minerals		Plastic Concrete				of pumping	3		3	
Gas Other:	Salty Minerals		Galvanized				Recommended pump	4		4	
m	Fresh Sulphur		Steel Fibreglass				type. Shallow Deep		***************************************		
	Salty Minerals		Plastic Concrete				Recommended pump	5		5	
Other:			Galvanized				depthmetres		mana		
	Fresh Sulphur Salty Minerals	Outside		Screen	1		Recommended pump rate.	10	****	10	
Other:	Total Trimoral	diam	Steel Fibreglass	1	0 12	3.66	(litres/min) If flowing give rate -	15 20		15 20	
emmany	ll yield, water was	3.67	Plastic Concrete	10	2113	~ ep	(litres/min)	25		25	
Clear and se		3, 87	Galvanized	ized (O			If pumping discontin- ued, give reason.	30		30	
Other, speci	fy		No (	Casing or Scr	een		ded, give reason.	40		40	
Chlorinated	Yes No		Open hole					50		50	
								60		60	
Depth set at - Me	Plugging and Sea				bandonment ne Placed		Location o				
From T	ivialerial and type		urry, neat cement slurr		c metres)	In diagram below	show distances of well fro arrow.	om road	, lot line, a	ind bui	ilding.
Bis O O.	3 CONCE 83 BENG 66 SANS	ETE -									
0.311	83 BENT	ひひげ	action.			İ	_ /	,			
	66 5ANS					MERP	PIVACE K	1.			
						(employed by an analysis of the second	11/		The state of the s	Contract of the Contract of th	SA Samples Sample
		, , , , , , , , , , , , , , , , , , ,						,			
	M	ethod of C	onstruction	I			1490		N	1	
Cable Tool	☐ Rotary (a		Diamond		Digging		31M \		1,		
Rotary (conve	/ =	ussion	Jetting		Other		1/2000		th	7	
Rotary (revers	se) Boring	Water	☐ Driving 4	oc opyro	<i></i>	{ .	bom		M.		
Domestic	Industria		Public Sup	nly -	Other		LY 2				
Stock	Commer	cial	☐ Not used	140 120	TOD ING	מושפרוווטוינו	8				
Irrigation	Municipa			air conditioning	WELL	Audit No.	66267 Date	e Well C	Completed	<del></del>	
Water Supply	Recharge wel	Final Statu		Abond	annad (Othan)			Delition			06/11
☐ Water Supply ☐ Observation w			☐ Unfinished  pply ☐ Dewatering	Abando	oned, (Other)	Was the well own package delivered		Deliver	eu yy	ΎΥ I	MM DD
Test Hole	Abandoned, p	oor quality	Replaceme	nt well	ECC						
Name of Mail C		ractor/Tech	nician Information		ioonee Nie	Data Source	Ministry Use	Only			
Name of Well Co	THE SPAIN	TOUND!	1111	/ell Contractor's I	, I		·	tractor	24	7	
Business Address	s (street name, number	er, city etc.)	200		<i></i>	Date Received	YYYY MM DD Date	of Insp	ection yy	∰j 'YY	MM DD
141 h	GT BEAL	SER CR	CEL KICITI	WOND H	THE ON		JUL <sub>I</sub> 1 7 <sub>1</sub> 2007			1	
/ / KC	s (street name, number ST BEAL of the street name, fire the street name, fire the street name, fire the street name, fire the street name, fire the street name, fire the street name, fire the street name, fire the street name, fire the street name, fire the street name, fire the street name, number name, fire the street name, number name, nu	કા name)	l <sub>w</sub>	reii jechnician's l	Licence No.	Remarks	Well	Record	d Number		



Well Tau No. (Place Sticker and r Print Below)

A 063281 A 063281

Well Record

	-	•	_		•		•	•	w	•	×	~
Regulation 903 Ontario	οV	Vά	ite	r	R	e:	50	)U	rc	es	A	c

116500000100000000000000000000000000000	s Information										
First Name PINCH	Last Nan	ne RON HENTA		ail Addre	SS			. 🗆 '	Well Co	onstructed I Owner	
Mailing Address	(Street Number/Name, RR)	Municipality	,		Province	Postal Code		Telephone N	-		
200-51			THW	4	ON	KRKB	94				
	ruction and/or Major Altera Location (Street Number/Name		vnship			Lot		Concession			
	HERRIVALE R		0777	NWA		Lot		Concession			
County/District/I	Municipality ,	City	/Town/Villag	e		<u> </u>	Provi		Posta	l Code	
UTM Coordinates	LETO W	orthing GPS I	Jnit Make	Model	Made of	Operation:	<u> </u>	ario			
NAD   8   3	1 10 1 . 07 1 13 6		RMIN		manager of the second	entiated, specify	Unain	erentiated	<u> </u>	eraged	
	d Bedrock Materials (see ins										
General Colour	Most Common Material	Other Material	ls-			Description			Depti From	n (Metres) To	
DRN	FILL	GRAVEL/SI	7.ND		2005	<u> </u>			00		
FRN	5/67	CLAY			RNO	-			), =	> 2,	
GRY	5167	CCAY			WET.			-	2,42	14.5	
(											
4											
						· · · · · · · · · · · · · · · · · · ·					
	Annular Space/Abando	onment Sealing Record				Results of W	all Via	d Testing			
Depth Set at (Me From   To	tres) Type of Se	alant Used	Volume F		Check box if after tes		Di	aw Down		ecovery	
	(,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	па туре).	(Cubic M	letres)	Clear and sand		Time (Min)	Water Level (Metres)	Time (Min)	Water Level (Metres)	
	3 CONCRETE.				Cannot develop	to sand-free	Static		Static Level		
0.2 10	22 BENJONIT	( <del>-</del> -			If pumping discontinu	ied, give reason:	1	***************************************	1	**************************************	
122 41	97 SAND.			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Pumping test metho	vd	2		2		
					, amping toot mound		3				
	of Construction	Water Use			Pump intake set at	(Metres)		***************************************	3		
Cable Tool Rotary (Conver	☐ Diamond ☐ Puntional) ☐ Jetting ☐ Do	iblic Commercia		t used watering	Pumping rate (Litres	/min)	4		4		
Rotary (Revers	e) 🗌 Drîving 📗 Liv	restock Test Hole	<b>₽</b> No	onitoring	, amping the time	,,,,,,,	5		5		
☐ Rotary (Air) ☐ Air percussion		igation Cooling & A	ir Conditionin	g	Duration of pumping	· · · I	10		10		
Other, specific	OF OF NOTE - OI	her, specify			hrs + Final water level end	min of pumping	15		15		
☐ Water Supply	Status	of Well  Observation	and/or Manita	dog Holo	(Metres)		20		20		
Replacement W	Vell Abandoned, Insufficie	nt Supply 🔲 Alteration (0	Construction)	ing note	Recommended pur	p type Deep	25		25	THE CANADA CANAD	
Test Hole Recharge Well	☐ Abandoned, Poor Wa ☐ Abandoned, other, <i>sp</i>		ify		Recommended pur	}	30	4-14-mi	30		
	Location				Metres						
Please provide a n	nap below showing: daries, and measurements sufficie	The state of the s	to fived pain	4-	Recommended purr (Litres/min)	ip rate	40		40		
<ul> <li>an arrow indicatir</li> </ul>	ng the North direction		•	us,	If flowing give rate (Litres/min)		50		50		
- vidigital pictures of	s can be provided as attachments of inside of well can also be provided on the can also be provided on the can also be provided on the can also be provided on the can also be provided on the can also be provided on the can also be provided on the can also be provided on the can also be provided as attachments of the can be provided as attachments of the can also be provided as attachments of the can also be provided as attachments of the can also be provided as attachments of the can also be provided as attachments of the can also be provided as attachments.	no larger than legal size (8.5° ed	oy 14")		(Litres/min)		60		60		
MERKE	ONCE RU.		/	,		Water	Detai	ls			
		130m	7		Water found at Dep		f Wate				
		30101	¥		Metres   Water found at Dep		f Wate	Salty Su	pnur	winerais	
1	17/6 <sub>W</sub>	, }			Metres	☐ Gas ☐ Fre	sh 📋	Salty _Su	phur	Minerals	
		<b>'</b>			Water found at Dep			r Salty	nhur	Minorala	
					Casing Used	Gas Green Used					
	1 7m	٧				Galvanized		Casing and meter of the H			
	<b>4</b> √32				☐Steel [	Steel		meter of the H			
Date Well Comple	eted   Was the well owner's inform	nation   Date the Well Reco	ord and Packa	age		Fibreglass—Plastic		oth of the Hole	(меиез	7	
(yyyy/mr/i/dd) /2	package delivered?	Delivered to Well C			1 -	Concrete	Wa	I Thickness (A			
<del>-                                    </del>	Well Contractor and Well		n		No Casing and	Screen Used	33322	O , Z 5 de Diameter o		sing (Metras)	
Business Name of	Well Contractor	A CONTRACTOR OF THE PROPERTY O	ntractor's Licer	2	Open Hote			<u>3,0</u>			
STATA 3 Business Address	OU SMUPC( W (Street No./Name, number, RR)	Municipality	14		Disinfected?  Yes No		Der	oth of the Casir	ng (Metr	es)	
	BEADER MEEK		no H	MC		Ministry	Usar	nlv	100		
Province	Postal Code Business	E-mail Address			Audit No.	100000000000000000000000000000000000000		intractor No.	100000000000000000000000000000000000000		
Bus Talanhana Ma	(inc. area code) Name of Well Te	udeana stu									
919 571614	19304 7047	HU FENE		3/	Date Received (yyyy/m DEC 1 3 2007	meuu)  I	Jate of	nspection (yy	ryimm/c	a)	
Well Technician's Lic	cence No. Signature of Technicia	Date Su	ubmitted (yy/y								
0506E (11/2006)			<u> </u>	10 / []					60/6/		
COUCE (TIMEOUD)	e e e e e e e e e e e e e e e e e e e		Ministrys	s Copy				© Queen's P	rinter for	Ontario, 2006	

# **APPENDIX 3**

**QUALIFICATIONS OF ASSESSORS** 

## MICHAEL BEAUDOIN, P.ENG.



## **POSITION**

**Environmental Engineer** 

#### **EDUCATION**

Carleton University, B.Eng. 2010 Environmental Engineering

#### **EXPERIENCE**

2010-present
Paterson Group Inc.
Consulting Engineers
Geotechnical and Environmental Division
Environmental Engineer

## Environmental Engineering

## **SELECT LIST OF PROJECTS**

Geotechnical Engineering Rideau Street Reconstruction - Ottawa
Main Street Reconstruction - Ottawa
Woodroffe Avenue Reconstruction - Ottawa
Westboro Connection Remediation - Ottawa
Former Alcan Plant Redevelopment - Kingston
Former Nordex Facility Redevelopment - Kingston
Jack Garland Airport Remediation - North Bay
Highway 17 Twinning Project - Arnprior
Watermain Construction - North Bay
Waste Audits - Various City of Ottawa Facilities

Waste Audits – Various City of Ottawa Facilities Parks Recycling Pilot Program – Various City of Ottawa parks

Special Events Recycling Pilot Program – Special Events with the City of Ottawa Groundwater Remediation and Monitoring Program Supervision – Ottawa Designated Substance Surveys – Residential and Commercial Sites – Ottawa Asbestos Air Testing – Various Locations - Ottawa

Materials Testing Quality Control

Mould Testing – Various Locations - Ottawa Phase I & II Environmental Site Assessments – Residential, Commercial and Industrial Sites – Ottawa (CSA Z768-01 and O.Reg 269/11)

**Building Sciences** 

Hydrogeology

**Archeological Services** 

# patersongroup solution oriented engineering

## Mark S. D'Arcy, P.Eng., QP<sub>ESA</sub> Senior Environmental/Geotechnical Engineer

After receiving his Bachelors of Applied Science from Queen's University in 1991 in Geological Engineering, Mark joined Paterson Group Inc. During the first 10 years of Mark's career, he was heavily involved in all aspects of field work, including drilling boreholes, excavating test pits, conducting phase I site inspections, environmental sampling and analysis and inspection of environmental remediations. During Mark's field experience, he gained invaluable field and office experience, which would prepare Mark to become the Environmental Division Manager. Mark's field experience ranges from Phase I Environmental Site Assessments (ESAs) to on-site soil and groundwater remediations, as well as, environmental/geotechnical borehole investigations. Mark's field experience has provided extensive knowledge of subsurface conditions, contractor relations and project management. These skills would provide Mark with the ability to understand a variety of situations, which has lead Paterson to an extremely successful Environmental Department, Mark became the Environmental Manager in 2006, which consisted of two engineers and two field technicians. Mark has been an integral part in growing the Environmental Division, which now consists of nine engineers and three field technicians. Mark is the Senior Project Manager for a wide variety of environmental projects within the Eastern Ontario area including Phase I ESAs, Phase II ESAs, remediations for filing Records of Site Condition in the Ontario Ministry of the Environment and Climate Change (MOECC) Environmental Site Registry, Brownfield Applications and Landfill Monitoring Programs. As the Senior Project Manager, Mark is responsible for directing project personnel, final report review and overall project success. Mark has proven leadership and ability to manage small to large scale projects within the allotted time and budget.

#### **EDUCATION**

B.A.Sc. 1991, Geological Engineering, Queen's University, Kingston, ON

# LICENCE/ PROFESSIONAL AFFILIATIONS

Professional Engineers of Ontario

ESA Qualified Person with MOECC

Ottawa Geotechnical Group

Consulting Engineers of Ontario

#### YEARS OF EXPERIENCE

With Paterson: 26

#### **OFFICE LOCATION**

154 Colonnade Road South, Nepean, Ontario, K2E 7J5

#### **SELECT LIST OF PROJECTS**

- 222 Beechwood Avenue, Ottawa, Ontario (Senior Project Manager for Phase I ESA, Phase II ESA, Phase III ESA, Environmental Remediation)
- 409 MacKay Street, Ottawa, Ontario (Senior Project Manager for Phase I ESA, Phase II ESA, Phase III ESA, Environmental Remediation)
- Art's Court Redevelopment, Ottawa, Ontario (Senior Project Manager for Phase I ESA, Phase II ESA, Phase III ESA, Environmental Remediation)
- Visitor Welcome Centre, Phase II and Phase III, Parliament Hill, Ottawa, Ontario (Senior Project Manager for Environmental Remediation)
- Mattawa Landfill, Mattawa, Ontario (Senior Project Manager, Annual Water Quality Monitoring report)
- Multi-Phase Redevelopment of the Ottawa Train Yards, Ottawa, Ontario (Senior Project Manager)
- Rideau Centre Expansion, Ottawa, Ontario( Senior Project Manager for Phase I ESA, Phase II ESA, Phase III ESA, Environmental Remediation)
- 26 Stanley Avenue, Ottawa, Ontario, Phase I ESA, Phase II ESA (Senior Project Manager)
- Riverview Development Kingston, Ontario, Phase I ESA, Phase II ESA, and filing of an RSC in the MOECC Environmental Site Registry (Senior Project Manager)
- Monitoring Landfills for River Valley, Kipling and Lavagine (Senior Project Manager)



## **Mark S. D'Arcy,** P.Eng., QP<sub>ESA</sub> Senior Environmental/Geotechnical Engineer

#### **PROFESSIONAL EXPERIENCE**

# May 2001 to present, **Manager of Environmental Division, Paterson Group Inc.,** Ottawa, Ontario

- Manage all aspects of the environmental division (management of personnel, budgeting, invoicing, scheduling, business development, reporting, marketing, and fieldwork).
- Review day to day operations within the environmental division.
- Design, perform, and lead Phase I, II and Phase III ESAs, Remediation's, Brownfield Applications and Record of Site conditions, fieldwork surveys, excavation, monitoring, laboratory analysis, and interpretation.
- Write, present, and publish reports with methodology and laboratory analysis results, along with recommendations for environmental findings.
- Responsible for ensuring projects meet Ministry of Environment and Climate Change Standards and Guidelines.
- Building and fostering relationships with clients, stakeholders, and Ministry officials.
- Supervise and continuous training of staff in environmental methods (environmental sampling techniques, technical expertise and guidance).
- Applied due diligence in ensuring the health and safety of staff and the public in field locations.

## 1991 to 2001, Geotechnical and Environmental Engineer, Paterson Group Inc., Ottawa, Ontario

- Provide on-site geotechnical and environmental expertise to various clients.
- Oversee geotechnical and environmental investigations for drilling and test pitting on numerous proposed utility installations, residential and commercial developments.
- Problem solving to help advance or maintain project schedules.
- Complete environmental reports with recommendations to meet environmental standards set by MOE and CCME standards.
- Conduct site inspections, bearing medium evaluations, bearing surface inspections, concrete testing and field density testing.
- Liaising with contractors, consultants and government officials.
- Provide cost estimates for geotechnical and environmental field programs and construction costs.
- Review RFI's, submittals, monthly progress reports and other various construction related work.